

PDI TUAS

PDI TUAS

HO CHING SUM
3 SPRINGLEAF RISE
Singapore, 787983
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV037860
Quote No. SER/QUO/1800540
QuoteDate 29/03/18
Salesperson Anthony Yong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG)	14	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SDV503C	WVWZZZAUZH116415	30/06/17	Anthony Yong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 146055	5G13HZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR FRONT	3	UNIT		840 2,520.00
P B&P ALEX LABOUR	LABOUR REAR	4	UNIT		1680 3,360.00
P B&P ALEX LABOUR	RE+REINSTALLED REAR WSREE	1	UNIT		840.00
P B&P ALEX LABOUR	TRANSFER BOOT LID PARTS	1	UNIT		420 840.00
P B&P ALEX PAINT	SPRAY PAINT	3	UNIT		800 2,400.00
P B&P ALEX PAINT	SPRAY PAINT	4	UNIT		1600 3,200.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT FRO	1	pcs		80.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT REA	1	pcs		80.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
P B&P MECH	COMPULSORY TO DO AFTER AC				
	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
	Sum Labor				14,080.00
P 5G0805915 9B9	FRONT LOWER SPOILER	1	Pieces		? 162.61
P 5G0805931	HEADLIGHT BRACE SUPPORT L	1	Pieces		? 30.18
P 5G0805932	HEADLIGHT BRACE SUPPORT R	1	Pieces		? 30.18
P 5G0807049A	FRONT BUMPER BRACKET LHS	1	Pieces		? 16.90
P 5G0807050A	FRONT BUMPER BRACKET RHS	1	Pieces		? 16.90
P 5G0807109H	FRONT BUMPER REINFORCEME	1	Pieces		? 460.54
	Use Predecessor 5G0807109B				
P 5G0807217BNGRU	FRONT BUMPER	1	Pieces		ME/98 999.11
P 5G0807248F	FOAM INSERT	1	Pieces		? 34.81
	Use Predecessor 5G0807248D				
P 5G0807305B	BUMPER REINFORCEMENT	1	Pieces		? 629.03
	Successor 5G0807305D				
Sum carried forward					16,460.26

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

HO CHING SUM
3 SPRINGLEAF RISE
Singapore, 787983
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV037860
Quote No. SER/QUO/1800540
QuoteDate 29/03/18
Salesperson Anthony Yong
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG)	14	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SDV503C	WVWZZZAUZH116415	30/06/17	Anthony Yong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 146055	5G13HZ

Continued			16,460.26
P 5G0853651G ZLL	FRONT UPPER GRILLE	1 Pieces	SCA ✓ 441.45
P 5G0853675 ZZZ	NAME PLATE TSI	1 Pieces	NE ✓ 47.16
P 5G0853675AT2ZZ	NAME PLATE 230	1 Pieces	NE ✓ 57.46
P 5G0853687 ZZZ	NAME PLATE GOLF	1 Pieces	NE ✓ 60.65
P 5G0919491	SENSOR BRACKET REAR	1 Pieces	NE ✓ 12.74
P 5G0919491	SENSOR BRACKET REAR	1 Pieces	NE ✓ 12.74
P 5G0919491A	SENSOR BRACKET REAR	1 Pieces	NE ✓ 12.74
P 5G0919492A	SENSOR BRACKET REAR	1 Pieces	NE ✓ 12.74
P 5G0919493	SENSOR BRACKET	1 Pieces	NE ✓ 12.74
P 5G0919493A	SENSOR BRACKET	2 Pieces	NE ✓ 25.48
P 5G0919494	SENSOR BRACKET	1 Pieces	NE ✓ 12.74
P 5G2941005E	HEADLAMP LHS	1 Pieces	? 929.96
	Use Predecessor 5G2941005		
P 5G2941006E	HEADLAMP RHS	1 Pieces	? 929.96
	Use Predecessor 5G2941006		
P 5G6807393	REAR BUMPER BRACKET LHS	1 Pieces	? 31.59
P 5G6807393A	REAR BUMPER RETAINER LHS	1 Pieces	? 31.59
P 5G6807394	REAR BUMPER BRACKET RHS	1 Pieces	? 31.59
P 5G6807394A	REAR BUMPER RETAINER RHS	1 Pieces	? 31.59
P 5G6807417APGRU	REAR BUMPER COVER	1 Pieces	DE ✓ 996.45
	Predecessor 5G6807417ARGRU		
P 5G6807568D 9B9	REAR DIFFUSER SPOILER	1 Pieces	cut ✓ 279.81
	Use Predecessor 5G6807568D		
P 5G6807863A	REAR CENTER STRIP	1 Pieces	? 58.12
	Use Predecessor 5G6807863		
P 5G6827025Q	REAR LID	1 Pieces	BT ✓ 1,174.75
	Use Predecessor 5G6827025H		

Sum carried forward

21,664.31

Payments to:

- BBN: - Acc.-No.:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PDI TUAS

HO CHING SUM
3 SPRINGLEAF RISE
Singapore, 787983
Singapore

PDI TUAS

Phone No.

Fax No.

E-Mail

VAT Registration No. M20098505-2

Tax No. 199101494Z

Service Quote

Customer No. CV037860
Quote No. SER/QUO/1800540
QuoteDate 29/03/18
Salesperson Anthony Yong
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.4 CL 92 (DSG)	14	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SDV503C	WVWZZZAUZH116415	30/06/17	Anthony Yong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CZC 146055	5G13HZ
Continued			21,664.31
P 5Q0919133 9B9	SENSOR O RING	8 Pieces	13.68
P D 002000A2	CLEANER	1 Pieces	128.14
P D 004660M2	2K GLUE	1 Pieces	159.35
P D 00920002	PRIMER	1 Pieces	27.89
P D 00950025	APPLICATOR	2 Pieces	19.38
P D 180KU2A1	2KADHESIVE	1 Pieces	89.84
P D 181802M1	ACTIVATOR	1 Pieces	25.53
P D 822150A1	BONDAGENT	1 Pieces	64.27
	Sum Item		8,112.39
Sum Labor			14,080.00
Sum Item			8,112.39
Total SGD			22,192.39
7% GST			1,553.47
Total SGD Incl. GST			23,745.86

Explanations

P = Proportionately Charged

Payment Terms

No Credit

Payments to:

- BBN: - Acc.-No.:

RASUL
Hp 90010068
8 days
05/04/18 @
Resurvey by paint