



DING AUTOMOTIVE PTE LTD

BLK 10, #01-20 SIN MING INDUSTRIAL EST. SEC C SINGAPORE 575645

TEL : 6452 1208 FAX : 6452 0614

TO :

ESTIMATE REPORT 1ST Quotation

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

FAX NO:

03/04/2018 11:30

JOB-NO: 50110547

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA8981R TRANS: AUTO
MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDi
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 1

CHASSIS: KMHET41VMAA785857
ENGINE: D4EAA868269

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,000.00	0.00	1,000.00		Y	500
2 R&R AC CONDENSER & CHARGE UP GAS	1.00	120.00	0.00	120.00		Y	X
3 ADJUST HEADLAMP AIM & CHECKING WIRING	1.00	50.00	0.00	50.00		Y	30
4 RUST PROOFING	1.00	80.00	0.00	80.00		Y	40
5 RESPRAY BONNET	1.00	250.00	0.00	250.00		Y	180
6 RESPRAY FRT FENDER LH	1.00	250.00	0.00	250.00		Y	180
7 RESPRAY FRT FENDER RH	1.00	250.00	0.00	250.00		Y	X
8 RESPRAY FRT BUMPER	1.00	250.00	0.00	250.00		Y	180
TOTAL:		2,250.00	0.00	2,250.00			

MATERIALS

1 BONNET	1.00	1,101.76	0.00	1,101.76	L	Y	R
2 BONNET HINGE LH	1.00	79.20	0.00	79.20	L	Y	X
3 BONNET HINGE RH	1.00	79.20	0.00	79.20	L	Y	X
4 BONNET DAMPER	1.00	67.76	0.00	67.76	L	Y	X
5 BONNET INSULATOR	1.00	222.75	0.00	222.75	L	Y	X
6 BONNET CHROME	1.00	101.75	0.00	101.75	L	Y	X
7 BONNET LOCK	1.00	108.90	0.00	108.90	L	Y	X
8 BONNET CABLE	1.00	27.61	0.00	27.61	L	Y	X
9 BONNET LOCK COVER	1.00	30.25	0.00	30.25	L	Y	X
10 BONNET SEAL X3	1.00	44.55	0.00	44.55	L	Y	X
11 FRT BUMPER	1.00	515.68	0.00	515.68	L	Y	DE
12 FRT BUMPER PROTECTOR LH	1.00	27.72	0.00	27.72	L	Y	R
13 FRT BUMPER PROTECTOR RH	1.00	27.72	0.00	27.72	L	Y	X
14 FRT BUMPER REINFORCEMENT	1.00	472.78	0.00	472.78	L	Y	X
15 FRT BUMPER BRACKET LH	1.00	79.75	0.00	79.75	L	Y	na
16 FRT BUMPER BRACKET RH	1.00	79.75	0.00	79.75	L	Y	X
17 FRT BUMPER RETAINER LH	1.00	15.40	0.00	15.40	L	Y	na
18 FRT BUMPER RETAINER RH	1.00	15.40	0.00	15.40	L	Y	X
19 FRT BUMPER FOGLAMP COVER LH	1.00	16.50	0.00	16.50	L	Y	X
20 FRT BUMPER FOGLAMP COVER RH	1.00	16.50	0.00	16.50	L	Y	X
21 FRT BUMPER CENTRE GRILL	1.00	49.50	0.00	49.50	L	Y	X
22 FRT BUMPER CHROME MLDG	1.00	91.52	0.00	91.52	L	Y	X
23 FRT BUMPER LWR EXT	1.00	40.04	0.00	40.04	L	Y	X
24 FRT BUMPER SPONGE	1.00	130.35	0.00	130.35	L	Y	X
25 FRT SUPPORT PANEL	1.00	922.02	0.00	922.02	L	Y	X

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
26 FRT SUPPORT PANEL LWR COVER	1.00	71.50	0.00	71.50	L	Y	X
27 HEADLAMP LH	1.00	763.18	0.00	763.18	L	Y	CRA ✓
28 HEADLAMP RH	1.00	763.18	0.00	763.18	L	Y	X
29 HORN LH	1.00	74.25	0.00	74.25	L	Y	X
30 HORN RH	1.00	74.25	0.00	74.25	L	Y	X
31 FRT AIR DUCT	1.00	166.98	0.00	166.98	L	Y	X
32 FRT GRILLE	1.00	265.87	0.00	265.87	L	Y	X
33 FRT GRILLE LOGO	1.00	22.00	0.00	22.00	L	Y	X
34 FRT FENDER LH	1.00	567.38	0.00	567.38	L	Y	PRU ✓
35 FRT FENDER RH	1.00	567.38	0.00	567.38	L	Y	X
36 FRT FENDER SIDE LAMP LH	1.00	40.59	0.00	40.59	L	Y	X
37 FRT FENDER SIDE LAMP RH	1.00	40.59	0.00	40.59	L	Y	X
38 FRT FENDER WHEELHOUSE PANEL LH	1.00	946.55	0.00	946.55	L	Y	X
39 FRT FENDER WHEELHOUSE PANEL RH	1.00	946.55	0.00	946.55	L	Y	X
40 FRT FENDER INNERSHIELD LH	1.00	72.49	0.00	72.49	L	Y	DE ✓
41 FRT FENDER INNERSHIELD RH	1.00	72.49	0.00	72.49	L	Y	X
42 FRT FENDER INNER RUBBER LH	1.00	71.50	0.00	71.50	L	Y	X
43 FRT FENDER INNER RUBBER RH	1.00	71.50	0.00	71.50	L	Y	X
44 BONNET INSULATOR CLIPS(1SET)	1.00	35.00	0.00	35.00	S	Y	X
45 FRT NUMBER PLATE	1.00	35.00	0.00	35.00	S	Y	X
TOTAL:		10,032.59	0.00	10,032.59			
TOTAL PARTS & LABOUR :		12,282.59	0.00	12,282.59			

EXCESS/LOADING:\$S\$ 0.00

No. Of Day:

5 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$S\$

DATE OF SURVEY:

04 / 04 / 18

SURVEYED BY:

Rafael CLKK

CONTACT NO:

900 60068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company