

Estimate

03/04/2018

MS FIRST CAPITAL INSURANCE LIMITED
36 Robinson Road
#16-01 City House
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SKK4943P

Veh Model :- CHEVROLET ORLANDO

Estimate# :- CK417311

Claim # :- TP/CK131213

ACC. Date :- 29/03/18

Terms :- C.O.D Days

Remarks :- MFR 24 JUL 2013 (2013)

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel : (65) 6272 3892
Fax : (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	HEADLAMP LH	1 PC	840.00	840.00
2.	FRONT BUMPER TOP	1 PC	1,125.00	1,125.00
3.	FRONT BUMPER LOWER	1 PC	413.00	413.00
4.	FRONT BUMPER SIDE RETAINER LH	1 PC	28.00	28.00
5.	FRONT BUMPER CLIPS	10 PC	2.50	25.00
6.	FOGLAMP LH - CHECK	1 PC		
7.	FRONT BUMPER SPONGE - CHECK	1 PC		
8.	FRONT BUMPER REINFORCEMENT - CHECK	1 PC		
9.	FRONT FENDER LH - REPAIR	1 PC		
LIST TOTAL S\$				2,431.00
10% DISCOUNT S\$				-243.10
				2,187.90

LABOUR :
TO INSPECT FRONT LIGHTING MECHANISM

TO REPAIR ON FRONT FENDER LH. TO REMOVE &
REPLACE DAMAGED ITEMS. REALIGN CONNECTION

TO SPRAY PAINT ON REPAIRED AREAS

LABOUR TOTAL S\$

Rasul
Hp 90010068
3 days
4/5
25/06/18 @ 1400
Ray after repair
30 50.00
350
300 500.00
400 500.00
1,110.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E. & O.E

NON-TAX AMOUNT S
AMOUNT S\$ 3,297.90
GST @ 7 % 230.85
AMOUNT DUE S\$ 3,528.75

Acknowledged by Repairer

Signature:
Date:

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**