

ASS. REC. BY:

REF: CS/CTI18006314/Urd3ⁿ²

Special Instruction:

Surveyor:
Menmen

ASSIGNMENT (Office)

From (Person): Adeline Chng of CTI Date/Time: 5/4/18 @ 2:38pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGX 7424E Insured: YP 1429K

at Workshop m/s: Specialist's Motor Tel: 6747 2112

of BIK 3018 A Ubi Road 1 # 01-24/25

Policy No: DMCKSN 3007341801 Claim No: SNM18D01765C02

Sum Insured: Excess:

Make of Veh: D.O.A. 31/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement:

Date/Time: 4:38pm @ 5/4/18 Person Contacted: Irene Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate	
	SGX 7424E - NA/MSG18005907/24	D.O.A: 31/03/18
	YP 1429K - NA/CTI17015999/h4	D.O.A: 17/08/17

071/
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGX7424Eat Workshop m/s Spent.

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 33

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

4/9/2022
Vehicle: IN / OUTVeh No: SGX7424EYr Regn: 1 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)Make: Honda StreamC.C. 1799Colour: Brown

A/C: _____

Insured / Std / NI / NA

Sp. Reading: 203407

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRN 684075200747

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6Rear 6

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. 3/3/18D.O.I. 12/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rpt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/4/18 Confirmed L7A 22134
2/5 @ 2100 with note.Red. \$2286.48, 521

RECEIVED 17 APR 2018

Date/Time, File Pass to?



Prel. Report

1) typist

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: -

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

\$ - RS \$

Photos

Others

TOTAL

220Report Format: TPLump Sum / T.B.I: (\$ 2100)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018		05 Apr 2018 14:38 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	MEI KENG ASSOCIATED		
Vehicle Reg. No.:	SGX7424E	Date of Loss:	31/03/2018 00:00 - :59
Claim Type:	TP / SNM18D01765C02	Policy/Cover Note No.:	DMCVSN3007341801
Vehicle Reg. No. (Insured):	YP1429K	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/04/2018]		
Adj Asg. Remarks:	EST \$4386.48, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4100A
Vehicle Details	
Vehicle No.:	SGX7424E
Vehicle to be Exported:	No
Intended De-registration Date:	12 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM SUNROOF 1.8L A
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	R18A11700769
Chassis No.:	JHMRN68407S200747
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,528.00
Original Registration Date:	05 Sep 2007
First Registration Date:	05 Sep 2007
Transfer Count:	2
Actual ARF Paid:	\$22,581.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Sep 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$25,178.00
COE Rebate Amount:	\$22,134.00
Total Rebate Amount:	\$22,134.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Apr 2018

OK

**Post an Advertisement**


Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

May 16 Infiniti Q50 2.0T Premium.Wearnes Warranty



Pristine Infiniti Q50,Most
Premier Mercedes Benz
Engine.LowMileage Done.Call
Now
Shine Connect StarAd



Browse by Category ▼

« Back (1 2 3 4) Next »

Sort b

71 vehicles

Honda Stream

Advan

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mil
Search Selection	Honda Stream		Any	Any	> 10 year(s) old	Any	
		Honda Stream 1.8A RSZ (New 5-yr COE)	\$38,800	\$7,760 /yr	11-Apr-2008	1,799 cc	
		\$2800 Down Payment, Lowest Monthly From \$738 Onwards. Low Interest At 3.68% Per Annum By GV Cars Financing. 1 Warranty/Service By GV In House Workshop. New Full Pure Leather... \$2800 Downpayment Monthly From \$738 Onwards. Lowest 3.68%P.A@GV Cars Financing. GV Credit Pte Ltd Posted: 12-Apr-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda					
		Honda Stream 1.8A RSZ (New 5-yr COE)	\$38,800	\$7,760 /yr	10-Apr-2008	1,799 cc	
		Graded B by STAR \$2800 Down Payment, Lowest Monthly From \$738 Onwards. Low Interest At 3.68% Per Annum By GV Cars Financing. 1 Warranty/service By GV In House Workshop. New Full Pure Leather... GV Credit Pte Ltd Posted: 12-Apr-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda					
		Honda Stream 1.8A (New 5-yr COE)	\$39,500	\$7,900 /yr	08-Apr-2008	1,799 cc	
		Efizzig Motor Traders \$4k All In Drive Away. Fully Serviced, New Paint And Tyre. You Wouldn't Believe The Tip Top Cond Viewing It. No Financial Strain As We Provide In House ... Posted: 12-Apr-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda					
		Honda Stream 1.8A RSZ (COE till 04/2023)	\$39,000	\$7,820 /yr	07-Apr-2008	1,799 cc	
		New Paint, Can Loan Up To 90%. Powerful Engine And Spacious 7 Seaters Mpv You Will Never Miss! Call Us For Viewing Allmotoring.sg ed: 12-Apr-2018 Tags: 2008 Honda Stream, Honda Stream, Honda, Stream, Used Honda					

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SGX7424E/1804069

02nd April 2018

The Manager

Motor Claim Department

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Delivered
2/5 ~~2100~~ 12/4/18
Luo Shu-Hui

Date of Accident : 31st March 2018

Location : 53 Ubi Avenue 1 Carpark

Third Party Claim Vehicle No : YP 1429 K

Repair Cost For Vehicle No : SGX 7424 E Honda Stream

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front fender LH <i>body</i>	1	486.20	\$ 486.20 ✓
2	Front fender cowling LH <i>11</i>	1	97.10	\$ 97.10 X
3	Front fender cowling clips <i>11</i>	1 set	35.00	\$ 35.00 X
4	Front fender lamp LH <i>cu</i>	1	28.00	\$ 28.00 =
5	Front door LH <i>body</i>	1	890.20	\$ 890.20 =
6	Front door w/strip <i>cu</i>	1	102.50	\$ 102.50 ✓
7	Front door mirror assy <i>Deep cut</i>	1	472.80	\$ 472.80 ✓
8	Front door power window regulator gear <i>11</i>	1	397.80	\$ 397.80 X
9	Front door window moulding <i>11</i>	1	89.50	\$ 89.50 X
10	Windscreen wiper garnish <i>11</i>	1	196.50	\$ 196.50 X
				\$ 2,795.60
Less			20%	\$ 559.12
				\$ 2,236.48

1979.7
1583.76

Labour Charges :-

Cut out, renew, knocking & welding front fender LH, front door LH, headlamp LH, door pillar A LH, front bumper, side mirror assy LH, remove & install all damage parts, straighten & re-align body

Amounts
\$ 1,000.00 *300*

Spray painting on damage parts

\$ 900.00 *600*

Tuff-kot on damage parts

\$ 80.00 *60*

Remove & install front door board, glass & etc

\$ 120.00 *60*

Check all lighting after repairs

\$ 50.00 *30*

Labour Charge

\$ 2,150.00 *2633.76*

Total Amount

\$ 4,386.48

GST will be reflected in the final bills.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118006314/URD3N2

Date: 19/04/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3007341801
Claimant Vehicle No :	SGX7424E	Insured Vehicle No :	YP1429K
Date of Loss:	31/03/2018	Nature of Claim:	TP
		Claim No:	SNM18D01765C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGX7424E	Engine No:	R18A11700769
Make & Model:	HONDA STREAM, 1.8 L SUNROOF (A)	Chassis No:	JHMRN68407S200747
Reg. Date:	05/09/2007 (Man. Year: 2007)	Odometer:	203407 km
Colour:	Brown		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,236.48	1,583.76	652.72	29.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,050.00	1,100.00	51.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,386.48	2,633.76	1,752.72	39.96
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	4,386.48	2,100.00	2,286.48	52.13
+ GST 7.00/7.00% (S\$)	307.05	147.00	160.05	52.13
Nett Amount (S\$)	4,693.53	2,247.00	2,446.53	52.13

INSPECTION

Date of Assignment:	05/04/2018	
Date Inspected:	12/04/2018	Inspected At: Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26 Singapore 408711
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Apr 2018)
Parts:	M1-MPV	HONDA STREAM 1.8 L SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGX7424E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER LH	Badly Dented	486.20 FL	*486.20 FL
2	1	*FRONT FENDER COWLING LH	Not Necessary	97.10 FL	*- FL
3	1	*SET FRONT FENDER COWLING CLIPS	Not Necessary	35.00 FL	*- FL
4	1	*FRONT FENDER LAMP LH	Cracked	28.00 FL	*28.00 FL
5	1	*FRONT DOOR LH	Badly Dented	890.20 FL	*890.20 FL
6	1	*FRONT DOOR W/STRIP	Necessary	102.50 FL	*102.50 FL
7	1	*FRONT DOOR MIRROR ASSY	Deep Cut	472.80 FL	*472.80 FL
8	1	*FRONT DOOR POWER WINDOW REGULATOR GEAR	Not Necessary	397.80 FL	*- FL
9	1	*FRONT DOOR WINDOW MOULDING	Not Necessary	89.50 FL	*- FL
10	1	*WINDSCREEN WIPER GARNISH	Not Necessary	196.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,795.60	1,979.70
- List Item Discount on L Items 20.00/20.00% (S\$)	559.12	395.94
Total Parts (S\$)	2,236.48	1,583.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT,RENEW,KNOCKING & WELDING FRONT FINDER LH,FRONT DOOR LH,HEADLAMP LH,DOOR PILLAR A LH,FRONT BUMPER,SIDE MIRROR ASSY LH,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN & RE-ALIGN BODY	New	1,000.00	300.00
2	SPRAY PAINTING ON DAMAGE PARTS	New	900.00	600.00
3	TUFF-KOTE ON DAMAGE PARTS	New	80.00	60.00
4	REMOVE & INSTALL FRONT DOOR BOARD,GLASS & ETC	New	120.00	60.00
5	CHECK ALL LIGHTING AFTER REPAIRS	New	50.00	30.00
Gross Labour Cost (\$\$)			2,150.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >