

INS. CASE OWNER:

Stacey

CC 4 / AXA1800

6/4/18

1/1/18

LKK:
IDAC:

ASSIGNMENT

Surveyor:

Kenneth

DOI:

6/4/2017

Date / Time:

5/4/18

Registered in Merimen:

Pre-assign / CCU / FTE

9FC 1918A



Insured Vehicle No.:

Name of Insured:

WILLIAM WEE LAM

Insured Tel No.:

HP:

92911918

Excess Sec II :S\$

D.O.A.:

1/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SBMOOCOT/38452

Policy No.:

6/1/18/1

Make / Model:

TRUMP

Place of Accident:

SEKANGOH GARDEN WAY

RINDOWBART

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SJB 80900



INSRS:

WSP:

Tel:

Liability:

RMKS:

Ah Lim



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

6/4/18

vinan

Smartclaim

11/4/18

confirm accident details. inform TP claim agree to settle. letter send out

23/7/18

File pass to typist type report

20/11/18

Sett made via SMART

27/11/18

made approve via SMART

letter print photo

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI:	
After call ltr to OI:	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup):	
After call ltr to OI:	
Authorisation To Act:	
Release Voucher:	
Final Repair Bill:	
Car Rental Invoice:	
Towing Invoice:	
LTA / GIA:	
Medical Bill:	
PIR:	
Mandate/Reject Instruction:	
LOD:	
Payment Breakdown Form:	
Post-Repair Photos:	
Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
	20/11/2018	LPP

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$ 3,527.90	(5 days) Reduction: 36%	Email <input type="checkbox"/> Call <input type="checkbox"/>

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	27

Repair Cost:	(w/let) S\$ 3,774.85		
Loss of Rental (LOR):	S\$ 650.00	(5 days) X 130.00	

Loss of Use (LOU):	S\$ -	(5 x days)	
Loss of Income (LOI):	S\$ -	(5 x days)	

LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	S\$ 2.00		

Medical:	S\$ -		
Disbursement:	S\$ -	(e.g. Tow/Independent)	
Legal Cost:	S\$ -		

Total:	S\$ 4,426.85	Global Sum S\$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>

Payee 1:	S\$ 4,426.85	Name 1:	Ah Lim Motor Company
Payee 2: (Strike if N.A.)	S\$ -	Name 2:	
Payee 3: (Strike if N.A.)	S\$ -	Name 3:	

COPY SENT

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: \$150.00

N/S	O/S



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18006323/wb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 05-04-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKC 1918A	Veh. Inspected	SJQ 8090D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	05/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/04/2018	Inspection Date		
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : LIM ENG LIANG ELISHA
BLK 535 SERANGOON NORTH AVE 4
#04-175
SINGAPORE 550535
TEL: 98786320
ATTN:

Claim No: MC0912984
No: MF0911079
Date: 01 Jun 2018
Policy No: SI17V08573
Veh Reg No: SJQ8090D
Make/Model: KIA CARENS 2.0 AT
ABS

Your Ref No: SJQ8090D
Claim Type: Third Party
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJQ8090D

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 TAILGATE	1 PC	1,088.00	
2 TAILGATE INNER LOCK	1 PC	107.00	
3 REAR BUMPER	1 PC	501.00	
4 REAR BUMPER SIDE RETAINERS LH	1 PC	48.50	
5 REAR BUMPER SIDE RETAINERS RH	1 PC	48.50	
6 REAR BUMPER CLIPS	12 PC	24.00	
7 REAR BUMPER LOWER SPOILER BLACK	1 PC	114.00	
		1,931.00	
	Less 10%	193.10	1,737.90
Special Nett			
8 TAILGATE LOGO (CARENS) LH	1 PC	35.00	
9 TAILGATE LOGO (CVVT) RH	1 PC	35.00	
10 TAILGATE LOGO (2.0) RH	1 PC	35.00	
11 TAILGATE LOGO (CYCLE CARRIAGE) RH	1 PC	50.00	
12 TAILGATE LOGO (ELITE)	1 PC	35.00	
13 REVERSE SENSOR	1 SET	200.00	
14 INNER SEAL	1 PC	20.00	
15 WINDSCREEN SEALANT	1 PC	40.00	
		450.00	450.00
LABOUR			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
17 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
18 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	60.00	
19 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	
20 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
21 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
22 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,REAR BUMPER REINFORCEMENT WITH BRACKET.TO KNOCK & REPAIR SPARE TYRE PANEL, TAILAMP PANEL INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmo@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : LIM ENG LIANG ELISHA
BLK 535 SERANGOON NORTH AVE 4
#04-175
SINGAPORE 550535
TEL: 98786320
ATTN:

Claim No: MC0912984
No: MF0911079
Date: 01 Jun 2018
Policy No: SI17V08573
Veh Reg No: SJQ8090D
Make/Model: KIA CARENS 2.0 AT
ABS

Your Ref No: SJQ8090D
Claim Type: Third Party
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJQ8090D

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
23 TO SPRAY TAILGATE,END PANEL,REAR BUMPER,REAR BUMPER REINFORCEMENT WITH BRACKET,TAILAMP PANEL,SPARE TYRE PANEL	1 PC	500.00	
		1,340.00	1,340.00
		Total	S\$ 3,527.90 ✓
		Less Excess	S\$ 0.00
		Amount Before GST	S\$ 3,527.90
		Add GST @ 7%	246.95
		Total Amount Payable	S\$ 3,774.85

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED SEVENTY FOUR AND CENTS EIGHTY FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 06/04/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
AUTHORISED SIGNATURE 3170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM ENG LIANG ELISHA
BLK 535 SERANGOON NORTH AVE 4
#04-175
SINGAPORE 550535
TEL: 98786320
ATTN:

Estimate No: MC0912984
Date: 04 Apr 2018
Policy No: SI17V08573
Veh Reg No: SJQ8090D
Make/Model: KIA CARENS 2.0 AT
ABS

Your Ref No: SJQ8090D
Claim Type: Third Party - Flt
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

Lk 210 PM

Not Authorised
11 Apr 8?
Refusing After Paint
9 - delay

Estimate Repair Cost to Vehicle No :SJQ8090D

Description	Quantity	List Price	Amount
		SS	SS

SPARE PARTS

1 TAILGATE	1 PC	1,088.00	✓
2 TAILGATE HINGE LH - CHECK PRICE	1 PC	0.00	X
3 TAILGATE HINGE RH - CHECK PRICE	1 PC	0.00	✓
4 TAILGATE ABSORBER LH	1 PC	90.00	✓
5 TAILGATE ABSORBER RH	1 PC	90.00	X
6 TAILGATE INNER LOCK - CHECK PRICE	1 PC	0.00	7 - Photo ✓
7 TAILGATE INNER LOCK CATCH	1 PC	13.00	X
8 TAILGATE RUBBER (AT BODY) - CHECK PRICE	1 PC	0.00	X
9 TAILGATE INNER TRIMBOARD - CHECK PRICE	1 PC	0.00	X
10 TAILGATE EMBLEM WITH CTR OUTER GARNISH ASSY - CHECK PRICE	1 PC	0.00	X
11 TAILGATE LOGO (CARENS) LH - CHECK PRICE	1 PC	0.00	35 S40
12 TAILGATE LOGO (CVVT) RH - CHECK PRICE	1 PC	0.00	35
13 TAILGATE LOGO (2.0) RH - CHECK PRICE	1 PC	0.00	35
14 TAILGATE LOGO (CYCLE CARRIAGE) RH - CHECK PRICE	1 PC	0.00	50
15 TAILGATE LOGO (ELITE) - CHECK PRICE	1 PC	0.00	35
16 REAR BUMPER	1 PC	501.00	✓
17 REAR BUMPER SIDE RETAINERS LH - CHECK PRICE	1 PC	0.00	X - photo 48.50
18 REAR BUMPER SIDE RETAINERS RH - CHECK PRICE	1 PC	0.00	X - photo 48.50
19 REAR BUMPER CLIPS	12 PC	24.00	✓
20 REAR BUMPER REINFORCEMENT WITH BRACKET	1 PC	422.00	X
21 REAR BUMPER SPONGE - CHECK PRICE	1 PC	0.00	X
22 REAR BUMPER LOWER SPOILER BLACK	1 PC	114.00	✓
23 REAR END PANEL CHECK PRICE	1 PC	0.00	X
24 REAR END PANEL TOP GARNISH - CHECK PRICE	1 PC	0.00	X
25 TAILLAMP LH	1 PC	357.00	X
26 TAILLAMP RH	1 PC	357.00	✓
27 TAILLAMP CLIPS	6 PC	12.00	X
		3,068.00	
Less 10%		306.80	2,761.20



Special Nett

28 REVERSE SENSOR	1 SET	200.00	X - photo ✓
29 REVERSE CAMERA - CHECK PRICE	1 PC	0.00	X
30 NUMBER PLATE	1 PC	35.00	X
31 INNER SEAL	1 PC	40.00	200.00
32 WINDSCREEN SEALANT	1 PC	40.00	✓
		315.00	315.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM ENG LIANG ELISHA
BLK 535 SERANGOON NORTH AVE 4
#04-175
SINGAPORE 550535
TEL: 98786320
ATTN:

Estimate No: MC0912984
Date: 04 Apr 2018
Policy No: S117V08573
Veh Reg No: SJQ8090D
Make/Model: KIA CARENS 2.0 AT
ABS

Your Ref No: SJQ8090D
Claim Type: Third Party
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

Estimate Repair Cost to Vehicle No :SJQ8090D

Description	Quantity	List Price SS	Amount SS
LABOUR			
33 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
34 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
35 TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	1 PC	80.00	601 *
36 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	280.00	601
37 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	601
38 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	501
39 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	80.00	301
40 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD END PANEL, REAR BUMPER REINFORCEMENT WITH BRACKET, TO KNOCK & REPAIR SPARE TYRE PANEL, TAILAMP PANEL INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	5001
41 TO SPRAY TAILGATE, END PANEL, REAR BUMPER, REAR BUMPER REINFORCEMENT WITH BRACKET, TAILAMP PANEL, SPARE TYRE PANEL.	1 PC	900.00	5001
		2,460.00	2,460.00
		Total	SS 5,536.20
		Add GST @ 7%	387.53
		Total Amount Payable	SS 5,923.73

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED TWENTY THREE AND CENTS SEVENTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
 GST M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM ENG LIANG ELISHA
 BLK 535 SERANGOON NORTH AVE 4
 #04-175
 SINGAPORE 550535
 TEL: 98786320
 ATTN:

Estimate No: MC0912984
 Date: 04 Apr 2018
 Policy No: SI17V08573
 Veh Reg No: SJQ8090D
 Make/Model: KIA CARENS 2.0 AT
 ABS

Your Ref No: SJQ8090D
 Claim Type: Third Party - Road
 Accident Date: 02/04/2018
 TP Veh Reg No: SKC1918A

Lik 210 PM

Not Authorized
 11 Day 8?
 Repair After Paint
 9-5 days

Estimate Repair Cost to Vehicle No :SJQ8090D

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
SPARE PARTS			
1 TAILGATE	1 PC	1,088.00	✓
2 TAILGATE HINGE LH - CHECK PRICE	1 PC	0.00	X
3 TAILGATE HINGE RH - CHECK PRICE	1 PC	0.00	✓
4 TAILGATE ABSORBER LH	1 PC	90.00	✓
5 TAILGATE ABSORBER RH	1 PC	90.00	✓
6 TAILGATE INNER LOCK - CHECK PRICE	1 PC	0.00	?
7 TAILGATE INNER LOCK CATCH	1 PC	13.00	X
8 TAILGATE RUBBER (AT BODY) - CHECK PRICE	1 PC	0.00	?
9 TAILGATE INNER TRIMBOARD - CHECK PRICE	1 PC	0.00	?
10 TAILGATE EMBLEM WITH CTR OUTER GARNISH ASSY - CHECK PRICE	1 PC	0.00	X
11 TAILGATE LOGO (CARENS) LH - CHECK PRICE	1 PC	0.00	—
12 TAILGATE LOGO (CVVT) RH - CHECK PRICE	1 PC	0.00	—
13 TAILGATE LOGO (2.0) RH - CHECK PRICE	1 PC	0.00	—
14 TAILGATE LOGO (CYCLE CARRIAGE) RH - CHECK PRICE	1 PC	0.00	—
15 TAILGATE LOGO (ELITE) - CHECK PRICE	1 PC	0.00	—
16 REAR BUMPER	1 PC	501.00	—
17 REAR BUMPER SIDE RETAINERS LH - CHECK PRICE	1 PC	0.00	X
18 REAR BUMPER SIDE RETAINERS RH - CHECK PRICE	1 PC	0.00	X
19 REAR BUMPER CLIPS	12 PC	24.00	—
20 REAR BUMPER REINFORCEMENT WITH BRACKET	1 PC	422.00	?
21 REAR BUMPER SPONGE - CHECK PRICE	1 PC	0.00	?
22 REAR BUMPER LOWER SPOILER BLACK	1 PC	114.00	✓
23 REAR END PANEL CHECK PRICE	1 PC	0.00	?
24 REAR END PANEL TOP GARNISH - CHECK PRICE	1 PC	0.00	?
25 TAILAMP LH	1 PC	357.00	X
26 TAILAMP RH	1 PC	357.00	✓
27 TAILAMP CLIPS	6 PC	12.00	X
		3,068.00	
	Less 10%	306.80	2,761.20
Special Nett			
28 REVERSE SENSOR	1 SET	200.00	X
29 REVERSE CAMERA - CHECK PRICE	1 PC	0.00	X
30 NUMBER PLATE	1 PC	35.00	X
31 INNER SEAL	1 PC	40.00	2 days
32 WINDSCREEN SEALANT	1 PC	40.00	✓
		315.00	315.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM ENG LIANG ELISHA
 BLK 535 SERANGOON NORTH AVE 4
 #04-175
 SINGAPORE 550535
TEL: 98786320
ATTN:

Estimate No: MC0912984
Date: 04 Apr 2018
Policy No: SH17V08573
Veh Reg No: SJQ8090D
Make/Model: KIA CARENS 2.0 AT
 ABS

Your Ref No: SJQ8090D
Claim Type: Third Party
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

Estimate Repair Cost to Vehicle No :SJQ8090D

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
LABOUR			
33 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
34 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
35 TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	1 PC	80.00	22 601 X
36 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	280.00	601
37 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	601
38 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	501
39 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	80.00	301
40 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD END PANEL, REAR BUMPER REINFORCEMENT WITH BRACKET TO KNOCK & REPAIR SPARE TYRE PANEL, TAILAMP PANEL INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	5001
41 TO SPRAY TAILGATE, END PANEL, REAR BUMPER, REAR BUMPER REINFORCEMENT WITH BRACKET, TAILAMP PANEL, SPARE TYRE PANEL.	1 PC	900.00	5001
		2,460.00	2,460.00
		Total	SS 5,536.20
		Add GST @ 7%	387.53
		Total Amount Payable	SS 5,923.73

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED TWENTY THREE AND CENTS SEVENTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.
 Thank You

LUCK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 0852C

Vehicle Details

Vehicle No.: SJQ8090D
Vehicle to be Exported: No
Intended De-registration Date: 04 Apr 2018
Vehicle Make: KIA
Vehicle Model: CARENS 2.0 AT ABS D/AIRBAG 2WD 5DR
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: G4KA9H352596
Chassis No.: KNAFG521397273674
Maximum Power Output: 108.9 kW (146 bhp)
Open Market Value: \$18,063.00
Original Registration Date: 27 May 2009
First Registration Date: 27 May 2009
Transfer Count: 0
Actual ARF Paid: \$18,063.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 May 2019
PARF Rebate Amount: \$9,934.00

Intended COE Rebate Details

COE Expiry Date: 26 May 2019
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$10,046.00
COE Rebate Amount: \$1,048.00
Total Rebate Amount: \$10,982.00

The information contained herein is correct as at 04 Apr 2018

OK

Poh Kin (LKKAUTO)

From: muihong@ahlimmotor.com.sg
Sent: Monday, 17 December 2018 4:21 PM
To: Vivian Lau (LKKAUTO)
Subject: Re: Claim Documents for our client SJQ8090D accident with AXA Insured - SKC1918A on 02.04.2018

Categories: clear

Dear Vivian,

We refer to your email below and thank you for the email.

For the purpose of a quick and amicable settlement, we will accept the offer.

Pls send over DV soonest

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

From: Vivian Lau (LKKAUTO)
Sent: Tuesday, December 11, 2018 2:16 PM
To: muihong@ahlimmotor.com.sg
Subject: RE: Claim Documents for our client SJQ8090D accident with AXA Insured - SKC1918A on 02.04.2018

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLE NO. SJQ 8090D AND SKC 1918A ON 2/04/2018

We refer to the above matter

On a without prejudice basis, our principal propose settlement as follow:

COST OF REPAIR	\$ 3,774.85
Loss of RENTAL (\$ 120.00 x 5days)	\$ 600.00
LTA SEARCH	\$ 2.00
	\$ 4,376.85

Kindly confirm acceptance

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: <mailto:Vivianlau@lkkauto.com> %7C fax:

6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vivian Lau (LKKAuto)

Sent: Tuesday, 27 November, 2018 2:02 PM

To: muihong@ahlimmotor.com.sg

Subject: RE: Claim Documents for our client SJQ8090D accident with AXA Insured - SKC1918A on 02.04.2018

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLE NO. SJQ 8090D AND SKC 1918A ON 2/04/2018

We refer to the above matter

On a without prejudice basis, our principal propose settlement as follow:

COST OF REPAIR	\$ 3,774.85
Loss of RENTAL (\$ 120.00 x 5days)	\$ 600.00
LTA SEARCH	\$ 2.00
	\$ 4,376.85

Kindly confirm acceptance

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: <mailto:Vivianlau@lkkauto.com> fax:

6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: muihong@ahlimmotor.com.sg [<mailto:muihong@ahlimmotor.com.sg>]

Sent: Tuesday, 17 July, 2018 4:53 PM

To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: Claim Documents for our client SJQ8090D accident with AXA Insured - SKC1918A on 02.04.2018

Dear Vivian,

Pls see attached the Claim Documents for our client SJQ8090D accident with AXA Insured - SKC1918A on 02.04.2018.

Pls assist to offer on the claim.

Thanks

Regards

Kee Mui Hong

Ah Lim Motor @ AMK

No. 10 Ang Mo Kio Ind Pk 2A

#01-09 AMK Autopoint

Singapore 568047

Tel : 64831244 Fax : 64836170

From: Vivian Lau (LKKAuto)

Sent: Monday, April 16, 2018 3:18 PM

To: Zila - Ah Lim Motor Co (AMK)

Subject: RE: TP CASE / SJQ8090D & SKC1918A

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SJQ8090D & SKC1918A

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at her DID 6841 8625.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: <mailto:Vivianlau@lkkauto.com> fax:

6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zila - Ah Lim Motor Co (AMK) [<mailto:zila@ahlimmotor.com.sg>]

Sent: Monday, 16 April, 2018 3:16 PM

To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: Re: TP CASE / SJQ8090D & SKC1918A

Hi Vivian,

Pls advise liability for this case.

Thanks.

Best Regards

Zila

Ah Lim Motor Company

10, Ang Mo Kio Ind Park 2A

#01-09 AMK Autopoint

Singapore 568047

Tel - 64831244 Fax - 64836170

From: Shu Pei (LKKAuto)

Sent: Monday, April 09, 2018 9:16 AM

To: Zila - Ah Lim Motor Co (AMK)
Cc: Admin A ; Vivian Lau (LKKAuto)
Subject: FW: TP CASE / SJQ8090D & SKC1918A

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CC4/ASM18006323/wb3	Vivian

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zila - Ah Lim Motor Co (AMK) [<mailto:zila@ahlimmotor.com.sg>]
Sent: Monday, 9 April 2018 9:10 AM
To: Admin A <admin-a@lkkauto.com>
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: Re: TP CASE / SJQ8090D & SKC1918A

Hi,

Pls advise liability for this case.

Thanks.

Best Regards

Zila

Ah Lim Motor Company

10, Ang Mo Kio Ind Park 2A

#01-09 AMK Autopoint

Singapore 568047

Tel - 64831244 Fax - 64836170

From: Zila - Ah Lim Motor Co (AMK)
Sent: Wednesday, April 04, 2018 5:45 PM
To: CLAIMSDEPT AXA
Subject: TP CASE / SJQ8090D & SKC1918A

Hi Claim Team,

Please kindly arrange survey.

Note: Vehicle is not in. - To be arrange

Best Regards

Zila

Ah Lim Motor Company

10, Ang Mo Kio Ind Park 2A

◀ Re:S8M00CQT- mandate appproval

Type

🔗 Question

Message

PLS PROCEED

Reply

◀ S8M00CQT- mandate approval

Type

🔗 Question

Message

Dear Stacey, we refer to the above matter. Enclosed is the IA Liability(TP) 100% Proposed repair cost \$3,774.85
Loss of use no. of days Loss of rental \$650.00 no. of days 5daysx \$130.00 Loss of income no. of days LTA search
fees \$2.00 Others Proposed Total \$4,426.85 Thank you.Vivian Lau (20.11.18)

Reply



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

Our Ref : MC0912984

Your Ref : SKC1918A

Date : 17/07/2018

AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

Dear Sir/Madam,

Request for Direct Settlement for Accident involving our client's vehicle SJQ8090D and your Insured SKC1918A ON 02/04/2018 16:40 ALONG SERANGOON GARDEN WAY

We refer to the above matter.

Please assess through your Insured's (SKC1918A) report and our Client (SJQ8090D) – LIM ENG LIANG ELISHA's report as attached and advise whether there are possibilities of direct settlement.

Please find attached the following :

- 1) Final Bill
- 2) GIA Motor Accident Report form
- 3) Certificate of Insurance, IC and Driving Licence
- 4) LTA Search & Rental Invoice

The above vehicle was surveyed by Mr Kenneth from LKK as appointed by AXA on 06/04/2018.

We would quantify our claim as below:-

Cost of Repair : \$3,774.85

Rental : \$650.00(5 Day X 130) Surveyor recommend 5 days

LTA Search : \$2.00

=====

Total : \$4,426.85

Kindly acknowledge and revert on the possibility of direct settlement within 14 days.

Thank You.

Yours faithfully,

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

Kee Mui Hong



Auto
Consultants
Pte Ltd

51 UBI AVE L, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

13 April 2018

CHIANG WEE LAM
39A Tavistock Ave
Singapore 555142

Dear Sir/ Mdm

OUR REF : CC4/ASM18006323/wb3
YOUR REF : SKC 1918A

**ACCIDENT INVOLVING SKC 1918A & SJQ 8090D ALONG SERANGOON GARDEN
WAY ON 02/04/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from AH LIM MOTOR CO acting on behalf of the owner of SJQ 8090D against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (0065) 62563561 FAX : (0065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively

Yours sincerely,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AXA Insurance Pte Ltd
(Motor Claims Dept)


Authorisation to Act

I, LIM ENG LIANG ELISHA (the third party claimant)
of BLK 535 #04-175 SERANGOON N. Ave 4 S(550535) (address), owner of
STQ8090D (Vehicle no) hereby authorise **Ah Lim Motor Company**
(the workshop) to act for me in respect to my claim for repair costs and / or rental
and /or loss of use (Claim) for my vehicle No. STQ8090D that was damaged
pursuant to the accident which occurred on 2 APR 2018 (date) along
SERANGOON GARDEN WAY (location) involving
vehicle Nos SKC 1918A (the Accident)

I further authorise the workshop to settle the above mentioned claim in a manner that
they deem fit and the workshop is further authorised to receive the payment further
to settlement of my claim with payment cheque/s made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is
on a without prejudice and without admission of liability basis insofar as the
driver/owner/insurers of the other vehicle is concerned.

Dated this 3 day of April (month) 20 18 (year)

X 
Signed by Third party claimant
Owner Veh No : STQ8090D

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
Signed by the workshop

Personal data Protection Act 2012

I/ We acknowledge and consent to Ah Lim Motor Company collecting , using and disclosing and
/or processing my/our personal data to Third Party service providers and/or Insurance company my
/ our personal data for the purpose of processing the claim and related insurance / claim matters.

X 
Owner Signature



redefining / insurance

CLAIM REF : S8M00CQT
INSURED : CHIANG WEE LAM

DISCHARGE VOUCHER

We/I LIM ENG LIANG ELISHA S7140852C hereby agree to accept the sum of dollars Four Thousand Four Hundred Twenty Six and Cents Eight Five Only (\$\$ 4,426.85) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. SKC 1918A as a result of an accident along SERANGOON GARDEN WAY ROUNABOUT on 02/04/2018 of which we/I were/was the driver/owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SIQ 8090D.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SKC 1918A in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SKC 1918A.

Dated this 1st day of JAN 2018

Claimant's Signature

[Signature] X

NRIC no./ Company Stamp

S7140852C

Occupation/ Business

Address

BIK 535, SERANGOON NORTH AVE 4 # 04-175 SE 550535

Telephone No.

AXA LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-03 AMK Autopoint Singapore 568047
Tel: 6453 1244 Fax: 6453 6170

Witness's Name

Witness's Signature

[Signature]

Witness's NRIC No.



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LIM ENG LIANG ELISHA
BLK 535 SERANGOON NORTH AVE 4
#04-175
SINGAPORE 550535
TEL: 98786320
ATTN:
Your Ref No: SJQ8090D
Claim Type: Third Party
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

Claim No: MC0912984
No: AL0928387
Date: 17 Jul 2018
Policy No: SI17V08573
Veh Reg No: SJQ8090D
Make/Model: KIA CARENS 2.0 AT ABS

Tax Invoice-Final Repair Cost to Vehicle No :SJQ8090D

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 TAILGATE	1 PC	1,088.00	
2 TAILGATE INNER LOCK	1 PC	107.00	
3 REAR BUMPER	1 PC	501.00	
4 REAR BUMPER SIDE RETAINERS LH	1 PC	48.50	
5 REAR BUMPER SIDE RETAINERS RH	1 PC	48.50	
6 REAR BUMPER CLIPS	12 PC	24.00	
7 REAR BUMPER LOWER SPOILER BLACK	1 PC	114.00	
		1,931.00	
	Less 10%	193.10	1,737.90
Special Nett			
8 TAILGATE LOGO (CARENS) LH	1 PC	35.00	
9 TAILGATE LOGO (CVVT) RH	1 PC	35.00	
10 TAILGATE LOGO (2.0) RH	1 PC	35.00	
11 TAILGATE LOGO (CYCLE CARRIAGE) RH	1 PC	50.00	
12 TAILGATE LOGO (ELITE)	1 PC	35.00	
13 REVERSE SENSOR	1 SET	200.00	
14 INNER SEAL	1 PC	20.00	
15 WINDSCREEN SEALANT	1 PC	40.00	
		450.00	450.00
LABOUR			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
17 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
18 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	60.00	
19 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	
20 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
21 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	30.00	
22 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,REAR BUMPER REINFORCEMENT WITH BRACKET.TO KNOCK & REPAIR SPARE TYRE PANEL, TAILAMP PANEL INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
23 TO SPRAY TAILGATE,END PANEL,REAR BUMPER,REAR BUMPER REINFORCEMENT WITH BRACKET,TAILAMP PANEL,SPARE TYRE PANEL.	1 PC	500.00	

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : LIM ENG LIANG ELISHA
BLK 535 SERANGOON NORTH AVE 4
#04-175
SINGAPORE 550535
TEL: 98786320
ATTN:
Your Ref No: SJQ8090D
Claim Type: Third Party
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

Claim No: MC0912984
No: AL0928387
Date: 17 Jul 2018
Policy No: SI17V08573
Veh Reg No: SJQ8090D
Make/Model: KIA CARENS 2.0 AT ABS

Tax Invoice-Final Repair Cost to Vehicle No :SJQ8090D

Description	Quantity	List Price	Amount
		S\$	S\$
		1,340.00	1,340.00
		Total	S\$ 3,527.90
		Less Excess	S\$ 0.00
		Amount Before GST	S\$ 3,527.90
		Add GST @ 7%	246.95
		Total Amount Payable	S\$ 3,774.85

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED SEVENTY FOUR AND CENTS EIGHTY FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 06/04/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park, /A/
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

E. & O. E.

AUTHORIZED SIGNATURE

ACE Auto

18 Ubi Road 4, #02-07 Singapore 408616
Tel: 6483 6143 Fax: 6483 6170
Registration No. 53029719 A

Excess \$12,500 O.D.
\$1,500 T.P

No. 4077

RENTAL AGREEMENT / INVOICE

Hirer's Name		Date of Birth	Passport / Nric No.	Nationality
Address		Occupation	Driving Licence No.	Date of Licence Obtained
Postal Code		Contact No.	Mobile Phone No.	Own Vehicle No.
Driver Name		Date of Birth	Passport / Nric No.	Nationality
Address		Occupation	Driving Licence No.	Date of Licence Obtained
Postal Code		Contact No.	Mobile Phone No.	

CHECK OUT

CHECK IN

Date	17/4/18	Time	5:30 AM	Mileage	124704 KM	E	1/2	3/4	F
Date	20/4/18	Time	3:45 PM	Mileage	124928 KM	E	1/2	3/4	F

VEHICLE NO.	SJP 14202	MODEL	Honda Civic 1.8 A-1
-------------	-----------	-------	---------------------

IMPORTANT NOTES:-

- This vehicle is restricted to SINGAPORE use only.
- BE WARNED: Hirer / Driver shall be fully responsible for all consequences including all outstanding summons and all costs incurred to & by the owner for any invalid entry in Malaysia.
- No refund will be given for vehicle that returns early.
- The hirer shall be liable to pay the first \$2500 for damage to vehicle plus loss of earnings while damaged vehicle is under repair.
- Third Party Liability is \$1500 any accident.
- Hirer shall pay all parking fines & traffic summons, incurred during the period of rental.
- Extension:- One day's advance notice is required otherwise No extension will be allowed.
- Vehicle should be returned at the same time as collection except on Saturday where return time is before 10am.
- Vehicle returned after office hour will be charged to the next working day.
- Hourly extension:- Refer to prevailing rates.
- Please check water & engine oil daily as preventive maintenance.

	UNIT	RATE (\$)	TOTAL (\$)
RATE PER DAY	@		
RATE PER WEEK	@		
RATE PER MONTH	@		
GRAND TOTAL			
DEPOSIT			
EXTENSION ____ DAYS			
TOTAL PAYABLE AMOUNT			
DEPOSIT REFUNDABLE	SS		
CHANGED OVER FROM VEH.		DATE	

I/We have read and agree to the terms and conditions of the rental agreement above and as set out hereof.
I/We declare that all information given on this form is true and accurate.

Hirer's Signature

Driver Signature

for ACE Auto

Ace Auto

18, Ubi Road 4 #02-05 Ubi Car Mall
Singapore 408616 Reg no : 53029719A

To : Ah Lim Motor Company
10 Ang Mo Kio Ind Park 2A
#01-09 AMK Autopoint
Singapore 568047

Invoice No : A4077

Date 22/04/2018

Vehicle No : SJP1420L

Make / Model : Honda Stream

Rent to : Teo Wee Gek - SJQ8090D

Account : Ah Lim Motor Company

Rental Ref : 4077

Duration : From: 17/04/2018 08.30am
To : 22/04/2018 08.45am

No. of days	Rate	Total
5	\$ 130.00	\$ 650.00
Grand Total		\$ 650.00

ACE AUTO


.....
for Ace Auto

**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-050493

Date of Request: 04/04/2018

Your Ref No:

Online Purchase

Ah Lim Motor Company
10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint
Singapore 568047

Dear Sir/Madam,

Enquiry Date 04/04/2018
Enquiry By Kee Mui Hong
TP Vehicle No. SKC1918A
Accident Date 02/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKC1918A	AXA Insurance Pte Ltd	28/02/2018-27/02/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-050493
Date of Request: 04/04/2018

Your Ref No: Online Purchase

Ah Lim Motor Company
10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint
Singapore 568047

Dear Sir/Madam,

Enquiry Date: 04/04/2018
Enquiry By: Kee Mui Hong
TP Vehicle No: SKC1918A
Accident Date: 02/04/2018

DESCRIPTION	AMOUNT (\$S)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKC 1918A (Insd veh)	Model:	KIA CARENS (A)
	SJQ 8090D (TP veh)		
Date of Accident:	02/04/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	6,323.49
Final Repair Cost	:	\$	3,774.85
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	650.00 5 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	4,426.85

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	AH LIM MOTOR COMPANY	:	\$ 4,426.85

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

11/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18006323/Kfb3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG		Date : 11-01-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKC 1918A	Veh. Inspected	SJQ 8090D	
Policy No.	GA168282/1	Coverage (\$)	0.00	
Claim No.	S8M00CQT	Excess (\$)	0.00	
Assign From		Assign Date	05/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA CARENS (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KNAFG521397273674	Colour	METALLIC SILVER	
Odometer	182780	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	FIRESTONE	6 mm	
L/H Front Tyre	215/45 R17	FIRESTONE	6 mm	
R/H Rear Tyre	215/45 R17	BRIDGESTONE	2 mm	
L/H Rear Tyre	215/45 R17	BRIDGESTONE	2 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/04/2018	Inspection Date	06/04/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJQ 8090D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE (CONSISTENT)	BENT	1,088.00	1,088.00
1	TAILGATE HINGE LH (NPA)(CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	TAILGATE HINGE RH (NPA)(CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	TAILGATE ABSORBER LH (CONSISTENT)	SERVICEABLE	90.00	-
1	TAILGATE ABSORBER RH (CONSISTENT)	SERVICEABLE	90.00	-
1	TAILGATE INNER LOCK (CONSISTENT)	DENTED	107.00	107.00
1	TAILGATE INNER LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	13.00	-
1	TAILGATE RUBBER (AT BODY) (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	TAILGATE INNER TRIMBOARD (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	TAILGATE EMBLEM WITH CTR OUTER GARNISH ASSY (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	REAR BUMPER (CONSISTENT)	BUCKLED	501.00	501.00
1	REAR BUMPER SIDE RETAINERS LH (CONSISTENT)	DISTORTED	48.50	48.50
1	REAR BUMPER SIDE RETAINERS RH (CONSISTENT)	DISTORTED	48.50	48.50
12	REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	24.00	24.00
1	REAR BUMPER REINFORCEMENT WITH BRACKET (CONSISTENT)	SERVICEABLE	422.00	-
1	REAR BUMPER SPONGE (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	REAR BUMPER LOWER SPOILER BLACK (CONSISTENT)	DENTED	114.00	114.00
1	REAR END PANEL (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR END PANEL TOP GARNISH (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	TAILAMP LH (CONSISTENT)	SERVICEABLE	357.00	-
1	TAILAMP RH (CONSISTENT)	SERVICEABLE	357.00	-
6	TAILAMP CLIPS (CONSISTENT)	NOT NECESSARY	12.00	-
	LESS 10% DISCOUNT		-327.20	-193.10
			2,944.80	1,737.90
SPECIAL NETT ITEMS				
1	TAILGATE LOGO (CARENS) LH (CONSISTENT) (SN)	NECESSARY	35.00	35.00

Report Ref No. CC4/ASM18006323/Kfb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE LOGO (CVVT) RH (CONSISTENT) (SN)	NECESSARY	✓ 35.00	35.00
1	TAILGATE LOGO (2.0) RH (CONSISTENT) (SN)	NECESSARY	✓ 35.00	35.00
1	TAILGATE LOGO (CYCLE CARRIAGE) RH (CONSISTENT) (SN)	NECESSARY	✓ 50.00	50.00
1	TAILGATE LOGO (ELITE) (CONSISTENT) (SN)	NECESSARY	✓ 35.00	35.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	✓ 200.00	200.00
1	REVERSE CAMERA (NPA) (SN) (CONSISTENT)	SERVICEABLE	✓ -	-
1	NUMBER PLATE (SN) (CONSISTENT)	SERVICEABLE	✓ 35.00	-
1	INNER SEAL (SN) (CONSISTENT)	NECESSARY	✓ 40.00	20.00
1	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	✓ 40.00	40.00
			505.00	450.00
	LABOUR			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING.		✓ 40.00	20.00
	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN.		✓ 120.00	120.00
	TO REMOVE & REINSTALL /REPLACE REVERSE CAMERA.	NOT NECESSARY	✓ 80.00	-
	TO REMOVE AND REINSTALL CUSHIONS,SEATS ,BACKREST,INNER TRIM ,GARNISH ,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.		✓ 280.00	60.00
	TO REMOVE AND REINSTALL /REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.		✓ 80.00	60.00
	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS.		✓ 80.00	50.00
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		✓ 80.00	30.00
	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD END PANEL,REAR BUMPER REINFORCEMENT WITH BRACKET.TO KNOCK & REPAIR SPARE TYRE PANEL,TAILLAMP PANEL INNER PANELS & AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF TAILGATE HINGE LH,TAILGATE HINGE RH,TAILGATE INNER LOCK CATCH AND REAR END PANEL .		✓ 800.00	500.00

Report Ref No. CC4/ASM18006323/Kfb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY TAILGATE ,END PANEL,REAR BUMPER ,REAR BUMPER REINFORCEMENT WITH BRACKET ,TAILAMP PANEL,SPARE TYRE PANEL.		900.00	500.00
			2,460.00	1,340.00
GRAND TOTAL			5,909.80	3,527.90
RECOMMENDED COST OF REPAIRS				3,527.90

Report Ref No. CC4/ASM18006323/Kfb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Vehicle Information	
Incident Vehicle Registration #	SJQ89900
Make	TPVD KIA
Model	CARENS 2.0 AT ABS D/ARBAG 2WD SDR
Service Address	
Primary Contact/Insured	
CHIANG WEE LAM 22, WORTHING ROAD, 554956, Singapore	
boby@ceibwell.com.sg	
Claim Handler	
NG Stacy 6568804351 stacy.ng@saka.com.sg	

Additional investigations

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type: Document Subtype						
<div> <div></div> <div></div> <div></div> </div>						
Upload Documents						

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LHKInvoice1 (3).pdf	Invoice	Surveyor/ Assessor expense	LHK AUTO CONSULTANTS PTE LTD (TP)	14 January 2019

