



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM ENG LIANG ELISHA
BLK 535 SERANGOON NORTH AVE 4
#04-175
SINGAPORE 550535
TEL: 98786320
ATTN:

Estimate No: MC0912984
Date: 04 Apr 2018
Policy No: SI17V08573
Veh Reg No: SJQ8090D
Make/Model: KIA CARENS 2.0 AT
ABS

Your Ref No: SJQ8090D
Claim Type: Third Party
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

Estimate Repair Cost to Vehicle No :SJQ8090D

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 TAILGATE	1 PC	1,088.00	
2 TAILGATE HINGE LH - CHECK PRICE	1 PC	0.00	
3 TAILGATE HINGE RH - CHECK PRICE	1 PC	0.00	
4 TAILGATE ABSORBER LH	1 PC	90.00	
5 TAILGATE ABSORBER RH	1 PC	90.00	
6 TAILGATE INNER LOCK - CHECK PRICE	1 PC	0.00	
7 TAILGATE INNER LOCK CATCH	1 PC	13.00	
8 TAILGATE RUBBER (AT BODY) - CHECK PRICE	1 PC	0.00	
9 TAILGATE INNER TRIMBOARD - CHECK PRICE	1 PC	0.00	
10 TAILGATE EMBLEM WITH CTR OUTER GARNISH ASSY - CHECK PRICE	1 PC	0.00	
11 TAILGATE LOGO (CARENS) LH - CHECK PRICE	1 PC	0.00	
12 TAILGATE LOGO (CVVT) RH - CHECK PRICE	1 PC	0.00	
13 TAILGATE LOGO (2.0) RH - CHECK PRICE	1 PC	0.00	
14 TAILGATE LOGO (CYCLE CARRIAGE) RH - CHECK PRICE	1 PC	0.00	
15 TAILGATE LOGO (ELITE) - CHECK PRICE	1 PC	0.00	
16 REAR BUMPER	1 PC	501.00	
17 REAR BUMPER SIDE RETAINERS LH - CHECK PRICE	1 PC	0.00	
18 REAR BUMPER SIDE RETAINERS RH - CHECK PRICE	1 PC	0.00	
19 REAR BUMPER CLIPS	12 PC	24.00	
20 REAR BUMPER REINFORCEMENT WITH BRACKET	1 PC	422.00	
21 REAR BUMPER SPONGE - CHECK PRICE	1 PC	0.00	
22 REAR BUMPER LOWER SPOILER BLACK	1 PC	114.00	
23 REAR END PANEL CHECK PRICE	1 PC	0.00	
24 REAR END PANEL TOP GARNISH - CHECK PRICE	1 PC	0.00	
25 TAILAMP LH	1 PC	357.00	
26 TAILAMP RH	1 PC	357.00	
27 TAILAMP CLIPS	6 PC	12.00	
		3,068.00	
	Less 10%	306.80	2,761.20
Special Nett			
28 REVERSE SENSOR	1 SET	200.00	
29 REVERSE CAMERA - CHECK PRICE	1 PC	0.00	
30 NUMBER PLATE	1 PC	35.00	
31 INNER SEAL	1 PC	40.00	
32 WINDSCREEN SEALANT	1 PC	40.00	
		315.00	315.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LIM ENG LIANG ELISHA
BLK 535 SERANGOON NORTH AVE 4
#04-175
SINGAPORE 550535
TEL: 98786320
ATTN:

Estimate No: MC0912984
Date: 04 Apr 2018
Policy No: SI17V08573
Veh Reg No: SJQ8090D
Make/Model: KIA CARENS 2.0 AT
ABS

Your Ref No: SJQ8090D
Claim Type: Third Party
Accident Date: 02/04/2018
TP Veh Reg No: SKC1918A

Estimate Repair Cost to Vehicle No :SJQ8090D

Description	Quantity	List Price S\$	Amount S\$
LABOUR			
33 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
34 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	
35 TO REMOVE & REINSTALL/REPLACE REVERSE CAMERA	1 PC	80.00	
36 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	280.00	
37 TO REMOVE AND REINSTALL/REPLACE WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	80.00	
38 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	
39 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	80.00	
40 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL,REAR BUMPER REINFORCEMENT WITH BRACKET.TO KNOCK & REPAIR SPARE TYRE PANEL, TAILAMP PANEL INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	
41 TO SPRAY TAILGATE,END PANEL,REAR BUMPER,REAR BUMPER REINFORCEMENT WITH BRACKET,TAILAMP PANEL,SPARE TYRE PANEL.	1 PC	900.00	
		2,460.00	2,460.00
		Total	S\$ 5,536.20
		Add GST @ 7%	387.53
		Total Amount Payable	S\$ 5,923.73

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED TWENTY THREE AND CENTS SEVENTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0852C

Vehicle Details

Vehicle No.: SJQ8090D
Vehicle to be Exported: No
Intended De-registration Date: 04 Apr 2018
Vehicle Make: KIA
Vehicle Model: CARENS 2.0 AT ABS D/AIRBAG 2WD 5DR
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: G4KA9H352596
Chassis No.: KNAFG521397273674
Maximum Power Output: 108.9 kW (146 bhp)
Open Market Value: \$18,063.00
Original Registration Date: 27 May 2009
First Registration Date: 27 May 2009
Transfer Count: 0
Actual ARF Paid: \$18,063.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 May 2019
PARF Rebate Amount: \$9,934.00

Intended COE Rebate Details

COE Expiry Date: 26 May 2019
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$10,046.00
COE Rebate Amount: \$1,048.00
Total Rebate Amount: \$10,982.00

The information contained herein is correct as at 04 Apr 2018

OK