



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18006325/T1pb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 10-06-2019



ATTN: VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 2800R	Veh. Inspected	SLC 39G
Policy No.	P1489850	Coverage (\$)	0.00
Claim No.	S8M00CLX	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	05/04/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ SLC180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDD1724312F152022	Colour	GREY
Odometer	2415	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/35R18	PIRELLI	6 mm
L/H Front Tyre	245/35R18	PIRELLI	6 mm
R/H Rear Tyre	245/35R18	PIRELLI	6 mm
L/H Rear Tyre	245/35R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/03/2018	Inspection Date	15/05/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------