



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32505

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 02/04/2018
CLAIM NO. : 11127
POLICY NO. : AVFMSB0000611801
FROM : RAYMOND

VEHICLE NO. : FBC6865S
MAKE/MODEL : YAM / YBR125

*Not Allowed
2 hr
P/P \$120
2 day.
6/4/18
Take photo After repair*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	2.00	\$35.00	70.00
2	LENS SIGNAL FRONT RH P/N: 26599	REPLACE	1.00	\$12.00	12.00 X
3	LEVER BRAKE P/N: 26343	REPLACE	1.00	\$19.00	19.00 X
4	MID WASHER WAVE 90206-06090 P/N: 22565	REPLACE	4.00	\$1.50	6.00 X
5	MIRROR RH P/N: 52701	REPLACE	1.00	\$30.00	30.00 X
6	PROTECTOR MUFFLER (REAR) P/N: 27115	REPLACE	1.00	\$32.00	32.00 X
7	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	1.00	\$14.00	14.00 X
8	SPRAY PAINT ON CRASH BAR	Spray	1.00	\$50.00	50.00 X
9	SPRAY PAINT ON FRONT cowling fender	Spray	1.00	\$65.00	65.00
10	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	\$35.00	35.00 ✓
11	WASHER, PLATE	REPLACE	4.00	\$1.50	6.00 X
12	WASHER, PLATE	REPLACE	4.00	\$1.50	6.00 X

SUB TOTAL

\$345.00



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL					\$369.15

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence **notify**
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during **resurvey**
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

