

ASS. REC. BY: Adrian King

REF:

003 / ALG18006401 / Agbrz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 17000 63086Claims No. 13157784555Sum Insured: _____ Excess: of - 9/4/13

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 125K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: 25 Consistent?: Yes or NoEst. Repairs: 1508/8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SL85124 Yr Regn: 2017, octType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q2 c.c. 999Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 8945 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ6AXA055607Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17R: 215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. ob mm R/Bal. ob mmL/Bal. ob mm L/Bal. ob mmD.O.A. _____ D.O.I. 06/04/18Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

09/4/18 @ 4.01pm report to Victor via messenger.
 09/4/18 @ 6.45pm Victor informed c/a via messenger.
 10/4/18 @ 8.49am informed Jeffrey c/a & ext of by email.
 09/11/18 @ 10.47am 2nd report to Victor via messenger (supplementary).
 11/4/19 @ 2.01pm Victor informed c/a at 825011.20 via messenger.
 08/4/19 @ 4.10pm confirmed with Carline from fig 825011.20, 18 days by email.
 (Ref 825046, 28%)

Date/Time, File Pass to?

☐ : Preli. Report

11/26/14 by [Signature]

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: MCR-00Lump Sum / I.B.I: (\$ 85011.20)

RECEIVED 26 APR 2019

Days Of Repair: 18Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18006451/Aqb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 09-04-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLS 8512U
Policy No. 1700063086	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	06/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 03/04/2018	Inspection Date 06/04/2018
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 09 Nov 2018

Preliminary Advice

Vehicle No	: SLS8512U	Accident Date	: 03/04/2018
Make	: AUDI Q2	Policy No.	: 1700063086
Assignment Date	: 09/04/2018	Excess	: S\$0.00
Date of Inspection	: 06/04/2018	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,657.20	(ESTIMATE \$33,954.80 + SUPPLEMENTARY 1 \$202.40 + SUPPLEMENTARY 2 \$500.00)
Revised Amount	:S\$	25,511.20	(INCLUSIVE OF SUPPLEMENTARY & CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	25,511.20	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	53,551.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,449.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 28 Mar 2019

Preliminary Advice

Vehicle No	: SLS8512U	Accident Date	: 03/04/2018
Make	: AUDI Q2	Policy No.	: 1700063086
Assignment Date	: 09/04/2018	Excess	: S\$0.00
Date of Inspection	: 06/04/2018	Est. Duration of Repair	: 18.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,657.20	(ESTIMATE \$33,954.80 + SUPPLEMENTARY 1 \$202.40 + SUPPLEMENTARY \$500.00)
Revised Amount	:S\$	25,011.20	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	25,011.20	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	53,551.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,449.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS. (EXCLUDE PAINT PROTECTION)

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 09 Apr 2018

Preliminary Advice

Vehicle No	: SLS8512U	Accident Date	: 03/04/2018
Make	: AUDI Q2	Policy No.	: 1700063086
Assignment Date	: 09/04/2018	Excess	: S\$0.00
Date of Inspection	: 06/04/2018	Est. Duration of Repair	: 15.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,732.00
Revised Amount	:S\$	20,109.00
Check Items (Estimated)	:S\$	7,050.00
Total	:S\$	27,159.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	125,000.00
COE / PARF Rebate	:S\$	53,551.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,449.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 8 April 2019 4:10 PM
To: Carrine Leong; Adrian Ling (LKKAUTO); SUR
Cc: 'Chang Chee Sing'; jayee.yap@premiumauto.com.sg;
nora.khai@premiumauto.com.sg; 'Johnny Boo'
Subject: RE: FINAL REVISION - SLS8512U - OD AIG - SURVEYED 6 APR 18

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$25,011.20 before excess \$0/- & GST and 18 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 28 March 2019 4:43 PM
To: Carrine Leong <carrine.leong@premiumauto.com.sg>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Chang Chee Sing' <claims@premiumauto.com.sg>; jayee.yap@premiumauto.com.sg;
nora.khai@premiumauto.com.sg; 'Johnny Boo' <boojohnny@gmail.com>
Subject: RE: FINAL REVISION - SLS8512U - OD AIG - SURVEYED 6 APR 18

Dear Carrine,

Please note that our surveyor recommend 18 repair days instead of 25 days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 28 March 2019 4:33 PM
To: Carrine Leong <carrine.leong@premiumauto.com.sg>; Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Chang Chee Sing' <claims@premiumauto.com.sg>; jayee.yap@premiumauto.com.sg;
nora.khai@premiumauto.com.sg; 'Johnny Boo' <boojohnny@gmail.com>
Subject: RE: FINAL REVISION - SLS8512U - OD AIG - SURVEYED 6 APR 18

Dear Carrine,

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	04 Apr 2018 19:43	Cim Veh Model Changed		[] Merimen Administrator
2	04 Apr 2018 19:43	Cim Created	Reg No: SLS8512U, Policy No: 1700063086, Acct Date: 2018/04/03, Claim Type: S C, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Cr eated from SAS:MPA118045186	[I] Merimen Administrator
3	09 Apr 2018 11:24	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	09 Apr 2018 11:24	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	09 Apr 2018 11:24	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	09 Apr 2018 11:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/18	[A] CATHERINE CHONG KAI LING
7	09 Apr 2018 11:24	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	09 Apr 2018 11:24	Cim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	09 Apr 2018 11:24	Cim Veh Model Changed	(205236) AUDI Q2 999cc TFSI S-TRONIC (A).	[A] CATHERINE CHONG KAI LING
10	09 Apr 2018 11:24	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	09 Apr 2018 15:37	Cim Registration Modified	Init.Est.:>5,000 - 6,000, Excess: -> 0.00, 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Tr, Tinesh
12	09 Apr 2018 15:37	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
13	09 Apr 2018 15:49	Adj Rpt Initiated		[A] SHIAU CHAN
14	09 Apr 2018 15:49	Cim Dtl Modified	JPI Reg. Date: -> 2017/10/09.	[A] SHIAU CHAN
15	09 Apr 2018 15:49	Cim Details Notified		[A] SHIAU CHAN
16	09 Apr 2018 15:58	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/18	[A] SHIAU CHAN
17	09 Apr 2018 16:00	Adj Mandate Request	Cur.Reg:27159.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	09 Apr 2018 16:45	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/18, Mandate Remarks: Re-inspection to be d one for damage check and supplementary items / labour. B/F paint photos require d.	[I] Koh, Victor-CK
19	09 Apr 2018 16:45	Adj Mandate Set	Approved:20109.00:Re-inspection to be done for damage check and supplementar y items / labour, B/F paint photos required.Reinsp:Yes.	[I] Koh, Victor-CK
20	12 Apr 2018 10:12	Cim Registration Modified	Acct Time:18:00:00->17:00:00.	[I] AIG OneClaim Integration User
21	09 Nov 2018 10:46	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/18	[A] SHIAU CHAN
22	09 Nov 2018 10:47	Adj Mandate Request	Cur.Reg:25511.20:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. KINDLY AP PROVE ON SUPPLEMENTARY & CHECK ITEMS.	[A] SHIAU CHAN
23	04 Dec 2018 12:03	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/04/18, Mandate Remarks: Damage photos o f Front silencer? Sales agreement for supplementary labour paint protection? Subm it survey report.	[I] Koh, Victor-CK
24	04 Dec 2018 12:03	Adj Mandate Set	Maintained:Damage photos of Front silencer? Sales agreement for supplementary l abour paint protection? Submit survey report.	[I] Koh, Victor-CK
25	05 Dec 2018 09:28	Adj Mandate Request	Cur.Reg:25511.20:Please refer to the photo 45 and 46 are show the front and rear silencer and document of sales agreement for supplementary labour paint protectio n already uploaded. Kindly advise on the authorisation.	[A] SHIAU CHAN
26	18 Jan 2019 14:53	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/04/18, Mandate Remarks: As mention, the p aint protection done by Insured is not cover. Kindly take out and re-finalise.	[I] Koh, Victor-CK
27	18 Jan 2019 14:53	Adj Mandate Set	Maintained:As mention, the paint protection done by Insured is not cover. Kindly ta ke out and re-finalise.	[I] Koh, Victor-CK
28	28 Mar 2019 16:05	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/18	[A] SHIAU CHAN

AUDIT TRAIL

No.	On	Audit	Remarks	By
29	28 Mar 2019 16:07	Adj Mandate Request	Cur.Req:25011.20:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY AP PROVE SUPPLEMENTARY & CHECK ITEMS. (EXCLUDE PAINT PROTECTION)	[A] SHIAU CHAN
30	01 Apr 2019 14:01	Adj Mandate Set	Approved:25011.20.	[I] Koh, Victor-CK

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1771215	09/04/2018 15:49	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLS8512U		10.70

Denise Tay (LKKAUTO)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Tuesday, 8 January 2019 3:24 PM
To: SUR
Subject: SLS8512U/ OD / 1315278745SG - Paint protection

Hi LKK,

I have check with our underwriter and confirm that the paint protection is not covered as it was not given at point of purchase.

Kindly take out and re-finalise.

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 1700063086
 Period of Insurance : 09 Oct 2017 to 08 Oct 2018

Endorsement No. : 000000000186716
 Issued Date : 16 Mar 2018

ABOUT THE POLICYHOLDER

Name of Policyholder : LAI WEIXIONG
 Address : 23 ANCHORVALE CRESENT
 16-26
 SINGAPORE 544655
 Occupation/Nature of Business : Others(Indoor)

ABOUT THE VEHICLE

Registration No. : SLS8512U
 Chassis No. : WAUZZZGAXHA055607
 Seating Capacity : 5
 Make/Model : AUDI Q2/ Q2 Sport 1.0 TFSI S Ironic
 Hire Purchase Company/Employer's Loan : DBS BANK LTD
 Engine Capacity/Tonnage : 999.00 CC
 Engine No. : CHZ401057
 Body Type : SUV
 First Year of Registration : 2017

ABOUT THE COVER

Sum Insured : Market Value
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive :
 Off Peak Car : No
 Insuring with COE/PARF : Yes

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission

This Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" (YIDRE) if You are or Your Authorized Driver (named or unnamed) is under the age of 25 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God, Strike, Riots and Civil Commotions, PA to Authorized Driver / Unnamed Passengers- \$10000, Dealer + AIG Authorized Workshops, PA Insured- \$100000, Fire and Accessories, (Cosmetics) \$5000, Side Film- \$1150, New For Old (36 months), Loss of Use, In-Car Camera Excess Waiver, Glass Rod/ Moon Roof/ Sun Roof/ Panoramic Glass Roof, Loyalty Home Cover, NCD Protector

ENDORSEMENT REMARK

It is hereby declared and agreed that with effect from 09/10/2017

1) NCD Details : Update NCD on Policy with AIG

Declared Previous Insurer: FWD SINGAPORE PTE LTD

Declared NCD: 50%

Verified NCD: 50%

With the update in Claims/NCD details, premium and/or excess are revised. Refer to details stated above.

Subject otherwise to the Terms, Exclusion and Conditions of this Policy.

Endorsement effective from: 09-Oct-2017. All other terms and conditions remain unchanged.

View Received Message

This mail is associated with :

***SLS8512U (1315278745SG)**

OD

Apr 3 2018 5:00PM

[LAI WEIXIONG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 04/12/2018 12:03 PM.

To LKK_HQ

Subject Alert - Adj Mandate Maintained - SLS8512U - Claim Handler: Tr, Tinesh

Maintained: Damage photos of Front silencer? Sales agreement for supplementary labour paint protection? Submit survey report.

DOCUMENTS SUMMARY

There are no documents.

Photo 45 and 46 show the front and rear silencer.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 10 April 2018 8:49 AM
To: Claims Dept; SUR
Subject: RE: SLS 8512 U Own Damage Claim (Vehicle IN)

Dear Jeffrey,

As instructed by our client AIG Insurance , please proceed to repair the insured vehicle SLS 8512U (Excess \$0/-).

Please note that the vehicle no. should be SLS 8512U instead of SLF 8512U.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Friday, 6 April 2018 5:45 PM
To: SUR <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: SLF 8512 U Own Damage Claim (Vehicle IN)

Dear all,

Kindly assist in the Own Damage Claim for the above mentioned vehicle.

Vehicle was survey earlier this afternoon.

As the vehicle is IN the workshop, kindly assist in the approval urgently.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 189902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	04 Apr 2018 19:43	Cim Veh Model Changed			[] Merimen Administrator
2	04 Apr 2018 19:43	Cim Created	Reg No: SLS8512U, Policy No: 1700063086, Acct Date: 2018/04/03, Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Cr eated from SAS:MPA118045186		[I] Merimen Administrator
3	09 Apr 2018 11:24	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.		[] CATHERINE CHONG KAI LING
4	09 Apr 2018 11:24	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[] CATHERINE CHONG KAI LING
5	09 Apr 2018 11:24	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] CATHERINE CHONG KAI LING
6	09 Apr 2018 11:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/18		[A] CATHERINE CHONG KAI LING
7	09 Apr 2018 11:24	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.		[A] CATHERINE CHONG KAI LING
8	09 Apr 2018 11:24	Cim Registration Modified	Rep:1137->200611.		[A] CATHERINE CHONG KAI LING
9	09 Apr 2018 11:24	Cim Veh Model Changed	(205236) AUDI Q2 999cc TFSI 5-TRONIC (A).		[A] CATHERINE CHONG KAI LING
10	09 Apr 2018 11:24	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] CATHERINE CHONG KAI LING
11	09 Apr 2018 15:37	Cim Registration Modified	Init.Est.:->5,000 - 6,000, Excess: -> 0.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.		[I] Tr, Tinesh
12	09 Apr 2018 15:37	Label Added	(20226):Coverage Confirmed.		[A] Merimen Administrator
13	09 Apr 2018 15:49	Adj Rpt Initiated			[A] SHIAU CHAN
14	09 Apr 2018 15:49	Cim Dtl Modified	JPJ Reg. Date: -> 2017/10/09.		[A] SHIAU CHAN
15	09 Apr 2018 15:49	Cim Details Notified			[A] SHIAU CHAN
16	09 Apr 2018 15:58	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/18		[A] SHIAU CHAN
17	09 Apr 2018 16:00	Adj Mandate Request	Cur.Req:27159.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
18	09 Apr 2018 16:45	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/18, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour. B/F paint photos required.		[I] Koh, Victor-CK
19	09 Apr 2018 16:45	Adj Mandate Set	Approved:20109.00:Re-inspection to be done for damage check and supplementary items / labour. B/F paint photos required,Reinsp:Yes.		[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc. Type	Acc. Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1771215	09/04/2018 15:49	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLS8512U		10.70

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4755A
Vehicle Details	
Vehicle No.:	SLS8512U
Vehicle to be Exported:	No
Intended De-registration Date:	09 Apr 2018
Vehicle Make:	AUDI
Vehicle Model:	Q2 1.0 TFSI S TRONIC
Primary Colour:	Yellow
Manufacturing Year:	2017
Engine No.:	CHZ401057
Chassis No.:	WAUZZZGAXHA055607
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$26,089.00
Original Registration Date:	09 Oct 2017
First Registration Date:	09 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$18,525.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Oct 2027
PARF Rebate Amount:	\$13,893.00
Intended COE Rebate Details	
COE Expiry Date:	08 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,761.00
COE Rebate Amount:	\$39,658.00
Total Rebate Amount:	\$53,551.00

The information contained herein is correct as at 09 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2018 19:03
Date Of Accident	03/04/2018 18:00
Exact Location Of Accident	INSIDE MCE TUNNEL FROM AYE - EXTREME RIGHT LANE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS8512U
Insured/Policyholder	
Name Of Registered Owner	LAI WEIXIONG
NRIC No	S8534755A
Email Address	KELVINLAI85@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-92315678
Alternative Phone No	OTHERS-92315678

Vehicle Particulars

Manufacturer	AUDI
Model	Q2 1.0 TFSI S-TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700063086
Cover Note Number	

Driver

Name of Driver	LAI WEIXIONG
NRIC No	S8534755A
Date Of Birth	11/11/1985
Occupation	INDOOR
Date Of Driving Pass	02/11/2004
Driving Experience	13 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92315678
Fax Number	
Contact Number	OTHERS-92315678
EMail Address	KELVINLAI85@YAHOO.COM.SG

Address	BLK 23 ANCHORVALE CRESCENT #16-26
Postcode	544655
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHAN HOI WAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NPC
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN & POLICE REPORT NO: T/20180404/2057

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFZ8871S
Vehicle Make/Model/Colour	HONDA / CITY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHAN MEI LING
NRIC/Passport Number	S7743203E
Contact Number	94315778
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKZ2563L

Vehicle Make/Model/Colour

HONDA / VEZEL

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

GUSAROV EVGENY

NRIC/Passport Number

S2768325H

Contact Number

81830735

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLS8512U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Justin Lim
NIC/FIN No.: G5349040



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to Police Report for accident details.
T/20180404/2057

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Lim Bing Su
NRIC/PPN No.: G5354109P



Police Report



**SINGAPORE
POLICE FORCE**



1201804040057

1 of 4

Police Station Of Origin:
Sengkang N.P.C.
2 Sengkang Square #01-02 SINGAPORE
545026
Tel No: 1800-343 8889

Report No: 1201804040057

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/04/2018 12:49	Video Report No.:	Station Diary No.: 03
--	-------------------	--------------------------

Informant's Particulars

Name of Informant: LAI WEIXIONG			Address: APT BLK 23 ANCHORVALE CRESCENT #16-26 SINGAPORE 544606	
ID Type / ID No.: NRIC NO / S8534755A			Contact No.:	Mobile: 82315678
Nationality: SINGAPORE CITIZEN			Home/Office:	
			Email:	
Sex: Male	Age: 32	Date of Birth: 11/11/1985	Type of Informant: Driver	
Race: Chinese		Language: English		Institution / School Name:
Occupation: MARKETING		Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

General Information of the Accident		Drink Drive:	Date/Time of Accident:	Type of Location:
Type of Accident:	Injury Others	No	03/04/2018 18:00	Expressway
Location: Along Road 1 AYER RAJAH EXPRESSWAY				
Inside MCE Tunnel From AYR (Lane 1 Extreme right most lane)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SFZ9871S	Car				Seriously Damaged	2
SK72533L	Car				Slightly Damaged	0
SL38512U	Car	AUDI	Q2 1.0 TFSI S TRONIC	Yellow	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

Police Report



**SINGAPORE
POLICE FORCE**



17201904042057

2 of 4

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
S45026
Tel No. 1800-343 8800

Report No. 17201904042057

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLS8512U	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700063086	09/10/2017	08/10/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Driver				
Name	CHAN MEI LING	ID No.	S7743203E	
Related Vehicle	SFZ6871S (Car)	Contact No.	94315776	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Driver				
Name	GUSAROV EVGENY	ID No.	S2758325H	
Related Vehicle	SKZ2563L (Car)	Contact No.	81830735	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Driver				
Name	LAU WEIXIONG	ID No.	S8534755A	
Related Vehicle	SLS8512U (Car)	Contact No.	90315878	
Hospital/Clinic	MOUNT ELIZABETH HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	03/04/2018	Date Discharge	03/04/2018	
No. of Days granted Medical Leave	05	Degree of Injury	Slight	

Police Report



**SINGAPORE
POLICE FORCE**



T201904042057

3 of 4

Police Station Of Origin:
Sengkang N.P.C.
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No. 1800-343 6999

Report No. T201904042057

CONTINUATION OF REPORT

Passenger			
Name	CHAN HOI WAN	ID No	S8779761L
Related Vehicle	SLS8512U (Car)	Contact No.	90910937
Hospital/Clinic	MOUNT ELIZABETH HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	03/04/2018	Date Discharge	03/04/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On the 03/04/2018 at about 1800hrs, I was driving at MCE towards KPE together with my wife to pick up my son in songkang from infant care. I was traveling at the extreme right (lane 1) of the said expressway. The weather was fine and road condition was dry. My speed during that point of time was moderate at a speed of 70Km/Hr. As I was driving at the said lane, I noticed a vehicle bearing plate number SK72583L that was in front of me made a sudden break as such I follow suit to apply my break too. At that point of time I notice my car was longly away from colliding to the said vehicle. As such I successfully manage to apply my break, however the vehicle on my rear bearing plate number SFZ8871S did not had time to stop in time as such the vehicle head on and collided on my rear part of my car.

As the impact took place, I manage to swerve my vehicle slightly to the right to avoid the collision. However, my left side mirror came colliding on his right tail light of the front vehicle. Due to the impact myself and my wife back body area and neck area hit the head rest and the seat of the vehicle. Upon exiting my vehicle to exchange particulars with the drivers, I felt aching pain on my back and neck area. All particulars was recorded on the said location.

Minutes later AFTOS rider was there to control traffic. My vehicle was later towed away by a EMAS to Fort Road heavy vehicle parking. I manage to call my vehicle service center that eventually towed away my vehicle to their Audi workshop. As for now the damage occur on my car during the RTA is damage on my left side mirror and some scratches on my left fender area.

Later that day me and my wife decided to made a check on our injuries at Mount Elizabeth A & E Hospital. We were then given 5 days due to our injuries. Doctor made assessment on myself and inform that I have a tense muscle and was given some painkillers. Doctor also inform that my wife did not suffer from any internal bleeding as she complain of pain at her abdominal area and back pain.

Police Report



SINGAPORE
POLICE FORCE



1201804042057

4 of 4

Report No. 1201804042057

Police Station Of Origin:
Sengkang N.P.C.
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8998

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474886 stating the report number as reference.

Signature Of Officer Recording The Report:

F/

Staff Sgt MUHAMMAD FADHLULLAH BIN
SHARIFFUDIN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEI /

Sgt 2 YEO KIA HUAT

Contact No.: 65476325

Authentication Stamp

W165

Signature Of Informant:

Date/Time:

04/04/2018 12:48

Classification Of Case:

Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S8534755A**

Name: **LAI WEIXIONG**

Birth Date: **11 Nov 1985**

Issue Date: **02 Nov 2004**

001296786J




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8534755A

Name: **LAI WEIXIONG**

賴 琿 雄

Race: **CHINESE**

Date of birth: **11-11-1985**

Country/Place of birth: **SINGAPORE**

Sex: **M**

58534755A





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars < 3000 kg with < 7 passengers, exclusive of the driver, and motor tractors / vehicles < 2500 kg

PASS DATE 02 Nov 2004

NP 428A

License No: **S8534755A**



5799310

S8534755A

13-09-2017

APT BLK 23 ANCHORVALE CRESCENT
#16-26
SINGAPORE 544655




AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LAI WEIXIONG
 Period of Insurance : 09 Oct 2017 To 08 Oct 2018
 Engine No. : CHZ401057
 Chassis No. : WAUZZZGAXHA055607

Vehicle No. : SLS8512U
 Policy No. : 1700063086
 Endorsement No. : 000000000186716
 Issued Date : 16 Mar 2018

ABOUT THE COVER

Make/Model	AUDI Q2/ Q2 Sport 1.0 TFSI S tronic		
Engine Capacity/Tonnage	999.00 CC	Sum Insured	Market Value
Driver Restriction	NA	Off Peak Car	No
		First Year of Registration	2017
		Insuring with COE/PAF	Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 25 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 186) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0, Own Damage - \$800, Theft - \$0, Flood Cover - \$0.

Section 2
 Property Damage - \$0

Windscreen - \$100

Named Driver and Excess (where applicable)

LAI WEIXIONG - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center, Add: 55 Ubi Road 1 Singapore 408669 89662323

For other Approved Reporting Centres/Audited Repairers, please contact our 24-hour accident emergency hotline at +65 6338 5200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 186), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125210

PREMIUM LEASING - VI

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

220001

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.**What can the 24-hour AIG Auto Emergency Hotline provide for you?**

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s)
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident

What should I do in the event of an accident?

- Keep calm and move your car to a safe place
- Do not admit or discuss fault or blame with the other party(ies)
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident
- Submit VPA/Summons/Correspondence from third party(ies) to AIG immediately

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 3 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Premium Automobiles Pte. Ltd.

Activation Hotline: 64741223

55 Ubi Road 1 Singapore 408699

Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 1pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0418/2018/CCS
Date : 5-Apr-18

Vehicle IN workshop. Kindly assist to arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lai WeiXiong
Address : 23 Anchorvale Crescent
#16-26
Singapore 544655
Telephone : HP +65 92315678
Type of Claim : Own Damage Claims
Policy No. : 1700063086
Vehicle No : **SLS 8512 U**
Model Code : Audi Q2 1.0 TFSI
Model / Year : Oct-17
Engine No : CHZ 401057
Chassis No : WAUZZZGAXHA055607
Mileage :
Date In : 3-Apr-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Apr-18
Place of Accident : Inside MCE tunnel from AYE - extreme right lane 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 8512 U.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and renew rear parking aid.	S/N \$	280.00	✓
2	To remove and reinstall rear wire harness, audio equipment, control units, relay and fuse trays, end panelling, spare wheel housing and rear lid harness.	S/N \$	1,800.00	✓
3	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage airbag system.	S/N \$	1,800.00	✓
4	To remove exhaust system and fuel tank assy. Renew center and rear exhaust silencer.	S/N \$	1,200.00	✓
5	To remove and reinstall rear suspension assy to facilitate cellette bench repairs. Inspect for damages and renew accordingly.	S/N \$	2,800.00	2 ✓ SLS
6	To set up and place vehicle on cellette bench.	S/N \$	1,200.00	2 ✓ SLS
SUB-TOTAL LABOUR CHARGES		:	<u>\$ 9,080.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 8512 U.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
7	To dismantle rear bumper assy. Cut out and weld rear end panelling, spare wheel housing and rear cross members. Repair and align whole rear substructure to position. Renew rear bumper and all damaged fittings. Reinstall all parts removed.	\$ 7,200.00	5000 ✓
8	To carry out stone chip primer work on rear end panelling and spare wheel housing.	S/N \$ 780.00	✓
9	To spray paint on rear bumper, rear lid, spare wheel housing, boot floor, front LSHS fender and LHS wing mirror assy. To carry out joint sealer works and cavity preservation.	\$ 4,300.00	2350 ✓
10	To carry out wheel alignment.	S/N \$ 240.00	7 ✓
11	To carry out diagnostic checks.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 21,984.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 8512 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Distorted</i>	\$ 1,016.00	✓ 812.80
2	REAR BUMPER FIXING PARTS <i>2pc new</i>	\$ 66.00	? X
3	REAR BUMPER SPOILER <i>Distorted</i>	\$ 247.00	✓ 197.20
4	REAR BUMPER LIGHT REFLECTOR - LH/RH <i>LH missing</i>	2 \$ 52.00	26 . 20.08
5	TAIL LIGHT - LH <i>new</i>	\$ 1,149.00	+
6	TAIL LIGHT TRIM - LH <i>new</i>	\$ 26.00	+
7	REAR REINFORCEMENT BEAM <i> Bent</i>	\$ 480.00	✓ 383.60
8	REAR BUMPER GUIDE - LH/RH <i>2pc LH bent</i>	2 \$ 92.00	+ 36.48 ✓
9	REAR BUMPER HOLDING STRAP - LH/RH <i>2pc</i>	2 \$ 22.00	✓ 16.80
10	REAR WHEEL ARCH TRIM - LH/RH <i>new</i>	2 \$ 298.00	✓ 738.40
11	REAR PARKING AID WIRING SET <i>2pc new</i>	\$ 458.00	? X
12	REAR PARKING AID SENSOR SEAL <i>new</i>	4 \$ 14.00	X
13	REAR PARKING AID SENSOR <i>new</i>	4 \$ 842.00	+
14	REAR LID AUDI LOGO <i>2pc</i>	\$ 108.00	X
15	REAR LID ' Q2 ' INSCRIPTION <i>2pc</i>	\$ 83.00	+
16	REAR LID ' TFSI ' INSCRIPTION <i>2pc</i>	\$ 83.00	+
17	REAR CROSS PANEL - OUTER <i>Distorted</i>	\$ 216.00	✓ 173.80
18	REAR CROSS PANEL REINFORCEMENT - INNER <i>2pc</i>	\$ 645.00	✓ 515.60
19	REAR CROSS PANEL CONNECTING PLATE - LH/RH <i>Distorted</i>	2 \$ 72.00	✓ 56.32
20	REAR CROSS MEMBER	\$ 190.00	✓ 152
SUB-TOTAL SPARE PARTS		\$ 6,159.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 8512 U.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
21	REAR SPARE WHEEL HOUSING <i>Distorted</i>	\$	1,603.00	✓ 1283.40
22	SPARE WHEEL HOUSING CONNECTING PLATE - LH/RH <i>Bulld</i>	2 \$	206.00	? 164.80 ✓
23	2 PACK BODY ADHESIVE AND SEALING COMPOUND <i>Dec</i>	\$	613.00	? 490.48 ✓
* 24	FRONT SILENCER <i>Best</i>	\$	561.00	? 448.80 ✓
25	FRONT SILENCER DUAL CLIP <i>Dec</i>	2 \$	106.00	? 39.28 ✓
26	REAR SILENCER <i>Best</i>	\$	533.00	✓ 506
27	REAR SILENCER DUAL CLIP <i>m</i>	\$	53.00	✓ 41.84
28	FRONT SILENCER RETAINER <i>new</i>	\$	36.00	X X 44
29	REAR SILENCER RETAINER <i>new</i>	2 \$	72.00	✓ 57.12
30	REAR SILENCER HEAT SHIELD <i>coupled</i>	\$	146.00	✓ 116.80
31	ACRYLIC SEALER <i>new</i>	S/N \$	360.00	✓
32	CAVITY WAX <i>new</i>	S/N \$	140.00	✓
33	STONE CHIP <i>new</i>	S/N \$	360.00	✓
34	FRONT WHEEL ARCH TRIM - LHS <i>lot not new</i>	TBC		X 277.80 ✓
35	SUNDRIES <i>NEC</i>	\$	800.00	? 142.40 ✓
TOTAL SPARE PARTS		:	\$ 11,748.00	
TOTAL LABOUR CHARGES		:	\$ 21,984.00	
GRAND TOTAL		:	\$ 33,732.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

34657.20

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L.
Surveyed Date : 06/04/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised. 15 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Panel Beating 10 Days
Spray Painting 5 Days
Cellulose Beating 04 Days
Undercarriage 02 Days
Exhaust and Fuel tank 01 Day
Upholstery and air bag 03 Days

25 Days.

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims D
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0418/2018/CCS
13-Apr-18
JB
ONE
SLS8512U
Q2 1.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	Wheel liner LHS <i>behind</i>	\$ 181.00	\$ 144.80 <i>OK ✓</i>
2	Sport tailpipe trim <i>Best.</i>	\$ 72.00	\$ 57.60 <i>OK ✓</i>
		\$ 253.00	\$ 202.40
LABORS			
TOTAL		\$ 253.00	\$ 202.40

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/OD/0418/2018/TF
Date	8-May-18
Service Advisor	Tony
Pages	1
Regn No	SLS 8S12 U
Model No	Audi Q2 1.0 TFSI

Quantity	Description	Unit Price	Amount
LABORS			
1	To apply paint protection on front lh fender, front lh wind mirror cover and rear bumper (S/N)	\$ 500.00	✓
TOTAL		\$ 500.00	

For Premium Automobiles Pte Ltd

Adrian Ling
SL
09/05/18.



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0418/2018/CCS
Date : 5-Apr-18

Vehicle IN workshop. Kindly assist to arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

You recommended 15 days

We took 25 days exclude 4 Sundays

1 Public Holiday - s/tyre housing

replaced on c/bench - jb 25 Jun 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lai WeiXiong
Address : 23 Anchorvale Crescent
#16-26
Singapore 544655
Telephone : HP +65 92315678
Type of Claim : Own Damage Claims
Policy No. : 1700063086
Vehicle No : **SLS 8512 U**
Model Code : Audi Q2 1.0 TFSI
Model / Year : Oct-17
Engine No : CHZ 401057
Chassis No : WAUZZZGAXHA055607
Mileage :
Date In : 3-Apr-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Apr-18
Place of Accident : Inside MCE tunnel from AYE - extreme right lane 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 8512 U.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and renew rear parking aid.	S/N	\$ 280.00	\$ 280.00
2	To remove and reinstall rear wire harness, audio equipment, control units, relay and fuse trays, end panelling, spare wheel housing and rear lid harness.	S/N	\$ 1,800.00	\$ 1,800.00
3	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage airbag system.	S/N	\$ 1,800.00	\$ 1,800.00
4	To remove exhaust system and fuel tank assy. Renew center and rear exhaust silencer.	S/N	\$ 1,200.00	\$ 1,200.00
5	To remove and reinstall rear suspension assy to facilitate cellette bench repairs. Inspect for damages and renew accordingly.	S/N	\$ 2,800.00	\$ 2,800.00
6	To set up and place vehicle on cellette bench.	S/N	\$ 1,200.00	\$ 1,200.00
SUB-TOTAL LABOUR CHARGES		:	\$ 9,080.00	\$ 9,080.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 8512 U.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
	<i>c/f</i>		\$ 9,080.00
7	To dismantle rear bumper assy. Cut out and weld rear end panelling, spare wheel housing and rear cross members. Repair and align whole rear substructure to position. Renew rear bumper and all damaged fittings. Reinstall all parts removed.	\$ 7,200.00	\$ 5,000.00
8	To carry out stone chip primer work on rear end panelling and spare wheel housing.	S/N \$ 780.00	\$ 780.00
9	To spray paint on rear bumper, rear lid, spare wheel housing, boot floor, front LSHS fender and LHS wing mirror assy. To carry out joint sealer works and cavity preservation.	\$ 4,300.00	\$ 2,350.00
10	To carry out wheel alignment.	S/N \$ 240.00	\$ 240.00
11	Added labour - owner	\$ 500.00	\$ 500.00
12	To carry out diagnostic checks.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		: \$ 22,484.00	\$ 18,334.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 8512 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,016.00	\$ 812.80
2	REAR BUMPER FIXING PARTS	\$ 66.00	
3	REAR BUMPER SPOILER	\$ 247.00	\$ 197.20
4	REAR BUMPER LIGHT REFLECTOR - LH/RH	2 \$ 52.00	\$ 20.08
5	TAIL LIGHT - LH	\$ 1,149.00	
6	TAIL LIGHT TRIM - LH	\$ 26.00	
7	REAR REINFORCEMENT BEAM	\$ 480.00	\$ 383.60
8	REAR BUMPER GUIDE - LH/RH	2 \$ 92.00	\$ 36.48
9	REAR BUMPER HOLDING STRAP - LH/RH	2 \$ 22.00	\$ 16.80
10	REAR WHEEL ARCH TRIM - LH/RH	2 \$ 298.00	\$ 238.40
11	REAR PARKING AID WIRING SET	\$ 458.00	
12	REAR PARKING AID SENSOR SEAL	4 \$ 14.00	
13	REAR PARKING AID SENSOR	4 \$ 842.00	
14	REAR LID AUDI LOGO	\$ 108.00	
15	REAR LID ' Q2 ' INSCRIPTION	\$ 83.00	
16	REAR LID ' TFSI ' INSCRIPTION	\$ 83.00	
17	REAR CROSS PANEL - OUTER	\$ 216.00	\$ 172.80
18	REAR CROSS PANEL REINFORCEMENT - INNER	\$ 645.00	\$ 515.60
19	REAR CROSS PANEL CONNECTING PLATE - LH/RH	2 \$ 72.00	\$ 56.32
20	REAR CROSS MEMBER	\$ 190.00	\$ 152.00
SUB-TOTAL SPARE PARTS		\$ 6,159.00	\$ 2,602.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 8512 U.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>	\$	2,602.08
21	REAR SPARE WHEEL HOUSING		\$ 1,603.00	\$ 1,282.40
22	SPARE WHEEL HOUSING CONNECTING PLATE - LH/RH	2	\$ 206.00	\$ 164.80
23	2 PACK BODY ADHESIVE AND SEALING COMPOUND		\$ 613.00	\$ 490.48
24	FRONT SILENCER		\$ 561.00	\$ 448.80
25	FRONT SILENCER DUAL CLIP	2	\$ 106.00	\$ 39.28
26	REAR SILENCER		\$ 533.00	\$ 506.00
27	REAR SILENCER DUAL CLIP		\$ 53.00	\$ 41.84
28	FRONT SILENCER RETAINER		\$ 36.00	
29	REAR SILENCER RETAINER	2	\$ 72.00	\$ 57.12
30	REAR SILENCER HEAT SHIELD		\$ 146.00	\$ 116.80
31	ACRYLIC SEALER	S/N	\$ 360.00	\$ 360.00
32	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
33	STONE CHIP	S/N	\$ 360.00	\$ 360.00
34	FRONT WHEEL ARCH TRIM - LHS (NEC)	TBC	\$	222.80
35	SUPPLEMENTARY		\$ 253.00	\$ 202.40
36	SUNDRIES		\$ 800.00	\$ 142.40
TOTAL SPARE PARTS		:	\$ 12,001.00	\$ 7,177.20
TOTAL LABOUR CHARGES		:	\$ 22,484.00	\$ 18,334.00
GRAND TOTAL		:	\$ 34,485.00	\$ 25,511.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/CD/0418/2018/TF
Date	8-May-18
Service Advisor	Tony
Pages	1
Regn No	SLS 8512 U
Model No	Audi Q2 1.0 TFSI

Quantity	Description	Unit Price	Amount
LABORS			
1	To apply paint protection on front lh fender, front lh wind mirror cover and rear bumper (S/N)	\$ 500.00	\$ 500.00
TOTAL		\$ 500.00	\$ 500.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLS 8512 U

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0418/2018/MAS

24 April 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLS 8512 U, Audi Q2 1.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLS 8512 U**, claimant, **Mr. Lai Weixiong**, please find the related document per attached.

1. A copy of the Original invoice no. 85013696 – S\$26,761.98
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLS 8512 U

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2018		09 Apr 2018 11:24 Edit Adj Rpt	\$525,011.20 Edit Estimates	\$525,011.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LAI WEIXIONG, ID: S8534755A, Tel: +6592315678, Email: KELVINLAI85@YAHOO.COM.SG								
Vehicle Reg. No.:	SLS8512U	Date of Loss:	03/04/2018 17:00 - :59 [5 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 1315278745SG	Policy/Cover Note No.:	1700063086 (Comprehensive) Coverage: 09/10/2017 - 08/10/2018						
		Excess:	\$50.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/04/2018]								
Driver/Custodian:	LAI WEIXIONG (32 / Male), NRIC: S8534755A, Tel: +6592315678 Email: KELVINLAI85@YAHOO.COM.SG								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (01/04/2019): Alert - Adj Mandate Approved (\$525011.20) - SLS8512U - Claim Handler: Tr, Tinesh - AIG_SG (18/01/2019): Alert - Adj Mandate Maintained - SLS8512U - Claim Handler: Tr, Tinesh - AIG_SG (04/12/2018): Alert - Adj Mandate Maintained - SLS8512U - Claim Handler: Tr, Tinesh - AIG_SG (09/04/2018): Alert - Adj Mandate Approved (\$520109.00) - SLS8512U - Claim Handler: Tr, Tinesh - AIG_SG (09/04/2018): SLS8512U / OD / 03/04/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS8512U (1315278745SG)
OD
Apr 3 2018 5:00PM
[LAI WEIXIONG]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		Use Viewer	
Video											1 per page			
No	Finalized On	Premium Automobiles Pte Ltd (UBI)									Thumbnail		Print	
1	04/04/18 19:37	Video - Accident [Linked Accident Report Documents]										Load MP4		
Assessment Reports											1 per page			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail		Print	
1	09/04/18 15:58	Adjuster Immediate Advice										Load HTM		
2	09/11/18 10:46	Adjuster Immediate Advice										Load HTM		
3	28/03/19 16:05	Adjuster Immediate Advice										Load HTM		
Photos/Images											3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail		Print	
1	09/04/18 16:00	General View										Load JPG		
2	09/04/18 16:00	Chassis Number										Load JPG		
3	09/04/18 16:00	General View										Load JPG		
4	09/04/18 16:00	General View										Load JPG		
5	09/04/18 16:00	General View										Load JPG		
6	09/04/18 16:00	General View										Load JPG		
7	09/04/18 16:00	General View										Load JPG		
8	09/04/18 16:00	General View										Load JPG		
9	09/04/18 16:00	General View										Load JPG		
10	09/04/18 16:00	General View										Load JPG		
11	09/04/18 16:00	General View										Load JPG		
12	09/04/18 16:00	General View										Load JPG		
13	09/04/18 16:00	General View										Load JPG		
14	09/04/18 16:00	General View										Load JPG		
15	09/04/18 16:00	General View										Load JPG		
16	09/04/18 16:00	General View										Load JPG		
17	09/04/18 16:00	General View										Load JPG		
18	09/04/18 16:00	General View										Load JPG		
19	09/04/18 16:00	General View										Load JPG		
20	09/04/18 16:00	General View										Load JPG		
21	09/04/18 16:00	General View										Load JPG		
22	09/04/18 16:00	General View										Load JPG		
23	09/04/18 16:00	General View										Load JPG		
24	09/04/18 16:00	General View										Load JPG		
25	09/04/18 16:00	General View										Load JPG		
26	09/04/18 16:00	General View										Load JPG		
27	09/04/18 16:00	General View										Load JPG		
28	09/04/18 16:00	General View										Load JPG		
29	09/04/18 16:00	General View										Load JPG		
30	09/04/18 16:00	General View										Load JPG		
31	09/04/18 16:00	General View										Load JPG		
32	09/04/18 16:00	General View										Load JPG		
33	09/04/18 16:00	General View										Load JPG		
34	09/04/18 16:00	General View										Load JPG		

35	09/04/18 16:00	General View	1	Load JPG	
36	09/04/18 16:00	General View	1	Load JPG	
37	09/04/18 16:00	General View	1	Load JPG	
38	05/11/18 14:54	Reinspection Photo	1	Load JPG	
39	05/11/18 14:54	Reinspection Photo	1	Load JPG	
40	05/11/18 14:54	Reinspection Photo	1	Load JPG	
41	05/11/18 14:54	Reinspection Photo	1	Load JPG	
42	05/11/18 14:54	Reinspection Photo	1	Load JPG	
43	05/11/18 14:54	Reinspection Photo	1	Load JPG	
44	05/11/18 14:54	Reinspection Photo	1	Load JPG	
45	05/11/18 14:54	Reinspection Photo	1	Load JPG	
46	05/11/18 14:54	Reinspection Photo	1	Load JPG	
47	04/12/18 14:52	Reinspection Photo	1	Load JPG	
Documentation				1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/04/18 15:58	Singapore Accident Statement	1	Load PDF	
2	09/04/18 15:58	Police Report	1	Load PDF	
3	09/04/18 15:58	Certificate of Insurance	1	Load PDF	
4	09/04/18 15:58	Driver's Driving License	1	Load PDF	
5	09/04/18 15:58	ESTIMATE	1	Load PDF	
6	09/11/18 10:39	SUPPLEMENTARY LIST	1	Load PDF	
7	09/11/18 10:39	REVISED ESTIMATE	1	Load PDF	
8	09/11/18 10:47	SUPPLEMENTARY LIST 2	1	Load PDF	
9	04/12/18 16:08	PAINT PROTECTION - SALES AGREEMENT	1	Load PDF	
10	30/04/19 11:18	WORKSHOP INVOICE	1	Load PDF	
11	30/04/19 11:18	DISCHARGE VOUCHER	1	Load PDF	

Linked Accident Report Documents

			View	Use Viewer	
Video			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	04/04/18 19:37	Video - Accident	1	Load MP4	
Assessment Reports			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	04/04/18 19:43	Accident Statement	1	Load HTM	
Photos/Images			3 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	04/04/18 19:29	Police Report	1	Load JPG	
2	04/04/18 19:29	Police Report	1	Load JPG	
3	04/04/18 19:29	Police Report	1	Load JPG	
4	04/04/18 19:29	Police Report	1	Load JPG	
5	04/04/18 19:34	Accident Photo	1	Load JPG	
6	04/04/18 19:34	Accident Photo	1	Load JPG	
7	04/04/18 19:34	Accident Photo	1	Load JPG	
8	04/04/18 19:34	Accident Photo	1	Load JPG	
9	04/04/18 19:34	Accident Photo	1	Load JPG	
10	04/04/18 19:34	Accident Photo	1	Load JPG	
11	04/04/18 19:34	Accident Photo	1	Load JPG	
12	04/04/18 19:34	Accident Photo	1	Load JPG	
13	04/04/18 19:34	Accident Photo	1	Load JPG	
14	04/04/18 19:34	ACCIDENT SCENE PHOTOS	1	Load JPG	
15	04/04/18 19:34	ACCIDENT SCENE PHOTOS	1	Load JPG	
16	04/04/18 19:34	ACCIDENT SCENE PHOTOS	1	Load JPG	
17	04/04/18 19:34	ACCIDENT SCENE PHOTOS	1	Load JPG	
18	04/04/18 19:34	ACCIDENT SCENE PHOTOS	1	Load JPG	
19	04/04/18 19:34	ACCIDENT SCENE PHOTOS	1	Load JPG	

					☒
20	04/04/18 19:34	ACCIDENT SCENE PHOTOS		Load JPG	☒
Documentation			1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	04/04/18 19:28	Sketch Plan		Load JPG	☒
2	04/04/18 19:28	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18006451/AQBN2

Date: 30/04/2019

REFERENCE

Insured/Claimant: LAI WEIXIONG Policy No: 1700063086
Date of Loss: 03/04/2018 Nature of Claim: OD Claim No: 1315278745SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS8512U
Make & Model: AUDI Q2, 999cc TFSI S-TRONIC (A) Engine No: CHZ401057
Reg. Date: 09/10/2017 (Man. Year: 2017) Chassis No: WAUZZZGAXHA055607
Colour: Yellow Odometer: 8945 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$125,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,173.20	7,177.20	4,996.00	41.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,484.00	17,834.00	4,650.00	20.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	34,657.20	25,011.20	9,646.00	27.83
+ GST 7.00/7.00% (S\$)	2,426.00	1,750.78	675.22	27.83
Nett Amount (S\$)	37,083.20	26,761.98	10,321.22	27.83

INSPECTION

Date of Assignment: 09/04/2018
Date Inspected: 06/04/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 25.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,016.00 FS	*812.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	66.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Distorted	247.00 FS	*197.20 FS
4	1		*REAR BUMPER LIGHT REFLECTOR-LH/RH	N/s Missing	52.00 FS	*20.08 FS
5	1		*TAIL LIGHT-LH	Not Necessary	1,149.00 FS	*- FS
6	1		*TAIL LIGHT TRIM-LH	Not Necessary	26.00 FS	*- FS
7	1		*REAR REINFORCEMENT BEAM	Bent	480.00 FS	*383.60 FS
8	1		*REAR BUMPER GUIDE-LH/RH	N/s Damaged	92.00 FS	*36.48 FS
9	2		*REAR BUMPER HOLDING STRAP-LH/RH	Damaged	22.00 FS	*16.80 FS
10	2		*REAR WHEEL ARCH TRIM-LH/RH	Necessary	298.00 FS	*238.40 FS
11	1		*SET REAR PARKING AID WIRING	Not Necessary	458.00 FS	*- FS
12	4		*REAR PARKING AID SENSOR SEAL	Not Necessary	14.00 FS	*- FS
13	4		*REAR PARKING AID SENSOR	Not Necessary	842.00 FS	*- FS
14	1		*REAR LID AUDI LOGO	Not Necessary	108.00 FS	*- FS
15	1		*REAR LID Q2 INSCRIPTION	Not Necessary	83.00 FS	*- FS
16	1		*REAR LID TFSI INSCRIPTION	Not Necessary	83.00 FS	*- FS
17	1		*REAR CROSS PANEL-OUTER	Distorted	216.00 FS	*172.80 FS
18	1		*REAR CROSS PANEL REINFORCEMENT-INNER	Distorted	645.00 FS	*515.60 FS
19	2		*REAR CROSS PANEL CONNECTING PLATE-LH/RH	Distorted	72.00 FS	*56.32 FS
20	1		*REAR CROSS MEMBER	Distorted	190.00 FS	*152.00 FS
21	1		*SPARE WHEEL PANEL HOUSING	Distorted	1,603.00 FS	*1,282.40 FS
22	2		*SPARE WHEEL HOUSING CONNECTING PLATE-LH/RH	Distorted	206.00 FS	*164.80 FS
23	1		*2 PACK BODY ADHESIVE AND SEALING COMPOUND	Necessary	613.00 FS	*490.48 FS
24	1		*FRONT SILENCER	Bent	561.00 FS	*448.80 FS
25	2		*FRONT SILENCER DUAL CLIP	Necessary	106.00 FS	*39.28 FS
26	1		*REAR SILENCER	Bent	533.00 FS	*506.00 FS
27	1		*REAR SILENCER DUAL CLIP	Necessary	53.00 FS	*41.84 FS
28	1		*FRONT SILENCER RETAINER	Not Necessary	36.00 FS	*- FS
29	2		*REAR SILENCER RETAINER	Damaged	72.00 FS	*57.12 FS
30	1		*REAR SILENCER HEAT SHIELD	Crumpled	146.00 FS	*116.80 FS
31	1		*ACRYLIC SEALER	Necessary	360.00 FS	*360.00 FS
32	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
33	1		*STONE CHIP	Necessary	360.00 FS	*360.00 FS
34	1		*FRONT WHEEL ARCH TRIM-LHS	Cut	222.80 FS	*222.80 FS
35	1		*SUNDRIES	Necessary	800.00 FS	*142.40 FS
36	1		*WHEEL LINER LHS	Deformed	144.80 FS	*144.80 FS
37	1		*SPORT TAILPIPE TRIM	Bent	57.60 FS	*57.60 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 12,173.20 7,177.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO APPLY PAINT PROTECTION ON FRONT LH FENDER,FRONT LH WIND MIRROR COVER AND REAR BUMPER	New	500.00	0.00
2	TO REMOVE AND RENEW REAR PARKING AID	New	280.00	280.00
3	TO REMOVE AND REINSTALL REAR WIRE HARNESS,AUDIO EQUIPMENT,CONTROL UNITS,RELAY AND FUSR TRAYS,END PANELLING,SPARE WHEEL HOUSING AND REAR LID HARNESS	New	1,800.00	1,800.00
4	TO REMOVE AND REINSTALL REAR SEATS,BACK REST,CARPETS,ABCD PILLAR TRIMS,DISENGAGE AIRBAG SYSTEM	New	1,800.00	1,800.00
5	TO REMOVE EXHAUST SYSTEM AND FUEL TANK ASSY,RENEW CENTER AND REAR EXHAUST SILENCER	New	1,200.00	1,200.00
6	TO REMOVE AND REINSTALL REAR SUSPENSION ASSY TO FACILITATE CELLETTE BENCH REPAIRS.INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	New	2,800.00	2,800.00
7	TO SET UP AND PLACE VEHICLE ON CELLETTE BENCH	New	1,200.00	1,200.00
8	TO DISMANTLE REAR BUMPER ASSY,CUT OUT AND WELD REAR END PANELLING.SPARE WHEEL HOUSING AND REAR CROSS MEMBERS.REPAIR AND ALIGN WHOLE REAR SUBSTRUCTURE TO POSITION.RENEW REAR BUMPER AND ALL DAMAGED FITTINGS.REINSTALL ALL PARTS REMOVED	New	7,200.00	5,000.00
9	TO CARRY OUT STONE CHIP PRIMER WORK ON REAR END PANELLING AND SPARE WHEEL HOUSING	New	780.00	780.00
10	TO SPRAY PAINT ON REAR BUMPER,REAR LID,SPARE WHEEL HOUSING,BOOT FLOOR,FRONT LSHS FENDER AND LHS WING MIRROR ASSY.TO CARRY OUT JOINT SEALER WORKS AND CAVITY PRESERVATION	New	4,300.00	2,350.00
11	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	240.00
12	TO CARRY OUT DIAGNOSTIC CHECKS	New	384.00	384.00
Gross Labour Cost (S\$)			22,484.00	17,834.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >