

ASS. REC. BY:

REF: CS/FCI18006456/K19d3ⁿ² Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): May chun of FCI Date/Time: 09/04/2018 @ 8:31am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 6923L Insured: SHC 8720S

at Workshop m/s Premier Automotive Tel: 6544 6689

of 23 Changi South Ave 2 # 03-02

Policy No: Claim No: D18002735MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 01/04/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time: 10:06am @ 9/4/18 Person Contacted: Vincent Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SHC 6923L - x

SHC 8720S - CS/FCI16016044/Gybg2

D.O.A: 20/8/16

17/4 @ 1:46pm revert via email preli Advice



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006456/K1qd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 09-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8720S	Veh. Inspected	SHC 6923L
Policy No.		Coverage (\$)	0.00
Claim No.	D18002735MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	09/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/04/2018	Inspection Date	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	06-04-2018	Our Ref No. D18002735MFSH
Accident Date	04-04-2018	Claim Type. Third Party
Insured Vehicle	SHC8720S	Third Party Vehicle. SHC6923L
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	VINCENT CHUA	
Contact No.	62148880/ 65446689	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236720)



PRI Documents



Close



PRI Header Details

Claim No	D18002735MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PREMIER LTD
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : VINCENT CHUA)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446689 , Phone: 62148880 , Fax: 62141511 EmailId: VINCENT.CHUA@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8720S	TP Vehicle No	SHC6923L
PRI Recieved Date	06-04-2018 04:12:34 PM	Surveyor Appointed Date	09-04-2018 08:29:50 AM	Surveyor Accept Date	09-04-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	09-04-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002735MFSH

Date: 17/4/2018

Our Ref: CS/FCI18006456/K1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6923L.

Please be informed that we had conducted the inspection of the abovementioned vehicle 16/04/2018 at the premises of M/s Premier Automotive and have the following to report:

-

Workshop Estimate Amount	: S\$ <u>1,711.90</u>
Revised Estimate Amount	: S\$ <u>500.00</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:
The vehicle sustained damages at the
n/s rear door portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Kalvin
Automotive Assessor

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Tuesday, 17 April 2018 1:46 PM
To: Admin-D (LKKAUTO); 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002735MFSH/1
Attachments: PRELI ADVISED SHC 6923L.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 6923L**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 9 April 2018 10:08 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002735MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 9 April 2018 8:31 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002735MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	22 Oct 2015 / 08:43:36	Receipt No.:	AACCK001-AX239-151022-000010
Asset Type:	Vehicle	Transaction Amount:	\$68,676.00
Asset ID:	SHC6923L	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151022084336502400		
Vehicle No.:	SHC6923L		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	22 Oct 2015		
Original Registration Date:	22 Oct 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5639409		
Engine No.:	D4FDEH313514		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$22,212.00		
Minimum PARF Benefit:	\$13,858.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	22 Oct 2015 08:43:36		
COE No.:	2015102201003733Z		
COE Expiry Date:	21 Oct 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$45,439.00		
Lifespan Expiry Date:	21 Oct 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

16-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6923 L

1 pc	Rear n/s door <i>x repair</i>	\$ 791.00
1 pc	Rear n/s door upper hinge @ \$34.00 <i>x su</i>	\$ 34.00
1 pc	Rear n/s door lower hinge @ \$34.00 <i>x su</i>	\$ 34.00
		\$ 791.00
	Less 10%	\$ 79.10
		\$ 711.90

S/NETT

1 set	n/s door sticker <i>ne</i>	\$ 100.00
	Sundry	\$ 50.00 <i>20</i> <i>net</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door, etc	\$ 450.00 <i>200</i>
	To putty and spray painting on rear n/s door	\$ 200.00 <i>160</i>
	To apply rustproofing on the repaired and replaced panels.	\$ 200.00 <i>x m</i>
		\$ 1,711.90
		1773.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Ko Lin (LKK)
16/4/18 1350hrs
2 hrs
4s
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006456/K1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 15-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8720S	Veh. Inspected	SHC 6923L	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002735MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	09/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5639409	Colour	SILVER	
Odometer	339160	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR DOOR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/04/2018	Inspection Date	16/04/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6923L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR N/S DOOR	TO REPAIR SEE LABOUR	791.00	-
1	REAR N/S DOOR UPPER HINGE	SERVICEABLE	34.00	-
1	REAR N/S DOOR LOWER HINGE	SERVICEABLE	34.00	-
	LESS 10% DISCOUNT		-85.90	-
			773.10	-
	<u>SPECIAL NETT ITEMS</u>			
1	SET N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			150.00	120.00
	<u>LABOUR</u>			
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE REAR N/S DOOR,ETC.		450.00	200.00
	TO PUTTY AND SPRAY PAINTING ON REAR N/S DOOR.		200.00	180.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	200.00	-
			850.00	380.00
	GRAND TOTAL		1,773.10	500.00
RECOMMENDED COST OF REPAIRS				500.00

Report Ref No. CS/FC118006456/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
 No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.