



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 22.10.2018

Survey Details:

Date of loss	06.04.2018
Date of appointment	09.04.2018
Date of survey	09.04.2018
Location of survey	CDGE LOYANG

Vehicle Details:

Claim Type:	Third party	
Vehicle number	SHC 3313S	
Make and Model	Hyundai I40 (1685cc)	
Date of registration	21.03.2014	
Excess	NIL	
Market Value/ Book Value		(est)
Parf/COE Rebate		(est)
Nett Loss		(est)

Repair details:

Initial Estimate	\$	2,051.44
------------------	----	----------

Proposed/Revised repair cost:

Parts	\$	1,381.44
Check items (estimate)		
Labour	\$	420.00
Supplementary	NIL	
Total	\$	1,801.44
Lump Sum(if applicable)	\$	1,450.00

Number of days for repair	<u>2</u>
---------------------------	----------



Date:

Remarks:

TP video shows that TP turned into the right lane and suddenly there is an impact. It is likely that both parties changing lane.

Mandate:

Liability(TP)	50%	
Proposed repair cost (w/GST)	\$ 1,551.50	
Loss of use	NIL	
Loss of rental	\$ 452.00	(4days x \$113.00)
Loss of income	\$ 200.00	(4days x \$50.00)
	\$ 2,203.50	
@ 50%	\$ 1,101.75	
LTA/GIA search fees	\$ 7.49	
Others	NIL	
Proposed Total	\$ 1,109.24	