

Surveyor

GR

ASSIGNMENT (Office)

From (Person): Eric WOO

at

LPC

Date/Time: 9/11/18 @ 4:51pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SQK 8268 B

Insured: SKG 8891 A

at Workshop n/s: Apple Hrv International

Tel:

of 600 Sin Ming Ave Level 3 Service Centre, 575733

Policy No:

Claim No: 17/18/18/VPOS/020522

Sum Insured:

Excess:

Make of Veh:

D.O.A. 5/1/2018

(Client's Record)

12/01/2018

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement

Date/Time: 5:04pm @ 9/11/18

Person Contacted:

Mr. Lee

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SQK 8268B - CS3/MSG16018695/1/1/vbs 2-1 DOA: 21/7/2016
	SKG 8891A - NAIAG16000862/13 DOA: 13/1/2016
14/6/18	@ 12:49pm Final fig \$4014.56 confirmed with Jun Hang (Red 2750.80, 419)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CS/LPC18006523/Gvd3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 09-04-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKG 8891A	Veh. Inspected	SGK 8268B
Policy No.		Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020522	Excess (\$)	0.00
Assign From	ERIC WOO	Assign Date	09/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	05/04/2018	Inspection Date	12/04/2018
Survey held at			
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Nivitha (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Monday, 9 April 2018 4:51 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG; ct-admin@visionlawllc.com
Subject: FW: Our Ref: 17/18/18/vp05/020522 Accident involving SKG8891A & SGK8268B along Marymount Rd on 5/4/8
Attachments: 1635_001.pdf

Dear Catherine,

Kindly refer to attachment.

Please proceed to appoint Mohammed Rasul conduct a survey of the vehicle SGK 8268B on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]
Sent: Monday, 9 April, 2018 4:24 PM
To: MT_Claim_SG; admin@hevshop.com
Subject: Scan Image

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
ONG BOCK KEE
ANG KIM NOI DIANE
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YING XIAN SELWYN

Unique Entity Number :200721148H
✓ **HEAD OFFICE:** 133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX ✓ : (65) 65356802 (General)
: (65) 65355905 (Litigation)
E-mail : jactan@visionlawllc.com

BRANCH

TEL : 65 63580703
FAX : 65 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: AM.jt.Ins.A99.106369.18 (sj)
Your Ref: SKG 8891 A

09 April 2018

LONPAC INSURANCE BERHAD
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
Attention: Motor Claims Department

BY FAX: 6296 2706

Email: mt_claim@lonpac.com

Dear Sirs,

ACCIDENT INVOLVING SGK 8268 B & SKG 8891 A ON 05 APRIL 2018 ALONG MARYMOUNT ROAD JUNCTION IN FRONT OF MRT STATION AT ABOUT 2130 HOURS

We refer to your letter dated 09 April 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Mohammed Rasul as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Apple Hev International Pte Ltd
600 Sin Ming Avenue
Level 3 Service Centre
Singapore 575733
Contact Person: Seok Hui @ 6352-9268

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully



ANJALLI M
(HEAD OFFICE)

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

cc: SGK 8268 B – by fax & email: admin@hevshop.com / 6352-9508

NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.

CONFIDENTIALITY
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6539D
Vehicle Details	
Vehicle No.:	SGK8268B
Vehicle to be Exported:	No
Intended De-registration Date:	13 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X A
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	LEB5079858
Chassis No.:	RU31129837
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$27,860.00
Original Registration Date:	13 May 2016
First Registration Date:	13 May 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 May 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 May 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$39,589.00
Total Rebate Amount:	\$43,339.00

The information contained herein is correct as at 13 Apr 2018

OK

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 14 June 2018 3:02 PM
To: 'servicing@hevshop.com'
Cc: SUR
Subject: RE: Before Painting Surveying

Dear Jun Hong,

WITHOUT PREJUDICE

As spoken this afternoon.

Confirmed finalize amount \$4014.56 @ 5 working days.

Final invoice and all supporting documents sent over to LONPAC INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 14 June 2018 11:38 AM
To: 'servicing@hevshop.com' <servicing@hevshop.com>
Subject: RE: Before Painting Surveying

Dear Jun Hong,

WITHOUT PREJUDICE

Please confirmed finalize amount \$3800 @ 5 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Thursday, 14 June 2018 11:01 AM
To: 'servicing@hevshop.com' <servicing@hevshop.com>
Subject: RE: Before Painting Surveying

Dear Jun Hong,

WITHOUT PREJUDICE

Please confirmed finalize amount \$3800 @ 5 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Guo Qiang (LKKAuto)

Sent: Tuesday, 12 June 2018 5:08 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: FW: Before Painting Surveying

From: Servicing hevshop [<mailto:servicing@hevshop.com>]

Sent: Friday, 13 April, 2018 6:06 PM

To: Guo Qiang (LKKAuto)

Subject: Before Painting Surveying

Hi Guo Qiang,

This is Jun Hong from Apple HEV International Pte Ltd. NAZ, your fellow colleague just came to conduct a pre-spray painting surveying for SGK8268B and had approved the following parts:

- 1) Tailgate Lock ASSY
- 2) SMART Buzzer ASSY

Please refer to the attachment below for NAZ's approval of parts. Thank you!

Best regards,

Lee Jun Hong

Service Advisor

Apple HEV International Pte Ltd

600 Sin Ming Ave

Level 3, CityCab Building

Singapore 575733

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/04/2018 16:29
Date Of Accident	05/04/2018 21:30
Exact Location Of Accident	MARYMOUNT ROAD JUNCTION IN FRONT OF MRT STATION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGK8268B
Insured/Policyholder	
Name Of Registered Owner	NG CHEN LENG
NRIC No	S7226539D
Email Address	GMLIM0084@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96370178
Alternative Phone No	OTHERS-96370178
Vehicle Particulars	
Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080215448-01
Cover Note Number	
Driver	
Name of Driver	LIM GEK MENG
NRIC No	S6918844C
Date Of Birth	30/05/1969
Occupation	INDOOR
Date Of Driving Pass	25/03/2003
Driving Experience	15 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96370178
Fax Number	
Contact Number	OTHERS-96370178
EEmail Address	GMLIM0084@YAHOO.COM

Address BLK 9 SIN MING WALK #17-06
SINGAPORE

Postcode 575578

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 4

Passenger 1 NAME: : NG CHEN LENG
GENDER: : FEMALE

Passenger 2 NAME: : LIM YUN FANG
GENDER: : FEMALE

Passenger 3 NAME: : LIM JING XUAN
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKG8891A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver SAMUEL JOSHUA POH YEE JIE

NRIC/Passport Number S9541979H

Contact Number 97356694

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Along Marymount Road, Red light is front of Marymount ART station, my vehicle stopped in front of Red light, while the light was still red, the vehicle behind me SKG 8891A (Mercedes) knocked my car from behind. Here video showing my car is stationary and light was still red when the car was knocked.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

APPLE HEV INTERNATIONAL PTE LTD

Hybrid & Electric Vehicle Service Center
 600 SIN MING AVE, LEVEL 3, SINGAPORE 575733
 Tel No. : 63529268 Fax No. : 63529508
 E-Mail : admin@hevshop.com
 Website : http://applehevinternational.com
 Tax Reg. No. : 201718701K

NG CHEN LENG
 9 Sin Min Walk #17-06
 Singapore 575578

Attention : Motor Claim Department
 Contact : 8338 6433

Estimate : ES000032

Date : 06/04/2018
 Vehicle Num. : SGK8268B
 Make/Model : Vezel Hybrid 1.5Z-2016
 Chassis/Eng# : RU31129837/LEB5079858
 Accident Date : 05/04/2018
 Claim No. :
 Reference :
 Policy No. : (13/05/2026)

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Tailgate ASSY / <i>Bruc.</i>		1,100.00
2.	1	Tailgate Weather Strip X <i>YNN</i>		151.70
3.	2	Tailgate Stopper X	21.00	42.00
4.	1	Tailgate Lock ASSY <i>DM</i>		145.70
5.	1	Tailgate Striker X <i>NN</i>		85.00
6.	1	Rear Bumper / <i>RE.</i>		980.00
7.	2	Rear Bumper Side Spacer (LH / RH) - <i>ACC</i>	28.80	57.60
8.	1	Rear Panel <i>Repair</i> X		476.00
9.	1	Rear Panel Top Garnish X <i>NN</i>		130.00
10.	1	Rear Wheel Arch Protector <i>X 2 - BR.</i>		268.20
11.	1	Rear Windscreen Moulding		220.20
12.	1	Rear Windscreen Sealant Kit - <i>SMC</i>		132.10
13.	1	Rear Floor Cover X <i>NN</i>		257.00
14.	1	Trunk Floor Box X		240.00
15.	1	SMART Buzzer ASSY <i>? DM</i>		220.00
16.	1	Antenna ASSY <i>? No damage</i>		145.00
17.	1	Reverse Sensor Set X <i>NN</i>		220.00
18.	1	'H' Emblem		25.00
19.	1	'VEZEL' Emblem - <i>ACC.</i>		58.00
20.	1	'HYBRID' Emblem - <i>ACC.</i>		85.00
List Total S\$:				5,038.50
20.00% Discount S\$:				1,007.70
				4,030.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

CONTINUE / ...

APPLE HEV INTERNATIONAL PTE LTD

Hybrid & Electric Vehicle Service Center
 600 SIN MING AVE, LEVEL 3, SINGAPORE 575733
 Tel No. : 63529268 Fax No. : 63529508
 E-Mail : admin@hevshop.com
 Website : http://applehevinternational.com
 Tax Reg. No. : 201718701K

NG CHEN LENG
 9 Sin Min Walk #17-06
 Singapore 575578

Attention : Motor Claim Department
 Contact : 8338 6433

Estimate : ES000032

Date : 06/04/2018
 Vehicle Num. : SGK8268B
 Make/Model : Vezel Hybrid 1.5Z-2016
 Chassis/Eng# : RU31129837/LEB5079858
 Accident Date : 05/04/2018
 Claim No. :
 Reference :
 Policy No. : (13/05/2026)

S/N	Quantity	Particular	Unit Price	Amount SS
1.	10	SPECIAL NETT ITEMS : Rear Bumper Clip <i>✓ MCL</i>	7.00	70.00
		Special Nett Total SS :		70.00
		LABOUR :		
		Panel Beating		<i>500</i> 1,100.00
		Spray Painting		<i>650</i> 850.00
		To remove, refix hybrid battery ASSY to facilitate rear panel epair work		<i>NNX</i> 300.00
		To remove, refix rear windscreen		<i>NNX</i> 100.00
		To conduct water test for rear car body		<i>NNX</i> 100.00
		Labour Total SS :		2,450.00

*5 Days.
 part by part. *Ng Chen Leng*
 before paint photos. / After paint photos.
 2/5/18.*

SingDollars : Six Thousand Five Hundred Fifty & Cents Eighty Only

Guo Qiang - 82880282 Total SS : 6,550.80
Guo Qiang @ lkkauto.com.

APPLE HEV INTERNATIONAL PTE LTD

12/4/18.

APPLE HEV INTERNATIONAL PTE LTD

Hybrid & Electric Vehicle Service Center
 600 SIN MING AVE, LEVEL 3, SINGAPORE 575733
 Tel No. : 63529268 Fax No. : 63529508
 E-Mail : admin@hevshop.com
 Website : http://applehevinternational.com
 Tax Reg. No. : 201718701K

NG CHEN LENG
 9 Sin Min Walk #17-06
 Singapore 575578

Attention : Motor Claim Department
 Contact : 8338 6433

Estimate : ES000032

Date : 06/04/2018
 Vehicle Num. : SCK8268B
 Make/Model : Vezel Hybrid 1.5Z-2016
 Chassis/Eng# : RU31129837/LEB5079858
 Accident Date : 05/04/2018
 Claim No. :
 Reference :
 Policy No. : (13/05/2026)

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Tailgate ASSY / <i>Price . 1100.90</i>		1,100.00
2.	1	Tailgate Weather Strip X <i>nn</i>		151.70
3.	2	Tailgate Stopper X <i>nn</i>	21.00	42.00
4.	1	Tailgate Lock ASSY X <i>nn dmg</i>		145.70
5.	1	Tailgate Striker X <i>nn</i>		85.00
6.	1	Rear Bumper / <i>RE . 850.70</i>		980.00
7.	2	Rear Bumper Side Spacer (LH / RH) / <i>NEC</i>	28.80	57.60
8.	1	Rear Panel <i>repair</i> X <i>nn</i>		476.00
9.	1	Rear Panel Top Garnish X <i>nn</i>		130.00
10.	2	Rear Wheel Arch Protector <i>BR . 5</i> X 2	536.40	268.20
11.	1	Rear Windscreen Moulding - <i>NEC</i>		220.20
12.	1	Rear Windscreen Sealant Kit - <i>NEC</i>		132.10
13.	1	Rear Floor Cover X <i>nn</i>		257.00
14.	1	Trunk Floor Box X <i>nn</i>		240.00
15.	1	SMART Buzzer ASSY X <i>nn dmg</i>		220.00
16.	1	Antenna ASSY X <i>no damage</i>		145.00
17.	1	Reverse Sensor Set X <i>nn</i>		220.00
18.	1	'H' Emblem /		25.00
19.	1	'VEZEL' Emblem /		58.00
20.	1	'HYBRID' Emblem / <i>NEC .</i>		85.00
List TotalS\$:				5,038.50
20.00% Discount S\$:				1,007.70
				4,030.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

CONTINUE / ...

APPLE HEV INTERNATIONAL PTE LTD

Hybrid & Electric Vehicle Service Center
 600 SIN MING AVE, LEVEL 3, SINGAPORE 575733
 Tel No. : 63529268 Fax No. : 63529508
 E-Mail : admin@hevshop.com
 Website : http://applehevinernational.com
 Tax Reg. No. : 201718701K

NG CHEN LENG
 9 Sin Min Walk #17-06
 Singapore 575578

Attention : Motor Claim Department
 Contact : 8338 6433

Estimate : ES000032

Date : 06/04/2018
 Vehicle Num. : SGK8268B
 Make/Model : Vezel Hybrid 1.5Z-2016
 Chassis/Eng# : RU31129837/LEB5079858
 Accident Date : 05/04/2018
 Claim No. :
 Reference :
 Policy No. : (13/05/2026)

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	10	SPECIAL NETT ITEMS : Rear Bumper Clip <i>✓ nec</i>	7.00	70.00
		Special Nett Total S\$:		70.00
		LABOUR :		<i>500</i>
		Panel Beating		<i>650</i> 1,100.00
		Spray Painting		<i>X</i> 850.00
		To remove, refix hybrid battery ASSY to facilitate rear panel repair work		<i>X</i> 300.00
		To remove, refix rear windscreen		<i>✓</i> 100.00
		To conduct water test for rear car body		<i>X</i> 100.00
		Labour Total S\$:		2,450.00

*5 Days.
 part by part.
 before paint photos. / After paint photos.*

SingDollars : Six Thousand Five Hundred Fifty & Cents Eighty Only

6765.36

*Guo Qiang - 82880282
 Guo Qiang @ lkkauto.com*

Total S\$: 6,550.80

APPLE HEV INTERNATIONAL PTE LTD

12/4/18.

*NAZ
 LKIC
 13/4/18 1715*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18006523/Gvd3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 21-06-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 8891A	Veh. Inspected	SGK 8268B
Policy No.		Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020522	Excess (\$)	0.00
Assign From	ERIC WOO	Assign Date	09/04/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31129837	Colour	GREY
Odometer	32237	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/04/2018	Inspection Date	12/04/2018
Survey held at	APPLE HEV INTERNATIONAL PTE LTD 600 SIN MING AVE 3		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 8268B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE ASSY	BUCKLED	1,100.00	1,100.00
1	TAILGATE WEATHER STRIP	NOT NECESSARY	151.70	-
2	TAILGATE STOPPER @\$21.00	NOT NECESSARY	42.00	-
1	TAILGATE LOCK ASSY	DAMAGED	145.70	145.70
1	TAILGATE STRIKER	NOT NECESSARY	85.00	-
1	REAR BUMPER	DEFORMED	980.00	850.70
2	REAR BUMPER SIDE SPACER LH/RH @\$28.80	NECESSARY	57.60	57.60
1	REAR PANEL	TO REPAIR SEE LABOUR	476.00	-
1	REAR PANEL TOP GARNISH	NOT NECESSARY	130.00	-
2	REAR WHEEL ARCH PROTECTOR @\$268.20	BROKEN	536.40	536.40
1	REAR WINDSCREEN MOULDING	NECESSARY	220.20	220.20
1	REAR WINDSCREEN SEALANT KIT	NECESSARY	132.10	132.10
1	REAR FLOOR COVER	NOT NECESSARY	257.00	-
1	TRUNK FLOOR BOX	NOT NECESSARY	240.00	-
1	SMART BUZZER ASSY	DAMAGED	220.00	220.00
1	ANTENNA ASSY	NO DAMAGE	145.00	-
1	SET REVERSE SENSOR	NOT NECESSARY	220.00	-
1	"H" EMBLEM	NECESSARY	25.00	25.00
1	"VEZEL" EMBLEM	NECESSARY	58.00	58.00
1	"HYBRID" EMBLEM	NECESSARY	85.00	85.00
	LESS 20% DISCOUNT		-1,061.34	-686.14
			4,245.36	2,744.56
<u>SPECIAL NETT ITEMS</u>				
10	REAR BUMPER CLIP @\$7.00 (SN)	NECESSARY	70.00	70.00
			70.00	70.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR PANEL.		1,100.00	500.00
	SPRAY PAINTING.		850.00	600.00

Report Ref No. CS/LPC18006523/Gvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE,REFIX HYBRID BATTERY ASSY TO FACILITATE REAR PANEL REPAIR WORK.	NOT NECESSARY	300.00	-
	TO REMOVE,REFIX REAR WINDSCREEN.		100.00	100.00
	TO CONDUCT WATER TEST FOR REAR CAR BODY.	NOT NECESSARY	100.00	-
			2,450.00	1,200.00
	GRAND TOTAL		6,765.36	4,014.56
	RECOMMENDED COST OF REPAIRS			4,014.56

Report Ref No. CS/LPC18006523/Gvd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.