







## Thatcham escribe

NTU	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC18006537/Nqbe2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	20-04-2018		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBB 557B	Veh. Ir	nspected	SHC 1583S	
	Policy No.	5084108819-01	Cover	age (\$)	0.00	
	Claim No.	MT/0989906-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	09/04/2018	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS HYBRID	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	JTDKB3FU803564914	Colou	r	BLUE	
	Odometer	75498	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/04/2018	Inspection Date 09/04/2018			
	Survey held at	vey held at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					