



Your Ref : S8M00D3F

Date: 20th April 2018

Our Ref : CS/ASM18006555/Kqd3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Peter Wang

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJG 852C
ACCIDENT ON 03/04/2018**

Instruction was received to inspect the vehicle Reg. No. SJG 852C. The inspection was conducted on 10/04/2018 at the premises of M/s Goldbell Engineering Pte Ltd, 29 Tanjong Penjuru Singapore 609026.

The following vehicle information was recorded:

Registration Number	: SJG 852C
Make/Model	: Toyota Mark X (A)
Year of Registration	: 2008
Body Colour	: Metallic Black
Chassis Number	: GRX1203050231
Engine Capacity	: 2499 cc

The vehicle sustained damages at the o/s body and n/s rear portion. The undercarriage and body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	17,000.00
Less: LTA Reimbursement Value (RV)	(S\$	13,363.00)
Nett Liability	S\$	<u>3,637.00</u>

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.