

CC 6/DAI1800 6673 AP63

ASSIGNMENT

Surveyor:

Adrian

DOI:

10/4/18

Date / Time:

10/4/18

Registered in Merit:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGA 22064

Claim No.:

26173/EP

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

6/4/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGC 3489E



INSRS:

WSP:

Tel:

Liability:

RMKS:

M3 solution



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT 18/4/18

1 Repudiated

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP \$300.00

REF:

ASS. REC. BY: Adrian Ling

ASSIGNMENT

15/01/06.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S6C3489E Yr Regn: 2006 / JanType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis cc 1598Colour: US Silver A/C: Insured / Std / NI / NASp. Reading: ✓ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053ZEC107108753Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/70R14R: 185/70R14BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or None

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 10/07/18Survey held at M.G. SolutionDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TR Direct Assn. COE Expiry: 15/01/21
	<u>US\$ 4900 (Reel 1-537.50/75%)</u>
	MV: 20.5K
	PV: 15.6K
	N44: 4.5K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS: \$ _____

Photos

Others

TOTAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/04/2018 15:23
Date Of Accident	06/04/2018 19:30
Exact Location Of Accident	JUNCTION OF SENGKANG EAST DR & SENGKANG EAST AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGC3489E
Insured/Policyholder	
Name Of Registered Owner	LOW YEW GEE
NRIC No	S0204879E
Email Address	TENGBENG.LOW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97681421
Alternative Phone No	OFFICE-88888888

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00223138/03
Cover Note Number	

Driver

Name of Driver	LOW YEW GEE
NRIC No	S0204879E
Date Of Birth	24/10/1948
Occupation	INDOOR
Date Of Driving Pass	28/11/1975
Driving Experience	42 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97681421
Fax Number	
Contact Number	OFFICE-88888888
Email Address	TENGBENG.LOW@GMAIL.COM

Address	BLK 171 ANG MO KIO AVE 4 #08-503
Postcode	2056
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 06/04/2018 AT ABOUT 1905HRS AT ALONG T-JUNCTION OF SENGKANG EAST DRIVE AND SENGKANG EAST AVE. I WAS TRAVELLING ON THE EXTREME LEFT LANE ALONG SENGKANG EAST DRIVE AND WHEN COMING TOWARDS SENGKANG EAST AVE. SUDDENLY A VEHICLE (B) FROM THE OPPOSITE DIRECTION MAKE A RIGHT TURN WITHOUT STOPPING AND WITHOUT GIVING WAY TO MY ON COMING TRAFFIC AND COLLIDED ONTO MY FRONT PORTION OF MY VEHICLE (A) CAUSING DAMAGES TO MY VEHICLE. I WISH TO STATE THAT TRAFFIC LIGHT WAS GREEN TO MY FAVOUR. (A) SGC3489E (B) SGA2206Y

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGA2206Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and for the Authorized Insurer.
3. Information provided must be as truthful and accurate as possible. Any initial misrepresentation or withholding of material facts may allow insurance companies to void/void policy liability.
4. The filing and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the police for investigation.
6. The report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - i. I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mailed packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their insurers' or firms' agents) who may be located outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to settle claims (including for the purposes of fraud detection, investigation and management's records and all future claims);
 - (e) transmission to collected under (d) will be encrypted and / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 06/04/2018 at about 1905 hrs at along T-Junction of Sengkang East Drive and Sengkang East Ave. I was travelling on the extreme left lane along Sengkang East Drive and when coming towards suddenly, a vehicle (B) from the opposite direction make a right turn without stopping and without way to my on coming giving a traffic and collided onto my front portion of my vehicle (A) causing damages to my vehicle. I wish to state that traffic light was green to my favour.

(A) SGC 3489 E

(B) SGA 2206 Y

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Signature
Name:
NSIC/PIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4879E
Vehicle Details	
Vehicle No.:	SGC3489E
Vehicle to be Exported:	Yes
Intended De-registration Date:	10 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA 1.6
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	3ZZ4536808
Chassis No.:	MR053ZEC107108753
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$16,772.00
Original Registration Date:	16 Jan 2006
First Registration Date:	16 Jan 2006
Transfer Count:	0
Actual ARF Paid:	\$18,450.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$28,317.00
COE Rebate Amount:	\$15,650.00
Total Rebate Amount:	\$15,650.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Apr 2018

OK



Altis Price Range Depreciation > 10 year(s) Vehicle Type

Advanced Search

Used Car Comparison

--- Comparing 3 Vehicles ---

Toyota Corolla Altis 1.6A (COE till 12/2020)



Add to Shortlist

Toyota Corolla Altis 1.6A (COE till 03/2021)



Add to Shortlist

Toyota Corolla Altis 1.6A (COE till 04/2021)



Add to Shortlist



Use search bar above to search to compare.

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

Price	\$22,988	\$21,000	\$23,800	-
Instalment	N.A.	N.A.	N.A.	-
Registration Date	22-Dec-2005	08-Mar-2006	20-Apr-2006	-
Manufactured	2005	2006	2006	-
Mileage	-	200,900 km	120,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,598 cc	1,598 cc	1,598 cc	-
Road Tax	\$965 /yr	\$890 /yr	\$890 /yr	-
Power	81.0 kW (108 bhp)	81.0 kW (108 bhp)	81.0 kW (108 bhp)	-
Curb Weight	0 kg	1,115 kg	1,115 kg	-
Features	1.6L 16 Valves VVTi DOHC 108Bhp Engine, Smooth Auto With ETC, Climatic Control Aircon, 2 x Airbags, ABS, Fog Lamps.	-	Reliable And Fuel Efficient 1.6L DOHC VVTi Engine DOHC Engine, Auto Transmission Gearbox, Climate Aircon Control, ABS, Dual Airbags.	-
Accessories	Leather Seats, Sports Rims, Factory Audio System, Reverse Sensors, Solar Film, Retractable Side Mirrors.	-	Sports Rims, Retractable Side Mirrors, Premium Leather Seats, Factory Integrated Audio Player With Steering Control, Fog Lamps, Walnut Interior Trim.	-
Description	\$0 Drive Away! 100% Accident Free, Very Well Maintained By Owner, Most Parts Has Been Replaced. In House Finance. In House Workshop. All In 1 Stop. Door Step Viewing Available. Kindly Arrange For Viewing.	Cheapest Price In Town, Has Been Drove For The Past 7 Years. Excellent Engine. Good Maintenance And Well Serviced. Sure Like Condition.	1 Owner, Genuine Low Mileage Done! Meticulously Well Maintained By Car Lover Owner With Super Smooth Engine & Gearbox Condition Assured! 100% Accident Free! Guaranteed No Further Repair Needed! Buy With A Peace Of Mind! Low Down Payment Or High Loan With Our Various Bank/In-House Loan Available To Cater To Your Requirements. Please Contact Our Friendly Sales Consultant For More Information Now!	-
COE	\$28,416	\$24,771	\$23,039	-
OMV	\$16,772	\$16,950	\$16,950	-
ARF	\$18,450	\$18,645	\$18,645	-
Depreciation	\$8,510 /yr	\$7,220 /yr	\$7,660 /yr	-
No. of Owners	2	4	1	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	COE Car	COE Car, Direct Owner Sale	COE Car, Low Mileage Car	-
Availability	Available	Available	Available	-

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03B Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: DIRECT ASIA	DATE	: 07/04/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGC3489E		
MODEL	: TOYOTA ALTIS 1.6 AUTO		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 7-Apr-18
		TIME	: 19:05HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET <i>distorted</i>	1	\$ 1,450.00	\$ 1,450.00
2	BONNET WEATHERSTRIP <i>at</i>	1	\$ 30.00	\$ 30.00
3	BONNET STOPPER <i>new</i>	4	\$ 20.00	\$ 80.00
4	BONNET HINGE <i>Best</i>	2	\$ 70.00	\$ 140.00
5	BONNET CABLE <i>new</i>	1	\$ 150.00	\$ 150.00
6	BONNET LOCK <i>changed</i>	1	\$ 80.00	\$ 80.00
7	BONNET INSULATOR <i>changed</i>	1	\$ 95.00	\$ 95.00
8	FRONT BUMPER <i>distorted</i>	1	\$ 422.00	\$ 422.00
9	FRONT BUMPER FOG LIGHT <i>PH changed</i>	2	\$ 190.00	\$ 380.00
10	FRONT BUMPER UNDER COVER GARNISH <i>new</i>	2	\$ 88.00	\$ 176.00
11	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 65.00	\$ 130.00
12	FRONT BUMPER REINFORCEMENT <i>distorted</i>	1	\$ 395.00	\$ 395.00
13	FRONT BUMPER CHASSIS BRACKET <i>new</i>	2	\$ 68.00	\$ 136.00
14	FRONT BRACE PANEL <i>Best</i>	1	\$ 125.00	\$ 125.00
15	FRONT GRILLE <i>changed</i>	1	\$ 295.00	\$ 295.00
16	FRONT GRILLE LOGO <i>new</i>	1	\$ 360.00	\$ 360.00
17	FRONT FENDER <i>distorted</i>	2	\$ 250.00	\$ 500.00
18	FRONT FENDER LAMP <i>new new</i>	2	\$ 45.00	\$ 90.00

19	FRONT FENDER INNER COWLING <i>new</i>	2	\$ 65.00	\$ 130.00	✓
20	HORN <i>2nd</i>	1	\$ 60.00	\$ 60.00	✓
21	HEADLAMP <i>cracked</i>	2	\$ 395.00	\$ 790.00	✓
22	FRONT SUPPORT PANEL <i>Disbld</i>	1	\$ 2,175.00	\$ 2,175.00	✓
23	AIR DUCT <i>new</i>	1	\$ 145.00	\$ 145.00	✓
24	RADIATOR <i>Disbld</i>	1	\$ 1,760.00	\$ 1,760.00	✓
25	RADIATOR TOP BRACKET <i>Best</i>	2	\$ 68.00	\$ 136.00	✓
26	RADIATOR TOP MOUNTING <i>new</i>	4	\$ 21.00	\$ 84.00	✓
27	RADIATOR BOTTOM MOUNTING <i>new</i>	4	\$ 29.00	\$ 116.00	✓
28	RADIATOR FAN COWLING <i>cracked</i>	1	\$ 276.00	\$ 276.00	✓
29	RADIATOR FAN MOTOR <i>Best</i>	1	\$ 250.00	\$ 250.00	✓
30	RADIATOR FAN BLADE <i>Best</i>	1	\$ 95.00	\$ 95.00	✓
31	RADIATOR SPARE TANK WITH COWLING <i>new</i>	1	\$ 242.00	\$ 242.00	✓
32	AIR CONDENSOR <i>Disbld</i>	1	\$ 1,395.00	\$ 1,395.00	✓
33	AIR CONDENSOR LOWER MOUNTING <i>new</i>	2	\$ 38.00	\$ 76.00	✓
34	AIR CON PIPE (SUCTION) <i>Best</i>	1	\$ 298.00	\$ 298.00	✓
35	AIR CON PIPE INLET PIPE <i>Best</i>	1	\$ 268.00	\$ 268.00	✓
36	AIR CON LIQUID PIPE <i>2nd new</i>	1	\$ 275.00	\$ 275.00	✓
37	AIR CLEANER HOUSING ASSY	1	\$ 445.00	\$ 445.00	✓
38	AIR CLEANER HOSE <i>2</i>	1	\$ 98.00	\$ 98.00	✓
39	ABS SOCKET	1	\$ 180.00	\$ 180.00	✓
40	ABS PUMP	1	\$ 1,985.00	\$ 1,985.00	✓
41	ABS BRACKET <i>At new</i>	1	\$ 165.00	\$ 165.00	✓
42	MANIFOLD	1	\$ 1,160.00	\$ 1,160.00	✓
43	BATTERY BRACKET	1	\$ 60.00	\$ 60.00	✓
44	FRONT ENGINE MOUNTING (SET)	4	\$ 498.00	\$ 1,992.00	✓

TOTAL PRICE \$ 19,690.00
 LESS 25% \$ 4,922.50
 SUB TOTAL PRICE \$ 14,767.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Missing</i>	1	\$ 50.00	\$ 50.00	✓
2	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
3	FRONT BUMPER UNDER COVER GARNISH CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
4	FRONT GRILLE CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
5	BONNET SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	✓
6	BONNET INSULATOR CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
7	FRONT FENDER SEALANT <i>At New</i>	2	\$ 80.00	\$ 160.00	✓
8	FRONT FENDER COWLING CLIPS(SET) <i>At New</i>	1	\$ 20.00	\$ 20.00	✓

9	BATTERY <i>Not in</i>	1	\$ 250.00	\$ 250.00	<i>x</i>
10	BRAKE OIL <i>Not in</i>	1	\$ 60.00	\$ 60.00	<i>x</i>

TOTAL \$ 700.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,800.00	1200	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	1000	
3	WIRING CHECK	\$ 150.00	30	
4	REFOCUS HEADLAMP BEAM	\$ 60.00	x.	
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60	
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60	
7	REMOVE AND REFIX ENGINE MOUNTING	\$ 280.00	x	
8	TO REMOVE AND REFIX FRONT DOOR	\$ 80.00	x	

TOTAL \$3,970.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 15,467.50
TOTAL LABOUR COST : \$ 3,970.00
TOTAL REPAIR COST : \$ 19,437.50

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :

NO OF DAYS :

Auto Consultants hence notify
the insurer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) **FAX**ed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li
L/S 10/04/18

08 Days

L/S \$4.9K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
DIRECT ASIA INSURANCE (SINGAPORE) PL		Ref : CC6/DAI18006673/Apb3		
88 SOUTH BRIDGE ROAD SINGAPORE 058716		Date : 11-04-2018		
		Code : DAI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGA 2206Y	Veh. Inspected	SGC 3489E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/04/2018	Inspection Date	10/04/2018	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

From: Elyn Pan <elyn@directasia.com>
Sent: Thursday, 12 April 2018 3:49 PM
To: Shu Pei (LKKAuto)
Subject: RE: [EXT] RE: Direct Settlement - Accident Involving SGA2206Y (OI :DAI - TBA) AND SGC3489E (TP : LKK REF - CC6/DAI18006673/App3) on 06.04.2018 -76173/EP

[!\[\]\(98b0d0ccc757b6bc0d84eb54a134e84b_img.jpg\)](#)
[!\[\]\(71c0e1b873ce5bacd02860899972a812_img.jpg\)](#)
[!\[\]\(8b4838a31ae42be6308fd9621a3178f4_img.jpg\)](#)
[!\[\]\(7cbaf772e3ab9270382f573df5f5b27f_img.jpg\)](#)
[!\[\]\(fdf452ab29386f5d9d0cac4afc592b6f_img.jpg\)](#)
[!\[\]\(679bd89e01162571d2bcb8591305f31c_img.jpg\)](#)

We had inspected the vehicle SGC 3489E at M/s MG Solution Pte Ltd and the repairer would like to do direct settlement with Direct Asia Insurance.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Please kindly advice liability soonest.

Meanwhile, kindly provide us the claim reference for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE: This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 13 April 2018 1:44 PM
To: 'mg3solution@gmail.com'
Cc: Admin A
Subject: Your Ref: SGC 3489E *Our Ref: CC6/DAI18006673/Apb3 [ACCIDENT INVOLVING SGA 2206Y(DIRECT ASIA) & SGC 3489E ON 06/04/2018]

Your Ref: **SGC 3489E** Without Prejudice
Our Ref: CC6/DAI18006673/Apb3

Dear Sirs,

ACCIDENT INVOLVING SGA 2206Y(DIRECT ASIA) & SGC 3489E ON 06/04/2018

We refer to the above matter.

Please be informed that our principal M/s Direct Asia Insurance (S) Pte Ltd had repudiated the claims in view of our insured has breach of policy terms and conditions.

Kindly re-direct your client's claim to our insured for redress.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

DIRECT ASIA INSURANCE (SINGAPORE) PL

Ref : CC6/DAI18006673/Apb3q2

88 SOUTH BRIDGE ROAD
SINGAPORE 058716

Date : 19-04-2018



Code : DAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGA 2206Y	Veh. Inspected	SGC 3489E
Policy No.		Coverage (\$)	0.00
Claim No.	76173/EP	Excess (\$)	0.00
Assign From		Assign Date	10/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053ZEC107108753	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	BRIDGESTONE	6 mm
L/H Front Tyre	185/70 R14	BRIDGESTONE	6 mm
R/H Rear Tyre	185/70 R14	BRIDGESTONE	6 mm
L/H Rear Tyre	185/70 R14	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/04/2018	Inspection Date	10/04/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGC 3489E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DISTORTED	1,450.00	1,450.00
1	BONNET WEATHERSTRIP	CUT	30.00	30.00
4	BONNET STOPPER @\$20.00	NOT NECESSARY	80.00	-
2	BONNET HINGE @\$70.00	BENT	140.00	140.00
1	BONNET CABLE	NOT NECESSARY	150.00	-
1	BONNET LOCK	DAMAGED	80.00	80.00
1	BONNET INSULATOR	CRUMPLED	95.00	95.00
1	FRONT BUMPER	DISTORTED	422.00	422.00
2	FRONT BUMPER FOG LIGHT @\$190.00	O/S CRACKED	380.00	190.00
2	FRONT BUMPER UNDER COVER GARNISH @\$88.00	TORN	176.00	176.00
2	FRONT BUMPER SIDE RETAINER @\$65.00	NECESSARY	130.00	130.00
1	FRONT BUMPER REINFORCEMENT	DISTORTED	395.00	395.00
2	FRONT BUMPER CHASSIS BRACKET @\$68.00	TO REPAIR SEE LABOUR	136.00	-
1	FRONT BRACE PANEL	BENT	125.00	125.00
1	FRONT GRILLE	CRACKED	295.00	295.00
1	FRONT GRILLE LOGO	NECESSARY	360.00	45.00
2	FRONT FENDER @\$250.00	BUCKLED	500.00	500.00
2	FRONT FENDER LAMP @\$45.00	NOT NECESSARY	90.00	-
2	FRONT FENDER INNER COWLING @\$65.00	NOT NECESSARY	130.00	-
1	HORN	DAMAGED	60.00	60.00
2	HEADLAMP @\$395.00	CRACKED	790.00	790.00
1	FRONT SUPPORT PANEL	DISTORTED	2,175.00	2,175.00
1	AIR DUCT	NOT NECESSARY	145.00	-
1	RADIATOR	DISTORTED	1,760.00	1,760.00
2	RADIATOR TOP BRACKET @\$68.00	BENT	136.00	136.00
4	RADIATOR TOP MOUNTING @\$21.00	NECESSARY	84.00	84.00
4	RADIATOR BOTTOM MOUNTING @\$29.00	NECESSARY	116.00	116.00
1	RADIATOR FAN COWLING	CRACKED	276.00	276.00
1	RADIATOR FAN MOTOR	DAMAGED	250.00	250.00
1	RADIATOR FAN BLADE	DAMAGED	95.00	95.00

Report Ref No. CC6/DAI18006673/Apb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR SPARE TANK WITH COWLING	NOT NECESSARY	242.00	-
1	AIR CONDENSOR	DISTORTED	1,395.00	1,395.00
2	AIR CONDENSOR LOWER MOUNTING @\$38.00	NECESSARY	76.00	76.00
1	AIR CON PIPE (SUCTION)	BENT	298.00	298.00
1	AIR CON PIPE INLET PIPE	BENT	268.00	268.00
1	AIR CON LIQUID PIPE	NOT NECESSARY	275.00	-
1	AIR CLEANER HOUSING ASSY	NOT NECESSARY	445.00	-
1	AIR CLEANER HOSE	NOT NECESSARY	98.00	-
1	ABS SOCKET	NOT NECESSARY	180.00	-
1	ABS PUMP	NOT NECESSARY	1,985.00	-
1	ABS BRACKET	NOT NECESSARY	165.00	-
1	MANIFOLD	NOT NECESSARY	1,160.00	-
1	BATTERY BRACKET	NOT NECESSARY	60.00	-
4	SET FRONT ENGINE MOUNTING @\$498.00	NOT NECESSARY	1,992.00	-
	LESS 25% DISCOUNT		-4,922.50	-2,963.00
			14,767.50	8,889.00
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	MISSING	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET FRONT BUMPER UNDER COVER GARNISH CLIP (SN)	NECESSARY	20.00	20.00
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	20.00	20.00
1	BONNET SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET BONNET INSULATOR CLIP (SN)	NECESSARY	20.00	20.00
2	FRONT FENDER SEALANT @\$80.00 (SN)	NOT NECESSARY	160.00	-
1	SET FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	20.00	-
1	BATTERY (SN)	NOT NECESSARY	250.00	-
1	BRAKE OIL (SN)	NOT NECESSARY	60.00	-
			700.00	130.00
	LABOUR			
	PANEL BEATING ,REMOVING AND REPLACING PARTS INCLUSIVE OF THE REPAIR OF FRONT BUMPER CHASSIS BRACKET.		1,800.00	1,200.00

Report Ref No. CC6/DAI18006673/Apb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING TO AFFECTED AREA.		1,400.00	1,000.00
	WIRING CHECK .		150.00	30.00
	REFOCUS HEADLAMP BEAM .	NOT NECESSARY	60.00	-
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS.		120.00	60.00
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.		80.00	60.00
	REMOVE AND REFIX ENGINE MOUNTING .	NOT NECESSARY	280.00	-
	TO REMOVE AND REFIX FRONT DOOR .	NOT NECESSARY	80.00	-
			3,970.00	2,350.00
GRAND TOTAL			19,437.50	11,369.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,900.00

Report Ref No. CC6/DAI18006673/Apb3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.