## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd 8 Shenton Way #24-01

AXA Tower Singapore 068811 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Khor Saw Theng Date: 13 Apr 2018

# **Preliminary Advice**

Insured Vehicle No : SHC5434M

TP Vehicle No : SHA3905U Accident Date : 08/04/2018

Make : RENAULT LATITUDE Assignment Date : 11/04/2018

Date of Inspection : 11/04/2018 Est. Duration of Repair : 2 days

Inspection At : ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive Singapore 508969

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages ....rear... portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 1,525.48 |
|-----------------------------|------|----------|
| Revised Amount              | :S\$ | 675.00   |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 675.00   |

Lump Sum Repair :S\$

#### **Total Loss Consideration**

(X) Other comments: We have not authorized repairs.

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

### Remarks

| ( | ) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|---|---|---|
| ( | ) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.   |