



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222 F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S KHIM SEAH ENTERPRISE PTE LTD
NO 71 WOODLANDS IND PARK E9
#06-08 WAVE 9
SINGAPORE 757048
Insured KHIM SEAH ENTERPRISE PTE LTD
Policy VFX/P0902358/00259

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 9/4/2018
Our Case Ref. SC18/04/076/4KS-TP
Accident Date 31/3/2018

Damaged Vehicle No: PC3251S

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					
1	RHS REAR VIEW MIRROR	1 PC	\$1,980.00	- <i>CRA</i>	\$1,980.00
<u>Labour Charges</u>					
1	LABOUR FOR WIRING	1	\$150.00	- <i>30</i>	\$150.00
2	SPRAY PAINTING	1	\$350.00	- <i>250</i>	\$350.00
3	LABOUR FOR REAR VIEW MIRROR	1	\$640.00	- <i>330</i>	\$640.00
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: <i>Rasul</i> <i>Hp 90010068</i> <i>2 days</i> <i>P/P</i> <i>11/04/18 @ 0945</i> <i>Reay by paint</i>					
Sub Total					\$ 3,120.00

Authorised Signature