

ASS. REC. BY:

REF: CS/MSG18006698/ Utd3

n2

Special Instruction:

Survivor:

Marus

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

M81G

Date/Time: 11/4/18 @ 2.19pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 9211S

Insured:

SKR 6526K

at Workshop m/s

Pegasus Engineering
51 Defu Lane 10

Tel:

6858 1846

of

Policy No:

29069368QMX

Claim No:

555125

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 08/04/2018

CA / REV / REP. / REV 24 HRS

lwp

19.04.2018 @ morning

H.O.D. Endorsement:

Date/Time:

3.32pm @ 11/4/18

Person Contacted:

Alvin

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ 9211S-X

SKR 6526K-CC3/CTI17014338/Uzb3q2

DOA: 22/07/2017

20/04/18

@ 15.07 pm. Revised to Catherine Thia Sh. Y. via meimer.

REF: MS16

Surveyor
Medimus

ASSIGNMENT

From:

Date:

19042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLQ 92115

at Workshop m/s

Pegasus

of

51 Deft Lane 10

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

morning

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / Seen:

2

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lufn Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLQ 92115

Yr Regn:

717

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

make 3

C.C.

1496

Colour

grey

A/C: Insured / Std / NI / NA

Sp. Reading

16060

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6BN22A8H0153023

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/R S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wist/che

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

8/4/18

D.O.I.

19/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS R.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/4/18 continued final by \$450 in the corner.
(Red: 380, 45%)

RECEIVED 26 APR 2018

Date/Time, File Pass to?



: Preli. Report

1) 20/4 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Invs (\$)



Weekend (\$)

Report Format:

TP

Lump Sum / I.B.I: (\$ 450)

150
10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2018		11 Apr 2018 14:19 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TU WEILONG, ID: S8851790C		
Main Claimant:	GRAB RENTALS 2 PTE LTD, Co. Reg. No.: 201701345N		
Vehicle Reg. No.:	SLQ9211S	Date of Loss:	08/04/2018 10:00 - :59 [8 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 555125	Policy/Cover Note No.:	29069368QMX Coverage: 19/01/2018 - 18/01/2019
Vehicle Reg. No. (Insured):	SKR6526K	Policy No. (Claimant):	
		Excess:	
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/04/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 20 Apr 2018

Preliminary Advice

Insured Vehicle No	: SKR6526K	Accident Date	: 08/04/2018
TP Vehicle No	: SLQ9211S	Assignment Date	: 11/04/2018
Make	: MAZDA M3	Est. Duration of Repair	: 2 days
Date of Inspection	: 19/04/2018		
Inspection At	: Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10 Singapore 539216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	830.00
Revised Amount	:S\$	450.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	450.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1345N

Vehicle Details

Vehicle No.:	SLQ92115
Vehicle to be Exported:	Yes
Intended De-registration Date:	10 Apr 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520444696
Chassis No.:	JM6BN22A8H0153023
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,761.00
Original Registration Date:	27 Jul 2017
First Registration Date:	27 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$9,761.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2027
PARF Rebate Amount:	\$7,320.00

Intended COE Rebate Details

COE Expiry Date:	26 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$34,240.00
Total Rebate Amount:	\$41,560.00

The information contained herein is correct as at 10 Apr 2018

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
GRAB RENTALS 2 PTE LTD
28, SIN MING LANE,
#07-71 MIDVIEW CITY
SINGAPORE 573969

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :
GRAB RENTALS 2 PTE LTD
28, SIN MING LANE,
#07-71 MIDVIEW CITY
SINGAPORE 573969

Attn :
Tel :
Fax :

Quotation No : QO18/04-1108	Quotation Date : 09/04/2018	Terms : 30 DAYS
Vehicle No : SLQ9211S	Chassis No : JM6BN22A8H0153023	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: MSIG, INSURED VEHICLE: SKR6526K, DOA: 08.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN FRONT FENDER LH AND FRONT BUMPER.	1	280.0000	280.00 120
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	550.0000	550.00 330

*Not Authorized
LKR
take photo after repair
19/4/18
2 day
1/1P 450/2*

*confirmed with Marcus
19.04.2018
@ 1015*

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane, 10 Singapore 539216

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications to be made
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____

Sub Total 830.00
GST(7.00%) 58.10
Total (SGD) 888.10

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006698/UTD3N2

Date: 26/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29069368QMX
Claimant Vehicle No :	SLQ9211S	Insured Vehicle No :	SKR6526K
Date of Loss:	08/04/2018	Nature of Claim:	TP
		Claim No:	555125

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ9211S	Engine No:	P520444696
Make & Model:	MAZDA M3, 1.6 (A)	Chassis No:	JM6BN22A8H0153023
Reg. Date:	27/07/2017 (Man. Year: 2017)	Odometer:	56060 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	450.00	380.00	45.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	830.00	450.00	380.00	45.78
+ GST 7.00/7.00% (S\$)	58.10	31.50	26.60	45.78
Nett Amount (S\$)	888.10	481.50	406.60	45.78

INSPECTION

Date of Assignment: 11/04/2018

Date Inspected: 19/04/2018 Inspected At:

Pegasus Engineering & Trading Pte Ltd
(HQ)
51 DEFU LANE 10
Singapore 539216

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2018)
Parts: 143	MAZDA M3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLQ9211S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION.REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN FRONT FENDER LH AND FRONT BUMPER	New	280.00	120.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	550.00	330.00
Gross Labour Cost (S\$)			830.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >