

22/03/2001

ASS. REC. BY:

REF: (S3/CTI18006705 / Gzld3<sup>3</sup>)

Special Instruction:

Surveyor:

From (Person):

IQ  
Irene Tay

ASSIGNMENT (Office)

of CTF

Date/Time: 11.4.18 @ 3.42pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 1812 J

Insured:

YN 83674

at Workshop m/s

Lian Her Motors

Tel:

64817221

of

1 Jalan Isnin

Policy No:

DMCV SN 3052911700

Claim No:

SNM18D01823C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05/04/2018

CA / REV / REP. / REV 24 HRS

(up)

Insp: Blk 5038 AMK Ave 3 #01-405 Ind. Park 2

12/04/18

H.O.D. Endorsement:

Date/Time:

3.54pm @ 11/4/18

Person Contacted:

Mr. James

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 1812 J - X
	YN 83 674 - X
13/4/18	Dismantled
18/4/18	After Repair

PRs xxx REF: CTI

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / (P) WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLV 1812J  
 at Workshop m/s Lian Her  
 of Blk 5138 Amk Ind Park 3 #01-415  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLV1812J Yr Regn: 2018  
 Type: (C) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Toyota C-UR C.C. 1797  
 Colour: Brown A/C Insured / Std / NI / NA  
 Sp. Reading: 28471 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: 8KX1020858-33  
 Gen. Cond: (C) Good / Fair / Poor / Burnt  
 Steering: (C) In order / Jammed / Leaked / Burnt or  
 Brake: (C) In order / Jammed / Leaked / Burnt or  
 Mod: (C) Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/60R17  
 R: 11

(C) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 12-04-18  
 Survey held at w/s 5:30pm  
 Des. of Damages: Frt / Rear / (C) N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\* Repair Estimate : S\$ 6000 - 7000

\* 3 days

4/5/18 Submit PRS report

RECEIVED 07 MAY 2018

Date/Time File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time File Return to?

2) \_\_\_\_\_

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) S + RS \$

2) Photos

3) Others

4) \_\_\_\_\_

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Ins (\$)

☐ Weekend (\$)

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2018		11 Apr 2018 15:42 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	W'RAY CONSTRUCTION PTE LTD, Co. Reg. No.: 200723544R		
Main Claimant:	HENG CHENG YONG, ID: S1644756J		
Vehicle Reg. No.:	SL1812	Date of Loss:	05/04/2018 14:00 - :59
Claim Type:	TP / SNM18D01823C02	Policy/Cover Note No.:	DMCVSN3052911700 (Comprehensive)
Vehicle Reg. No. (Insured):	YN8367U	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Lian Her Motors (HQ) 1 JALAN ISNIN, 577939 Ang Mo Kio - Tel: 64817221		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/04/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Lucas Lee

---

**From:** Prestina Moh <prestinamoh@visionlawllc.com>  
**Sent:** Wednesday, 11 April, 2018 3:37 PM  
**To:** Lucas Lee; Irene Tay  
**Subject:** RE: PRI FOR SLV1812J (CTI REF: SNM18D01823C02)

**IMMEDIATE ATTENTION**  
**WITHOUT PREJUDICE**  
**Our ref: SLV 1812 J**

Dear Sir/Mdm

We refer to your email on even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

<b>Venue</b>	:	<b>LIAN HER MOTORS</b> Block 5038 Ang Mo Kio Avenue 3 #01-405 Ang Mo Kio Industrial Park 2 Singapore 569541
<b>Contact Person</b>	:	<b>Mr. James @ 8299 0599 (Please call before going)</b>

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Regards,

Prestina Moh (Secretary)  
Vision Law LLC  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
Tel: 6534-2811 (Ext. 146)  
Fax: 6535-6802

---

**From:** Lucas Lee [mailto:lucas.lee@sg.cntaiping.com]  
**Sent:** Wednesday, 11 April, 2018 2:03 PM  
**To:** Prestina Moh  
**Subject:** RE: PRI FOR SLV1812J (CTI REF: SNM18D01823C02)

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Regards,

Lucas Lee

Claims Department (Motor)  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
3, Anson Road, #16-00  
Springleaf Tower,  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6181  
Fax: 6224 7175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** Prestina Moh [<mailto:prestinamoh@visionlawllc.com>]  
**Sent:** Tuesday, 10 April, 2018 5:49 PM  
**To:** Lucas Lee; Irene Tay  
**Subject:** RE: PRI FOR SLV1812J (CTI REF: SNM18D01823C02)

**WITHOUT PREJUDICE**  
**Our ref: SLV 1812 J**

Dear Sir/Mdm

We refer to your email of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following surveyors for your consideration:

1. Chartered Auto Assessors – C.S. Tan

Please reply within 2 working days.

Regards,

Prestina Moh (Secretary)  
Vision Law LLC  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
Tel: 6534-2811 (Ext. 146)  
Fax: 6535-6802

---

**From:** Lucas Lee [<mailto:lucas.lee@sg.cntaiping.com>]  
**Sent:** Tuesday, 10 April, 2018 5:28 PM  
**To:** Prestina Moh  
**Subject:** PRI FOR SLV1812J (CTI REF: SNM18D01823C02)

**Without Prejudice**

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Case Handler: Irene Tay

Regards,

Lucas Lee  
Claims Department (Motor)  
**China Taiping Insurance (Singapore) Pte. Ltd.**  
3, Anson Road, #16-00  
Springleaf Tower,  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6181  
Fax: 6224 7175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** Prestina Moh [<mailto:prestinaamoh@visionlawllc.com>]  
**Sent:** Tuesday, 10 April, 2018 5:25 PM  
**To:** Lucas Lee  
**Subject:** PRE-REPAIR SURVEY

## **REMINDER**

**WITHOUT PREJUDICE**

**Our ref: SLV 1812 J**

Dear Sir/Mdm

Please revert to our request dated 09.04.2018 urgently.

Regards,

Prestina Moh (Secretary)  
Vision Law LLC  
133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413  
Tel: 6534-2811 (Ext. 146)  
Fax: 6535-6802

---

VISION LAW LLC

Advocates & Solicitors  
(Incorporated with limited liability)  
Unique Entity No. 200721148H  
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413  
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

VISION LAW LLC

Advocates & Solicitors  
(Incorporated with limited liability)  
Unique Entity No. 200721148H  
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413  
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

**VISION LAW LLC**

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

---

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2018		11 Apr 2018 15:42 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	<b>W'RAY CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 200723544R		
Main Claimant:	<b>HENG CHENG YONG</b> , ID: S1644756J		
Vehicle Reg. No.:	<b>SL1812</b>	Date of Loss:	05/04/2018 14:00 - :59 [339 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM18D01823C02</b>	Policy/Cover Note No.:	DMCVSN3052911700 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>YN8367U</b>	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	<b>Lian Her Motors (HQ)</b> Block 5038 Ang Mo Kio Avenue 3, #01-405 Ang Mo Kio Industrial Park 2, 569541 Ang Mo Kio - Tel: 82990599		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 20/04/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SL1812 (SNM18D01823C02)**  
**[YN8367U]**  
**TP**  
**HENG CHENG YONG**  
**Apr 5 2018 2:00PM**  
**[W'RAY CONSTRUCTION PTE LTD]**  
**Lian Her Motors**

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports				1 per page ▼	✓
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	06/04/18 12:14	<b>Accident Statement</b>	1	Load HTM	
2	06/04/18 12:58	<b>Addendum Sheet</b>	1	Load JPG	✓
3	06/04/18 12:58	<b>Accident Statement Addm. #1</b>	1	Load HTM	
Photos/Images				3 per page ▼	✓
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	06/04/18 12:13	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	✓
2	06/04/18 12:13	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	✓
3	06/04/18 12:13	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	✓
4	06/04/18 12:13	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	✓
5	06/04/18 12:13	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	✓
6	06/04/18 12:13	<b>Accident Photo</b> [Linked Accident Report Documents]	1	Load JPG	✓
Documentation				1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	11/04/18 15:41	<b>PRS</b>	1	Load PDF	
2	11/04/18 15:42	<b>OI GIA REPORT</b>	1	Load PDF	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	06/04/18 09:22	<b>Sketch Plan</b> [Linked Accident Report Documents]	1	Load JPG	✓
2	06/04/18 09:22	<b>Sketch Plan #2</b> [Linked Accident Report Documents]	1	Load JPG	✓
3	06/04/18 12:52	<b>AUHTORISATION LETTER</b> [Linked Accident Report Documents]	1	Load JPG	✓
4	06/04/18 12:53	<b>WP &amp; DL</b> [Linked Accident Report Documents]	1	Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/04/18 20:15	<b>LKKPhotosIn6-1</b>	1	Load PDF	
2	17/04/18 20:15	<b>LKKPhotosIn6-2</b>	1	Load PDF	
3	27/04/18 10:46	<b>LKKPhotosIn6-3</b>	1	Load PDF	

## Linked Accident Report Documents

View View in Browser ▼

Assessment Reports				1 per page ▼	✓
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	06/04/18 12:14	<b>Accident Statement</b>	1	Load HTM	
2	06/04/18 12:58	<b>Addendum Sheet</b>	1	Load JPG	✓
3	06/04/18 12:58	<b>Accident Statement Addm. #1</b>	1	Load HTM	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	06/04/18 12:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	06/04/18 12:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	06/04/18 12:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	06/04/18 12:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	06/04/18 12:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	06/04/18 12:13	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	06/04/18 09:22	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	06/04/18 09:22	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	06/04/18 12:52	AUHTORISATION LETTER	 Load JPG	<input checked="" type="checkbox"/>
4	06/04/18 12:53	WP & DL	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18006705/GZ4D3S2

Date: 14/05/2018

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3052911700

Claimant Vehicle No: SL1812 Insured Vehicle No: YN8367U

Date of Loss: 05/04/2018 Nature of Claim: TP Claim No: SNM18D01823C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SL1812**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: HIDDEN

Reg. Date: 01/01/1990 (Man. Year: 1990) Chassis No: ZYX102085833

Colour: Brown Odometer: 28471 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 11/04/2018

Date Inspected: 12/04/2018 Inspected At: Lian Her Motors  
BLK 5038 ANG MO KIO INDUSTRIAL PARK 2,  
#01-405 SINGAPORE 569541.

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/14/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 - \$7,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 14 May 2018)

**Parts:** M1-SUV      TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SL1812)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >