

Surveyor

REF: CS/FCL18006700/T/Hb

Special Instruction:

US: \$ 16700.00

ASSIGNMENT (Office)

From (Person): Teo Swee Keong of FCL Date/Time: 11/04/2018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: LH Teo Appraisal

Workshop: I-Motoring Credit

OD/TP Re-inspection Evaluation

To Inspect Vehicle No: FBK 7237G Insured: SHA 4139H

at Workshop m/s I-Motoring Credit Tel: Blk 1008 Bukit Merah Lane 3 # 01-14

Policy No: Claim No: D18000357MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 01-01-2018

(Client's Record)

12-04-2018 (Thursday) @ 10am

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 9 days)

Date/Time: Submit Final Fig \$14,800.00, 8 days (Red \$ 1900 / 11 %; Original 9 days)

Date/Time	Action/Instruction
	FBK 7237G - NBA / INC 18000175/Y
	SHA 4139H - CS/FCL18006700/Avbg
	Submit TP- Reinspection
	RECEIVED 12 JUN 2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/  
Evaluated by:

Fee Charged:

Date:

Basic & Add

Transport

Photos

Others

Total

335

50

159

344

1) Date/Time 12/4/18 File Pass to tipat

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

REF:

## ASSIGNMENT

LOE 2019 July

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop no: \_\_\_\_\_

of: \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: FBK 72376Regn: 2009

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kawasaki ZG1400AColour: Grey

Sp Reading: \_\_\_\_\_

Eng/No: \_\_\_\_\_

C/No: JKBZGT40AAA 022849Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SR Rim / STD A/Rim orTyre Size: F: 120/70K17R: 110/50K17

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mm

L/Bal. \_\_\_\_\_ mm

L/Bal. \_\_\_\_\_ mm

D.O.A. \_\_\_\_\_

D.O.I. 12/4/2018

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Insp (\$)

☐

Week-end (\$)

Report Format :

Lump Sum / I.B.T. (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. \$ + \$ = \$

2. Total:

3. Other:

4.

TOTAL:

**Catherine Chong (LKK Auto)**

---

**From:** roynpartners <roynpartners@roynpartners.com.sg>  
**Sent:** Wednesday, 11 April, 2018 2:39 PM  
**To:** 'Teo Swee Keong'  
**Cc:** 'Serene Ler'; assignments@lkkauto.com  
**Subject:** RE: YR REF: MKR/201/7730/2018/AS.W1 OUR REF: D18000357MFSH  
**Importance:** High

Dear Swee Keong,

Our client's motorcycle FBK 7237G will be available for post-repair inspection with details as follows :-

Date and time: 12th April 2018 (Thursday) at 10.00am

Location: I-Motoring Credit Pte Ltd  
Block 1008 Bukit Merah Lane 3  
#01-14, Singapore 159722

Kindly confirm as soon as possible.

BCC: Clients (FBK 7237G)

Thanks & regards,

Ashley Su (Mr)  
Legal Executive  
M/s Roy & Partners  
101 Cecil Street  
#11-09 Tong Eng Building  
Singapore 069533  
Tel : 6536 8466 Fax : 6536 1963  
Email : ashley@roynpartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

-----Original Message-----

From: Teo Swee Keong [mailto:TeoSweeKeong@msfirstcapital.com.sg]  
Sent: Wednesday, 11 April, 2018 2:35 PM  
To: roynpartners <roynpartners@roynpartners.com.sg>  
Cc: Serene Ler <SereneLer@msfirstcapital.com.sg>; 'assignments@lkkauto.com'  
<assignments@lkkauto.com>  
Subject: YR REF: MKR/201/7730/2018/AS.W1 OUR REF: D18000357MFSH

Dear Ashley

Please kindly provide us your Workshop detail so that we arrange our surveyor (LKK) to conduct post-repair inspection as soon as possible.

To LKK

Please assist.

Thank you.

Thanks and Regards,

SK Teo  
Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 |

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to [www.msfirstcapital.com.sg](http://www.msfirstcapital.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

-----Original Message-----

From: roynpartners [mailto:[roynpartners@roynpartners.com.sg](mailto:roynpartners@roynpartners.com.sg)]

Sent: Monday, April 09, 2018 10:47 AM

To: Teo Swee Keong <[TeoSweeKeong@msfirstcapital.com.sg](mailto:TeoSweeKeong@msfirstcapital.com.sg)>;  
[smcoordinator@vac.com.sg](mailto:smcoordinator@vac.com.sg)

Cc: [vacsm@singnet.com.sg](mailto:vacsm@singnet.com.sg); Serene Ler <[Sereneler@msfirstcapital.com.sg](mailto:Sereneler@msfirstcapital.com.sg)>

Subject: RE: NEW SURVEY ASSIGNMENT - OUR REF: SHA4139H DOA 01/01/2018

Importance: High

Dear Swee Keong,

We refer to your email of 16th January 2018.

Our client's motorcycle FBK 7237G is repaired. Kindly let us know if you intend to do a post-repair inspection as soon as possible.

Bcc: clients  
(FBK 7237G)

Thanks & regards,

Ashley Su (Mr)  
Legal Executive  
M/s Roy & Partners  
101 Cecil Street  
#11-09 Tong Eng Building  
Singapore 069533

Tel : 6536 8466 Fax : 6536 1963  
Email : ashley@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

-----Original Message-----

From: Teo Swee Keong [mailto:TeoSweeKeong@msfirstcapital.com.sg]  
Sent: Tuesday, 16 January, 2018 12:17 PM  
To: smcoordinator@vac.com.sg  
Cc: 'vacsm@singnet.com.sg' <vacsm@singnet.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>; roynpartners@roypartners.com.sg  
Subject: NEW SURVEY ASSIGNMENT - OUR REF: SHA4139H DOA 01/01/2018  
Importance: High

Dear Sirs

New survey request for your handling.

Thanks and Regards,

SK Teo  
Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 |

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to [www.msfirstcapital.com.sg](http://www.msfirstcapital.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

-----Original Message-----

From: roynpartners [mailto:roynpartners@roypartners.com.sg]  
Sent: Tuesday, January 16, 2018 11:15 AM  
To: Teo Swee Keong <TeoSweeKeong@msfirstcapital.com.sg>  
Cc: Serene Ler <Sereneler@msfirstcapital.com.sg>  
Subject: RE: YR REF: MKR/201/7730/2018/AS.W1 OUR REF: SHA4139H DOA 01/01/2018  
Importance: High

Dear Swee Keong,

We attached herewith our email dated 16th January 2018 sent to you on 11.09am for your attention.

Thanks & regards,

Ashley Su (Mr)  
Legal Executive  
M/s Roy & Partners  
101 Cecil Street  
#11-09 Tong Eng Building  
Singapore 069533  
Tel : 6536 8466 Fax : 6536 1963  
Email : ashley@roypartners.com.sg

IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.

-----Original Message-----

From: Teo Swee Keong [mailto:TeoSweeKeong@msfirstcapital.com.sg]  
Sent: Tuesday, 16 January, 2018 11:12 AM  
To: roynpartners@roypartners.com.sg  
Cc: Serene Ler <Sereneler@msfirstcapital.com.sg>  
Subject: RE: YR REF: MKR/201/7730/2018/AS.W1 OUR REF: SHA4139H DOA  
01/01/2018

Dear Sirs,

Kindly ignore my earlier emails & we apologise for the previous email

Please find below our list of surveyors for your reference. Kindly select from our list below and inform us of your choice within the next 2 days.

1. LKK Auto Consultants Pte Ltd
2. Vicom Ltd

Once you inform us of your choice, the surveyor will be appointed within 2 working days of your email.

If you do not agree to any of the surveyors above, you may proceed to appoint your own surveyor. In this instance, we will also appoint a surveyor from our list above to conduct the PRI. Upon completion of repairs, please contact our appointed surveyor to conduct a physical re-inspection of the vehicle.

Thank you.

Thanks and Regards,

SK Teo  
Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 |

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to [www.msfirstcapital.com.sg](http://www.msfirstcapital.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

-----Original Message-----

From: Teo Swee Keong

Sent: Tuesday, January 16, 2018 10:51 AM

To: 'roynpartners@roynpartners.com.sg' <roynpartners@roynpartners.com.sg>

Cc: Serene Ler <SereneLer@msfirstcapital.com.sg>

Subject: YR REF: MKR/201/7730/2018/AS.W1 OUR REF: SHA4139H DOA 01/01/2018

Dear Sirs,

Please refer to our attached email earlier.

As we did not hear from you within 2 working days, we have appointed our surveyor to conduct the pre-repair survey.

Thank you

Thanks and Regards,

SK Teo

Motor Claims Dept

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 |

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to [www.msfirstcapital.com.sg](http://www.msfirstcapital.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

-----Original Message-----

From: Teo Swee Keong

Sent: Friday, January 12, 2018 5:03 PM

To: 'roynpartners@roynpartners.com.sg' <roynpartners@roynpartners.com.sg>

Cc: Serene Ler <SereneLer@first-insurance.com.sg>

Dear Sirs

New survey request for your handling.

Thanks and Regards,

SK Teo  
Motor Claims Dept

36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3848 | Fax No. : 6507 3849 | Company Regn. No. 195000106C  
email: MotorClaims@first-insurance.com.sg

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to [www.first-insurance.com.sg](http://www.first-insurance.com.sg) for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

-----Original Message-----

From: Nandu Kumar  
Sent: Friday, January 12, 2018 9:12 AM  
To: Teo Swee Keong <TeoSweeKeong@first-insurance.com.sg>  
Subject: FW: Fax data from cwsmotorclaims@first-insurance.com.sg

-----Original Message-----

From: CWS Motor Claims  
Sent: Thursday, 11 January, 2018 5:37 PM  
To: CLFax <CLFax@first-insurance.com.sg>  
Subject: Fax data from cwsmotorclaims@first-insurance.com.sg

---

This email has been checked for viruses by AVG.  
<http://www.avg.com>



# ROY & PARTNERS

(Business Registration No. 53131170L)

Advocates & Solicitors

Commissioner For Oaths

Notary Public

MONOJ KUMAR ROY LLB (Hons.) S'pore

GERALD MARTIN WEE LLB (Hons.) Liverpool

101 Cecil Street #11-09 Tong Eng Building, Singapore 069533

Tel : 6536 8466

Fax : 6536 1963 (Not For Service Of Documents)

Enquiries: [roynpartners@roynpartners.com.sg](mailto:roynpartners@roynpartners.com.sg)

Your Ref : Your insured vehicle: SHA 4139H

Our Ref : MKR/201/7730/2018/as.wl;

11<sup>th</sup> January 2018

**IMMEDIATE ATTENTION**

**M/S FIRST CAPITAL INSURANCE LTD**

30 Robinson Road

#10-01/02 Robinson Towers

Singapore 048546

(Attn: Motor Claims Department)

**BY FAX: 6507 3849 ONLY**

Dear Sirs,

**CLAIMANT : MOHAMED SHAFUDDIN BIN GANI (OWNER OF FBK 7237G)  
ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. FBK 7237G AND SHA 4139H  
ALONG WOODLANDS CENTRE ROAD ON 01.01.2018 AT ABOUT 2325 HOURS.**

We refer to the above matter.

We act for Mohamed Shafuddin Bin Gani, the owner of motorcycle No. FBK 7237G.

We are instructed by our client to notify you of a road traffic accident on 01.01.2018 at about 11.25pm along Woodlands Centre Road involving our client's motorcycle registration number **FBK 7237G** and motor taxi registration number **SHA 4139G** driven by your insured at the material time. A copy of the Singapore Accident Statement filed and Traffic Police report is enclosed.

As a result of the accident, our client's motorcycle **FBK 7237G** has been damaged. Before our client proceed to repair the damaged motorcycle, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motorcycle **FBK 7237G** at our client's repairer workshop, M/s I-Motoring Credit Pte Ltd at Blk 1008, Bukit Merah Lane 3 #01-14, Singapore 159722. Your said surveyor may contact Sally at 6316 1611. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motorcycle without further reference to you.

Yours faithfully,

  
**MONOJ KUMAR ROY**

Encl.

Cc: Clients (I-Motoring Credit Pte Ltd)  
(FBK/7237G)

(Fax No. 6316 7881)

Atti Sally

MDM46001012 / National Assessment Centre Services - Bukit Merah  
ENTRY DATE & TIME: 02/01/2018 10:18  
SUBMITTED BY: ROSLI BIN ABDUL WAHAB

Your NCD will be affected due to late reporting  
Actual e-Filing Submission Date & Time: 03/01/2018 16:59

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 02/01/2018 19:18  
Date Of Accident 01/01/2018 23:25  
Exact Location Of Accident ALONG WOODLANDS CENTRE ROAD  
Country/State Of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number FBK7237G  
Insured/Policyholder  
Name Of Registered Owner MOHAMED SHAFUDDIN BIN GANI  
NRIC No S7235657H  
Email Address SHAHGANI72@GMAIL.COM  
Mobile Phone No (LOCAL) +65-98343344  
Alternative Phone No OTHERS-98343344

Vehicle Particulars  
Manufacturer KAWASAKI  
Model ZG1400A-1.4 (M)  
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE  
Are you claiming under your own insurance policy for repair to your vehicle? NO  
If No, Please state action to be taken THIRD PARTY  
Vehicle Category MOTORCYCLE

Insurance Company  
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
Fleet Policy NO  
Policy Number 5077150689-01  
Cover Note Number

Driver  
Name of Driver MOHAMED SHAFUDDIN BIN GANI  
NRIC No S7235657H  
Date Of Birth 05/10/1972  
Occupation INDOOR  
Date Of Driving Pass 22/11/2005  
Driving Experience 12 YEARS AND 1 MONTH  
Gender MALE  
Mobile Number (LOCAL) +65-98343344  
Fax Number  
Contact Number OTHERS-98343344  
Email Address SHAHGANI72@GMAIL.COM

Address BLK 1G CANTONMENT ROAD  
#20-83  
Postcode 085701  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
-  
-  
Insurance Company of Driver's Own Vehicle -  
-  
-

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name BUKIT MERAH EAST NEIGHBOURHOOD POLICE CENTRE  
Police Station Address ROAD: 391 NEW BRIDGE ROAD POLICE CANTONMENT COMPLEX  
BLOCK A, POSTCODE: 088762, COUNTRY: SINGAPORE  
Police Station Contact TEL NO: 1800-2369989 - FAX NO: 62268438  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

**Circumstances of Accident**

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT T/20180102/2184

**Attachment(s)**

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHA4139H  
Vehicle Make/Model/Colour HYUNDAI  
Details Of Properties  
Vehicle Category TAXI  
Name of Driver WAN  
NRIC/Passport Number  
Contact Number 84022101  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage

No. Of Passenger (Including Driver)

1

**DETAILS OF INJURED PERSON 1**

Name

MOHAMED SHAFUDDIN BIN GANI

Approximate Age

Injuries Sustain

SLIGHT INJURY

Injured person in which vehicle?

FBK7237G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address


Postcode

**IMPORTANT NOTICE**

- I understand, acknowledge, agree and consent that:

- Glasgow: Scottish Landowners' Association.





## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 01/01/18 abt 2325hrs I was travelling along Woodlands Town Centre. I was travelling in a middle lane. Suddenly a taxi register SHA 4139 H. dashed from Woodland Centre Road hit on right side of my bike causing me off & flew off ~~my bike~~ from my bike and landed on the road (2nd lane).

Ambulance was conveyed as passerby called. Due to this incident I sustained both legs injuries. ~~Raffles hospital~~ I went to Raffles hospital for further medical check up. Bike reg no ~~FBK~~ FBK 7327 G was badly damaged and towed immediately to workshop.

SHOCK HUMANITY FULL FACT DAMAGE

POLICE REPORT 1/20180102/2194

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 02-01-2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

03/01/2017

Rishi GATHER


**SINGAPORE  
POLICE FORCE**


T/20180102/2164

1 of 3

Report No, T/20180102/2164

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 02/01/2018 20:20		Vide Report No.:		Station Diary No.: 216	
<b>Informant's Particulars</b>					
Name of Informant: MOHAMED SHAFUDDIN BIN GANI			Address: APT BLK 1G CANTONMENT ROAD #20-83 SINGAPORE 085701		
ID Type / ID No.: NRIC NO / S7235657H			Contact No.: Home/Office:		Mobile: 98343344
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 45	Date of Birth: 05/10/1972	Type of Informant: Rider		Institution / School Name:
Race: Malay			Language: English		
Occupation: OPERATIONS MANAGER			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 01/01/2018 23:25	Type of Location: Straight Road
Location: Along Road 1 WOODLANDS CENTRE ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
FBK7237G	Motorcycle	KAWASAKI	ZG1400A	Grey	Seriously Damaged	0
SHA4139H	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue	Slightly Damaged	0

<b>Details of Vehicle Insurance</b>			
Vehicle No.	Insurance Company	Insurance No.	Effective - Expiry Date


**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999



T/20180102/2194

2 of 3

Report No. T/20180102/2194

**CONTINUATION OF REPORT**

Details of Vehicle Insurance			
Vehicle No.	Insurance Company	Insurance No.	Effective / Expiry Date
FBK7237G	NTUC Income Insurance Co-Operative Limited	5077150689-01	31/01/2017 / 30/01/2018

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Rider			
Name	MOHAMED SHAFUDDIN BIN GANI	ID No.	S7235657H
Related Vehicle	FBK7237G (Motorcycle)	Contact No.	98343344
Hospital/Clinic	RAFFLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	02/01/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Serious

**Brief Details.**

On 01/01/2018 at around 2325hrs, I was travelling along Woodlands Town Centre. I was travelling in the second lane of the road. At that point in time, a taxi with registration plate number, SHA4139H was driving along Woodlands Centre Road and entered Woodlands Town Centre and straightaway dashed to the second lane. However, he did not see me travelling in the second lane and he collided onto my vehicle. His left front of his vehicle collided onto my right side of my motorcycle.

Due to the collision, I flew from my motorcycle and landed on the second lane of the road. However, my motorcycle travelled another 100 meters and landed near the pavement. The passerby called for assistance and traffic police and ambulance attended to us. However, no one was conveyed through ambulance. The police took down our particulars. After which, my sibling brought me to Raffles Hospital to get checked up and I was given 3 days of medical leave. The injuries I incurred are swelling in both my knees and right, lower thigh and bruises on my right knuckle.

Due to the collision, my motorcycle was seriously damaged and was towed away to the workshop from the incident location. The front of my vehicle is totally damaged and thus was towed away. Due to the fall, my Shoei Full Face helmet was heavily damaged and had serious dents on it.

The damages to the other vehicle are as follows:

- 1) Front left bumper had a slight dent.





**SINGAPORE  
POLICE FORCE**



T/20180102/2194

3 of 3

Report No. T/20180102/2194

Police Station Of Origin:  
Bukit Merah East N.P.C  
A 391 New Bridge Road Police Cantonment  
Complex SINGAPORE 088762  
Tel No: 1800-2369999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A/  
SHAFEER AHAMED HSignature Of Interpreter:  
Not applicable

Officer In Charge Of Case:

TP / GIT /  
Staff Sgt SHAHRUL NIZAM BIN SAMARRI  
Contact No.: 65476904Authentication Stamp  
NP158

Signature Of Informant:

Date/Time:  
02/01/2018 20:20

Classification Of Case:

## Enquire Vehicle & Owner Information ( Vehicle No. SHA4139H As At 01 Jan 2018 / 23:25:00 )

### Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: MKR/201/7730/2018

### Current Owner Details

Owner ID Type: Company

Owner ID: 199303821R

Owner Name: COMFORT TRANSPORTATION PTE LTD

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office  
Complexes

Registered Block/House  
No.: 383

Registered Street Name: SIN MING DRIVE

Registered Unit No.: -

Registered Building Name: GAS BUILDING

Registered Postal Code: 575717

### Current Vehicle Details

Vehicle No.: SHA4139H

Make Description/Model: HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Insurance Company Name: FIRST CAPITAL INS LTD

**Loss Adjuster, Consulting Automotive Engineer, Accident Reconstruction & Analyst.****VEHICLE APPRAISAL REPORT**

Mr. Mohamed Shafuddin Bin Gani  
Apt Blk 1G Contonment Road  
#20 -83  
Singapore- 085701

Our Ref : TP/1801/FBK7237/TM  
Date : 14 March 2018

**REFERENCE PARTICULARS**

Your Reference No : Not Advised  
Date of Accident : 01 Jan 2018

Date of Assignment : 16 Jan 2018  
Date of Inspection : 16 Jan 2018  
Date of Re-inspn. : N/A

**PARTICULARS OF VEHICLE**

Regn. No	: FBK 7237G	Odometer	: Meter Damage
Make	: KAWASAKI	Color	: Grey
Model	: ZG1400A	Chassis No.	: JKBZGT40AAA022849
Year	: 2009 (COE Exp : Jul 2019)	Engine No	: ZXT40AE054044

**TYRE / CONDITION**

<u>Location</u>	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Bridgestone	120 /70 R17	6 mm
Rear	Bridgestone	190 /50 R17	6 mm

**DAMAGE PROFILE**

The motor cycle sustained damage on all sides

Please refer to photographs and assessment of repairs for details.

**ASSESSMENT SUMMARY**

Repair cost to the vehicle is assessed as \$ **16,700.00 lump sum.**

Survey conducted at: I-Motoring

Enclosed (65) photographs depicting damage to the vehicle.

Estimated time required for repairs: (9) days.

The survey was conducted on a **WITHOUT PREJUDICE BASIS.**

**ASSESSMENT FOR REPAIR : FBK 7237 G**

<u>Qty</u>	<u>Description</u>	<u>Condition</u>	<u>Repairer's Estimate</u>	<u>Our Assessment</u>
1 pc	Handle bar LH	Usable	216.40	~ NH
1 pc	Clutch master assy	Cut	564.90	564.90
2 pcs	Inner covers @139.30	Torn / Deformed LH	278.60	278.60 139.30 Δ
2 pcs	Mirror assy @278.60	Broken / Cut LH	557.20	557.20 278.60 Δ
1 pc	Mirror bracket	Bent	254.00	254.00
1 pc	Wind shield assy	Cut / Bracket Bent	1,159.20	1,159.20
1 pc	Head cowling	Torn	492.00	492.00
1 pc	Head cowling bracket	Bent	231.20	231.20
1 pc	Air intake cowling	Cracked	65.70	65.70
1 pc	Air duct complete LH	Torn	384.40	384.40
1 pc	Head lamp complete	Broken	978.50	978.50
1 pc	Front fender	Cracked	330.00	330.00
2 pcs	Fender side cover @33.10	Cracked	66.20	66.20
1 pc	Front wheel assy	Cut	1,411.20	1,411.20
1 pc	Front brake disc LH	Cut	461.90	461.90 X NH Δ
2 pcs	Front signal lamp @77.00	Cut	154.00	154.00
2 pcs	Side cowling front @394.20	Cracked / Cut	788.40	788.40
2 pcs	Side cowling shroud @43.90	Cut	87.80	87.80
2 pcs	Side cowling pad @22.10	Necessary	44.20	44.20
2 pcs	Heat guard pad @55.00	Necessary	110.00	110.00
2 pcs	Side cowling bracket @18.40	Bent	36.80	36.80
2 pcs	Center cowling @473.20	Cracked / Cut	946.40	946.40
2 pcs	Hot wind cowling @136.20	Torn / Cut	272.40	272.40
1 pc	Lower cowling, front center	Deformed	52.40	52.40
2 pcs	Lower cowling, side @222.60	Cut	445.20	445.20
2 pcs	Lower cowling bracket @11.00	Bent	22.00	22.00
2 pcs	Lower cowling pad @24.50	Necessary	49.00	49.00
2 pcs	Lower cowling pad bracket @27.50	Bent	55.00	55.00
1 pc	Rear Footrest LH	Wash - Reuse	103.10	~ NH
1 pc	Rear Footrest Stay LH	Wash - Reuse	196.00	~ NH
2 pcs	Tail grip @202.00	Broken / Bent LH	404.00	404.00 202 Δ
1 pc	Carrier plate	Broken	92.10	92.10
2 pcs	Saddlebag hook @154.40	Cut / Warped LH	308.80	308.80 154.40 Δ
2 pcs	Tail side cover @348.80	Cracked / Deformed LH	697.60	697.60 348.80 Δ
1 pc	Tail cover inner	Cracked	117.60	117.60
1 pc	Tail signal light cover	Cracked	165.10	165.10
2 pcs	Tail signal light @77.00	LH Broken	154.00	77.00
1 pc	Rear under cover	Cracked	253.20	253.20
1 pc	Rear flap complete	Warped	124.70	124.70
2 pcs	Rear stay @201.80	Bent	403.60	403.60
1 set	Number plate lamp	Usable	84.70	~ NH
1 pc	Drive shaft outer cover	Cut	102.70	102.70
2 pcs	Saddlebag Assy @1527.90 1050	Broken / Cut	3,055.80	3,055.80 2100
			16,778.00	16,100.80 15145
		Less 10%	1,677.80	1,610.08
			15,100.20	14,490.72 13,630.50

Our Ref.: TP/1801/FBK7237/IM

Supplementary Items

1 pc	Radiator assy	Dented / Deformed	1,733.30	1,733.30
1 pc	Rear subframe complete	Bent	1,390.00	1,390.00
1 pc	Frame cover LH	Cracked	360.10	360.10
			3,483.40	3,483.40
		Less 10%	348.34	348.34
			3,135.06	3,135.06

Special Nett Items

1 set	Spot light	Broken	200.00	180.00
1 set	Body frame slider, GSG Mototechnik	Cut / Bent	460.00	460.00
	Swing arm slider LH, GSG			
1 pc	Mototechnik	Cut	76.00	76.00
1 pc	Exhaust muffler, Remus	Cracked	1,475.00	1,475.00
1 pc	Front number plate	Necessary	15.00	12.00
1 pc	Rear number plate	Bent	18.00	15.00
			2,244.00	2,218.00

Labours

1	Towing	80.00	60.00
2	Renew and balance front wheel hub	100.00	60.00
3	Repair & align front fork, body chassis and swing arm	500.00	450.00
4	Workmanship to repair and renew damaged areas	550.00	500.00
		1,230.00	1,070.00

Total Parts & Labours Concluded

21,709.26 20,913.78 19,535.52


Lump Sum Repair Adjustment

16,700.00 15,900


ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle. We have listed the breakdown of our findings and our recommendation as per assessment above.

Inspected by

  
Dylan Lee

Faithfully Yours  
L H TEO Appraisal Services

  
Teo Liak Hoo  
Advance Automotive Engineer (UK)  
Dip. Mech. Engr. M Prof BTM(Dip.BTM)  
MIIE, MIMI, AMSIM an




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006720/T1rbs2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-06-2018		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
Insured Veh.	SHA 4139H	Veh. Inspected	FBK 7237G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18000357MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	11/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KAWASAKI ZG1400 A	c.c	0	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JKBZGT40AAA022849	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/70R17	BRIDGESTONE	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	190/50R17	BRIDGESTONE	6 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/01/2018	Inspection Date	12/04/2018	
Survey held at	I-MOTERING CREDIT PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-14 SINGAPORE 159722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 7237G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HANDLE BAR LH	NOT CHANGED	216.40	-
1	CLUTCH MASTER ASSY	REPLACED	564.90	564.90
2	INNER COVERS @ \$139.30	N/S REPLACED	278.60	139.30
2	MIRROR ASSY @ \$278.60	N/S REPLACED	557.20	278.60
1	MIRROR BRACKET	REPLACED	254.00	254.00
1	WIND SHIELD ASSY	REPLACED	1,159.20	1,159.20
1	HEAD COWLING	REPLACED	492.00	492.00
1	HEAD COWLING BRACKET	REPLACED	231.20	231.20
1	AIR INTAKE COWLING	REPLACED	65.70	65.70
1	AIR DUCT COMPLETE LH	REPLACED	384.40	384.40
1	HEAD LAMP COMPLETE	REPLACED	978.50	978.50
1	FRONT FENDER	REPLACED	330.00	330.00
2	FENDER SIDE COVER @ \$33.10	REPLACED	66.20	66.20
1	FRONT WHEEL ASSY	REPLACED	1,411.20	1,411.20
1	FRONT BRAKE DISC LH	NOT NECESSARY	461.90	-
2	FRONT SIGNAL LAMP @ \$77.00	REPLACED	154.00	154.00
2	SIDE COWLING FRONT @ \$394.20	REPLACED	788.40	788.40
2	SIDE COWLING SHROUD @ \$43.90	REPLACED	87.80	87.80
2	SIDE COWLING PAD @ \$22.10	REPLACED	44.20	44.20
2	HEAT GUARD PAD @ \$55.00	REPLACED	110.00	110.00
2	SIDE COWLING BRACKET @ \$18.40	REPLACED	36.80	36.80
2	CENTER COWLING @ \$473.20	REPLACED	946.40	946.40
2	HOT WIND COWLING @ \$136.20	REPLACED	272.40	272.40
1	LOWER COWLING, FRONT CENTER	REPLACED	52.40	52.40
2	LOWER COWLING, SIDE @ \$222.60	REPLACED	445.20	445.20
2	LOWER COWLING BRACKET @ \$11.00	REPLACED	22.00	22.00
2	LOWER COWLING PAD @ \$24.50	REPLACED	49.00	49.00
2	LOWER COWLING PAD BRACKET @ \$27.50	REPLACED	55.00	55.00
1	REAR FOOTREST LH	NOT CHANGED	103.10	-
1	REAR FOOT REST STAY LH	NOT CHANGED	196.00	-
2	TAIL GRIP @ \$202.00	N/S REPLACED	404.00	202.00

Report Ref No. CS/FCI18006720/T1rbs2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CARRIER PLATE	REPLACED	92.10	92.10
2	SADDLEBAG HOOK @ \$154.40	N/S REPLACED	308.80	154.40
2	TAIL SIDE COVER @ \$348.80	N/S REPLACED	697.60	348.80
1	TAIL COVER INNER	REPLACED	117.60	117.60
1	TAIL SIGNAL LIGHT COVER	REPLACED	165.10	165.10
2	TAIL SIGNAL LIGHT @ \$77.00	N/S REPLACED	154.00	77.00
1	REAR UNDER COVER	REPLACED	253.20	253.20
1	REAR FLAP COMPLETE	REPLACED	124.70	124.70
2	REAR STAY @ \$201.80	REPLACED	403.60	403.60
1	SET NUMBER PLATE LAMP	NOT CHANGED	84.70	-
1	DRIVE SHAFT OUTER COVER	REPLACED	102.70	102.70
2	SADDLEBAG ASSY @ \$1527.90	REPLACED	3,055.80	2,100.00
1	RADIATOR ASSY (ADDITIONAL)	REPLACED	1,733.30	1,733.30
1	REAR SUBFRAME COMPLETE (ADDITIONAL)	REPLACED	1,390.00	1,390.00
1	FRAME COVER LH (ADDITIONAL)	REPLACED	360.10	360.10
	LESS 10% DISCOUNT		-2,026.14	-1,704.34
			18,235.26	15,339.06
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET SPOT LIGHT (SN)	REPLACED	200.00	180.00
1	SET BODY FRAME SLIDER, GSG MOTOTECHNIK SWING ARM SLIDER LH, GSG (SN)	REPLACED	460.00	460.00
1	MOTOTECHNIK (SN)	REPLACED	76.00	76.00
1	EXHAUST MUFFLER, REMUS (SN)	REPLACED	1,475.00	1,475.00
1	FRONT NUMBER PLATE (SN)	REPLACED	15.00	12.00
1	REAR NUMBER PLATE (SN)	REPLACED	18.00	15.00
			2,244.00	2,218.00
	<b><u>LABOUR</u></b>			
	TOWING.		80.00	60.00
	RENEW AND BALANCE FRONT WHEEL HUB.		100.00	60.00
	REPAIR & ALIGN FRONT FORK, BODY CHASSIS AND SWING ARM.		500.00	400.00

Report Ref No. CS/FCI18006720/T1rbs2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WORKMANSHIP TO REPAIR AND RENEW DAMAGED AREAS.		550.00	450.00
			1,230.00	970.00
	GRAND TOTAL		21,709.26	18,527.06
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,800.00

Report Ref No. CS/FCI18006720/T1rbs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.