

ASS. REC. BY:

REF: CS / msh 18006755 / Trbnz Special Instruction:

ASSIGNMENT (Office)

From (Person): Pearllyn Kung of msh Date/Time: 11-04-2018 4:55 pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC 7847G Insured:

at Workshop m/s Performance Tel: 9116 5779

of 303 Alexandra Rd

Policy No: 27195744 SMP Claim No: 551791

Sum Insured: Excess: \$500.00

Make of Veh: D.O.A. 05042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 12-04-2018 H.O.D. Endorsement:

Date/Time: 11-04-2018 Person Contacted: Gary Vehicle: IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|--|
| | SKC 7847G - X |
| 12/4/18 | Revert to insurance thru merimen. Advise repair inform repairer to proceed. |
| | |
| | |

maimen *Tangpin*

REF: MS66

ASSIGNMENT

From: Date: 12042018

Estimated Cost: TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKC 7847G
at Workshop n/s: Performana
of: 303 Alexandra Rd

Insured:
Policy No.:

Claims No.:

Sum Insured: Excess: \$ 500.00
(Client's Record)

Make of Veh:
(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Bal. or Market Value: \$54K.
IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No
Lum Sum: % 3 Val: Yes or No

CA / REP. / 24 HRS.
Date: Person Contacted: *Gary*

Date / Time Action / Instruction

Vehicle: SKC 7847G Regn: 2011 Sep

Type: Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: BMW 318i cc: 1995
Colour: Black A/C: Insured / Std / NI / NA

Sp Reading: 60413 T/Radio: Insured / Std / NI / NA

Eng/No:
C/No: WSP PF7 2020 F 690348

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim: or
Tyre Size: F: 225 / 45 R17
R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Continental*

Front R/Bal: 6 mm Rear R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I: 12/4/18 @ 12pm
Survey held at: *PML*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision

confirm \$10,496.75 @ 6 days
Red: \$2091.70, 17%

[Signature]
23/5/2018

RECEIVED 24 MAY 2018

Date/Time File Pass to? : Preli. Report
 : Final Report

Date/Time File Return to?

Days Of Repair: 6
Resurvey No. of Trip: 1

Add Fee: Site Insp \$5
 Interview \$5
 Tech \$15
 Weekend \$5

Report Format:
Lump Sum / L.B.R: \$ 10496.75

| | |
|----------------|------------|
| Survey Fee | 200 |
| Transportation | 10 |
| Photo | |
| Other | |
| Total | 210 |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|---------------------------|---|
| MSIG INSURANCE (SINGAPORE) PTE LTD | | Ref : CS/MSG18006755/T1rb | |
| 16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581 | | Date : 12-04-2018 |  |
| | | Code : MSG | |
| 1. Policy Particulars :- OWN DAMAGE | | | |
| | Insured Veh. | Veh. Inspected | SKC 7847G |
| | Policy No. 27195744SMP | Coverage (\$) | 0.00 |
| | Claim No. 554791 | Excess (\$) | 500.00 |
| | Assign From MERIMEN (PEARLLYN KANG) | Assign Date | 11/04/2018 |
| 2. Vehicle Particulars & Condition | | | |
| | Make & Model | c.c | 0 |
| | Engine No. HIDDEN | Year of Reg. | |
| | Chassis No. | Colour | |
| | Odometer - | Steering | |
| | Brakes | Modification | |
| | General | | |
| 3. Conditions of Tyres | | | |
| | | Size | Make |
| | R/H Front Tyre | | Balance |
| | L/H Front Tyre | | mm |
| | R/H Rear Tyre | | mm |
| | L/H Rear Tyre | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| | Accident Date 05/04/2018 | Inspection Date | 12/04/2018 |
| | Survey held at PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941 | | |
| 5a. Remarks | | | |
| A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearllyn Kang Yen Lin

Date: 16 May 2018

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|---------------|
| Vehicle No | : SKC7847G | Accident Date | : 05/04/2018 |
| Make | : BMW 318I | Policy No. | : 27195744SMP |
| Assignment Date | : 11/04/2018 | Excess | : S\$500.00 |
| Date of Inspection | : 12/04/2018 | Est. Duration of Repair | : 6.00 |
| Inspection At | : PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

| | | | |
|-----------------------------|-----|-----------|---------------------------------|
| Repairer's Estimate (Gross) | :SS | 12,588.45 | (Include supplementary \$23.90) |
| Revised Amount | :SS | 10,496.75 | |
| Check Items (Estimated) | :SS | 0.00 | |
| Total | :SS | 10,496.75 | |
| Lump Sum Repair | :SS | | |

Total Loss Consideration

| | | |
|--------------------|-----|-----------|
| New for Old Value | :SS | |
| Pre-Accident Value | :SS | 54,000.00 |
| COE / PARF Rebate | :SS | 41,916.00 |
| Salvage Value | :SS | |
| Margin for Repair | :SS | 12,084.00 |

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--------------------------------|---------|---------------|-------------|---|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 09 Apr 2018 | | 11 Apr 2018 16:55 Assign | | | | New Assignment Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

| CLAIM SUBFOLDER DETAILS | | [Created by insurer] | | | | | | | |
|----------------------------------|---|--|------------|---------|---------|-------------|--------------|------------|-------|
| Insured: | TEO KIM HOCK RAYMOND, ID: S1469434Z, Tel: +6596745345 | | | | | | | | |
| Vehicle Reg. No.: | SKC7847G | Date of Loss: 05/04/2018 15:00 - :59 [78 Months and 6 Days From LTA Reg Date (Man Yr)] | | | | | | | |
| Claim Type: | OD / 554791 | Policy/Cover Note No.: 27195744SMP (Comprehensive) Coverage: 30/09/2017 - 29/09/2018 | | | | | | | |
| | | Excess: S\$500.00 | | | | | | | |
| Repairer: | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174 | | | | | | | | |
| Handling Insurer: | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588] | | | | | | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/04/2018] | | | | | | | | |
| Driver/Custodian: | LEE SOO SAIK (52 / Female), NRIC: S2619132G, Tel: +6583805225 | | | | | | | | |
| Adj Asg. Remarks: | Car in tomorrow 12/04/2018 about 9 to 9.30am. survey anytime after 10.30am. Please survey and revert. Thank you. | | | | | | | | |
| ASSOCIATED MAIL RECEIVED | | | | | | | | | |
| | | View All Compose Case Mail | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS | | | | | | | | | |
| | | View All Search Tasks Create New Task Complete | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearllyn Kang Yen Lin

Date: 13 Apr 2018

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|---------------|
| Vehicle No | : SKC7847G | Accident Date | : 05/04/2018 |
| Make | : BMW 318I | Policy No. | : 27195744SMP |
| Assignment Date | : 11/04/2018 | Excess | : S\$500.00 |
| Date of Inspection | : 12/04/2018 | Est. Duration of Repair | : 6.00 |
| Inspection At | : PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 12,564.55 |
| Revised Amount | :S\$ | 10,341.75 |
| Check Items (Estimated) | :S\$ | 276.50 |
| Total | :S\$ | 10,618.25 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | | |
|--------------------|------|-----------|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | 54,000.00 |
| COE / PARF Rebate | :S\$ | 41,916.00 |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | 12,084.00 |

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

***SKC7847G (554791)**
OD
Apr 5 2018 3:00PM
[TEO KIM HOCK RAYMOND]
Performance Motors Limited

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 13/04/2018 11:03 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10341.75) - SKC7847G - Claim Handler: Pearllyn Kang
Yen Lin

Approved:10341.75:a if c; check items to be confirmed

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Friday, April 13, 2018 12:36 PM
To: 'Gary Poh Chai Hoon'
Cc: SUR
Subject: RE: SKC7847G

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKC 7847G (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Gary Poh Chai Hoon [mailto:gary.poh.chaihoon@simedarby.com.sg]
Sent: Thursday, April 12, 2018 3:29 PM
To: SUR <sur@lkkauto.com>
Subject: SKC7847G

Dear Janice

Please refer to the surveyor marking and revert asap (pending for authorize)

Thank you.

Best Regards,

Gary Poh

Customer Service Advisor | Body and Paint

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

Singapore 159941

Hp (+65) 9116 5779| Fax (+65) 6479 4601

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------------|---------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 9434Z |
| Vehicle Details | |
| Vehicle No.: | SKC7847G |
| Vehicle to be Exported: | No |
| Intended De-registration Date: | 13 Apr 2018 |
| Vehicle Make: | B.M.W. |
| Vehicle Model: | 318I 2.0 AT D/AB 2WD 4DR GAS/D SR DRL |
| Primary Colour: | Black |
| Manufacturing Year: | 2011 |
| Engine No.: | A554I985N46B20BZ |
| Chassis No.: | WBAPF72020FG90348 |
| Maximum Power Output: | 100.0 kW (134 bhp) |
| Open Market Value: | \$29,599.00 |
| Original Registration Date: | 30 Sep 2011 |
| First Registration Date: | 30 Sep 2011 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$29,599.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 29 Sep 2021 |
| PARF Rebate Amount: | \$19,239.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 29 Sep 2021 |
| COE Category: | E - Open Category |
| COE Period(Years): | 10 |
| QP Paid: | \$67,000.00 |
| COE Rebate Amount: | \$22,677.00 |
| Total Rebate Amount: | \$41,916.00 |

The information contained herein is correct as at 13 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|---------------------|
| Date Of Report | 07/04/2018 11:13 |
| Date Of Accident | 05/04/2018 15:30 |
| Exact Location Of Accident | 8 PEREIRARD CARPARK |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|------------------------|
| Vehicle Registration Number | SKC7847G |
| Insured/Policyholder | |
| Name Of Registered Owner | TEO KIM HOCK RAYMOND |
| NRIC No | S1469434Z |
| Email Address | MOND101@SINGNET.COM.SG |
| Mobile Phone No | (LOCAL) +65-96745345 |
| Alternative Phone No | OTHERS-83805225 |

Vehicle Particulars

| | |
|--|-------------|
| Manufacturer | BMW |
| Model | 318I 2.0 AT |
| Exact Purpose for which vehicle was being used at time of accident | PARK |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES |
| If No, Please state action to be taken | |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | B27195744 SMP |
| Cover Note Number: | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | LEE SOO SAIK |
| NRIC No | S2619132G |
| Date Of Birth | 02/07/1965 |
| Occupation | INDOOR |
| Date Of Driving Pass | 03/02/1993 |
| Driving Experience | 25 YEARS AND 2 MONTHS |
| Gender | FEMALE |
| Mobile Number | (LOCAL) +65-83805225 |
| Fax Number | |
| Contact Number | |
| Email Address | SOOSAIKLEE@GMAIL.COM |

| | |
|---|--|
| Address | 51 BEDOK RD #02-28 COUNTRY PARK S'PORE |
| Postcode | 469568 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | SPOUSE |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |

General Information of the Accident

| | |
|--------------------|---|
| Type Of Accident | HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles involved in the accident | |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 0 |

Details of Police Action

| | |
|---|-----------------|
| Was the accident reported to the police? | YES |
| If Yes, Please state which Police Station | |
| POLICE STATION NAME [OTHER] | TANAH MERAH NPP |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|---------------|
| Vehicle Registration Number | GBE9816D |
| Vehicle Make/Model/Colour | TOYOTA |
| Details Of Properties | |
| Vehicle Category | GOODS VEHICLE |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder Signature
 Date & Time: 7/4/18


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 7/4/18.


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:
 7/4/18
 10:45

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

1. CAR WAS STATIONARY PARKED (SEC 7&7G)
2. AS VAN WAS EXITING CAR PARK LOT NEXT TO MY CAR, HE GRAZED FRONT PORTION OF MY CAR CAUSING DAMAGE TO BUMPER, FENDER, RIGHT SIDE HEAD LAMP AND BONNET
3. FOOTAGE CAPTURED BY BUILDING MANAGEMENT.
4. FOOTAGE RECEIVED FROM BUILDING MANAGEMENT ON THE 6/4/18.

DECLARATION

We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time: 7/4/18


Driver's Signature
(if driver is not the policyholder)
Date & Time: 7/4/18


Reporting Centre Personnel's Signature
Name: 7/4/18
NRIC/FIN No: 10145

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6224 0010 Fax (65) 6224 0030
 Operating Hours : Monday to Friday, 09:00 - 17:00
 UEN: S665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : mpwl 18046323 Vehicle Registration No: SKC 78476
 Name (as shown in NRIC) : LEE SIO SAIK NRIC/FIN/Passport No : S2619132A
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address : 51 BEDOK ROAD # 02-28 Singapore 469568
 Contact (Tel) : _____ Mobile No. : 83805225
 Email Address : _____
 Date of Accident : 5/4/18 Time of Accident : 15:30
 Place of Accident : B PERTHARD (MPARK)
 Insurance Company : MSIG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Add ON police report

FCh 9/4/18 0830

Policyholder / Driver's Signature
 Date:

GARY POH CHAI HOON
 Performance Motors Limited
 303 Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941

Reporting Centre Personnel's Signature 0830
 Name:
 NRIC/FIN No.:
 Date:



**SINGAPORE
POLICE FORCE**



T/20180407/2059

1 of 3

Police Station Of Origin:
Tengah Merah NPP
51 New Upper Changi Road #01-1514
SINGAPORE 461051
Tel No: 1800-4499999

Report No. T/20180407/2059

REPORT OF A TRAFFIC ACCIDENT

| | | |
|--|------------------|--------------------------|
| Date/Time Report Made: 07/04/2018 13:19 | Vide Report No.: | Station Diary No.: 13 |
|--|------------------|--------------------------|

Informant's Particulars

| | | | |
|--|------------|---|-------------------------------------|
| Name of Informant: TEO KIM HOCK RAYMOND | | Address: 51 BEDOK ROAD #02-28 SINGAPORE 469568 | |
| ID Type / ID No.: NRIC NO / S1469434Z | | Contact No.: | Mobile: 83805225 |
| Nationality: SINGAPORE CITIZEN | | Email: | |
| Sex: Male | Age: 60 | Date of Birth: 10/01/1958 | Type of Informant: Vehicle Owner |
| Race: Chinese | | Language: | Institution / School Name: |
| Occupation: FLIGHT CREW | | Driving Licence Information: Class: | Date of Expiry: |

General Information of the Accident

| | | | | |
|---|---------------------------|------------------------------------|--|-------------------------------|
| Type of Accident: | Non-Injury Hit and Run | Drink Drive: No | Date/Time of Accident: 05/04/2018 15:30 | Type of Location: Car Park |
| Location: Along Road 1 PEREIRA ROAD at the open space car park of 8 Pereira Road | | | | |
| Weather: Clear | | Road Surface: Dry | Road Speed Limit: | |
| Traffic Flow: | | Traffic Control: Not Controlled | Traffic Volume: No Traffic | |
| Type of Collision: Moving Vehicle Against - Parked Vehicle | | | Anyone conveyed by ambulance: No | |

Details of Vehicle Involved

| Vehicle No. | Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------|------|-------|-------|-----------|-----------------|
| GBE9816D | | | | | | 0 |
| SKC7847G | Car | | | | | 0 |

Details of Vehicle Insurance

| Vehicle No. | Insurance Company | Insurance No | Effective | Expiry Date |
|-------------|---|--------------|------------|-------------|
| SKC7847G | MSIG INSURANCE (SINGAPORE) PTE. LTD. | 10115496 | 30/09/2017 | 29/09/2018 |



**SINGAPORE
POLICE FORCE**



T/20180407/2059

2 of 3

Report No. T/20180407/2059

Police Station Of Origin:
Tanah Merah NPP
51 New Upper Changi Road #01-1514
SINGAPORE 461051
Tel No: 1800-4499999

CONTINUATION OF REPORT

| Details of Person Involved | | | |
|-----------------------------------|----------------------|--|-----------------------------------|
| Any Pedestrian Involved: No | | | |
| No. of Pedestrians Injured: NIL | | Use of Pedestrian Crossing: NA | |
| Vehicle Owner | | | |
| Name | TEO KIM HOCK RAYMOND | ID No. | S1469434Z |
| Related Vehicle | SKC7847G (Car) | Contact No. | 83805225 |
| Hospital/Clinic | NIL | Class of Driving Licence & Expiry Date | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL | Date Discharge | NIL |
| No. of Days granted Medical Leave | NIL | Degree of Injury | NIL |

Brief Details.

On 05/04/2018 at about 0900hrs, my wife (Yvonne) had parked my vehicle (SKC7847G) at her office (CPL Engineering Services Private Limited) located at 8 Pereira Road into one of the red parking lot of the open space car park.

On the same day at about 1800hrs, one of her college had informed her that the vehicle she had parked had some damage as such she then went down to make a check. She later make a check and discovered that the front right portion of the vehicle had some grazed mark. She then went back home and tried to view the footage from the vehicle in-built camera. However, there was no footage capture as the camera had no battery as such she then contacted the management to check if they had any CCTV footage at the open space carpark.

On 06/04/2018 at about 1226hrs, my wife had received a "Watsapp" message from the management which consist of the CCTV footage of the car park. Subsequently after viewing the footage, on 05/04/2018 at about 1530hrs one lorry (GBE9816D) which was parked on the right side of my vehicle was seen exiting the parking lot turning left.

However, in the midst of turning out of the parking lot the vehicle had stopped and reverse back into the parking lot followed by exiting the parking lot. However, this time the vehicle was seen heading straight followed by a left turn to exit the parking lot.

I wish to state that I believed the said lorry had grazed onto my vehicle as such he had reverse and later exit the parking lot again.



SINGAPORE
POLICE FORCE



T/20180407/2059

3 of 3

Report No. T/20180407/2059

Police Station Of Origin:
Tanah Merah NPP
51 New Upper Changi Road #01-1514
SINGAPORE 461051
Tel No: 1800-4499999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G/
Sgt 1 TAN EDMUND NEIL

Signature Of Informant:


Signature Of Interpreter:
Not applicable

Date/Time:
07/04/2018 13:19

Officer In Charge Of Case:
TP / HRT /
SI KALESWARI PALANI
Contact No.: 65476902

Classification Of Case:

Authentication Stamp
NP168

 SINGAPORE
POLICE FORCE

SIGNATURE



Name
LEE SOO SAIK

Race
CHINESE
Date of birth
02-07-1965 Sex
F
Country of birth
MALAYSIA



Name
TEO KIM HOCK RAYMOND

Race
CHINESE
Date of Birth
10-01-1958 Sex
M
Country of Birth
SINGAPORE



47731W7



NRIC No. S2619132G

Date of issue
20-09-2011

Address
51 BEDOK ROAD
#02-28
SINGAPORE 469568



1053190



NRIC No. S1469434Z

Blood Group: O+ Date of issue: 22-06-1993

51 BEDOK ROAD #02-28
SINGAPORE 469568
NRIC No: S1469434Z

Date: 24/10/2003 (R)

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

| Class | Description | PASS DATE |
|---------|--|-------------|
| Class 3 | Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms | 03 Feb 1993 |



Your alternative contact:

Sime Darby Insurance
Brokers (Singapore) Pte Ltd
Tel: 6222 2244
Mon to Fri (excluding PH)

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA) (CAP. 308) (REVISED EDITION)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1
Individual Ownership

SIME MOTOR PRIVATE
Comprehensive

Certificate No. B 27195744 SMP

Excess: SGD500

1. Index Mark and Registration Number of Vehicle
SKC7847G

2. Name of Policyholder
Teo Kim Hock Raymond (Not Driving)

3. Effective Date of the Commencement of Insurance for the purposes of the Act
30/09/2017

4. Date of Expiry of Insurance
29/09/2018

5. Persons or Classes of Persons entitled to drive*
Lee Soo Saik

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.
The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT PERFORMANCE MOTORS LTD OR AT ANY WORKSHOP OF YOUR CHOICE.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers



for Chief Executive Officer



FACSIMILE MESSAGE

DATE 9/4/18 TIME 0955
 TO MSIG FAX NO. 62257402
 ATTENTION motor claim NO. OF PAGES 12
 (INCLUSIVE OF THIS PAGE)
 CC _____
 ATTENTION _____ FAX NO. _____
 FROM Garry FAX NO. _____
 TEL NO. 91165779

Your Ref:
 Our Ref:
 Date:
 Subject:

If this fax is not received in order, please do call us. Thank you

Attached is the repair estimate for SKC 7847 G
 (Vehicle Regn. No)

The vehicle is presently **IN / Not IN** our workshop.

This is an Own Damage Claim.
 Please arrange for a surveyor to inspect the vehicle.

This is a 3rd Party Claim.
 If we do not hear from you within the next 24 hours, exclude Saturday and Sunday, we shall proceed with our survey and repair the vehicle.

Ch

CC

FAX:

Performance Motors Limited
 1800-Call-BMW (1800-2255-269)
 www.pml.com.sg
 303 Alexandra Road Sime Darby Performance Centre Singapore 159941
 Tel Sales 6319 0100 Tel AfterSales 6319 0111 Fax 6474 7770
 315 Alexandra Road Sime Darby Business Centre Singapore 159944
 Tel Sales 6319 0511 Tel AfterSales 6319 0527 Fax 6479 6624
 896 Dunearn Road #01-01 Sime Darby Centre Singapore 585472
 Tel Sales 6319 0500 Tel AfterSales 6319 0555 Fax 6469 1709
 280 Kampong Arang Rd East Coast Centre Singapore 438180
 Tel AfterSales 6319 0888 Fax 6344 1332
 Registered office 305 Alexandra Road #02-01 Vantage Automotive Centre Singapore 159942
 Co. Reg. No. 197401559W

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Tampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190328 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46517
Date Estimated : 07/04/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Teo Kim Hock Raymond
51 Bedok Road
#02-28

Singapore 469568

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|------------|---------|
| SKC7847G | FG90348 | 30/09/2011 | 318i/4 (A) | 0 |

DESCRIPTION

To replace right front fender ,bumper ,bonnet and attachment
include knocking cause by the accident

2550 3,480.00

Painting front bumper , right front fender , bonnet

2898 3,221.00

To replace right headlight including program
and conduct tests for proper function.

451 531.00

To carry out body cavity preservation.
(Per panel).

200 236.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 177.00

Sundries.

2 150.00

Total Labour 1: **7,795.00**

DESCRIPTION

FRT RH FENDER
BONNET
FRT BUMPER RH SUPPORT BKT
FRT BUMPER RH INSERT
FRT BUMPER CARRIER
PRIMED FRT BUMPER TRIM (M)
Cover
FRT BUMPER RH GRID LATERAL
EMBLEM GROMMET
BMW EMBLEM
HEADLIGHT RH

| QTY | PRIC | VALUE |
|-----|----------|----------|
| 1 | 648.35 | 648.35 |
| 1 | 1,166.55 | 1,166.55 |
| 1 | 8.45 | 8.45 |
| 1 | 11.45 | 11.45 |
| 1 | 550.30 | 550.30 |
| 1 | 1,078.20 | 1,078.20 |
| 1 | 65.40 | 65.40 |
| 1 | 61.10 | 61.10 |
| 2 | 0.80 | 1.60 |
| 1 | 69.50 | 69.50 |
| 1 | 1,108.65 | 1,108.65 |

Total Parts : **4,769.55**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401599W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

| | |
|----------------------------------|-------------------|
| Estimate No. : b1 46517 | Page No. : 2 of 2 |
| Date Estimated : 07/04/2018 | |
| Prepared By : Gary Poh Chai Hoon | |

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | MILEAGE |
|-----------|-------------|------------|------------|---------|
| SKC7847G | FG90348 | 30/09/2011 | 318i/4 (A) | 0 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims 0D / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 12/4/18 @ 12pm Loss \$ 500

Surveyor's Name Tan Jiah Sign _____

Surveyor's Tel 97447749 Authorised Yes / 0

Authorised Date Revert Title _____

RESURVEY PHOTO BY _____

Surveyor's E-mail tanjiah@lkkauto.com

No. of Working Days Recommended 6 days

12588.45

| | | | |
|--------------------|----------|----------|------------------|
| Labour 1 | : | 12564.55 | 7,795.00 |
| Parts | : | | 4,769.55 |
| Labour 2 | : | | 0.00 |
| Excess | : | | 0.00 |
| Total GST @ 7% | : | | 879.52 |
| Grand Total | : | | 13,444.07 |

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46517
Date Estimated : 07/04/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -

Teo Kim Hock Raymond
51 Bedok Road
#02-28

Singapore 469568

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

| REGN NO | CHASSIS NO | REGN DATE | MODEL | M LEAGE | | |
|-------------|------------|------------|------------|----------------|---------|------|
| SKC7847G | FG90348 | 30/09/2011 | 318i/4 (A) | 0 | | |
| DESCRIPTION | | | | ORIGINAL PRICE | DISC. % | NETT |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|-------------------|------------|------|---------|------------------|
| # RIVET * | 0.45 | 4.00 | | 1.80 <i>net</i> |
| # LABEL COOLANT * | 22.10 | 1.00 | | 22.10 <i>net</i> |

| | |
|------------------------|-------|
| Total Labour : | |
| Total Parts : | 23.90 |
| Total Labour & Parts : | 23.90 |

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46517
Date Estimated : 07/04/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Teo Kim Hock Raymond
51 Bedok Road
#02-28

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 469568

| REGN NO | CHASSIS NO | REGN DATE | MODEL | MILEAGE |
|--|----------------|------------|------------|---------|
| SKC7847G | FG90348 | 30/09/2011 | 318i/4 (A) | 0 |
| DESCRIPTION | ORIGINAL PRICE | DISC. % | NETT | |
| To replace front bumper and attachments, bonnet, front RH fender include knocking out dents caused by the accident | 2550.00 | | 2,550.00 | |
| To spray paint front bumper, front RH fender and bonnet | 2899.00 | | 2,899.00 | |
| To replace RH headlight include programming and conducting tests for proper function | 451.00 | | 451.00 | |
| To carry out body cavity preservation. (Per panel). | 200.00 | | 200.00 | |
| To check electrical wiring systems at the front section for proper function including adjustments of headlights. | 150.00 | | 150.00 | |
| Sundries. | 150.00 | | 150.00 | |

| DESCRIPTION | UNIT PRICE | QTY | DISC. % | NETT |
|----------------------------|------------|------|---------|----------|
| FRT RH FENDER | 648.35 | 1.00 | | 648.35 |
| BONNET | 1,166.55 | 1.00 | | 1,166.55 |
| PRIMED FRT BUMPER TRIM (M) | 1,078.20 | 1.00 | | 1,078.20 |
| EMBLEM GROMMET | 0.80 | 2.00 | | 1.60 |
| BMW EMBLEM | 69.50 | 1.00 | | 69.50 |
| # RIVET * | 0.45 | 4.00 | | 1.80 |
| HEADLIGHT RH | 1,108.65 | 1.00 | | 1,108.65 |
| # LABEL COOLANT * | 22.10 | 1.00 | | 22.10 |

SUPPLEMENTARY ITEMS

| | |
|---------------------------------|------------------|
| Total Labour : | 6,400.00 |
| Total Parts : | 4,096.75 |
| Total Labour & Parts : | 10,496.75 |
| Deduction for Excess : | 500.00 |
| Total Repair Costs less Excess: | 9,996.75 |
| GST @7%: | 699.77 |
| Grand Total : | 10,696.52 |

Janice Lee (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Friday, May 11, 2018 10:28 AM
To: Taufikh (LKKAUTO); SUR
Subject: Fw: FINAL REPORT / SKC7847G
Attachments: Final Report SKC7847G.pdf, Final Report SKC7847G_2.pdf

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,400.00
Total Parts : 4,096.75
Total Labour & Parts : 10,496.75

Repair days: 6

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18006755/T1RBN2
Date: 25/05/2018

REFERENCE

| | | | |
|-------------------|----------------------|------------------|------------------|
| Insured/Claimant: | TEO KIM HOCK RAYMOND | Policy No: | 27195744SMP |
| Date of Loss: | 05/04/2018 | Nature of Claim: | OD |
| | | | Claim No: 554791 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SKC7847G | Engine No: | A554I985N46B20BZ |
| Make & Model: | BMW 318i, 2.0 (A) | Chassis No: | WBAPF72020FG90348 |
| Reg. Date: | 30/09/2011 (Man. Year: 2011) | Odometer: | 60413 km |
| Colour: | Black | | |
| Engine Capacity: | 1995 cc | | |
| Market Value/New Car Price: | S\$54,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 225/45R17 | Rear Tyre Size: | 225/45R17 |
| Front Left Side: | Continental 6 mm | Rear Left Side: | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|------------------|------------------|-----------------|--------------|
| Parts | 4,943.45 | 4,246.75 | 696.70 | 14.09 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 7,645.00 | 6,250.00 | 1,395.00 | 18.25 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,588.45 | 10,496.75 | 2,091.70 | 16.62 |
| - Excess (S\$) | 500.00 | 500.00 | 0.00 | 0.00 |
| (S\$) | 12,088.45 | 9,996.75 | 2,091.70 | 17.30 |
| + GST 7.00/7.00% (S\$) | 846.19 | 699.77 | 146.42 | 17.30 |
| Nett Amount (S\$) | 12,934.64 | 10,696.52 | 2,238.12 | 17.30 |

INSPECTION

| | | |
|---------------------|--------------------------|---|
| Date of Assignment: | 11/04/2018 | |
| Date Inspected: | 12/04/2018 Inspected At: | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941 |

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|---|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 25 May 2018) |
| Parts: 143 | BMW 318I 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SKC7847G) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--------------------------|-----|----------|-----------------------------|---------------|-----------------|-----------------|
| 1 | 1 | | *FRT RH FENDER | Bent | 648.35 FS | *648.35 FS |
| 2 | 1 | | *BONNET | Bent | 1,166.55 FS | *1,166.55 FS |
| 3 | 1 | | *FRT BUMPER RH SUPPORT BKT | Not Necessary | 8.45 FS | *- FS |
| 4 | 1 | | *FRT BUMPER RH INSERT | Not Necessary | 11.45 FS | *- FS |
| 5 | 1 | | *FRT BUMPER CARRIER | Not Necessary | 550.30 FS | *- FS |
| 6 | 1 | | *PRIMED FRT BUMPER TRIM (M) | Deformed | 1,078.20 FS | *1,078.20 FS |
| 7 | 1 | | *COVER | Not Necessary | 65.40 FS | *- FS |
| 8 | 1 | | *FRT BUMPER RH GRID LATERAL | Not Necessary | 61.10 FS | *- FS |
| 9 | 2 | | *EMBLEM GROMMET | Necessary | 1.60 FS | *1.60 FS |
| 10 | 1 | | *HEADLIGHT RH | Cracked | 1,108.65 FS | *1,108.65 FS |
| 11 | 4 | | *RIVET | Necessary | 1.80 FS | *1.80 FS |
| 12 | 1 | | *LABEL COOLANT | Necessary | 22.10 FS | *22.10 FS |
| 13 | 1 | | *SUNDRIES | Necessary | 150.00 FS | *150.00 FS |
| 14 | 1 | | *BMW EMBLEM | Necessary | 69.50 FS | *69.50 FS |
| Total Parts (S\$) | | | | | 4,943.45 | 4,246.75 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE RIGHT FRONT FENDER,BUMPER,BONNET AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT | New | 3,480.00 | 2,550.00 |
| 2 | PAINTING FRONT BUMPER,RIGHT FRONT FENDER,BONNET | New | 3,221.00 | 2,899.00 |
| 3 | TO REPLACE,RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION | New | 531.00 | 451.00 |
| 4 | TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) | New | 236.00 | 200.00 |
| 5 | TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS | New | 177.00 | 150.00 |
| Gross Labour Cost (S\$) | | | 7,645.00 | 6,250.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >