

ASS. ETC. BY:

REF:

CS3 / CTU8006757 / GZ45

Special Instruction:

Surveyor

GL

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

11/04/2018 4:54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JKK 8175

Insured:

GX 378B

at Workshop m/s

United Sq Automobile

Tel:

6747 4454

of

53 Ubi Ave 1 #01-56

Policy No:

DMCVSN 3030111703

Claim No:

SNM18001832 C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/04/2018

CA / REV / REP. / REV 24 HRS 'wpr

H.O.D. Endorsement:

Date/Time:

12/04/2018 9:41am

Person Contacted:

Vicky

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	JKK 8175 - X
	GX 378B - X
13/4/18	Disman'tled ✓
16/4/18	Disman'tled ✓
27/4/18	After Repair

PRS

REF: CTL

mer/min

Xcel.

ASSIGNMENT

From: Date 12042018

Estimated Cost:

OD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JKK 8175
at Workshop n/s: United SG Automobile
of: 53 Ubi Ave 1 #01-56

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="radio"/>	<input checked="" type="radio"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA + REV / REP. / 24 HRS

Date Person Contacted:

Vehicle: IN / OUT

Vehicle No: JKK 8175 Yr Regn: -

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota oc 1478

Colour: Gold A/C Insured / Std / NI / NA

Sp. Reading: 175044 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PN2F 80 2M 236167874

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HANKOOK

Front

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I: 12-04-18

Survey held at w/s 12:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S ht, rear o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimated repair range \$8,000 - \$10,000

[Signature]
20/6/2018

21/6/18 Submit PRS Report.

Date/Time File Pass to? : Preli. Report

by : Final Report

Date/Time File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: Site Insp \$

Interview \$

Test Insp \$

Weekend \$

Report Format:

Lump Sum / LB 1:15

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2018		11 Apr 2018 16:34 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	THE LINE I.D PTE LTD, Co. Reg. No.: 200707401G								
Main Claimant:	YUN POH SUM								
Vehicle Reg. No.:	JKK8175	Date of Loss:	07/04/2018 16:00 - :59						
Claim Type:	TP / SNM18D01832C02	Policy/Cover Note No.:	DMCVSN3030111703 (Third Party Only)						
Vehicle Reg. No. (Insured):	GX378B	Policy No. (Claimant):							
		Excess:	\$0.00						
Repairer:	United SG Automobile Pte Ltd (HQ) 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park, 408934 Ubi - Tel: 9007 7556								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/04/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS									
<input type="checkbox"/>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

12042018 @ T416m
 Vicky voh in
 GA

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Apr 2018		11 Apr 2018 16:34 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	THE LINE I.D PTE LTD, Co. Reg. No.: 200707401G		
Main Claimant:	YUN POH SUM		
Vehicle Reg. No.:	JKK8175	Date of Loss:	07/04/2018 16:00 - :59 [339 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01832C02	Policy/Cover Note No.:	DMCVSN3030111703 (Third Party Only)
Vehicle Reg. No. (Insured):	GX378B	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	United SG Automobile Pte Ltd (HQ) 53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park, 408934 Ubi - Tel: 9007 7556		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/04/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***JKK8175 (SNM18D01832C02)**
[GX378B]
TP
YUN POH SUM
Apr 7 2018 4:00PM
[THE LINE I.D PTE LTD]
United SG Automobile Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Assessment Reports			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	10/04/18 10:33	Accident Statement	Load HTM	
Photos/Images			3 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
2	09/04/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
3	09/04/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
4	09/04/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
5	09/04/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
6	09/04/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
7	09/04/18 17:29	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>	
Documentation			1 per page ▼ <input checked="" type="checkbox"/>	
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 17:28	POLICE REPORT [Linked Accident Report Documents]	Load TIF	
2	09/04/18 17:28	POLICE REPORT [Linked Accident Report Documents]	Load TIF	
3	09/04/18 17:28	POLICE REPORT [Linked Accident Report Documents]	Load TIF	
4	09/04/18 17:28	DRIVER DETAIL [Linked Accident Report Documents]	Load TIF	
5	09/04/18 17:29	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	Load TIF	
6	10/04/18 10:22	Accident Sketch Plan [Linked Accident Report Documents]	Load TIF	
7	10/04/18 10:22	Accident Sketch Plan [Linked Accident Report Documents]	Load TIF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/04/18 16:33	PRS	Load PDF	
2	11/04/18 16:33	OI GIA REPORT	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/04/18 19:53	LKKPhotosIn6-1	Load PDF	
2	17/04/18 19:53	LKKPhotosIn6-2	Load PDF	
3	17/04/18 19:53	LKKPhotosIn6-3	Load PDF	
4	21/06/18 10:11	LKKPhotosIn6-4.pdf	Load PDF	

Linked Accident Report Documents

View [View in Browser](#) ▼

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	10/04/18 10:33	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	09/04/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	09/04/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	09/04/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	09/04/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	09/04/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	09/04/18 17:29	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 17:28	POLICE REPORT	 Load TIF	
2	09/04/18 17:28	POLICE REPORT	 Load TIF	
3	09/04/18 17:28	POLICE REPORT	 Load TIF	
4	09/04/18 17:28	DRIVER DETAIL	 Load TIF	
5	09/04/18 17:29	CERTIFICATE OF INSURANCE	 Load TIF	
6	10/04/18 10:22	Accident Sketch Plan	 Load TIF	
7	10/04/18 10:22	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118006757/GZ4BS2

Date: 22/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN3030111703

Claimant Vehicle No: JKK8175 Insured Vehicle No: GX378B

Date of Loss: 07/04/2018 Nature of Claim: TP Claim No: SNM18D01832C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JKK8175**

Make & Model: TOYOTA AVANZA, 1.5 (A) Engine No: HIDDEN

Reg. Date: 01/01/1990 (Man. Year: 1990) Chassis No: PN2F802M236167874

Colour: Gold Odometer: 175044 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15

Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/04/2018

Date Inspected: 12/04/2018 Inspected At: United SG Automobile Pte Ltd (HQ)
53 Ubi Avenue 1, #01-56 Paya Ubi Industrial Park
Singapore 408934

Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 - \$10,000.00

REGISTRATION DATE UNABLE TO TRADE:DUE TO FOREIGNER VEHICLE.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jun 2018)

Parts: M1-MPV TOYOTA AVANZA 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for JKK8175)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >