

SS. REC. BY:

REF: CS/ASM18006769/Kyber

Special Instruction:

Survivor

Kenneth

ASSIGNMENT (Office)

Smart claim

From (Person):

Peter Wang

of

ASM

Date/Time: 12042018 11:10am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SWU 9658R

Insured:

at Workshop m/s

An Lim Motor

Tel:

6463 1244

of

Blk 10 AMK Ind Park 2A #01-09

Policy No:

Claim No:

SSMOODL1

Sum Insured:

Excess:

\$ 1500.00

Make of Veh:

(Client's Record)

D.O.A. 09042018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12042018 1:33pm

Person Contacted:

Eileen

Vehicle: IN / OUT

Date/Time

Action/Instruction () Estimate

SWU 9658R - X

13/4/18

Revert by SMART claim

23/5/18

Rece authorize repair by SMART claim (Peter Wang)

23/5/18

Informed Eileen c/A ex \$1500 by email

ASS. REC. BY:

REF: AAA/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s AK Lim

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 1500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 81226

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLU 9658R Yr Regn: 12, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Jaguar A1 XJL c.c. 2995

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 85372 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SATA C22 A808 V41805

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: Continental 245/45R19

R: Mic 275/40R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front R/Bal. 7 mm Rear R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 9/4/18 D.O.I. 12/4/18

Survey held at _____ @ 304pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

olsm & uic

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>13/4</u>	<u>File sent to Catherine</u>
<u>20/8</u>	<u>814715.00 Confirmed (Red 4326.10, 2370) (No LS)</u>

RECEIVED 21 AUG 2018

20/8/2018

Date/Time, File Pass to? : Prell. Report : Final Report

1) _____
2) 20/8 - typist

Days Of Repair: 5
Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$) : Interview (\$) : Tech Invs (\$) : Weekend (\$)

Survey Fee:	<u>250</u>
Transportation:	
S - RS, SI	
Photos	
Others	
TOTAL	<u>250</u>

Report Format: SMART claim
Lump Sum / I.B.I.: (\$) 14,715/21




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS/ASM18006769/Kvb	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 12-04-2018	
		Code : ASM	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLU 9658R
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00DL1	Excess (\$)	1,500.00
Assign From	SMART CLAIM (PETER WANG)	Assign Date	12/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/04/2018	Inspection Date	12/04/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			


LKK AUTO CONSULTANTS PTE LTD (OD) ▾

◀ Service Request Details

Claim

S8M00DL1

Reference

None 

Loss Date

April 9, 2018

Request Date

April 12, 2018

Due Date

April 19, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLU9658R

Make

JAGUAR

Service Address

10 Ang Mo Kio Ind. Park 2A, , 568047

Primary Contact/Insured

CHUA HWEE NGEE
45, TOH TUCK ROAD, #01-10, 596720, Singapore
83227971
FRANKIE.TEO@GMAIL.COM

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Wkshop: Ah Lim @ AMK Excess: \$1500

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

4/12/18 11:13 AM

FROM

WANG Peter

SUBJECT

DO NOT authorize repair yet - Pending estimate from Ah Lim

BODY

Pending estimate from Ah Lim. Please DO NOT autho...



New Message

Type *

Message

Subject *

SUPPLEMENTARY FOR SLU 9658R

Message *

Dear Sir/Madam,

We have received supplementary of \$1834/- from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. IA has submitted. Best Regards Veron Chen

Cancel

Send

Immediate Advice

To : AXA Insurance Pte Ltd

Date:20/8/2018

Survey details

Date of loss	9/4/2018
Date of appointment	12/4/2018
Date of survey	12/4/2018
Location of survey	AH LIM MOTOR COMPANY

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SLU 9658R
Make and Model	JAGUAR XJ 3.0S
Date of registration	24/12/2012
Excess	\$1,500
Market Value	\$122,000.00
Parf Rebate	\$99,318.00
Nett Loss	\$22,682.00

Repair details

Initial Estimate	\$19,041.10 (INCL.SUPPLEMENTARY \$1834)
------------------	---

Proposed/Revised repair cost:

Parts	\$12,905.00
"Check items (Estimated)	
Labour	\$1,810.00
Total	\$14,715.00 (INCL.SUPPLEMENTARY \$1834)
Lump Sum (Estimated)	

Number of days of repair	5 days (est)
--------------------------	--------------

Remarks:

The vehicle sustained damages at the o/s front portion and undercarriage

Damages Consistent
Repair Cost Economical

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 23 May 2018 2:17 PM
To: Eileen Chua
Cc: SUR
Subject: RE: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS (AXA Ref: S8M00DL1)

Dear Eileen,

As instructed by our client , please proceed to repair the insured vehicle **SLU 9658R (Excess \$1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: WANG Peter [mailto:peter.wang@axa.com.sg]
Sent: Friday, 18 May 2018 10:12 AM
To: Eileen Chua <ahlimmc@singnet.com.sg>
Cc: assignments <assignments@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS (AXA Ref: S8M00DL1)

Dear Eileen

Currently we are still pending for input from our investigator.

We will keep you updated once I hear from investigator.

Regards

Peter Wang | Specialist, Motor Claims Department
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: peter.wang@axa.com.sg (wef 1 May 2018)

From: Eileen Chua [mailto:ahlimmc@singnet.com.sg]
Sent: Wednesday, May 16, 2018 3:11 PM
To: WANG Peter <peter.wang@axa.com.sg>

Cc: LKK - Assignments <assignments@lkkauto.com>; LKK - Veron Chen <veronchen@lkkauto.com>
Subject: Re: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS (AXA Ref: S8M00DL1)

Hi Peter,

Any news on the Authorised status?

Best Regards,
Eileen Chua
Ah Lim Motor Company
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint S(568047)
Tel: 64831244 Fax: 64836170

From: WANG Peter
Sent: Friday, May 04, 2018 11:33 AM
To: Eileen Chua
Subject: RE: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS (AXA Ref: S8M00DL1)

Hi Eileen

I only came back from my leave on Wednesday was not able to respond to you promptly.

Our investigator (AJAX) tried to contact insured since beginning of last week, and insured agreed to have the interview on 3 May (yesterday). I will keep you updated after investigator comes back to me.

Regards

Peter Wang | Specialist, Motor Claims Department
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: peter.wang@axa.com.sg (wef 1 May 2018)

From: Eileen Chua [<mailto:ahlimmc@singnet.com.sg>]
Sent: Friday, April 20, 2018 2:12 PM
To: WANG Peter <peter.wang@axa.com.sg>
Subject: Fw: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS
Importance: High

resend

Best Regards,
Eileen Chua
Ah Lim Motor Company
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint S(568047)
Tel: 64831244 Fax: 64836170

From: Eileen Chua

Sent: Friday, April 20, 2018 1:57 PM
To: AXA - Peter Wang
Cc: LKK - Catherine ; LKK - Kenneth Kong ; LKK - Veron Chen
Subject: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS

Hi Peter,

Please kindly advise the status for the authorisation. Car is still in our workshop.
Survey Done on 12/4/18

Best Regards,
Eileen Chua
Ah Lim Motor Company
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint S(568047)
Tel: 64831244 Fax: 64836170

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

⏪ **Authorized - Mandate approved** - 23/5/18

Type

🔗 Question

Message

Pls proceed to authorize OD repair. Excess: \$1000 basic excess + \$500 unnamed driver excess.

Reply

Veron Chen (LKKAuto)

From: WANG Peter <peter.wang@axa.com.sg>
Sent: Friday, 18 May 2018 10:12 AM
To: Eileen Chua
Cc: assignments; Veron Chen (LKKAuto)
Subject: RE: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS (AXA Ref: S8M00DL1)

Dear Eileen

Currently we are still pending for input from our investigator.

We will keep you updated once I hear from investigator.

Regards

Peter Wang | Specialist, Motor Claims Department
AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg
Email: peter.wang@axa.com.sg (wef 1 May 2018)

From: Eileen Chua [mailto:ahlimmc@singnet.com.sg]
Sent: Wednesday, May 16, 2018 3:11 PM
To: WANG Peter <peter.wang@axa.com.sg>
Cc: LKK - Assignments <assignments@lkkauto.com>; LKK - Veron Chen <veronchen@lkkauto.com>
Subject: Re: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS (AXA Ref: S8M00DL1)

Hi Peter,

Any news on the Authorised status?

Best Regards,
Eileen Chua
Ah Lim Motor Company
No. 10 Ang Mo Kio Ind. Park 2A
#01-09 AMK Autopoint S(568047)
Tel: 64831244 Fax: 64836170

From: WANG Peter
Sent: Friday, May 04, 2018 11:33 AM
To: Eileen Chua
Subject: RE: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS (AXA Ref: S8M00DL1)

Hi Eileen

I only came back from my leave on Wednesday was not able to respond to you promptly.

- Our investigator (AJAX) tried to contact insured since beginning of last week, and insured agreed to have the interview on 3 May (yesterday). I will keep you updated after investigator comes back to me.

Regards

Peter Wang | Specialist, Motor Claims Department

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: peter.wang@axa.com.sg (wef 1 May 2018)

From: Eileen Chua [<mailto:ahlimmc@singnet.com.sg>]

Sent: Friday, April 20, 2018 2:12 PM

To: WANG Peter <peter.wang@axa.com.sg>

Subject: Fw: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS

Importance: High

resend

Best Regards,

Eileen Chua

Ah Lim Motor Company

No. 10 Ang Mo Kio Ind. Park 2A

#01-09 AMK Autopoint S(568047)

Tel: 64831244 Fax: 64836170

From: Eileen Chua

Sent: Friday, April 20, 2018 1:57 PM

To: AXA - Peter Wang

Cc: LKK - Catherine ; LKK - Kenneth Kong ; LKK - Veron Chen

Subject: SLU9658R - OWN DAMAGE CLAIM - CHECK STATUS

Hi Peter,

Please kindly advise the status for the authorisation. Car is still in our workshop.

Survey Done on 12/4/18

Best Regards,

Eileen Chua

Ah Lim Motor Company

No. 10 Ang Mo Kio Ind. Park 2A

#01-09 AMK Autopoint S(568047)

Tel: 64831244 Fax: 64836170

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.



IA SUBMITTED FOR SLU 9658R

Type

🔔 Question

Message

Dear Sir/Madam, Please be informed that IA submitted. We have Not Authorize repair. Kindly let us have your approval please. Repairer's Estimate (Gross) : S\$16,691.10 Revised Estimate Amount : S\$6,096.50 "Check" Items Amount : S\$7,454.60 Total : S\$13,551.10 Market Value : S\$122,000.00 COE/PARF Rebate : S\$99,318.00 Nett Value : S\$22,682.00 Thanks Veron Chen

Reply



Your ref: S8M00DL1
Our ref: CS/ASM18006769/Kvb

Date: 13/4/2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SLU 9658R

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12/4/2018 at the premises of M/s AH LIM MOTOR COMPANY and have the following to report:-

Repairer's Estimate (Gross)	: S\$16,691.10
Revised Estimate Amount	: S\$6,096.50
"Check" Items Amount	: S\$7,454.60
Total	: S\$13,551.10
Market Value	: S\$122,000.00
COE/PARF Rebate	: S\$99,318.00
Nett Value	: S\$22,682.00

Description of Damage:

The vehicle sustained damages at the o/s front portion and undercarriage



Survey date and time: 12/4/2018 at 3.04PM

We have Not authorise repair.

No of days :5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2368J
Vehicle Details	
Vehicle No.:	SLU9658R
Vehicle to be Exported:	No
Intended De-registration Date:	13 Apr 2018
Vehicle Make:	JAGUAR
Vehicle Model:	XJ 3.0S/C PL LWB
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	12091715434306PS
Chassis No.:	SAJAC22A8D8V41805
Maximum Power Output:	250.0 kW (335 bhp)
Open Market Value:	\$81,405.00
Original Registration Date:	24 Dec 2012
First Registration Date:	24 Dec 2012
Transfer Count:	1
Actual ARF Paid:	\$81,405.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Dec 2022
PARF Rebate Amount:	\$56,983.00
Intended COE Rebate Details	
COE Expiry Date:	23 Dec 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$90,200.00
COE Rebate Amount:	\$42,335.00
Total Rebate Amount:	\$99,318.00

The information contained herein is correct as at 13 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 2368J

Vehicle Details

Vehicle No.: SLU9658R
Vehicle to be Exported: Yes
Intended De-registration Date: 10 Apr 2018
Vehicle Make: JAGUAR
Vehicle Model: XJ 3.0S/C PL LWB
Primary Colour: White
Manufacturing Year: 2012
Engine No.: 12091715434306PS
Chassis No.: SAJAC22A8D8V41805
Maximum Power Output: 250.0 kW (335 bhp)
Open Market Value: \$81,405.00
Original Registration Date: 24 Dec 2012
First Registration Date: 24 Dec 2012
Transfer Count: 1
Actual ARF Paid: \$81,405.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 23 Dec 2022
PARF Rebate Amount: \$56,983.00

Intended COE Rebate Details

COE Expiry Date: 23 Dec 2022
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$90,200.00
COE Rebate Amount: \$42,408.00
Total Rebate Amount: \$99,391.00

The information contained herein is correct as at 10 Apr 2018

OK


redefining / insurance

AXA Insurance Pte Ltd

 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)

(65) 6880 4740

customer.care@axa.com.sg

www.axa.com.sg

 CHUA HWEE NGEE
 45
 TOH TUCK ROAD
 #01-10
 SINGAPORE 596720

New business

 date
 26/01/2018

 your servicing distributor
 ASSURE INSURANCE AGENCY PTE LTD /
 11517

 your servicing distributor contact
 6848 9119

Policy Schedule

Your SmartDrive Comprehensive For Her

Your policy snapshot

Policyholder name	CHUA HWEE NGEE	Policy number	VA1 / GA316866
Cover	Comprehensive	FIN / NRIC	S7672368J
Period of Insurance	from 27/01/2018 to 26/01/2019 (both dates inclusive)		

Premium breakdown

Gross Premium after 50% NCD	SGD 1,574.66
7% GST	SGD 110.23
Final Premium	SGD 1,684.89

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive For Her Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess
- Guaranteed Repairs for twelve (12) Months
- Loss or Damage
- Legal Liability
- Medical and dental expenses up to \$1,000 per person for you, your named drivers and your immediate family members
- Daily Transport Allowance of \$50 for a maximum of ten (10) days
- Basic Own Damage Excess Waiver from Third Year If you are accident-free during the first two (2) years.
- Phone assistance and roadside support
- Reimbursement of 110% of your car's market value in the event of total loss due to flood (without Basic Own Damage Excess)

Vehicle details

Make & Model of Vehicle	JAGUAR XJ 3.0	Year of manufacture	2012
Vehicle registration number	SLU9658R	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	2995
Seating capacity (excl driver)	4	Engine number	12091715434306PS
Off-Peak car	No	Chassis number	SAJAC22A8D8V41805

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 1,000.00
Windscreen Excess	SGD 100.00

EMPLOYMENT PASS
 Employment of Foreign Manpower Act (Chapter 91A)
 Republic of Singapore

Employer
 DP JOY INTERNATIONAL (S) PTE. LTD.



Name
JIN NUOQI
 Occupation
MANAGING DIRECTOR

FIH
 G6253114U

Date of Application
 29-04-2016

Date of Issue
 13-05-2016

Date of Expiry
 02-08-2019



L6796762

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number
G6253114U

Name
JIN NUOQI

Birth Date: 18 Jul 1988
 Issue Date: 15 Nov 2016
 Valid Till 14/11/2021



002629094F

Hp: 8322 7971 (9822 0053

Email: frankie.teo@gmail.com
 jinnuoqi@gmail.com

VISIT PASS
 Immigration Regulations

Name
 JIN NUOQI



Date of Birth	Sex	Nationality
18-07-1988	F	CHINESE
FIH	Date of Issue	Date of Expiry
G6253114U	13-05-2016	02-08-2019

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	EFFECTIVE DATE
Class 3 Motor cars with unladen weight =< 3000kg with =< 7 passengers, exclusive of driver; and other motor vehicles with unladen weight =< 2500kg	30 Apr 2011

NP 428A



any
 up no
 can no
 total 1.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/04/2018 13:33
Date Of Accident	09/04/2018 15:10
Exact Location Of Accident	SINARAN DRIVE TO MOULMEIN ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLU9658R
Insured/Policyholder	
Name Of Registered Owner	CHUA HWEE NGEE
NRIC No	S7672368J
Email Address	FRANKIE.TEO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98220053
Alternative Phone No	OTHERS-83227971
Vehicle Particulars	
Manufacturer	JAGUAR
Model	XJ 3.0S/C PL LWB
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA316866
Cover Note Number	27/1/2018 - 26/1/2019
Driver	
Name of Driver	JIN NUOQI
Passport No/FIN	G6253114U
Date Of Birth	18/07/1988
Occupation	INDOOR
Date Of Driving Pass	30/04/2011
Driving Experience	6 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83227971
Fax Number	
Contact Number	
EEmail Address	FRANKIE.TEO@GMAIL.COM

Sketch Plan Pg. 1

Date of accident: 09/04/2018 Time: 3:10pm Location: Sineran Drive to Moulmein Road
 My Vehicle A: SLU 9638R Vehicle B: SHC 5970G Vehicle C: —

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I drive my vehicle and stop at the fiber lane slightly out the line vehicle B can't avoid and knock onto my front right side corner.

Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop :
 Email address :
 & myself :
 Email address :

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 10/04/2018

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



AH LIM MOTOR COMPANY



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 63382522
 ATTN: Motor Claim Department

Estimate No: MC0912999
Date: 11 Apr 2018
Policy No: GA316866
Veh Reg No: SLU9658R
Make/Model: JAGUAR XJ 3.0S/C PL
 LWB

Your Ref No: S8M00DL1
 Claim Type: Own Damage
 Accident Date: 09/04/2018

Handwritten notes:
 Not Authorized
 Reserve Bk paint 1-B.1
 Fax: 62564315
 5days
 Ex @ 1500

Estimate Repair Cost to Vehicle No :SLU9658R

Description	U/Price	Quantity	Cost	Amount
				SS
SPARE PARTS				
1 HEADLAMP RH		1 PC	1,900.00	✓
2 FRONT BUMPER		1 PC	1,700.00	✓
3 FRONT BUMPER SIDE RETAINER RH		1 PC	40.00	✓
4 FRONT BUMPER CLIPS X 15	nn	15 PC	52.50	X
5 FRONT BUMPER REINFORCEMENT		1 PC	510.00	X
6 FRONT BUMPER SPONGE		1 PC	240.00	X
7 FOGLAMP COVER RH		1 PC	170.00	X
8 FOGLAMP CHROME MOULDING RH		1 PC	230.00	X
9 FRONT FENDER RH		1 PC	1,120.00	✓
10 FRONT FENDER V6 LOGO	NN	1 PC	204.00	X
11 FRONT FENDER COWLING		1 PC	250.00	?
12 FRONT FENDER COWLING CLIPS X 8		8 PC	9.60	X
13 FRONT WHEEL BEARING WITH HUB RH		1 PC	320.00	?
14 FRONT KNUCKLE ARM RH		1 PC	420.00	?
15 FRONT LOWER ARM RH		1 PC	270.00	?
16 FRONT SIDE ARM NO. 1 RH - CHECK PRICE		1 PC	0.0000	330 ✓
17 FRONT SIDE ARM NO. 2 RH - CHECK PRICE		1 PC	0.0000	X
18 FRONT UPPER ARM RH		1 PC	250.00	?
19 FRONT TIE ROD RH		1 PC	85.00	?
20 FRONT TIE ROD BALL JOINT RH		1 PC	65.00	?
21 FRONT STEERING RACK	B1/2	1 PC	4,300.00	?
22 FRONT SHOCK ABSORBER RH		1 PC	440.00	?
23 FRONT SHOCK ABSORBER TOP MOUNTING		1 PC	95.00	?
				12,671.10
				12991.10
Special Nett				
24 TYRE RHF - CHECK PRICE		1 PC	0.0000	70/80 196
25 SPORT RIM RHF	Rd	1 PC	1,280.00	X 180 ✓
	L.A			1,280.00
LABOUR				
26 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	20 ✓
27 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.		1 PC	500.00	? 330 ✓
28 TO REMOVE AND REINSTALL/REPLACE FRONT BUMPER SENSORS.		1 PC	120.00	60 ✓



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912999
Date: 11 Apr 2018
Policy No: GA316866
Veh Reg No: SLU9658R
Make/Model: JAGUAR XJ 3.0S/C PL
LWB

Your Ref No: -
Claim Type: Own Damage
Accident Date: 09/04/2018

Estimate Repair Cost to Vehicle No :SLU9658R

Description	U/Price	Quantity	Cost	Amount
29 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	280.00	150 ✓
30 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	900.00	500 700
31 TO SPRAY FRONT BONNET, FRONT FENDER RH, FRONT BUMPER		1 PC	900.00	500 ✓
				2,740.00

19,041.10

Amount Before Excess	S\$ 16,691.10
Add GST @ 7%	1,168.38
Total Amount payable	S\$ 17,859.48

TOTAL: SINGAPORE DOLLAR SEVENTEEN THOUSAND EIGHT HUNDRED FIFTY NINE AND CENTS FORTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



19125-10



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B



M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 TEL: 63387288 FAX: 63382522
 ATTN: Motor Claim Department

Claim No: MC0912999
 Ref No: MF0911232
 Date: 08 Aug 2018
 Policy No: GA316866
 Veh Reg No: SLU9658R
 Make/Model: JAGUAR XJ 3.0S/C PL
 LWB

Your Ref No: S8M00DL1
 Claim Type: Own Damage
 Accident Date: 09/04/2018

FAULT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLU9658R

Description	U/Price	Quantity	Cost S\$	Amount S\$
SPARE PARTS				
1 FRONT SHOCK ABSORBER RH		1 PC	440.00	
2 HEADLAMP RH		1 PC	1,900.00	
3 FRONT BUMPER		1 PC	1,700.00	
4 FRONT BUMPER SIDE RETAINER RH		1 PC	40.00	
5 FRONT FENDER RH		1 PC	1,120.00	
6 FRONT FENDER COWLING		1 PC	250.00	
7 FRONT WHEEL BEARING WITH HUB RH		1 PC	320.00	
8 FRONT KNUCKLE ARM RH		1 PC	420.00	
9 FRONT LOWER ARM RH		1 PC	270.00	
10 FRONT SIDE ARM NO. 1 RH		1 PC	320.00	
11 FRONT UPPER ARM RH		1 PC	250.00	
12 FRONT TIE ROD RH		1 PC	85.00	
13 FRONT TIE ROD BALL JOINT RH		1 PC	65.00	
14 FRONT STEERING RACK		1 PC	4,300.00	
15 FRONT SHOCK ABSORBER TOP MOUNTING		1 PC	95.00	
16 STEERING DUCT COVER		1 PC	65.00	(A)
17 ANTI ROLL BAR LINK		1 PC	55.00	
18 SUPPORT TOP PANEL		1 PC	800.00	
19 POWER STEERING FLUID		1 PC	34.00	
				12,529.00
Special Nett				
20 TYRE RHF (70% OF 280)		1 PC	196.00	
21 SPORT RIM RHF -REPAIR		1 PC	180.00	
				376.00
LABOUR				
22 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	20.00	
23 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.		1 PC	320.00	
24 TO REMOVE AND REINSTALL/REPLACE FRONT BUMPER SENSORS.		1 PC	60.00	
25 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	150.00	
26 TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	700.00	
27 TO SPRAY FRONT BONNET, FRONT FENDER RH, FRONT BUMPER		1 PC	500.00	

AH LIM MOTOR COMPANY
 No. 10 Ang Mo Kio Industrial Park 2A
 #01-09 AMK Autopoint Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Claim No: MC0912999
Ref No: MF0911232
Date: 08 Aug 2018
Policy No: GA316866
Veh Reg No: SLU9658R
Make/Model: JAGUAR XJ 3.0S/C PL
LWB

Your Ref No: S8M00DL1
Claim Type: Own Damage
Accident Date: 09/04/2018

RAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SLU9658R

Description	U/Price	Quantity	Cost	Amount
			SS	SS
28 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	60.00	(A) 1,810.00

Amount Before Excess	SS 14,715.00
Less Excess	SS 1,500.00
Amount Before GST	SS 13,215.00
Add GST @ 7%	925.05
Total Amount payable	SS 14,140.05

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND ONE HUNDRED FORTY AND CENTS FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 12/04/2018

For AH LIM MOTOR COMPANY


AH LIM MOTOR COMPANY
 AUTHORIZED SIGNATURE
 No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK, Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300E

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 TEL: 63387288 FAX: 63382522
 ATTN: Motor Claim Department

Estimate No: MC0912999
 Date: 11 Apr 2018
 Policy No: GA316866
 Veh Reg No: SLU9658R
 Make/Model: JAGUAR XJ 3.0S/C PL
 LWB

Your Ref No: *S & M 0001*
 Claim Type: Own Damage
 Accident Date: 09/04/2018

Handwritten notes:
 Not authorized
 Repair by paint
 1.B.1
 5 days
 Ex \$1500
 Fax: 62564315

Estimate Repair Cost to Vehicle No :SLU9658R

Description	U/Price	Quantity	Cost	Amount
			SS	SS
SPARE PARTS				
-1 HEADLAMP RH	1 PC	<i>CIP</i>	1,900.00	—
-2 FRONT BUMPER	1 PC	<i>Buz</i>	1,700.00	—
-3 FRONT BUMPER SIDE RETAINER RH	1 PC	<i>011</i>	40.00	—
-4 FRONT BUMPER CLIPS X 15	15 PC	<i>12</i>	52.50	—
-5 FRONT BUMPER REINFORCEMENT	1 PC	<i>12</i>	510.00	X
-6 FRONT BUMPER SPONGE	1 PC	<i>12</i>	240.00	X
-7 FOGLAMP COVER RH	1 PC		170.00	?
-8 FOGLAMP CHROME MOULDING RH	1 PC	<i>12</i>	250.00	X
-9 FRONT FENDER RH	1 PC	<i>12</i>	1,120.00	—
-10 FRONT FENDER V6 LOGO	1 PC	<i>12</i>	204.00	—
-11 FRONT FENDER COWLING	1 PC	<i>12</i>	250.00	?
-12 FRONT FENDER COWLING CLIPS X 8	8 PC		9.60	?
13 FRONT WHEEL BEARING WITH HUB RH	1 PC		320.00	?
14 FRONT KNUCKLE ARM RH	1 PC		420.00	?
15 FRONT LOWER ARM RH	1 PC		270.00	?
16 FRONT SIDE ARM NO. 1 RH - CHECK PRICE	1 PC		0.0000	?
-17 FRONT SIDE ARM NO. 2 RH - CHECK PRICE	1 PC		0.0000	?
18 FRONT UPPER ARM RH	1 PC		250.00	?
19 FRONT TIE ROD RH	1 PC		85.00	?
20 FRONT TIE ROD BALL JOINT RH	1 PC		65.00	?
21 FRONT STEERING RACK	1 PC		4,300.00	?
22 FRONT SHOCK ABSORBER RH	1 PC		440.00	?
23 FRONT SHOCK ABSORBER TOP MOUNTING	1 PC		95.00	?
				12,671.10
Special Nett				
24 TYRE RHF - CHECK PRICE	1 PC	<i>12</i>	0.0000	?
25 SPORT RIM RHF	1 PC	<i>12</i>	1,280.00	X
				1,280.00
LABOUR				
26 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC		40.00	?
27 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC		500.00	?
28 TO REMOVE AND REINSTALL/REPLACE FRONT BUMPER SENSORS	1 PC		100.00	?

Handwritten:
 Gino Gulp
 07/6/18



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 560047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912999
Date: 11 Apr 2018
Policy No: GA316866
Veh Reg No: SLU9658R
Make/Model: JAGUAR XJ 3.0S/C PL
LWB

Your Ref No: -
Claim Type: Own Damage
Accident Date: 09/04/2018

Estimate Repair Cost to Vehicle No :SLU9658R

Description	U/Price	Quantity	Cost	Amount
			SS	SS
29 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		1 PC	280.00	750
30 TO DISMANTLE ALL DAMAGED PARTS, TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS, TO REFIT LISTED PARTS BACK SAME.		1 PC	900.00	700
31 TO SPRAY FRONT BOORNET, FRONT FENDER RH, FRONT BUMPER.		1 PC	900.00	500
				2,730.00

Amount Before Excess	S\$ 16,691.10
Add GST @ 7%	1,108.38
Total Amount payable	S\$ 17,859.48

TOTAL: SINGAPORE DOLLAR SEVENTEEN THOUSAND EIGHT HUNDRED FIFTY NINE AND CENTS FORTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

AUTHORIZED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912999
Date: 07 Jun 2018
Policy No: GA316866
Veh Reg No: SLU9658R
Make/Model: JAGUAR XJ 3.0S/C PL
LWB

Your Ref No: S8M00DL1
Claim Type: Own Damage
Accident Date: 09/04/2018

Estimate Repair Cost to Vehicle No :SLU9658R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
SPARE PARTS				
1 STEERING DUCT COVER		1 PC	65.00	920.00
2 ANTI ROLL BAR LINK		1 PC	55.00	
3 SUPPORT TOP PANEL		1 PC	800.00	
 LABOUR				
4 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		1 PC	80.00	60 80.00
 <i>E Side Arm Rubber fast.</i>				
			Amount Before Excess	S\$ 1,000.00
			GST Amount	S\$ 70.00
			Total Amount payable	S\$ 1,070.00

The above vehicle was surveyed by KENNETH KONG -LKK on 12/04/2018

For AH LIM MOTOR COMPANY





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0912999
Date: 13 Jun 2018
Policy No: GA316866
Veh Reg No: SLU9658R
Make/Model: JAGUAR XJ 3.0S/C PL
LWB

Your Ref No: S8M00DL1
Claim Type: Own Damage
Accident Date: 09/04/2018

Estimate Repair Cost to Vehicle No :SLU9658R

Description	U/Price	Quantity	Cost SS	Amount SS
Supplementary Parts to Repair				
SPARE PARTS				
1 POWER STEERING FLUID <i>nec</i>		1 PC	34.00 ✓	34.00
LABOUR				
2 TO REMOVE AND DISMANTLE.REPLACE CUT & RADIATOR SUPPORT PANEL		1 PC	800.00 X	800.00

Amount Before Excess	S\$ 834.00
GST Amount	S\$ 58.38
Total Amount payable	S\$ 892.38

The above vehicle was surveyed by KENNETH KONG -LKK on 12/04/2018

*Res 13/6/18
Kenneth Kong*

For AH LIM MOTOR COMPANY



實利基機件(私人)有限公司
SELEGIE SPAREPARTS PTE LTD

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



Ah Lim Motor

M/s

Tax Invoice

Ang Mok Kah

SSP No. 41429

Order No.

SLU9658R

Date: 12/6/18 20

Item	Quantity	Description	Unit Price	Amount
1	16	CRP 2014 Steering Rack		4300.00
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				

Sub Total

4300.00

Add GST @ 7%

301.00

Total Amount

4601.00

Delivered by Received by

N. B. Goods are not returnable after two days.

E. & O. E.

實利基機件(私人)有限公司 SELEGIE SPAREPARTS PTE LTD

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s Oh Lim Motor Co

Tax Invoice

Ang Moh Kah

SSP No. 41373

Order No.

Sin Maen SHU 9658R

Date: 1/6/18 20

Item	Quantity	Description	Unit Price	Amount
✓ 1	1/	C2D 16483 Front Pit shock Absorber		440 ✓
✓ 2	1/	C2P 22948 Absorber Mounting		95 ✓
3	1/	C2D 16903 1 Isolator		95 00
4	1/	C2P 3211 St. Absorber Mounting		65 00
✓ 5	1/	C2D 24220 F/Buti Ball Joint		55 ✓
6				
7				
8				
9				
10				
11				
12				
13				
14				

Sub Total

Add GST @ 7%

Total Amount

Delivered by Received by
N. B. Goods are not returnable after two days.

E. & O. E.

實利基機件(私人)有限公司 SELEGIE SPAREPARTS PTE LTD

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s Ch Lim Motor Co

Tax Invoice

Ang M. Koh

SSP No. 41372

Order No.

SLU 9568R

Date: 1.6.18

20

Item	Quantity	Description	Unit Price	Amount
1	1/2	C2D 20215 Front RH fender		1120 00 ✓
2	1/2	C2D 43781 F/RH Wheel Line		250 00 ✓
3	1/2	C2D 3171 F/RH Head Lamp		1900 00 ✓
4	1/2	C2D 5386XXX Front Bumper		1700 00 ✓
5	1/2	C2D 43333 F/Bumper Brakes		40 00 ✓
6	1/2	C2D 2474 Front RH Upper ARM		230 00 ✓
7	1/2	C2D 1536 F/RH Lower ARM		270 00 ✓
8	1/2	C2D 6343 F/RH LOWER ARM		320 00 ✓
9	1/2	C2D 33598 F/RH Knuckle ARM		420 00 ✓
10	1/2	C2D 3285 F/RH Knuckle ARM bearing		320 00 ✓
11	1/2	C2D 7778 RH TU Pod end		85 00 ✓
12	1/2	C2D 2214 RH Steering Rod		65 00 ✓
13				
14				

Sub Total

Add GST @ 7%

Total Amount

Delivered by Received by

N. B. Goods are not returnable after two days.

E. & O. E.

實利基機件(私人)有限公司
SELEGIE SPAREPARTS PTE LTD

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s Mr Lim Mee

Tax Invoice

Ang Moh Kiat

SSP No. 41378

Order No.

SHU 9658R

Date: 2.6.18 20

Item	Quantity	Description	Unit Price	Amount
1	1/2	XPS 30016 Steering Dust Cover		✓ 65 → SUP
2	1/2	CRD 18181 Front Top Panel		✓ 800 → SUP
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				

✓

Sub Total

865 00

Delivered by Received by

N. B. Goods are not returnable after two days.

Add GST @ 7%

60 55

Total Amount

925 55

E. & O. E.

實利基機件(私人)有限公司
SELEGIE SPAREPARTS PTE LTD

No. 19 Birch Road Singapore 219887

Tel: 65-6292 5737 (4 Lines) Fax: 65-6292 2270

Email: selegie@singnet.com.sg

Co. Reg. No. 198501965N GST Reg. No. M2-0071043-6

WE SPECIALISED IN ALL KINDS OF KONI • VOGTLAND SPORT SPRING • VOLVO GENUINE SPAREPARTS



M/s ah Lim Motor

Tax Invoice

Ang Moh Kah

SSP No. 41435

Order No. CSLU 9658R

Date: 12/6/18 20.....

Item	Quantity	Description	Unit Price	Amount
1	<u>1</u>	<u>Power Steering ni</u>		<u>34</u>
2				
3				<u>gnd</u>
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				

Delivered by [Signature] Received by [Signature]
N. B. Goods are not returnable after two days.

E. & O. E.

Sub Total	<u>34</u>	<u>00</u>
Add GST @ 7%	<u>2</u>	<u>38</u>
Total Amount	<u>36</u>	<u>38</u>

Veron Chen (LKKAuto)

From: muihong@ahlimmotor.com.sg
Sent: Friday, 17 August 2018 1:50 PM
To: Veron Chen (LKKAuto)
Subject: Draft Finalisation - SLU9658R
Attachments: Draft Finalisation - SLU9658R.pdf

Dear Kenneth,

Pls see attached the Draft Finalisation – SLU9658R.

Pls advise.

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CS/ASM18006769/Kvbe2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 09-10-2018	
ATTN : PETER WANG		Code : ASM	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLU 9658R
Policy No.	GA316866	Coverage (\$)	0.00
Claim No.	S8M00DL1	Excess (\$)	1,500.00
Assign From	PETER WANG	Assign Date	12/04/2018
2. Vehicle Particulars & Condition			
Make & Model	JAGUAR XJL (A)	c.c	2995
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	SAJAC22A8D8V41805	Colour	METALLIC PEARL WHITE
Odometer	85372	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/45 R19	CONTINENTAL	7 mm
L/H Front Tyre	245/45 R19	CONTINENTAL	7 mm
R/H Rear Tyre	275/40 R19	MICHELIN	7 mm
L/H Rear Tyre	275/40 R19	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND UNDERCARRIAGE PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/04/2018	Inspection Date	12/04/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE MARKET VALUE IS S\$122,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 9658R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP RH (CONSISTENT)	CRACKED	1,900.00	1,900.00
1	FRONT BUMPER (CONSISTENT)	BUCKLED	1,700.00	1,700.00
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	DISTORTED	40.00	40.00
15	FRONT BUMPER CLIPS (CONSISTENT)	NOT NECESSARY	52.50	-
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	510.00	-
1	FRONT BUMPER SPONGE (CONSISTENT)	SERVICEABLE	240.00	-
1	FOGLAMP COVER RH (CONSISTENT)	SERVICEABLE	170.00	-
1	FOGLAMP CHROME MOULDING RH (CONSISTENT)	SERVICEABLE	230.00	-
1	FRONT FENDER RH (CONSISTENT)	BUCKLED	1,120.00	1,120.00
1	FRONT FENDER V6 LOGO (CONSISTENT)	NOT NECESSARY	204.00	-
1	FRONT FENDER COWLING (CONSISTENT)	CRACKED	250.00	250.00
8	FRONT FENDER COWLING CLIPS (CONSISTENT)	NOT NECESSARY	9.60	-
1	FRONT WHEEL BEARING WITH HUB RH (CONSISTENT)	BENT	320.00	320.00
1	FRONT KNUCKLE ARM RH (CONSISTENT)	BENT	420.00	420.00
1	FRONT LOWER ARM RH (CONSISTENT)	DISTORTED	270.00	270.00
1	FRONT SIDE ARM NO.1 RH (CONSISTENT)	DISTORTED	320.00	320.00
1	FRONT SIDE ARM NO.2 RH (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	FRONT UPPER ARM RH (CONSISTENT)	BENT	250.00	250.00
1	FRONT TIE ROD RH (CONSISTENT)	BENT	85.00	85.00
1	FRONT TIE ROD BALL JOINT RH (CONSISTENT)	BENT	65.00	65.00
1	FRONT STEERING RACK (CONSISTENT)	BENT / JAMMED	4,300.00	4,300.00
1	FRONT SHOCK ABSORBER RH (CONSISTENT)	BENT	440.00	440.00
1	FRONT SHOCK ABSORBER TOP MOUNTING (CONSISTENT)	BENT	95.00	95.00
1	STEERING DUCT COVER (ADDITIONAL) (CONSISTENT)	CRACKED	65.00	65.00
1	ANTI ROLL BAR LINK (ADDITIONAL) (CONSISTENT)	DISTORTED	55.00	55.00
1	SUPPORT TOP PANEL (ADDITIONAL) (CONSISTENT)	BUCKLED	800.00	800.00
1	POWER STEERING FLUID (ADDITIONAL) (CONSISTENT)	NECESSARY	34.00	34.00
			13,945.10	12,529.00

Report Ref No. CS/ASM18006769/Kvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	TYRE RHF (SN) (70%) (CONSISTENT)	CUT	280.00	196.00
1	SPORT RIM RHF (SN) (CONSISTENT) (LOCAL REPAIR)	DENTED	1,280.00	180.00
			1,560.00	376.00
	<u>LABOUR</u>			
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.		500.00	320.00
	TO REMOVE AND REINSTALL / REPLACE FRONT BUMPER SENSORS.		120.00	60.00
	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT.		280.00	150.00
	TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT.		900.00	700.00
	TO SPRAY FRONT BONNET, FRONT FENDER RH, FRONT BUMPER.		900.00	500.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT. (ADDITIONAL)		80.00	60.00
	TO REMOVE AND DISMANTLE, REPLACE CUT RADIATOR SUPPORT PANEL. (ADDITIONAL)	NOT NECESSARY	800.00	-
			3,620.00	1,810.00
GRAND TOTAL			19,125.10	14,715.00
RECOMMENDED COST OF REPAIRS				14,715.00
LESS EXCESS				-1,500.00
NETT LIABILITY				13,215.00

Report Ref No. CS/ASM18006769/Kvbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.