



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

M/S AT RESERVATION NETWORK PTE LTD
NO.11 LORONG 3 TOA PAYOH
#04-20 BLK B JACKSON SQUARE
SINGAPORE 319579
Insured AT RESERVATION NETWORK PTE LTD
Policy VFX/P1431455/00060

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 9/3/2018
Our Case Ref. SC18/03/044/4AT-TP
Accident Date ~~8/3/2018~~
28-02-2018

Damaged Vehicle No: PA9236H

S/no	Description	QTY	Price	Disc	Amount
Replaced Parts					
1	ARTWORK ?	1 ST	\$1,200.00	-	\$1,200.00
Labour Charges					
1	LABOUR & SPRAY PAINTING 640 /day	1	\$1,600.00	-	\$1,600.00 1,000.
3 days.					
Sebastian. 26/4/18. - Photo After Paint. 90036121 sebastian.yeang@lkkauto.com.					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
Sub Total					\$ 2,800.00

Authorised Signature