Meimon -	Monus		ASSIGNME				1001/00/
From (Person):	Irene Tai	4	of	CTL	Date/	Time:	12042018
Estimated Cost)	111.00	Bill to:			
od/m/ws	TP RES / OD			S		* 7.0	
To Inspect Veh	icle No:	SKI	applap		Hight cu.		11881
at Workshop m	ds	Trans	Eurokars		Tel: 7	127	7928
of		5 Ubi	dose				
Policy No:	DMPCSI	1151652171	D	Claim No:	SMM18D	0183	39 CO2
Sum Insured:				Excess:			
Make of Veh:					DO.	Λ	810611080
			11 0				
(Client's Record)	REP. / REV	24 HRS WP	, 13.0	4.2018 C 4	oM		dorsement:
(Client's Record) CA / REV /	REP. / REV	1			pm H.C).D, En	dorsement:
(Client's Record) CA / REV / Date/Time:	REP. / REV 2	15pm Per	son Contacted:	Ronuld	oM).D, En	dorsement:
(Client's Record) CA / REV / Date/Time:	REP. / REV	15pm Per		Ronuld	pm H.C).D, En	dorsement:
(Client's Record) CA / REV /	REP. / REV 2	ispm Per	son Contacted:	Ronuld	pm H.C).D, En	dorsement:
(Client's Record) CA / REV / Date/Time:	REP. / REV 2	15pm Person (/ D - X	son Contacted:	Ronuld	pm H.C).D, En	dorsement:
(Client's Record) CA / REV / Date/Time:	Action/Instruct	15pm Person (/ D - X	son Contacted:	Ronuld	pm H.C).D, En	dorsement:
(Client's Record) CA / REV / Date/Time:	Action/Instruct	15pm Person (/ D - X	son Contacted:	Ronuld	pm H.C).D, En	dorsement:

A 1971 (10)	CIL		
	A	SOLGNMENT	
Fion.	Date 13042018	SK2967	4D 2 /4
Estimated Cost	Dank		/ Lorry / Taxi / Prime Mover (
	RES / EVA / INV / MV	Truck/Trailer or A	/
	SKZ 9674D	Make Marda 3	1496
at Workshop m/s	Truns Eurokars	Colour ned	A/C Insured / Std / NI / NA
of	5 ubi llose	Sp.Reading 3350	T/Radio Insured / Std / NI / NA
Insured	y- da-0	Emp/No	
Policy No		CNO JMLRI	M 42A860334695
Claims No		Gen, Cond. Good / Fair / Poor / B	urnt 4 014 9 9 9 9 1 0 13
Sum Insured	Excess	Steering Invided / Jammed / Lea	ked / Burnt or
(Client's Record)		Brake: Inordel / Jammed / Lea	ked / Burnt or
Make of Veh.	Ronald	Modi: Nil SIRim / STD A/Rin	
	12	Tyre Size: F: 20	8/601/6
(Policy Condition)	Чрт	R:	7
Remark. The veh had comm	enced its N/S C	BS DUN / EXNOVA / GY / FS / L	IZA / MIC / OHTSU / PIR / SUMI /
repair at the time of	of inspection.	TOYO YOKO or	
Bal, or Market Value,		Front	Rear
IDAC Accident Rport	Consistent? : Yes or No	R/Bal mm	R/Bal. mm
GIL PR Seen:	Consistent? : Yes or No	L/Bal mm	L/Bal. P mg
Est. Repairs: 3	days Res. Yes or No	D.O.A. 8/4/18	0.01/3/4/18
Lum Sum: 131	% 3 Val. Yes or No	Survey held at	
CA / REV / REP. / 2	4 HRS	Des. of Damages: Frt / Rear /	OIS I NIS LUIC I Rooftop or
	Vehicle: IN /		for.
200710	n Contacted:	The U/C / Chassis frame /	Body Structure affected due to collision.
Date / Time Action / In:	le basalt se	1 in for rese	
18/5/18 Sum	he hasn't sen,	1 7	
10 0	1 -61.		
	-		
	RECEIVED 16 N	MAY 201	
191 1/4			
NATIONAL AMERICAN CONTRACTOR AND ADMINISTRATION OF THE PARTY OF THE PA	7		
Cate-Time, File Pass hr?	: Preli. Report	Days Of Repair:	
Date Time File Return to?	: Final Report	Resurvey No. of Trip:	Survey Fee Transportance
	Δdd	Fee: Site Insp. (\$	N_S-RS SI
	Add	Interview (\$	Bon
Report Format :	79	Tech love 15	Others
Lump Sum / LB I: (5		Weavenu 15	
		1	The same of the sa

...CLAIM SUBFOLDER...(New Assignment)

	Main	F	eference	C	laim Details	Doc	uments	Show All
Main	II npi zozo		13:41 Assign				Cancel Case	
- Care	11 Apr 2018		12 Apr 2018				New Assignment	
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	

Main	Reference	Claim Details	Documents St	IIA wor
CLAIM SUBFOLDER DETAILS		Committee of the Commit	[Created by insurer]	
Insured:	THONG HOUNG YEW ALMUR, I	D: S1759735C		
Main Claimant:	VEERA KOTI NAGA SANKARAM,	ID: S7284351G		
Vehicle Reg. No.:	SKZ9674D	Date of Loss:	08/04/2018 10:00 - :59	
Claim Type:	TP / SNM18D01839C02	Policy/Cover Note No.:	DMPCSN1516521702 (Comprehensive)	
Vehicle Reg. No. (Insured):	SJR1188Y	Policy No. (Claimant):	2100455315-02	
		Excess:	S\$0.00	
Repairer:	Trans Eurokars Pte Ltd (Sunge	Kadut) 12 Sungei Kadut Ave, 7	29648 Sungel Kadut - Tel: 63602845	
Handling Insurer:	China Taiping Insurance (Singa 638986192]	apore) Pte. Ltd. (HQ) - Tel: 638	9 6111 [Handled by Irene Tay H	ui Ping
Claimant's Insurer:	AIG Asia Pacific Insurance Pte.	Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Final	Rpt due 23/04/2018]	
Driver/Custodian (Insured):	CHRISTINA LEE GEOK LAN (47 / F	emale), NRIC: S7103539E, T	el: +6592995259	
Adj Asg. Remarks:	EST \$5400.45, CASE WITH SJE.	- M		
ASSOCIATED MAIL RECEIVE)		View All Compose Case	Mail
There are no mail for this case.				
E ALL ASSOCIATED TASKS		View All Search 1	asks Create New Task Cr	omplete
		The state of the s	ompleted On Created On	Done?

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

atoresaid.	
	ACCIDENT STATEMENT
Date Of Report	09/04/2018 14:20
Date Of Accident	08/04/2018 10:00
Exact Location Of Accident	NEAR CARPARK BLK 26 CANBERRA DRIVE
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SKZ9674D
Insured/Policyholder	
Name Of Registered Owner	VEERA KOTI NAGA SANKARAM
NRIC No	S7284351G
Email Address	SIRI_SANKAR@YAHOO.COM
Mobile Phone No	(LOCAL) +65-90218725
Alternative Phone No	OTHERS-65202095
Vehicle Particulars	
Manufacturer	MAZDA
Model	MAZDA 3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE, LTD.

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 2100455315-02

Cover Note Number

Driver

Name of Driver VEERA KOTI NAGA SANKARAM

 NRIC No
 S7284351G

 Date Of Birth
 10/02/1972

 Occupation
 INDOOR

 Date Of Driving Pass
 13/08/2004

Driving Experience 13 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90218725

Fax Number

Contact Number OTHERS-65202095

EMail Address SIRI_SANKAR@YAHOO.COM

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN

MEME SEE DEW

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 08/04/2018 10AM, MY WEIGHBOUR INFORMED
THAT HER CHRISTINA) CAR NO SJR 1188 Y
HIT MY CAR (SKZ9674D) WHILE REVERSING
DURING THE PARKING AND DAMAGED FRONT
PANNEL AND SOME DAMAGE TO RIMS.
AFTER MEETING THEM THEY AGREED TO
GET REPAIR MY CAR AND EXAMLED ICS.
NOTE THAT PURING THE ACCEPTAT MY
CAR WAS PARKED IN PARKING LOT AND
I WAS NOT PRESENT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	4351G
Vehicle No.:	SKZ9674D
Vehicle to be Exported:	No
Intended De-registration Date:	16 Apr 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	P520350641
Chassis No.:	JM6BM42A8G0334695
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$19,110.00
Original Registration Date:	17 Feb 2016
First Registration Date:	17 Feb 2016
Transfer Count:	Ô
Actual ARF Paid: Intended PARF Rebate Details	\$14,110.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Feb 2026
PARF Rebate Amount: Intended COE Rebate Details	\$10,582.00
COE Expiry Date:	16 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,002.00
COE Rebate Amount:	\$35,251.00
Total Rebate Amount:	\$45,833.00

The information contained herein is correct as at 16 Apr 2018

ОК



ATTN.:

TRANS EUROKARS PTE LTD NO:5 UBI CLOSE, SINGAPORE 408605

ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L NAME: Mr Veera Koti Naga Sankaram EXCESS: 3 ANSON ROAD ADDRESS : 26 Canberra Drive

DATE: 10-Apr-18 #09-14 #16-00 SPRINGLEAF TOWER

Singapore 768428 SINGAPORE 079909 90218725

FAX:

TEL:

MOTOR CLAIMS

RONALD 6395 7875 SKZ9674D DATE IN: CONTACT PERSON: VEH NO : TYPE OF CLAIM: THIRD PARTY CLAIM JM6BM42A8G0334695 MILEAGE: CHASSIS NO:

MAZDA3 1.5L DATE REG.: 17-Feb-16 POLICY NO. : MODEL: NATURE OF WORKS Parts Description PRICES REVISED QTY NO 30 333.90 S RHS FRONT FENDER 1 MB45A-52-111B 1 MB4YA-52-10Y nu \$ 39.90 2 STAY(RHS), FRONT FENDER 1 1 MB45A-56-130H 11 \$ 97.00 RHS FRONT MUDGUARD 3 \$ 28.00, FASTENER, MUDGUARD 10 MB45A-56-146A 4 1.101.70 1 M9965-D0-6560 5 WHEEL, DISC (RHF) 1,600.50 **TOTAL PARTS** \$ 160.05 **LESS 10%** 1,440.45 \$ TOTAL PARTS COST **Labour Description** TO REPLACE RHS FRONT FENDER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. \$ 1,320.00 1 TO RESPRAY RHS FRONT FENDER, Sugar \$ 1,260.00 2 MZ-BR-WHEBAL TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING. 120.00 3 MZ-BR-WHEALI TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT. 560.00 NETT 5 4 120 250.00 MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. 5 MZ-BR-REPROG TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. \$ 350.00 150 6 30 NETT \$ 100.00 MZ-BR-SUNDRI SUNDRIES. 7 M TOTAL LABOUR \$ 3,960.00 TOTAL PARTS 1,440.45

TOTAL	\$ *	\$ 5,400.45
LESS EXCESS	\$ 8	\$
TOTAL AFTER EXCESS	\$	
GST 7%	\$	\$ 2
GRAND TOTAL	\$	\$

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TDA	NIC	CI	IDOL	CARS	DTE	ITD
1 1 1 1	14		184 11	CHH	PIF	

Authorised Signature

LKK Auto Consultants to once notify the Repairer of the following:

- . To resurvey to forelatter spray painting
- To display damaged part(s) during resurvey
- Parts prices are served to confirmation
- Third party survey is an a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18006783/URBN2

Date:

18/05/2018

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN1516521702

Claimant

SKZ9674D

No:

Insured Vehicle **SJR1188Y**

Vehicle No: Date of Loss:

08/04/2018

Nature of Claim:

TP

Claim No:

SNM18D01839C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKZ9674D

Make & Model:

MAZDA 3, 1.6 L (A)

Engine No:

P520350641

Reg. Date:

17/02/2016 (Man. Year: 2016)

Chassis No: Odometer:

JM6BM42A8G0334695

Colour:

Engine Capacity:

Red 1496 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

33506 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Yes Engine Modification:

205/60R16

Front Tyre Size: Front Left Side:

205/60R16

Rear Tyre Size:

Toyo 8 mm

Toyo 8 mm

Rear Left Side:

Front Right Side:

Toyo 8 mm

Rear Right Side:

Toyo 8 mm

The above values represent the remaining tyre treads depth

Paintwork Labour Towing	0.00 0.00	0.00	0.00	
Gross Total (S\$)	5,400.45	2,466.62	2,933.83	54.33
	3.5	172.66	205.37	54.33
+ GST 7.00/7.00% (S\$)	378.03	1/2.66	205.37	54.53
Nett Amount (S\$)	5,778.48	2,639.28	3,139.20	54.33

INSPECTION

Date of Assignment:

12/04/2018

Date Inspected:

13/04/2018 Inspected At:

Trans Eurokars Pte Ltd (Sungei Kadut)

12 Sungei Kadut Ave Singapore 729648

Estimated Period of Repair:

3.0 days

MARCUS CHUA Adjuster:

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 18 May 2018)

Parts:

143

MAZDA 3 1.6 L (A) (Catalogue: Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ9674D)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHS FRONT FENDER	Badly Dented	333.90 FL	*333.90 FL
2	1		*STAY (RHS), FRONT FENDER	Necessary	39.90 FL	*39.90 FL
3	1		*RHS FRONT MUDGUARD *FASTENER,MUDGUARD	Not Necessary Necessary	97.00 FL 28.00 FL	*- FL *28.00 FL
5	1		*WHEEL,DISC (RHF) *SUNDRIES	Repair Necessary	1,101.70 FL 100.00 FS	*-FL *30.00FS
F=Fra	anchise	part. S=SpcNe	ett. L=ListItemDisc List Item Discount on L	Sub Total (S\$) . Items 10.00/10.00% (S\$)	1,700.50 160.05	431.80 40.18
				Total Parts (S\$)	1,540.45	391.62
			Report was unsubmitte	d during this print-out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REPLACE RHS FRONT FENDER.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,320.00	660.00
2	TO RESPRAY RHS FRONT FENDER, BUMPER	New	1,260.00	945.00
3	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	*
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	200.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	150.00
	Gross Labo	our Cost (S\$)	3,860.00	2,075.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >