

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

ALG

Name : Norisham Bin Abdul Razak

Accident Date : 2-Apr-18

Vehicle No : FBL 8177 J

Vehicle Model : Piaggio Vespa
GTS

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	Deep \$ cur 160.00 —
1	Front fork assy	\$ n 780.00 x
1	Front cowling moulding	\$ to 95.00 —
1	Front signal -R/H	\$ 17 75.00 x
1	Side mirror -R/H	\$ cur 85.00 —
1	Handle bar	\$ 320.00 ?
1	Hand grip (1 set)	\$ 17 60.00 x
1	Handle bar balancer -R/H	\$ 512 80.00 —
1	Lower belly panel	\$ cur 198.00 —
1	Footstep panel	\$ n 550.00 x
1	Footstep rear cover	\$ cur 45.00 —
1	Step panel moulding	\$ cur 90.00 —
1	Rear footrest -R/H	\$ 17 68.00 —
1	Seat lower panel -R/H	\$ Deepam 395.00 —
1	Exhaust pipe	\$ n 750.00 x
1	Exhaust protector	\$ 17 90.00 —
1	Rear side lower panel	\$ Deepam 215.00 —
		\$ 4,056.00
	Less 10%	\$ 405.60
		\$ 3,650.40

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Name : Norisham Bin Abdul Razak

Accident Date : 2-Apr-18

Vehicle No : FBL 8177 J

Vehicle Model : Piaggio Vespa
GTS

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	\$ 11	28.00	X
1	Steering cone (1 set)	\$ 11	120.00	X
1	"GTS 300" emblem	\$ net	65.00	✓
1	ERP IU	\$ 11	175.00	165
		\$	388.00	

S/No. Labour

1	To provide towing service.	\$	45.00	35
2	To check wiring and reset headlamp focusing.	\$ 11	80.00	X
3	To provide labour.	\$	380.00	✓
4	To respray painting.	\$	800.00	500
5	To check , repair and straighten body frame.	\$ 11	350.00	X
		\$	1,655.00	

Grand Total

\$ 5,693.40

Dollars: Five Thousand Six Hundred Ninety-Three And Forty Cents Only.


EROFIA MOTOR TRADING PTE LTD