

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref : DM18HO00927/JT

Date: 18th October 2018

Our Ref

: CC4/EQI18006814/Dpb3s2

M/s EO Insurance Company Ltd

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 (The Motor Claims Department)

Dear Sir/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO SJH 2350R ACCIDENT ON 07/04/2018 INSURED SDQ 8178G

Instruction was received to inspect the vehicle Reg. No. SJH 2350R. The inspection was conducted on 18/04/2018 at the premises of M/s Teamwork Garage Pte Ltd, 53 Ubi Avenue 1 #01-23/24 Singapore 408934.

The following information were recorded: -

Registration Number

: SJH 2350R

Make & Model

: Mitsubishi Lancer

Year of Registration

: 2008

Engine Capacity

: 1499 cc : Black

Body Colour Chassis Number

: JMYSRCY2A8U004223

Speedometer Reading

: 126927 km

The vehicle sustained damages at the front and rear portion. The Estimated repair cost of such vehicle is S\$15,000.00 (Sin Dollars: Fifteen Thousand only.) (Details see photographs enclosed).



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

In view of this repair work, we are of the opinion that it would be uneconomical to proceed with the repairs and recommend it's to be written off as "Total Loss".

(a) If the vehicle to be "Total Loss"

Market Value

SS 14,000.00

Less: LTA Reimbursement Value (RV)

(S\$ 9,600.00)

Nett Liability

SS 4,400.00

> 4,400.00 SS

(b) If the vehicle to be "Repair"

Repair Cost (Est)

15,000.00

Nett Liability

S\$ 15,000.00

(a) - (b) =

(SS 10,600.00)

The amount of estimated saving of S\$10,600.00 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehiele Inspected By:

ANG BRYAN TANI

Automotive Assessor / Investigator

MSc(Eng.M), B Eng(Hons), Peng(UK), MASMB(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA),

AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.