

Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Singapore 408934 Paya Ubi Industrial Park Tel: 6844 2475 Fax: 6844 2474

Email: claims@teamworkgargae.com GST Register No: 201015366H

25th June 2018

Our reference: 1804-10 Your reference: SDQ8178G

EQ Insurance Company Limited

BY HAND

5 Maxwell Road #17-00

Tower Block, MND Complex

Singapore 069110

Attn: Motor Claims Department

Dear Sir/Mdm,

ACCIDENT INVOLVING SJH2350R / SDQ8178G ON 07 APR 2018 @ AYE TWDS CHANGI AIRPORT - REPAIR COST FOR MITSUBISHI LANCER - SJH2350R

We would like to propose that the repair cost of <u>SJH2350R</u> to be at <u>SGD\$15,000.00*</u> (<u>Singdollars Fifteen Thousand</u>). However in view of the life span of 3 months (COE due on 29 July 2018) and current market value for the said vehicle, it is not economical to proceed with the repair.

As such, we suggest on scraping the said vehicle. Please offer us a total loss amount in order to facilitate the claim.

Thank you.

Yours faithfully,

Darren Ng

Teamwork Garage Pte Ltd