Veron Chen (LKKAuto)

From: Mei Kwan (LKKAuto)

Sent: Saturday, 5 May 2018 6:14 PM

To: Veron Chen (LKKAuto)

Cc: SUR

Subject: FW: LOD to NTUC - BUS/04/18/7015/AW - TIB1129P AND SLX5295P ON 8 APRIL

2018 ALONG WOODLANDS CTR ROAD JUNCTION WITH EXIT OF TAXI STAND

Attachments: img-504115935-0001.pdf

Importance: High

Follow Up Flag: Follow up Flag Status: Flagged

HI,

Fyi please. NS/INC18006825/R1vbn2.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Audrey Woo (Auto Svcs/Ext Biz Svcs/Claims & IA/Buses) [mailto:audrey@smrt.com.sg]

Sent: Friday, 4 May, 2018 12:04 PM

To: motor@income.com.sg

Cc: Admin A <admin-a@lkkauto.com>; Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: LOD to NTUC - BUS/04/18/7015/AW - TIB1129P AND SLX5295P ON 8 APRIL 2018 ALONG WOODLANDS CTR

ROAD JUNCTION WITH EXIT OF TAXI STAND

Importance: High

SMRT: BUS/04/18/7015/AW

NTUC: SLX5295P

Dear NTUC Motor Claims Officer,

We claim on behalf of SMRT BUSES LTD, owner of the vehicle registration number TIB1129P. Your client's negligent driving has caused the above accident. As a result, my client has suffered the following losses,

| Cost of Repair | \$ 2150.00 |
|----------------|------------|
| Loss of Use | \$875.00 |
| LTA search fee | \$7.00 |
| Total | \$ 3032.00 |

We enclose the following documents,

Repair Invoice

- GIA report
- LTA Search
- Survey Report and Bus Photos, please retrieve from NTUC's own appointed surveyor LKK.

We look forward to your confirmation to settle our claims within 15 days from the date of this email. Payment by cheque shall be crossed and made payable to **SMRT BUSES LTD**.

Audrey Woo | DID: 6556 3521 | FAX: 6368 7421 | Email: audrey@smrt.com.sg | Claims Department | SMRT BUSES LTD | 6 Ang Mo Kio Street 62 Singapore 569140

