

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 17 Apr 2018

Preliminary Advice

Insured Vehicle No : YP9992Y

TP Vehicle No : SLX1949M

Make : NISSAN QASHQAI

Date of Inspection : 16/04/2018

Inspection At : TAN CHONG MOTOR SALES PTE LTD (HQ)
911 BUKIT TIMAH ROAD
SINGAPORE 589623

Accident Date : 27/03/2018

Assignment Date : 13/04/2018

Est. Duration of Repair : 7.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,761.76
Revised Amount	:S\$	10,047.16
Check Items (Estimated)	:S\$	1,769.60
Total	:S\$	11,816.76

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.