



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : SFR9899Z
Make & Model : B.M.W., 730LI AT ABS D/AB 2WD 4DR NAV HID
Year of Manufacture : 2010
Estimation No. : E18040048
DOA : 09/04/2018
SR,WBAKB22030CN74762

No	Description	Qty	U/P	Amt
Section: List Items				
1	inner centre bracket CRA	1.00	391.80	391.80
2	Reinforcement garnish CRA	1.00	288.50	288.50
3	Number plate garnish CRA	1.00	87.90	87.90
4	Exhaust heat shield BUC	1.00	157.20	157.20
				Amt S\$ 925.40
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 925.40

P = 9706.80 - 5%

= 9221.46

SN: D

L: 1520.00

10741.46

* 1/5 \$ 8600 @ 6 repair days

List Items Subtotal S\$ 925.40
Total S\$ 925.40