

22/03/2002

ASS. REC. BY:

REF: CS/FCU8006862/Urbn2 Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): W3 Eileen Lee of FCI Date/Time: 12042018 4.46pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GZ 6437P Insured: SHD 4448Aat Workshop m/s SME Motor Tel: 6747 6106of Bk 1 Kaki Bukit Ave 6 #02-17Policy No: _____ Claim No: D18002798MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 09042018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement: _____

Date/Time: 12042018 5:18pm Person Contacted: Pai Ying Vehicle IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>GZ 6437P - x</u>
	<u>SHD 4448A - CS / CTI 7011466 / M1wb3n2</u> <u>DIA: 150617</u>

REF:

Fcl

ASSIGNMENT

From: Date: 23042018

Estimated Cost:

OD TP WS TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

G2 6437P

at Workshop m/s

SME

of

Blk 1 Katil Bukit Ave 6 # 02-15

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

9.30am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

226.

IDAC Accident Rpt:

Consistent? : Yes or No

E/S / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

26473

Date:

Person Contacted:

Vehicle: IN / OUT
16/7/2018

Veh No: G2 6437P Yr Regn: 7.06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM /

Make:

m.f 2300

C.C

2477

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

353511

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMAJNP15V6A001344

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185-214

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

condor

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

9/4/18

D.O.I.

24/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 14355

3 yrs - 3 mth.

asking insurance report.

20/7/18 confirmed 2/5 & 2300 with Airtag

Red: \$2050.80, 47%.

NW: \$22K, LTA: \$14355.00, NV: \$7645.00

Date/Time, File Pass to?



: Preli. Report

1) fypst



: Final Report

Date/Time, File Return to?

2) -

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format:

Tp

Lump Sum / T.B. (\$ 2300

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

135

50

50+50

48

333

MOTOR SURVEY ASSIGNMENT

Date	10-04-2018	Our Ref No. D18002798MFSH
Accident Date	09-04-2018	Claim Type. Third Party
Insured Vehicle	SHD4448A	Third Party Vehicle. GZ6437P
Survey Location	1 KAKI BUKIT AVE 6 #02-17AUTOBAY@KAKI BUKIT	
Contact Person.	PEIYING	
Contact No.	67476106/ 0	Fax No. 67442368
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SME MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



\$2500 Downpayment Monthly
From \$580 Onwards. Lowest
3.68%P.A@Gv Cars Financing.
GV Credit Pte Ltd StarAd

Lake View
Credit Pte Ltd

view our cars

> Low prices guaranteed
> Specialist in Japanese cars
> Easy loan approval
> All terms are negotiable

Browse by Category

Sort by Date Posted 20 results/page

9 vehicles

Mitsubishi L300

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi L300		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Mitsubishi L300 (COE till 08/2020)		\$19,800	\$8,480 /yr	24-Aug-2005	2,477 cc	-	Van	Available
	Fuel Type: Diesel Fast Loan Approval! Low Interest High Loan! Negotiable! Call Fast For An No Obligation Discussion! Door Step Viewing Possible! Net Link Partners Pte Ltd Posted: 22-Apr-2018 Tags: 2005 Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, Used Mitsubishi								
	Mitsubishi L300 (COE till 07/2020)		\$21,800	\$9,730 /yr	21-Jul-2005	2,477 cc	-	Van	Available
	Fuel Type: Diesel One Of The Cheap And Reliable Vans Compared To Other Model, Easy To Maintain, Showroom Condition, New Paint And Leather Seats, High Trade In And High Loan Available, For More Information Please Contact... KSL Automotive Pte Ltd Posted: 21-Apr-2018 Tags: 2005 Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, Used Mitsubishi								
	Mitsubishi L300 (COE till 01/2021)		\$21,800	\$8,010 /yr	13-Jan-2006	2,477 cc	-	Van	Available
	Fuel Type: Diesel 5 Door For Easy Load, Well Maintained, High COE Value, New Paintwork, Rear Wooden Floor Board, Engine And Gearbox In Excellent Condition, All Wear And Tear Just Replaced. No Repair Needed To Be Done. OK2 Pte Ltd Posted: 20-Apr-2018 Tags: 2006 Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, Used Mitsubishi								
	Mitsubishi L300 (COE till 10/2020)		\$20,800	\$8,290 /yr	27-Oct-2005	2,477 cc	-	Van	Available
	Fuel Type: Diesel Cheapest In Market! Flexible Loan Available! New Paint And No Repair Needed! Big Space Heavy Duty For Business. Call Us Now For Viewing. \$1000 Discount For ALL Young Entrepreneurs Age 20-25 Years Old ... OK2 Pte Ltd Posted: 20-Apr-2018 Tags: 2005 Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, Used Mitsubishi								
Car Buying	Car Selling	Car Ownership							
Car Aftermarket	On The Move	Lifestyle							
	Mitsubishi L300 (COE till 06/2021)		\$23,888	\$7,650 /yr	08-Jun-2006	2,477 cc	-	Van	Available
	Fuel Type: Diesel Healthy Engine With Great Condition. View To Believe. Hurry Now. High Loan And Trade In Available. Posted: 20-Apr-2018 Tags: 2006 Mitsubishi L300, Mitsubishi L300, Mitsubishi, L300, Used Mitsubishi								
Compare	Mitsubishi L300 (COE till 11/2020)		\$16,000	\$6,200 /yr	22-Nov-2005	2,477 cc	-	Van	Available



Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 2647B

Vehicle Details

Vehicle No.: GZ6437P

Vehicle to be Exported: No

Intended De-registration Date: 24 Apr 2018

Vehicle Make: MITSUBISHI

Vehicle Model: L300 HR M

Primary Colour: White

Manufacturing Year: 2006

Engine No.: 4D56LC0772

Chassis No.: JMAJNP15V6A001344

Maximum Power Output: -

Open Market Value: \$11,526.00

Original Registration Date: 17 Jul 2006

First Registration Date: 17 Jul 2006

Transfer Count: 1

Actual ARF Paid: \$577.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 16 Jul 2021

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$22,247.00

COE Rebate Amount: \$14,355.00

Total Rebate Amount: \$14,355.00**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 24 Apr 2018

OK

LETTER OF UNDERTAKING

I/We, M & L FURNISHING, the owner of vehicle no. 926437F

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, SME MOTOR PTE LTD

Signed and Acknowledge by:



Nric no. and signature of policyholder



Company Stamp

10/04/2018

Date

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

Not Approved
2/592300/c
4 days
24/4/18
Wheeler's Office
ng

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 18/FC/TP-077 (04)

Claim Type: Third Party

Accident Date: 09/04/2018

TP Veh Reg No: SHD4448A

Estimate No: EST0004055

Date: 11 Apr 2018

Policy No: GA216971

Veh Reg No: GZ6437P

Make/Model: MITSUBISHI L300

Chasis No: JMAJNP15V6A001344

Engine No: 4D56LC0772

Reg. Date: 17/07/2006

Estimate Repair Cost to Vehicle No :GZ6437P

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1 REAR WINDSCREEN RUBBER	1 PC	183.00	183.00
2 REAR GATE	1 PC	788.00	788.00
3 REAR GATE LOCK	1 PC	114.00	114.00
4 REAR GATE 'MITSUBISHI' STICKER	1 PC	133.00	133.00
5 REAR GATE OUTER GARNISH	1 PC	104.00	104.00
6 REAR BUMPER	1 PC	134.00	134.00
7 REAR BUMPER SIDE RETAINER	2 PC	100.00	200.00
8 REAR BUMPER CLIP	10 PC	50.00	500.00
9 REAR NUMBER PLATE LAMP	2 PC	180.00	360.00
10 REAR END PANEL -INNER	1 PC	444.00	444.00
11 END PANEL -OUTER	1 PC	511.00	511.00
12 REAR GATE '2.5' STICKER	1 PC	55.00	55.00
13 REAR SPARE TYRE BRACKET	1 PC	195.00	195.00
		2,991.00	
	Less 20%	598.20	2,392.80
Special Net			
14 REAR GATE STICKER '70KM/H'	1 PC	25.00	25.00
15 REAR NUMBER PLATE	1 PC	35.00	35.00
		60.00	60.00
Labour			
16 WIRE CHECKING	1 UNIT	20.00	20.00
17 REMOVE & REFIX REAR WINDSCREEN	1 UNIT	120.00	120.00
18 LABOUR CHARGE	1 UNIT	800.00	800.00
19 SPRAY PAINTING	1 UNIT	800.00	800.00
		1,740.00	1,740.00

Total 43508 SS 4,192.80

Add GST @ 7% 293.50

Total Amount Payable SS 4,486.30

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND FOUR HUNDRED EIGHTY SIX AND CENTS THIRTY ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Fault" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

1-1638-5
2908-0
2327

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST: 201119451E RCB NO: 201119451E

M/S : M & L FURNISHING

Singapore

ATTN:

Your Ref No: 18/FC/TP-077 (04)

Claim Type: Third Party

Accident Date: 09/04/2018

TP Veh Reg No: SHD4448A

Estimate No: EST0004055

Date: 12 Jul 2018

Policy No: GA216971

Veh Reg No: GZ6437P

Make/Model: MITSUBISHI L300

Chasis No: JMAJNP15V6A001344

Engine No: 4D56LC0772

Reg. Date: 17/07/2006

Estimate Repair Cost to Vehicle No :GZ6437P

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
Supplementary Parts to Repair			
List Price			
1 REAR GATE INNER RUBBER	1 PC	197.50	
		197.50	
	Less 20%	39.50	158.00
Total			SS 158.00
GST Amount			SS 11.06
Total Amount Payable			SS 169.06

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

List -
-20%



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006862/Urbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4448A	Veh. Inspected	GZ 6437P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002798MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	12/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI L300 (M)	c.c	2477	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JMAJNP15V6A001344	Colour	WHITE	
Odometer	353511	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14	CONDOR	6 mm	
L/H Front Tyre	185 R14	CONDOR	6 mm	
R/H Rear Tyre	185 R14	CONDOR	6 mm	
L/H Rear Tyre	185 R14	CONDOR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/04/2018	Inspection Date	24/04/2018	
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GZ 6437P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN RUBBER	NOT NECESSARY	183.00	-
1	REAR GATE LOCK	DENTED / JAMMED	114.00	114.00
1	REAR GATE "MITSUBISHI" STICKER	NECESSARY	133.00	133.00
1	REAR GATE OUTER GARNISH	NOT NECESSARY	104.00	-
1	REAR BUMPER	DISTORTED	134.00	134.00
2	REAR BUMPER SIDE RETAINER	NOT NECESSARY	100.00	-
10	REAR BUMPER CLIP	NECESSARY	50.00	50.00
2	REAR NUMBER PLATE LAMP	NOT NECESSARY	180.00	-
1	REAR END PANEL-INNER	BADLY DENTED	444.00	444.00
1	END PANEL-OUTER	BADLY DENTED	511.00	511.00
1	REAR GATE "2.5" STICKER	NECESSARY	55.00	55.00
1	REAR SPARE TYRE BRACKET	NOT NECESSARY	195.00	-
1	REAR GATE INNER RUBBER (ADDITIONAL)	TORN	197.50	197.50
	LESS 20% DISCOUNT		-480.10	-327.70
			1,920.40	1,310.80
1	REAR GATE (50%)(SN)	DENTED / BENT	788.00	394.00
	LESS 20% DISCOUNT		-157.60	-
			630.40	394.00
SPECIAL NETT ITEMS				
1	REAR GATE STICKER "70KM/H" (SN)	NECESSARY	25.00	10.00
1	REAR NUMBER PLATE (SN)	BENT	35.00	14.00
			60.00	24.00
LABOUR				
	WIRE CHECKING.		20.00	20.00
	REMOVE & REFIX REAR WINDSCREEN.		120.00	60.00
	LABOUR CHARGE.		800.00	600.00
	SPRAY PAINTING.		800.00	500.00
			1,740.00	1,180.00

Report Ref No. CS/FC118006862/Urbn2



GRAND TOTAL		4,350.80	2,908.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,300.00

Report Ref No. CS/FCI18006862/Urbn2

MARKET VALUE: \$22,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,355.00=NETT VALUE: \$7,645.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.