# Mei Kwan (LKKAuto)

**From:** Francis Ng <francis.ng@eqinsurance.com.sg>

Sent: Wednesday, 18 April, 2018 2:16 PM

To: Mei Kwan (LKKAuto)

Cc: Vic (LKKAuto); Bevan Lim (LKK Auto); Admin A

Subject: RE: Direct Settlement - Accident Involving GBD6624R (OI : EQI - TBA) AND

SHD422A (TP: LKK REF - CC3/EQI18006863/Kma3) on 09.04.2018; EQ REF:

DM18HO00957/FN

Attachments: GBD6624R 09.04.2018.PDF

Follow Up Flag: Follow up Flag Status: Completed

Categories: HMK

Dear Mei Kwan,

Our insured's report is attached.

Regards, Francis Ng

Executive | Claims



#### **EQ Insurance Company Limited**

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190 www.eqinsurance.com.sg





Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]

Sent: Wednesday, April 18, 2018 1:58 PM

To: Francis Ng <francis.ng@eqinsurance.com.sg>

Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>; Admin A <admin-

a@lkkauto.com>

Subject: Direct Settlement - Accident Involving GBD6624R (OI: EQI - TBA) AND SHD422A (TP: LKK REF -

CC3/EQI18006863/Kma3) on 09.04.2018

### WITHOUT PREJUDICE

Dear Francis.

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHD 422A at M/s Trans-cab Auto Services Pte Ltd - Ang Mo Kio.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Bevan and he can be contacted at DID: 6749 4274.

## To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

#### LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: <u>MeiKwan@lkkauto.com</u> | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)