

Signature

INS CASE OWNER

CC 6/III1800

Surveyor

Adrian

DOI

ASSIGNMENT

13/4/18

Date / Time

13/4/18

Registered in Merimen

13/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.

SH 9001X

Name of Insured

CTP

Insured Tel No.

HP

Excess Sec II :SS

D.O.A

11/4/18

Is driver the owner?

(YES / NO)

Nature of Accident

If NO, Driver Name / Age

WONG HEE MENG

Driver Tel No.

(V/L: YES / NO)

Claim No.

MT18V80V86

Policy No.

M10M0015

Make / Model

TOYOTA

Place of Accident

BRIMBORO RD TINDS STEVEN RD
DUNSMITH & BRIMBORO

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability

%

Final ? Yes / No

SLN 1117A



INSRS:
WSP:
Tel:
Liability:
RMKS:

modern



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
16/4/18	SLN 1117A - F	Non-Reporting Itr (1st):	
16/4/18	Adrian	Non-Reporting Itr (2nd):	
16/4/18		Non-Reporting Itr (Final):	
16/4/18		Notification Itr (if non-pickup):	
16/4/18		Call OI:	
16/4/18		After call Itr to OI:	
24/4/18	Seek liability via merimen.	Documentation Check List:	Handler
24/4/18	Receive OAD video	Notification Itr (if non-pickup)	Typist
25/6/18	Liability clear via Merimen	After call Itr to OI	
11/6/18	File pass to typist + type report.	Authorisation To Act:	
11/6/18	Seek mandate via merimen	Release Voucher:	
8/6/18	Mandate approve via merimen	Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: \$5 (days) Reduction: % Email: Call:

FINAL SETTLEMENT Date/Time: 27/11/18 Confirm with: Grath. Email: Call:

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 26

Repair Cost: +632 \$5 6241.00

Loss of Rental (LOR): \$5 (days)

Loss of Use (LOU): \$5 840.00 (\$120 x 7 days)

Loss of Income (LOI): \$5 1050.00 (\$150 x 7 days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)

GIA/LTA Search \$5 7.49.

Medical: \$5

Disbursement: \$5 (e.g. Tow/ Independent)

Legal Cost: \$5

Total: \$5 8638.49 Global Sum \$5:

FINAL PAYMENT Date/Time: Confirm with: Email: Call:

Payee 1: \$5 8638.49 Name 1: Modern Automotive Pte Ltd

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

COPY SENT
26/6/18

ASS. REC. BY: Adrian Ling

REF:

W

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLN 1117A Yr Regn: 2015 / LineType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E200 o.o. 1991Colour: Black A/C: Insured / Std / NI / NASp. Reading: 153784 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120342B144290Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40R18R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 17/04/18Survey held at ModernDes. of Damages: Frt / Rear / O/S N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP III

11/6/18 confirm US \$6300.00 with 6 working days(20 - \$8159.20
56/-)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

LETTER OF AUTHORIZATION

Date: 12/04/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SLN 1117A & SH9001X

ON 11/4/18 ALONG Balmoral Rd towards

Stevens Rd

This letter is to authorize MODERN AUTOMOTIVE PTE LTD at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, MODERN AUTOMOTIVE PTE LTD has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of MODERN AUTOMOTIVE PTE LTD.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully


.....

SUPER STAR LIMO & CAR RENTAL
Reg. No.: 53359119L

Signature of Owner

LEON G TIEN SAN S6900429/F

Name / NRIC

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MU18040286
Claimant Ref: SLN 1117A

We/I, Modern Automotive Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 6,741.00 (repair cost), S\$ 1,890.00 (loss of use/rental), S\$ 7.49 (search fee), vehicle no. SLN 1117A that was damaged pursuant to the accident which occurred on 11/04/2018 (date) at BALMORAL TWDS STEVENS RD (location) involving vehicle no. SH 9001X (insured vehicle). This is pursuant to the inspection conducted on 17/04/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SUPER STAR LIMO & CAR RENTAL ("the third party claimant") of vehicle no. SLN 1117A to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLN 1117A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 8,638.49 to Modern Automotive Pte Ltd

Dated this 27 day of August 2018

CLAIMANT:

Signature: 

Signed by "the workshop" (with chop)

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1
#01-61, SINGAPORE 408717
TEL: 6747 4422 FAX: 6747 6720

WITNESS:

Signature: 

Signed by appointed Surveyor

Name: _____

NRIC: _____

Address: _____

Nationality: _____

Occupation: _____

LKK
LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25,
Paya Ubi Industrial Park
Singapore 408933

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street #04-05 IOB Building
Singapore 049711


Attention : Motor Claim Department
Contact : 6347 - 6100 Fax No. : 6224 - 4174

Tax Invoice : TP001204

Date : 01/06/2018
Vehicle Num. : SLN 1117A
Make/Model : MERCEDES E200-2015
Chassis/Eng# :
Accident Date : 11/04/2018
Claim No. :
Reference : CC6/III18006867/wb3
Policy No. : 5090133177

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR : ACCIDENT REPAIR (LUMPSUM)		6,300.00
		Labour Total S\$:		6,300.00

Total S\$:	6,300.00
GST @ 7% S\$:	441.00
Amount Due S\$:	6,741.00
	=====


MODERN AUTOMOTIVE PTE LTD

Thank you



Minder Kaur has successfully logged out.

Your last login date and time was 13 Apr 2018, 12:00:03.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SH9001X	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49	13 Apr 2018 / 12:01:29

Enquire Vehicle & Owner Information (Vehicle No. SH9001X As At 11 Apr 2018 / 12:10:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: MODERNAUTOMOTIVE43

Current Owner Details

Owner ID Type: Company
Owner ID: 199303821R
Owner Name: COMFORT TRANSPORTATION PTE LTD
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 383
Registered Street Name: SIN MING DRIVE
Registered Unit No.: -
Registered Building Name: GAS BUILDING
Registered Postal Code: 575717

Current Vehicle Details

Vehicle No.: SH9001X
Make Description/Model: TOYOTA / PRIUS HYBRID 1.8 CVT
Insurance Company Name: INDIA INT'L INS PTE LTD

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2018 Edit Reg		17 Apr 2018 00:00 Edit Adj Rpt	S\$6,300.00 Edit Estimates	S\$6,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -			
Main Claimant:	SUPER STAR LIMO & CAR RENTAL, Co. Reg. No.: 53359119L			
Vehicle Reg. No.:	SLN1117A	Date of Loss:	11/04/2018 12:00 - :59 [33 Months and 16 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / MCT18040286	Policy/Cover Note No.:	MCOM0015	
Vehicle Reg. No. (Insured):	SH9001X	Policy No. (Claimant):	5090133177	
		Excess:		
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422			
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/04/2018]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- III_SG (20/07/2018): Alert - Adj Mandate Approved (S\$8638.49) - SLN1117A - Claim Handler: Zuhaidah Bt...
- III_SG (08/06/2018): Alert - Adj Mandate Approved (S\$7588.49) - SLN1117A - Claim Handler: Zuhaidah Bt...
- III_SG (24/04/2018): Alert - Adj Mandate Approved (S\$0.00) - SLN1117A - Claim Handler: Zuhaidah Bte S...
- III_SG (17/04/2018): Alert - Adj Mandate Maintained - SLN1117A - Claim Handler: Zuhaidah Bte Samsuri

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN1117A (MCT18040286)
[SH9001X]
TP
SUPER STAR LIMO & CAR RENTAL
Apr 11 2018 12:00PM
[COMFORT TRANSPORTATION PTE LTD]
Modern Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Video									1 per page		☒
No	Finalized On	India International Insurance Pte Ltd (HQ)							Thumbnail	Print	
1	24/04/18 11:11	Video - Accident (OID)								Load MP4	
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	22/05/18 09:16	General View								Load JPG ☒	
2	22/05/18 09:16	General View								Load JPG ☒	
3	22/05/18 09:16	General View								Load JPG ☒	
4	22/05/18 09:16	General View								Load JPG ☒	
5	22/05/18 09:16	General View								Load JPG ☒	
6	22/05/18 09:16	General View								Load JPG ☒	
7	22/05/18 09:16	General View								Load JPG ☒	
8	22/05/18 09:16	General View								Load JPG ☒	
9	22/05/18 09:16	General View								Load JPG ☒	
10	22/05/18 09:16	General View								Load JPG ☒	
11	22/05/18 09:16	General View								Load JPG ☒	
12	22/05/18 09:16	General View								Load JPG ☒	
13	22/05/18 09:16	General View								Load JPG ☒	
14	22/05/18 09:16	General View								Load JPG ☒	
15	22/05/18 09:16	General View								Load JPG ☒	
16	22/05/18 09:16	General View								Load JPG ☒	
17	22/05/18 09:16	General View								Load JPG ☒	
18	22/05/18 09:16	General View								Load JPG ☒	
19	22/05/18 09:16	General View								Load JPG ☒	
20	22/05/18 09:16	General View								Load JPG ☒	
21	22/05/18 09:16	General View								Load JPG ☒	
22	22/05/18 09:16	General View								Load JPG ☒	
23	22/05/18 09:16	General View								Load JPG ☒	
24	22/05/18 09:16	General View								Load JPG ☒	
25	22/05/18 09:16	General View								Load JPG ☒	
26	22/05/18 09:16	General View								Load JPG ☒	
27	22/05/18 09:16	General View								Load JPG ☒	
28	22/05/18 09:16	General View								Load JPG ☒	
29	22/05/18 09:16	General View								Load JPG ☒	
30	22/05/18 09:16	General View								Load JPG ☒	
31	22/05/18 09:16	General View								Load JPG ☒	
32	22/05/18 09:16	General View								Load JPG ☒	
33	22/05/18 09:16	General View								Load JPG ☒	
34	22/05/18 09:16	General View								Load JPG ☒	

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				☒
35	22/05/18 09:16	General View	 Load JPG	☒
36	22/05/18 09:16	General View	 Load JPG	☒
37	22/05/18 09:16	General View	 Load JPG	☒
38	22/05/18 09:16	General View	 Load JPG	☒
39	22/05/18 09:16	General View	 Load JPG	☒
40	22/05/18 09:16	General View	 Load JPG	☒
41	22/05/18 09:16	General View	 Load JPG	☒
42	22/05/18 09:16	General View	 Load JPG	☒
43	22/05/18 09:16	General View	 Load JPG	☒
44	22/05/18 09:16	General View	 Load JPG	☒
45	22/05/18 09:16	General View	 Load JPG	☒
46	22/05/18 09:16	General View	 Load JPG	☒
47	22/05/18 09:16	General View	 Load JPG	☒
48	22/05/18 09:16	General View	 Load JPG	☒
49	22/05/18 09:16	General View	 Load JPG	☒
50	22/05/18 09:16	General View	 Load JPG	☒
51	22/05/18 09:16	Reinspection Photo	 Load JPG	☒
52	22/05/18 09:16	Reinspection Photo	 Load JPG	☒
53	22/05/18 09:16	Reinspection Photo	 Load JPG	☒
54	22/05/18 09:16	Reinspection Photo	 Load JPG	☒
55	22/05/18 09:16	Reinspection Photo	 Load JPG	☒
56	22/05/18 09:16	Reinspection Photo	 Load JPG	☒
57	22/05/18 09:16	Reinspection Photo	 Load JPG	☒
58	22/05/18 09:16	Reinspection Photo	 Load JPG	☒
59	22/05/18 09:17	Reinspection Photo	 Load JPG	☒
60	22/05/18 09:17	Reinspection Photo	 Load JPG	☒
61	22/05/18 09:17	Reinspection Photo	 Load JPG	☒
62	22/05/18 09:17	Reinspection Photo	 Load JPG	☒
63	22/05/18 09:17	Reinspection Photo	 Load JPG	☒
64	22/05/18 09:17	Reinspection Photo	 Load JPG	☒
65	22/05/18 09:17	Reinspection Photo	 Load JPG	☒
66	22/05/18 09:17	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/04/18 15:57	TP GIA REPORT	 Load PDF	
2	01/06/18 15:54	WORKSHOP INVOICE	 Load PDF	
3	01/06/18 15:54	LTA SEARCH	 Load PDF	
4	01/06/18 15:54	LOD	 Load PDF	
5	17/07/18 16:24	INCOME TAX	 Load PDF	
6	17/07/18 16:24	INCOME TAX	 Load PDF	
7	17/07/18 16:24	INCOME TAX	 Load PDF	
8	29/08/18 08:41	DISCHARGE VOUCHER	 Load PDF	
9	29/08/18 08:41	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	16/04/18 08:50	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18006867/AWB3Q2

Date: 29/08/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No: SLN1117A

Insured Vehicle No: SH9001X

Date of Loss: 11/04/2018

Nature of Claim:

TP

Claim No: MCT18040286

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN1117A

Make & Model: MERCEDES-BENZ E200, 2.0 (A)

Engine No: 27492030370902

Reg. Date: 26/06/2015 (Man. Year: 2015)

Chassis No: WDD2120342B144290

Colour: Black

Odometer: 153784 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Kumho 6 mm

Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,119.20	5,479.80	5,639.40	50.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	2,390.00	920.00	27.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,429.20	7,869.80	6,559.40	45.46
Approved Total (Overridden) (S\$)		6,300.00		
(S\$)	14,429.20	6,300.00	8,129.20	56.34
+ GST 7.00/7.00% (S\$)	1,010.04	441.00	569.04	56.34
Nett Amount (S\$)	15,439.24	6,741.00	8,698.24	56.34
+ Loss of Use (7.0 x S\$120.00/day) (S\$)		840.00		
+ Loss of Earnings (7.0 x S\$150.00/day) (S\$)		1,050.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		8,638.49		

INSPECTION

Date of Assignment: 17/04/2018

Date Inspected: 17/04/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Jun 2018)
Parts: M1-COUPE	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN1117A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,285.00 FL	*- FL
2	1		*FRONT FENDER -LH	Repair	1,020.00 FL	*- FL
3	1		*FRONT WINDSCREEN PILLAR -LH	Repair	1,230.00 FL	*- FL
4	1		*FRONT WINDSCREEN MOULDING -LH	Necessary	175.00 FL	*175.00 FL
5	1		*FRONT DOOR -LH	Dented	2,127.00 FL	*2,127.00 FL
6	1		*FRONT DOOR LOCK -LH	Not Necessary	297.00 FL	*- FL
7	1		*FRONT DOOR WEATHERSTRIP -LH	Necessary	264.00 FL	*264.00 FL
8	1		*FRONT DOOR OUTER HANDLE -LH	Cut	266.00 FL	*266.00 FL
9	1		*FRONT DOOR GLASS OUTER MOULDING -LH	Not Necessary	138.00 FL	*- FL
10	1		*FRONT DOOR CHROME MOULDING -LH	Cut	155.00 FL	*155.00 FL
11	1		*FRONT DOOR MIRROR COVER -LH	Cut	330.00 FL	*330.00 FL
12	1		*FRONT DOOR MIRROR SIGNAL LAMP -LH	Cut	148.00 FL	*148.00 FL
13	1		*FRONT DOOR MIRROR MOULDING -LH	Not Necessary	896.00 FL	*- FL
14	1		*REAR DOOR -LH	Dented	2,030.00 FL	*2,030.00 FL
15	1		*REAR DOOR LOCK -LH	Not Necessary	271.00 FL	*- FL
16	1		*REAR DOOR WEATHERSTRIP -LH	Necessary	252.00 FL	*252.00 FL
17	1		*REAR DOOR OUTER HANDLE -LH	Cut	275.00 FL	*275.00 FL
18	1		*REAR DOOR GLASS OUTER MOULDING -LH	Not Necessary	129.00 FL	*- FL
19	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,348.00	6,082.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,228.80	602.20
Total Parts (\$\$)	11,119.20	5,479.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT FRONT & REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	800.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	1,100.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	40.00
5	TO REMOE FRONT WINDSCREEN	New	180.00	120.00
6	TO TRANSFER FRONT & REAR DOOR FITTINGS	New	380.00	200.00
7	TO PERFORM DIAGNOSTIC TEST	New	150.00	100.00
Gross Labour Cost (S\$)			3,310.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >