

SS. REC. BY:

REF: CS/MKH 18006885 / (gfbn2) Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Chhin Nyuk Pui

of

MSTH

Date/Time: 13/01/2018 2:55pm

Estimated Cost:

Bill to:

OD / (TR) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIA 601T

Insured:

SIN 2335D

at Workshop n/s:

An Cheng Motor

Tel:

91117978

of

Blk 10 AMK Ind Park 2A #03-16

Policy No:

29053390MKF

Claim No:

555305

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/04/2018

CA / REV / REP. / REV 24 HRS ^{up}

20042018

H.O.D. Endorsement:

Date/Time:

13/01/2018 11:00pm

Person Contacted:

An Boon

Vehicle IN / ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate
	SIA 601T - X
	SIN 2335D - X
	Wmp Sum \$40007. (Red. 2676.94; 67%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Apr 2018		13 Apr 2018 14:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	SGRENTACAR PTE LTD, Co. Reg. No.: NA		
Main Claimant:	EY ZHAO HONG, ID: S8513360H		
Vehicle Reg. No.:	SLA601T	Date of Loss:	12/04/2018 00:00 - :59 [72 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 555305	Policy/Cover Note No.:	29053390MKF (Comprehensive) Coverage: 24/11/2017 - 23/11/2018
Vehicle Reg. No. (Insured):	SJN2335D	Policy No. (Claimant):	
		Excess:	
Repairer:	Ah Chang Motor Service Centre (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, ANG MO KIO POINT #03-16, 568047 Ang Mo Kio - Tel: 64835434		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/04/2018]		
Adj Asg. Remarks:	Third Party Pre-Repair Survey		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
<input type="checkbox"/> ALL ASSOCIATED TASKS			
		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

From: Margaret Loh margaret_loh@sg.msig-asia.com
 Subject: FW: Accident involving SJN2335D & SLA601T on 12.04.2018
 Date: April 13, 2018 at 11:05 AM
 To: MAIL@CHEONGHOH.SG
 Cc: Chhia Nyuk Pui NyukPui_Chhia@sg.msig-asia.com



Your Ref : LCH.my/AMK10-80325.18
 Our Ref : SJN2335D

Dear Sirs,

We refer to your fax dated 12.04.2018.

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

3?

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert)

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

3?

13/4/2018

CHEONGHOH LAW CORPORATION		Date:
To: Ah Chang	Fax:	
Attn: Mr. Ng	From: Margaret Loh	
(SLA 601T)		
<input type="checkbox"/>	for your records	
<input type="checkbox"/>	as per your request	
<input checked="" type="checkbox"/>	for your urgent instructions and revision	
<input type="checkbox"/>	for your information	
<input type="checkbox"/>	for your approval and return	

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 180053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number

FACSIMILE TRANSMISSION

To	: Ah Chang Motor Service Centre	Your ref no	: SLA 601 T
Attn	: Ah Chang	Your fax no	: 6484 2124
From	: Lee Cheong Hoh	Date	: 13 April 2018
Our ref no	: LCH.my/AMK10-80325.18	No. of page(s)	: one (1) (including this page)

If you have any problem with this transmission, please call us immediately. This fax is for the addressee only and may contain confidential and/or privileged information. If it has reached you in error please inform us immediately at telephone number (65) 63373700, reverse charges if necessary.

ACCIDENT INVOLVING SLA 601 T & S/N 2336 D ON 12 APRIL 2018 AT JUNCTION OF NEIL ROAD / CANTONMENT ROAD

We refer to the above matter.

In order to proceed further with our client's/your customer's claim, please forward to us the following documents:

- 1) final repair bill & receipt or excess receipt
- 2) survey report including original photographs and invoice/receipt
- 3) vehicle registration card
- 4) certificate of insurance
- 5) Idac Damage Assessment Report
- 6) COE/PARF certificate
- 7) rental agreement & receipt, if any

Kindly let us have the above documents as soon as possible to enable us to proceed with the letter of demand.

Yours faithfully

CHEONGHOH LAW CORPORATION

This is a computer-generated document and requires no signature

From: **Cheong Hoh Lee** mail@cheonghoh.sg
Subject: **Re: Accident involving SJN2335D & SLA601T on 12.04.2018; Our ref: LCH.my/AMK10-80325.18**
Date: April 13, 2018 at 2:29 PM
To: Margaret Loh margaret_loh@sg.msig-asia.com
Cc: Chhia Nyuk Pui NyukPui_Chhia@sg.msig-asia.com
Bcc: Cheonghoh Law Corporation Corporation mail@cheonghoh.sg



Dear Margaret,

We refer to the above matter and your email of even date.

Our client hereby nominate surveyor from LKK Auto Consultants Pte Ltd named in paragraph 2 serial no 1 of your said email for the pre-repair survey ("PRS") of the damages to our client's vehicle but not a single joint expert arising out of the above mentioned accident.

Please be informed that our client's vehicle, SLA 601 T is currently laying at our client's workshop, Ah Chang Motor Service Centre, Blk 10 Ang Mo Kio Industrial Park 2A, Ang Mo kio Point #03-16 Singapore 568047.

Kindly proceed to do the needful.

Regards,

Melody

Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

On Apr 13, 2018, at 11:04 AM, Margaret Loh <margaret_loh@sg.msig-asia.com> wrote:

Your Ref : LCH.my/AMK10-80325.18

Our Ref : SJN2335D

Dear Sirs,

We refer to your fax dated 12.04.2018.

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert)

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

(ACCIDENT STATEMENT FORM)

This is NOT an admission of blame / liability, but a summary of identities and facts which will speed up the settlement claim. This form is to facilitate the mobile reporting service for E-filing

Chew Goon Motor

Date of Accident	Time	Exact Location of Accident
12/04/18	1230 am	Junction of NEIL RD / Cantonment Rd

REGISTERED OWNER VEHICLE DETAILS

Registration No: SLA601T	Vehicle Make:	Model:	Colour:
Name of Registered Owner: EY ZHAO HONG	NRIC/FIN/Company Reg. No:		
Owner Contact: 83320027	Office: -	Owner Email: kaiXuan7@yahoo.com	

INSURANCE

Name of Insurance Company: NTUC	Policy No:
Policy Type: <input checked="" type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party, Fire & Theft <input type="checkbox"/> Third Party	Fleet Policy: <input type="checkbox"/> Yes <input type="checkbox"/> No
Vehicle Category: <input type="checkbox"/> Private <input type="checkbox"/> Commercial <input checked="" type="checkbox"/> Private Hire	Are you claiming your own insurance Policy for the repair of your Vehicle: <input type="checkbox"/> Yes <input type="checkbox"/> No, Reporting Only <input checked="" type="checkbox"/> No, Claim 3rd Party

DRIVER'S DETAIL

Name of Driver: AS ABOVE	NRIC/FIN/Passport No:
Driver Address:	Date of Birth:
Driver Contact:	Driver Email:
Occupation: <input type="checkbox"/> Indoor <input checked="" type="checkbox"/> Outdoor	<input type="checkbox"/> Male <input type="checkbox"/> Female
Driving Pass Date:	
Was Driver an Employee of the Insured? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Relationship of the Driver with the Insured if not an Employee: OWNER
If Yes, please state Name of Company:	

ACCIDENT DETAILS

Exact Purpose for which vehicle was being used at the time of accident: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Commercial <input type="checkbox"/> Hire & Reward <input type="checkbox"/> Others	Weather Condition: <input type="checkbox"/> Raining <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Other:
	Road Surface: <input type="checkbox"/> Wet <input checked="" type="checkbox"/> Dry <input type="checkbox"/> Other:

POLICE DETAILS

Was Accident reported to the Police? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Was Notice of Prosecution Given? <input type="checkbox"/> Yes <input type="checkbox"/> No
If Yes, please state which Police Station the report made?	If Yes, against whom?

WAS ANY OTHER VEHICLE OR PROPERTY INVOLVED?

* Registration No: SJN 2355 D	Vehicle Category: PRIVATE HIRE	Vehicle Make:	Colour:
Name of Driver: Sharon	NRIC / FIN:	Contact: 82530771	
* Registration No:	Vehicle Category:	Vehicle Make:	Colour:
Name of Driver:	NRIC / FIN:	Contact:	
* Registration No:	Vehicle Category:	Vehicle Make:	Colour:
Name of Driver:	NRIC / FIN:	Contact:	

DETAILS OF INJURED PERSON

Name of Injured Person:	Contact:	If passenger, State which Vehicle:
Conveyed to Hospital? <input type="checkbox"/> Yes <input type="checkbox"/> No	<input type="checkbox"/> Male <input type="checkbox"/> Female	Was seat belts worn? <input type="checkbox"/> Yes <input type="checkbox"/> No

WITNESS

Name of Witness:	NRIC/FIN/Passport No:
Witness Contact:	Email Address:
Is Witness a passenger or insured or third party? <input type="checkbox"/> Insured <input type="checkbox"/> Third Party <input type="checkbox"/> Independent Witness	

Declaration:

We declare that the above particulars & information provided above are true in every aspect.

Registered Owner or Driver's Signature

Video Footage: Yes or No

Total Pax (Included driver): 2

Name Of Passenger: TRACEY

Gender: Female

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 12/4/18

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12th April 2018 0030 Hrs, My veh SLA6017 was stationary waiting for the red light to turn green. I was on neil rd. Suddenly a car SJN2335D arrive behind me and hit my car.

Will repair and claim @ ACM service centre #03-16 Amk Arb point.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 12/4/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5097769219

Cover : drivo CLASSIC

- | | |
|--|---------------------|
| 1. Index mark and Registration Number of Vehicle | : SLA601T |
| Chassis Number | : WVWZZZ16ZCM100209 |
| 2. Name of Policyholder | : EY ZHAO HONG |
| 3. Effective Date of Insurance | : 29 Jan 2018 |
| 4. Expiry Date of Insurance | : 28 Jan 2019 |
| 5. Persons or Classes of Persons entitled to drive# | |
| (a) The Policyholder. | |
| (b) Any other person who is driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. | |
| 6. Limitations as to Use# | |
| (a) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business. | |

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (c) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$1,500
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: EY ZHAO HONG
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: TOKYO CENTURY LEASING (S) PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : ASSURE (SINGAPORE) PTE. LTD. (00000615327)
Date of Issue : 29 Jan 2018 16:21 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8513360H**

EY ZHAO HONG

Birth Date: **03 May 1985**

Issue Date: **22 Apr 2008**

001594767C




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

Class 3 **Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg**

PASS DATE **24 Mar 2006**

Licence No: **S8513360H**



NP 428A

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8513360H




Name: **EY ZHAO HONG**

Race: **CHINESE**

Date of birth: **03-05-1985**

Country/Place of birth: **SINGAPORE**

Sex: **M**




S630333



NRIC No: **S8513360H**

Date of Issue: **02-08-2016**



APT BLK 784C WOODLANDS RISE #11-40
SINGAPORE 733784

NRIC No: **S8513360H** Date: **26/08/2017 (R)**

Enquire PARF/COE Rebate for Registered Vehicle


Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3360H
Vehicle Details	
Vehicle No.:	SLA601T
Vehicle to be Exported:	No
Intended De-registration Date:	25 Apr 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA 1.4 TSI AT 1623Q5
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	CAV369807
Chassis No.:	WVWZZZ16ZCM100209
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$24,647.00
Original Registration Date:	12 Apr 2012
First Registration Date:	12 Apr 2012
Transfer Count:	1
Actual ARF Paid:	\$24,647.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Apr 2022
PARF Rebate Amount:	\$16,020.00
Intended COE Rebate Details	
COE Expiry Date:	11 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$52,809.00
COE Rebate Amount:	\$20,930.00
Total Rebate Amount:	\$36,950.00

The information contained herein is correct as at 25 Apr 2018

OK

▶ Jetta Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabl
Volkswagen Jetta 1.4A TSI	\$50,800	\$10,780 /yr	16-Jan-2012	1,390 cc	96,000 km	Hua Yang Credit Pte Ltd	Availat
Beautiful Interior And Exterior Conditions Taken Care Of By 1 Owner. Low Mileage Down, Smooth And Responsive Transmission For Excellent Fuel Efficiency Equip With Enhance Body Material For Extra Safe... Office No. - 64545111 Dominic Tan - 94230390 Edison Ng - 82698288							
Volkswagen Jetta 1.4A TSI	\$46,500	\$8,970 /yr	14-Feb-2012	1,390 cc	-	Wunder Auto Pte Ltd	Availat
1 Owner, The Most Reliable And Fuel Efficient Sedan With A New Set Of Eibach Spring, Bilstein Shock Absorbers And Michelin Pilot Sport 4 Tyre. Well Maintained By Previous Owner. In Excellent Condition... Office No. - 63838222 Thomass Ang - 97688222 Carol Koh - 90695887 Joe Chen - 94278222							
Volkswagen Jetta Sport 1.4A TSI	\$48,800	\$9,490 /yr	27-Feb-2012	1,390 cc	93,339 km	Cosmo Automobiles	Availat
1 Year Comprehensive Warranty Inclusive! \$3K Down Payment! STA Certified Accident Free Quality Pre Owned With Low Mileage And Full Agent Service History For Peace Of Mind. 100% Loan Approval With Our ... Office No. - 64632995 David - 81216660 Sam - 97926962 Winfield - 98227717 Andy - 98502116							
Volkswagen Jetta 1.4A TSI	\$46,800	\$9,710 /yr	29-Feb-2012	1,390 cc	94,935 km	Tim Bock Enterprise	Availat
Cheapest In The Market! Lowest Depreciation! The Most Reliable And Fuel Efficient Sedan. Reliable! Well Maintained By Previous Owner. In Excellent Condition. Trade In Welcomed. Call Us To Test Drive N... Office No. - 64595611 Raymond - 91596282 Richard - 98197977							
Volkswagen Jetta 1.4A TSI	\$53,800	\$10,890 /yr	13-Apr-2012	1,390 cc	86,000 km	Car Search	Availat
Well Maintained By Meticulous Owner! Sparkling STA Evaluation Welcome! Drive With A Peace Of Mind! Flexible Loan Packages, Trade In Welcome. Consignment Car, Viewing By Appointment Only. Office No. - 62620728 Rachel - 91126538 Kelvin - 97593539 Brandon - 94222654 Daryl - 98186406							
Volkswagen Jetta 1.4A TSI	\$47,800	\$9,270 /yr	30-Apr-2012	1,390 cc	104,504 km	Benefit Auto Enterprise Pte Ltd	Availat
New Arrival, 1 Owner Only, Dark Grey Color, Very Well Maintained Engine Conditions, Various Loan Easily Arrange, Cash Deal Non-Penalty, Buy With A Peace Of Mind From A Company Accredited With Good Cre... Office No. - 68444161 Kevin - 90268203 Ben Neo - 92222719 Aris Sidek - 91086131							
Volkswagen Jetta 1.4A TSI	\$45,000	\$8,560 /yr	03-May-2012	1,390 cc	-	Splendid Automobile Pte Ltd	Availat
Fully Serviced At Volkswagen, Lady Owner. Mint Condition, 100% Accident Free! Selling At Low Depreciation And Fuel Consumption Friendly! High Trade Available, Low Down Payment, Cheap Insurance Prem... Office No. - 69085055 Aloysius - 87485055 Ivan - 88685055							
Volkswagen Jetta Sport 1.4A TSI	\$48,800	\$8,660 /yr	12-Jul-2012	1,390 cc	-	Auto Zoom Enterprise Pte Ltd	Availat
Immaculate Condition. High Loan/Low Downpayment Available. Midnight Blue Paintwork With Black Leather Interior. Comes With GPS And Front Recording Camera. 38 More BHP Than Standard Jetta. Contact Us F... Office No. - 63421000 Francis - 81014919 Robin - 97603335 Jeff - 90041167 Daniel - 82220489							
Volkswagen Jetta Sport 1.4A TSI	\$61,500	\$11,420 /yr	23-Aug-2012	1,390 cc	105,390 km	Top Marque Auto	Availat
Facelifted By Current Owner To GLI Aesthetic Spec! A Car That Offers Both Power And Fuel Economy With It Buzzy 1.4L TSI Engine. Genuine Mileage							




91117978

AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SLA 601T Volkswagen

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear Bumper Assembly /	\$ 778.90 DD
2	1	Rear Bumper Reinforcement X NN	\$ 425.80
3	2	Rear Bumper Bracket 1pc /	\$ 58.2 116.40 DD
4	2	Rear Bumper Retainer 1pc /	\$ 59.20 118.40 DIS
5	1	Rear Bumper Inner Beam /	\$ 233.40 DD
6	1	Rear Bumper Right Reflector X	\$ 116.80
7	1	Rear Bumper Left Reflector X	\$ 116.80
8	1	Rear Bumper Left Lower Cover X	\$ 169.00
9	1	Rear Bumper Right Lower Cover X X	\$ 169.00
10	1	Rear Bumper Lower Pad /	\$ 757.10 CRA
11	1	Rear Left Tail Lamp /	\$ 599.70 CRA
12	1	Rear Right Tail Lamp /	\$ 599.70 CRA
13	1	Rear Bootlid Assembly Repair.	\$ 1,633.50
14	1	Rear Bootlid Centre Logo /	\$ 125.80
15	1	Rear Bootlid Jetta Emblem /	\$ 86.50
16	1	Rear Bootlid TSI Emblem /	\$ 85.60
17	2	Rear Bootlid Hinges X	\$ 170.00 NN
18	1	Rear Bootlid Lock Mechanism X	\$ 125.50 NN
19	1	Rear Bootlid Weather Strip /	\$ 188.90 CUT
20	1	Rear Bootlid Left Tail Lamp X	\$ 360.20
21	1	Rear Bootlid Right Tail Lamp X	\$ 360.20
22	1	Rear Bootlid Inner Board X	\$ 238.00
23	1	Rear Bootlid Lock Catch X	\$ 68.60
24	1	Rear Bootlid Lock Switch X	\$ 220.10
25	2	Rear Number Plate Lamp X	\$ 120.00
26	1	Rear End Lower Panel Repair.	\$ 990.40
27	1	Rear End Lower Panel Top Garnish /	\$ 125.30 CRA
28	1	Rear Spare Type Top Cover X	\$ 197.00 NN
			\$ 9,296.60
Less 10%			\$ 929.66
			\$ 8,366.94




AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SLA 601T Volkswagen

<u>No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Estimated Parts Price</u>
<u>Special Nett Items</u>			
1	10	Rear Bumper Clips /	\$ 50.00 NEC
2	6	Rear End Lower Panel Top Garnish Clips /	\$ 30.00 NEC
3	1	Rear End Lower Panel Sealant X	\$ 120.00 } *N
4	10	Rear Bootlid Inner Board Clips X	\$ 30.00
5	2	Rear Bumper Reverse Sensor X ✓ short	\$ 200 300.00
6	10	Rear Bumper Lower Pad Clips /	\$ 40.00 NEC
7	1	Rear Number Plate With Garnish X	\$ 120.00 NN
			<hr/> \$ 690.00 <hr/>



AH CHANG MOTOR SERVICE CENTRE

Bik 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

SLA 601T Volkswagen

<u>No</u>	<u>Qty</u>	<u>Labour Description</u>	<u>Labour Charge</u>
1		To apply anti rust proofing to rear affected area	\$ X 120.00
2		Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts	\$ ⁵⁰⁰⁺¹⁰⁰ 1,400.00
3		To putty and spray painting rear portion	\$ ⁶⁰⁰ 1,400.00
4		To check rear lighting and wiring	\$ ³⁰ 50.00
5		To removed and install rear bootlid lock mechanism	\$ ²⁰ 80.00
6		To remove and install rear bumper reverse sensor	\$ ⁴⁰ 80.00
7		To repair, straighten and align both rear fender panel	\$ X 350.00
8		To remove and install rear inner trim and garnish to facilitate the repair	\$ ⁶⁰ 140.00

5 ~~4~~ Days.

Lumpsum Repair.

After repair photos.

Erico Qiang - 82880282

23/4/18. 7pm.

\$ 3,620.00

Total Parts \$ 9,056.94

Total Labour \$ 3,620.00

Total Repair Cost \$ 12,676.94

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006885/GTBN2
Date: 01/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29053390MKF
Claimant Vehicle No :	SLA601T	Insured Vehicle No :	SJN2335D
Date of Loss:	12/04/2018	Nature of Claim:	TP
			Claim No: 555305

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA601T	Engine No:	CAV369807
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI (A)	Chassis No:	WWWZZZ16ZCM100209
Reg. Date:	12/04/2012 (Man. Year: 2012)	Odometer:	138445 km
Colour:	Blue		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 ZR17	Rear Tyre Size:	225/45 ZR17
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 6 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,056.94	3,648.47	5,408.47	59.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	1,350.00	2,270.00	62.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,676.94	4,998.47	7,678.47	60.57
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	12,676.94	4,000.00	8,676.94	68.45
+ GST 7.00/7.00% (S\$)	887.39	280.00	607.39	68.45
Nett Amount (S\$)	13,564.33	4,280.00	9,284.33	68.45

INSPECTION

Date of Assignment:	13/04/2018	
Date Inspected:	23/04/2018 Inspected At:	Ah Chang Motor Service Centre (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, ANG MO KIO POINT #03-16 Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Aug 2018)
Parts: 143	VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA601T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSEMBLY	Dented	778.90 FL	*778.90 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	425.80 FL	*- FL
3	1		*REAR BUMPER BRACKET	Dented (1 Pc only)	116.40 FL	*58.20 FL
			(2 Pcs)			
4	1		*REAR BUMPER RETAINER	Distorted (1 Pc only)	118.40 FL	*59.20 FL
			(2 Pcs)			
5	1		*REAR BUMPER INNER BEAM	Dented	233.40 FL	*233.40 FL
6	1		*REAR BUMPER RIGHT REFLECTOR	Not Necessary	116.80 FL	*- FL
7	1		*REAR BUMPER LEFT REFLECTOR	Not Necessary	116.80 FL	*- FL
8	1		*REAR BUMPER LEFT LOWER COVER	Not Necessary	169.00 FL	*- FL
9	1		*REAR BUMPER RIGHT LOWER COVER	Not Necessary	169.00 FL	*- FL
10	1		*REAR BUMPER LOWER PAD	Cracked	757.10 FL	*757.10 FL
11	1		*REAR LEFT TAIL LAMP	Cracked	599.70 FL	*599.70 FL
12	1		*REAR RIGHT TAIL LAMP	Cracked	599.70 FL	*599.70 FL
13	1		*REAR BOOTLID ASSEMBLY	Repair	1,633.50 FL	*- FL
14	1		*REAR BOOTLID CENTRE LOGO	Necessary	125.80 FL	*125.80 FL
15	1		*REAR BOOTLID JETTA EMBLEM	Necessary	86.50 FL	*86.50 FL
16	1		*REAR BOOTLID TSI EMBLEM	Necessary	85.60 FL	*85.60 FL
17	2		*REAR BOOTLID HINGES	Not Necessary	170.00 FL	*- FL
18	1		*REAR BOOTLID LOCK MECHANISM	Not Necessary	125.50 FL	*- FL
19	1		*REAR BOOTLID WEATHER STRIP	Cut	188.90 FL	*188.90 FL
20	1		*REAR BOOTLID LEFT TAIL LAMP	Not Necessary	360.20 FL	*- FL
21	1		*REAR BOOTLID RIGHT TAIL LAMP	Not Necessary	360.20 FL	*- FL
22	1		*REAR BOOTLID INNER BOARD	Not Necessary	238.00 FL	*- FL
23	1		*REAR BOOTLID LOCK CATCH	Not Necessary	68.60 FL	*- FL
24	1		*REAR BOOTLID LOCK SWITCH	Not Necessary	220.10 FL	*- FL
25	2		*REAR NUMBER PLATE LAMP	Not Necessary	120.00 FL	*- FL
26	1		*REAR END LOWER PANEL	Repair	990.40 FL	*- FL
27	1		*REAR END LOWER PANEL TOP GARNISH	Cracked	125.30 FL	*125.30 FL
28	1		*REAR SPARE TYRE TOP COVER	Not Necessary	197.00 FL	*- FL
29	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
30	6		*REAR END LOWER PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
31	1		*REAR END LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
32	10		*REAR BOOTLID INNER BOARD CLIPS	Not Necessary	30.00 FS	*- FS
33	2		*REAR BUMPER REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
34	10		*REAR BUMPER LOWER PAD CLIPS	Necessary	40.00 FS	*40.00 FS
35	1		*REAR NUMBER PLATE WITH GARNISH	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 9,986.60 4,018.30
 - List Item Discount on L Items 10.00/10.00% (\$\$) 929.66 369.83

Total Parts (\$\$) 9,056.94 3,648.47

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	-
2	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS	New	1,400.00	600.00
3	TO PUTTY AND SPRAY PAINTING REAR PORTION	New	1,400.00	600.00
4	TO CHECK REAR LIGHTING AND WIRING	New	50.00	30.00
5	TO REMOVED AND INSTALL REAR BOOTLID LOCK MECHANISM	New	80.00	20.00
6	TO REMOVED AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	40.00
7	TO REPAIR,STRAIGHTEN AND ALIGN BOTH REAR FENDER PANEL	New	350.00	-
8	TO REMOVE AND INSTALL REAR INNER TRIM AND GARNISH TO FACILITATE THE REPAIR	New	140.00	60.00
Gross Labour Cost (S\$)			3,620.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >