

ASS. REC. BY:

REF: CS/FCL1800 69114 / A vlon2

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

CWS

Eileen Lee

of

FCL

Date/Time:

13.04.2018 6:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 4945H

Insured:

SHD 6718H

at Workshop m/s

Yi Heng Motor

Tel:

6509 0052

of

Blk 1 Kaki Bukit Ave 6 #02-19

Policy No:

Claim No:

D18001717MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

26.02.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpa

16.04.2018

H.O.D. Endorsement:

Date/Time:

13.04.2018

Person Contacted:

Wan Pong

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GY 4945H - X
	SHD 6718H - CS/FCL1702430/Andse1 DA: 25/17
17/4/18	Informed FCI pending workshop est by email
24/4/18	Adrian confirmed LS \$2250 (Ref 3040.35, 5910)
24/4/18	Email preli revised to FCI

REF: FCL

ASSIGNMENT

From: Date: 16042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no:

of:

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh.:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$17K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lump Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle IN / OUT

Veh No:

G Y 4945H

Yr Regn:

2005 April

Type: M Car / M Cycle / Bus / Van / Con / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

cc 2986

Colour:

Blue

A/C

Insured / Std / NI / NA

Sp Reading:

498856

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFUF34Y003010471

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size

F: 185R14C

R: 155R12C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

06

mm

R/Bal:

06

mm

L/Bal:

06

mm

L/Bal:

06

mm

D.O.A.

D.O.I.

16/04/18

Survey held at

Yi Heng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

COE Exping: 27/04/20.

Note:

MV: \$17K (EST)

LTA: \$11,276

NV: \$5724

RECEIVED 24 APR 2018

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

24/4 - typist

Days Of Repair:

4

Resurvey No. of Trip:

—

Survey Fee:

Transportation:

1. \$ + RT \$

2. Photo

3. Other

4. TOTAL

TOTAL

Report Format:

CWS

Lump Sum / I.B. / I.S.

22502

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Wheel and (\$

140

50

11

201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18006914/Avb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 14-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6718H	Veh. Inspected	GY 4945H
Policy No.		Coverage (\$)	0.00
Claim No.	D18001717MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	13/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/02/2018	Inspection Date	16/04/2018
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18001717MFSH
Our ref: CS/FCI18006914/Avb

Date : 24/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GY 4945H


We thank you for your instruction on 13/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/4/2018 at the premises of M/s YI HENG MOTOR WORKSHOP and have the following to report:-

Workshop Estimate Amount	: S\$5,490.35
Revised Estimate Amount	: S\$2,250.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s poriton



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	28-02-2018	Our Ref No. D18001717MFSH
Accident Date	26-02-2018	Claim Type. Third Party
Insured Vehicle	SHD6718H	Third Party Vehicle. GY4945H
Survey Location	BLK 1 KAKI BUKIT AVENUE 6 #02-19	
Contact Person.	WAN PING	
Contact No.	65090052/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE: NO EST. PROVIDED *	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	YI HENG MOTOR WORKSHOP	Attention. NIL
Cc : TP Solicitor	VISION LAW LLC	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 24 April 2018 4:50 PM
To: 'Claim Workflow System'
Cc: 'EILEENLEE@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18001717MFSH/1, GY 4945H
Attachments: GY 4945H PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GY 4945H
Date of survey: 16/4/2018
Number of days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 17 April 2018 8:11 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001717MFSH/1, GY 4945H

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GY 4945H on 16/4/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Saturday, 14 April 2018 12:29 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001717MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Friday, 13 April, 2018 6:02 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18001717MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 17 April 2018 8:11 AM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001717MFSH/1, GY 4945H

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GY 4945H on 16/4/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Saturday, 14 April 2018 12:29 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18001717MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 13 April, 2018 6:02 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18001717MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Lexus IS Turbo 15200t Executive



Low Mileage! Almost Brand New
Cordibright
Direct Owner - StarAd



**CERTIFIED PRE-OWNED
MERCEDES-BENZ**

[View our cars](#)

[Browse by Category](#)
[« Back \(1 2 3 4 \) Next »](#)
[Sort by Date Posted](#)
[20 results/page](#)

67 vehicles

Dyna

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Dyna		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota	Dyna 150 (COE till 03/2020)	\$18,800	\$9,710 /yr	04-May-2005	2,986 cc	-	Truck	Available
Fuel Type: Diesel 1 Owner Only, Previous Owner Retired, Super Good Original Condition, No Need Repair, Cheapest In Town, Price Negotiable, High Loan With Lowest Interest Rate Available, High Trade In, Call Now! ABWIN Bus Pte Ltd Posted: 24-Apr-2018 Tags: 2005 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
	Toyota	Dyna 150 (COE till 07/2020)	\$21,800	\$9,890 /yr	08-Jul-2005	2,986 cc	-	Truck	Available
Fuel Type: Diesel Cheapest In Town! Tip Top Condition, Well Maintained, New Road Tax, High Loan Available, Trade In Welcome, Price Negotiable And Call Us For Viewing Or Test Drive Now! ABWIN Bus Pte Ltd Posted: 03-Apr-2018 Tags: 2005 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
	Toyota	Dyna 150 (COE till 07/2020)	\$20,800	\$9,180 /yr	30-Jul-2005	2,986 cc	-	Truck	Available
Fuel Type: Diesel 2 Owners 10 Feet Lorry, Cheapest Dyna In The Market, Super Low Interest Rate Available, 0% Down Payment Can Be Arranged, Call Us For A Discussion Now! Posted: 02-Apr-2018 Tags: 2005 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
	Toyota	Dyna 150 (COE till 08/2020)	\$24,800	\$10,830 /yr	08-Aug-2005	2,986 cc	-	Truck	Available
Fuel Type: Diesel Please Call In Advance Before Viewing. Thanks. Posted: 21-Mar-2018 Tags: 2005 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
Car Buying Car Selling Car Ownership Car Aftermarket On The Move Lifestyle Buy Tyres Online! Latest Special Offers from Tyrepack!									
	Toyota	Dyna 150 (COE till 10/2020)	\$20,800	\$8,430 /yr	12-Oct-2005	2,986 cc	-	Truck	Available
Fuel Type: Diesel 1 Careful Owner, Regular Servicing, Just Pass Inspection, Tip Top Condition, 100% Loan At 4 %, Trade In Welcome. Posted: 09-Apr-2018 Tags: 2005 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
	Toyota	Dyna 150 (COE till 11/2020)	\$18,800	\$7,350 /yr	14-Nov-2005	2,986 cc	167,000 km	Truck	Available
Fuel Type: Diesel Entitle To ETS, 1 Owner Cheapest In Town, New Paint Work And Leather Seat, No Need Repairs, Regular Servicing Done, Good Condition And Well Maintenance, Price Negotiable, High Loan With Lowest Interest... Posted: 19-Apr-2018 Tags: 2005 Toyota Dyna, Toyota Dyna, Toyota, Dyna, Used Toyota									
Compare	Toyota	Dyna 150 (COE till	\$23,800	\$8,710 /yr	16-Jan-2006	2,986 cc	-	Truck	Available

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 5428H

Vehicle Details

Vehicle No.: GY4945H

Vehicle to be Exported: Yes

Intended De-registration Date: 13 Apr 2018

Vehicle Make: TOYOTA

Vehicle Model: DYNA 150 D

Primary Colour: Blue

Manufacturing Year: 2005

Engine No.: 5L5582537

Chassis No.: JTFUF34Y003010471

Maximum Power Output: -

Open Market Value: \$23,690.00

Original Registration Date: 28 Apr 2005

First Registration Date: 28 Apr 2005

Transfer Count: 2

Actual ARF Paid: \$11,185.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 27 Apr 2020

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 5

PQP Paid: \$27,653.00

COE Rebate Amount: \$11,276.00

Total Rebate Amount: \$11,276.00**Message**

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 13 Apr 2018

OK

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

13-04-18

OUR REF NO. GY 4945H

SING HUAT MING ELETRONICS PTE LTD
NO 15, DEFU AVE 1
SINGAPORE 539538

TP 1st CAP
Veron.

JTFUF34Y003010471

ESTIMATE BILL FOR VEHICLE NO. GY 4945H MODEL : TOYOTA DYNA 150 D

LIST ITEM

1) SIDE GATE (LH)	Dented.		1,837.00
2) SIDE GATE HINGE PIN (LH)	2 pieces But	5 PCS @ \$ 184.00	920.00 122.80
3) SIDE GATE LOWER PANEL (LH)	Dented		987.00 650
4) SIDE GATE LOWER PANEL HOOK (LH)		4 PCS @ \$ 40.20 2 pieces But	160.80 80.40
5) REAR WHEEL FRONT MUDGUARD (LH)	Dented		422.00 233.10
6) REAR WHEEL REAR MUDGUARD (LH)	Repair		311.00 x.
			4,637.80
			1,159.45
			3,478.35

SPECIAL NETT ITEM

1) REAR TYRE	new	182.00 x.
		182.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM	50.00 3.0
2) TO APPLY UNDER SEALING ON AFFECTED AREAS	120.00 x
3) TO REMOVE AND REFIX SIDE GATE STEEL GUARD	220.00 100
4) TO CONDUCT 4 WHEEL ALIGNMENT	120.00 x.
5) TO REPLACE NEW PARTS,CUT,WELD,KNOCK AND ETC	660.00 400
6) TO RESPRAY ON AFFECTED AREAS	660.00 400

GRAND TOTAL

1,830.00
5,490.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2838.55
H/s: 2250.

Adrian Lj
H/s 16/04/18.
04 sup.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006914/Avbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6718H	Veh. Inspected	GY 4945H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18001717MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	13/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2005	
Chassis No.	JTFUF34Y003010471	Colour	BLUE	
Odometer	498856	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14C	MICHELIN	6 mm	
L/H Front Tyre	185 R14C	MICHELIN	6 mm	
R/H Rear Tyre	155 R12C	MICHELIN	6 mm	
L/H Rear Tyre	155 R12C	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/02/2018	Inspection Date	16/04/2018	
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 4945H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SIDE GATE (LH)	DENTED	1,837.00	1,485.10
5	SIDE GATE HINGE PIN (LH) @\$184.00	BENT (2 PCS ONLY)	920.00	122.80
1	SIDE GATE LOWER PANEL (LH)	DENTED	987.00	650.00
4	SIDE GATE LOWER PANEL HOOK (LH) @\$40.20	BENT (2 PCS ONLY)	160.80	80.40
1	REAR WHEEL FRONT MUDGUARD (LH)	DENTED	422.00	233.10
1	REAR WHEEL REAR MUDGUARD (LH)	TO REPAIR SEE LABOUR	311.00	-
	LESS 25% DISCOUNT		-1,159.45	-642.85
			3,478.35	1,928.55
SPECIAL NETT ITEMS				
1	REAR TYRE (SN)	NOT NECESSARY	182.00	-
			182.00	-
LABOUR				
	TO CHECK WIRING SYSTEM.		50.00	30.00
	TO APPLY UNDER SEALING ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX SIDE GATE STEEL GUARD.		220.00	100.00
	TO CONDUCT 4 WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO REPLACE NEW PARTS,CUT,WELD,KNOCK AND ETC.INCLUSIVE OF THE REPAIR OF REAR WHEEL REAR MUDGUARD (LH).		660.00	400.00
	TO RESPRAY ON AFFECTED AREAS.		660.00	400.00
			1,830.00	930.00
GRAND TOTAL			5,490.35	2,858.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CS/FCI18006914/Avbn2

MARKET VALUE: \$17,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$11,276.00=NETT VALUE: \$5,724.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.