

15/5/2010

INS. CASE OWNER:

CC 6/CTI1800 6644, 4m67n2

LKK:

IDAC:

Surveyor:

MARINS

DOI:

ASSIGNMENT

6644/18

Date / Time:

16/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

G7 91594

Claim No.:

SNM187199002

Name of Insured:

BROADWAY CONTRACTS & SERVICES

Policy No.:

MCVSN1667611701

Insured Tel No.:

HP:

Make / Model:

F14

Excess Sec II :SS

D.O.A.:

14/4/18

Place of Accident:

COMMONWEALTH AVE WEST TO
WEMENTI AVE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LIAM WAI MING EDMUND

OI GIA REPORT: YES

NO

TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLA 7776B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

20/4/18
LIAM

SLA 7776B - X

G7 91594 - X

old record TP. later sent to OI

18.10.18

FILE PASS TO TYPIST TO PREPARE REPORT.

RECEIVED 10 OCT 2018

RECEIVED 02 JAN 2019

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 27.04.18

Confirm with: LIAM

Confirm by: CKS

Repair Cost:

43 \$57,200

(6 days)

Reduction:

61 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 28.11.18

Confirm with: JASON

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

WLS:

\$57,151.50

Loss of Rental (LOR):

\$5 800.00

(5 days)

x 160

Loss of Use (LOU):

\$5 -

(\$ x days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$52.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost:

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

9400

Total:

\$58,559.50

Global Sum \$5:

FINAL PAYMENT

Date/Time: 28.11.18

Confirm with: JASON

Email ☐ Call ☐

Payee 1:

\$58,559.50

Name 1:

FASTTECH AUTO PRE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

(08/11/13) Wei

ASS. REC. BY: MORIS

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 77763at Workshop m/s fr.

of _____

Insured: 6791594

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 31k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

(A / PR Seen:) 4 Consistent? : Yes or NoEst. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLA 77763 Yr Regn: 18/11 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Honda accord c.c. 2354Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 178737 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHCP263082020493

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 14/4/18 D.O.I. 15/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
27/4/18	Confirmed 1/5 & 7250 with Mr. LTA 20620 14.7m. Sep 10k.

(RED: 11,243.70 6%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) ☐ : Final Report

Resurvey No. of Trlp: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ - RS - SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI18006994/Umb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 16-04-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 9159Y	Veh. Inspected	SLA 7776B	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	16/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/04/2018	Inspection Date	16/04/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



ANNOUNCING Universe Motoring as sgCarMart Premium Dealer 2018

UNIVERSE

MOTORING

Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Asking \$29.8K! 12/2009 Nissan Teana. Brand New Cond



Selling At \$7k+ Depreciation. All
Wear & Tears Replaced. Like
New Cond. \$ Nego.
Direct Owner StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD








Browse by Category

Sort by Date Posted 20 results/page

11 vehicles

Honda Accord

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Accord		Any	Any	2009	Any	Any	Any	Available
	Honda Accord	2.0A	\$29,800	\$11,560 /yr	10-Jun-2009	1,997 cc	102,000 km	Luxury	Available
Luxury And Spacious Sedan, Well Serviced And Maintained By Previous Owner, Original Condition, Flexible Loan High OMV \$33066, Low Depreciation, Interior Well Kept, Low Cost Maintenance, Reliable Japan...									
Posted: 16-Apr-2018 Tags: 2009 Honda Accord, Honda Accord, Honda, Accord, Used Honda									
	Honda Accord	2.4A	\$23,800	\$8,990 /yr	20-Jan-2009	2,354 cc	-	Luxury	Available
Super Low Depreciation! Less Than \$9K For Accord 2.4 A. 1 Owner Only! Well Maintained, Excellent Condition! Minimum Down Payment With Bank Or In House Loan Available. Call For More Enquiries!									
Posted: 15-Apr-2018 Tags: 2009 Honda Accord, Honda Accord, Honda, Accord, Used Honda									
	Honda Accord	2.4A	\$24,800	\$9,720 /yr	16-Mar-2009	2,354 cc	116,000 km	Luxury	Available
1 Owner, Super Well Kept, Best Short Term Car, Power And Comfort All In This Beautiful Accord, Whats Best Is This Car Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In ...									
Posted: 14-Apr-2018 Tags: 2009 Honda Accord, Honda Accord, Honda, Accord, Used Honda									
	Honda Accord	2.4A	\$32,998	\$10,660 /yr	20-Nov-2009	2,354 cc	138,618 km	Luxury	Available
New Road Tax! Balloon Scheme Available! Low Monthly Installment \$710! Tip Top Conditions! Servicing Just Done! Most Of The Wear And Tear Parts Replaced! View To Believe! Down Payment \$5,998 Easy Appro...									
Posted: 06-Apr-2018 Tags: 2009 Honda Accord, Honda Accord, Honda, Accord, Used Honda									
	Honda Accord	2.0A	\$23,500	\$10,860 /yr	07-Apr-2009	1,998 cc	212,600 km	Luxury	Available
Good Condition, Well Maintained. In-house Finance Available At Low Interest Rate, Trade In Is Available. Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome!									
Think One Automobile & Trading									
Posted: 04-Apr-2018 Tags: 2009 Honda Accord, Honda Accord, Honda, Accord, Used Honda									
	Honda Accord	2.4A	\$32,800	\$10,880 /yr	04-Nov-2009	2,354 cc	109,867 km	Luxury	Available
Luxury Sedan With Spacious Interior To Drive Away! Fancy For A Powerful Drive With Low Depreciation For Such A High End Car Do Look Here! Low Down Payment Available! In House/Bank Loan All Are Welcome...									
Posted: 04-Apr-2018 Tags: 2009 Honda Accord, Honda Accord, Honda, Accord, Used Honda									
	Honda Accord	2.4A	\$24,800	\$8,260 /yr	02-Mar-2009	2,354 cc	130,000 km	Luxury	Available
Well Kept Condition. No Repairs Needed. High Perf Value Of \$17,578. New 6 Months Road Tax. Spacious & Comfortable Ride. Call Now For A Non Obligatory Discussion. Loan Can Be Arranged. Trade In Welcome...									
Posted: 02-Apr-2018 Tags: 2009 Honda Accord, Honda Accord, Honda, Accord, Used Honda									

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

[Buy Tyres Online!](#)
[Latest Special Offers from Tyrepack!](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	6565B

Vehicle Details

Vehicle No.:	SLA7776B
Vehicle to be Exported:	No
Intended De-registration Date:	16 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	ACCORD 2.4L
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	K24Z21957496
Chassis No.:	MRHCP26308P020493
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$31,866.00
Original Registration Date:	18 Nov 2009
First Registration Date:	18 Nov 2009
Transfer Count:	1
Actual ARF Paid:	\$31,866.00 15-933

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Nov 2019
PARF Rebate Amount:	\$17,526.00

Intended COE Rebate Details

COE Expiry Date:	17 Nov 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,510.00
COE Rebate Amount:	\$3,094.00
Total Rebate Amount:	\$20,620.00

The information contained herein is correct as at 16 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 6565B

Vehicle Details

Vehicle No.: SLA7776B
Vehicle to be Exported: Yes
Intended De-registration Date: 16 Apr 2018
Vehicle Make: HONDA
Vehicle Model: ACCORD 2.4L
Primary Colour: Grey
Manufacturing Year: 2008
Engine No.: K24Z21957496
Chassis No.: MRHCP26308P020493
Maximum Power Output: 133.0 kW (178 bhp)
Open Market Value: \$31,866.00
Original Registration Date: 18 Nov 2009
First Registration Date: 18 Nov 2009
Transfer Count: 1
Actual ARF Paid: \$31,866.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 17 Nov 2019
PARF Rebate Amount: \$17,526.00

Intended COE Rebate Details

COE Expiry Date: 17 Nov 2019
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$19,510.00
COE Rebate Amount: \$3,094.00
Total Rebate Amount: \$20,620.00

The information contained herein is correct as at 16 Apr 2018

OK



Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960****ROAD TRANSPORT ACT, 1987 (MALAYSIA)****MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Policy No.: 17-MV010453-R01 (Private Motor Car)

1. Index Mark and Registration Number of Vehicle SLA7776B Chassis No.: MRHCP26308P020493
2. Name of Policyholder MR TAN ZEH CHIAH
3. Effective date of the Commencement of Insurance for the purposes of the Act 19/11/2017
4. Date of Expiry of Insurance 18/11/2018
5. Persons or Class of Persons entitled to drive*
 - (a) The Policyholder.
 - (b) Any other person who is driving on the Policyholder's order or with his permission.

* Provided that the Person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please refer to the Policy Schedule for full details, terms and conditions of the insurance.

IMPORTANT NOTICE

This Certificate is not transferable. During its currency, if the insurance is cancelled for whatsoever reason, you must return the Certificate to Tokio Marine Insurance Singapore Ltd. within 7 days thereof or, if the Certificate has been lost destroyed, you must make a statutory declaration to that effect. Failure to comply with this duty is an offence under Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).

ADDITIONAL INFORMATION

Account: 0896DDB

Insurance Plan:	Comprehensive Approved Workshop Plan	
Limit for total loss or theft:	Prevailing Market Value	
Policy Excess:	Own Damage Claims	SGD 1,500
	Windscreen Excess	SGD 100
Financial Interest:	KENSO LEASING PTE LTD	

Tokio Marine Insurance Singapore Ltd.

Authorised Signature

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S7246565B



Name

TAN ZEH CHIAH
(CHEN ZIJIA)

陈子佳

Race

CHINESE



Date of birth

08-12-1972

Sex

M

S7246565B

Country/Place of birth

SINGAPORE

5182127



NRIC No. S7246565B



Date of issue

14-06-2013

Address

APT BLK 536 BUKIT BATOK STREET 52
#09-653
SINGAPORE 650536

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S7246565B**

Name

TAN ZEH CHIAH
(CHEN ZIJIA)

Birth Date: 08 Dec 1972

Issue Date: 22 Aug 2003



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(es)

Class 2B Motorcycles not exceeding 200 cc
Class 2A Motorcycles between 201 cc and 400 cc
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

27 Feb 1990
26 May 1995
31 Aug 1993



Licence No: S7246565B

NP 428A

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-48 AUTOBAY
SINGAPORE 417883

N. of Arthur
R. R.
a/s 7250
6dy,
16/4/18

VEHCILE NO:SLA 7776B

QTY	PARTICULAR	AMOUNT
1 PCS	BOOTLID	5045.00 \$921.20 ✓
1 PCS	BOOTLID 'H' LOGO	rec \$35.00 ✓
1 PCS	BOOTLID 'ACCORD' EMBLEM	rec \$38.20 ✓
1 PCS	BOOTLID '2.4' EMBLEM	rec \$30.50 ✓
1 PCS	BOOTLID 'IVTEC' EMBLEM	rec \$46.00 ✓
1 PCS	BOOTLID OUTER GARNISH	320 \$485.20 ✓
1 SET	BOOTLID OUTER GARNISH CLIPS	11 \$30.00 ✓
2 PCS	BOOTLID REFLECTORS @\$265.30	one \$530.60 ✓
1 PCS	BOOTLID INNER LOCK	twi \$266.50 ✓
1 PCS	BOOTLID WEATHERSTRIP 185.20	twi \$292.30 ✓
1 PCS	BOOTLID INNER TRIM	Del/Torn \$288.50 ✓
1 SET	BOOTLID INNER TRIM CLIPS	122 \$35.00 ✓
1 PCS	REAR BUMPER	11.5 \$766.30 ✓
1 PCS	REAR BUMPER LOWER SPOILER 620.	11.5 \$820.50 ✓
2 PCS	REAR BUMPER RETAINERS @\$30.50	3rd \$61.00 ✓
1 PCS	REAR BUMPER BEAM	3rd \$182.30 ✓
4 PCS	REAR BUMPER PDC SENSOR @\$225.00	Shut \$900.00 2pcs ✓
1 PCS	REAR END PANEL 485.20	5.0dy.00 \$588.20 ✓
1 PCS	REAR END PANEL TOP GARNISH	twi \$168.90 ✓
1 PCS	REAR FLOOR PANEL	1 \$911.20 ✓
1 PCS	REAR FLOOR PANEL TOP BOARD	Torn \$388.60 ✓
1 PCS	REAR FLOOR PANEL TOOLS SPONGE N/S	Torn \$385.30 ✓
1 PCS	REAR FLOOR PANEL SPONGE O/S	Torn \$366.50 ✓
2 PCS	TAILLAMPS @\$325.50	one \$651.00 ✓
2 PCS	TAILLAMP HOUSING PANELS @\$145.00	o/s n/s 202 \$290.00 ✓
1 PCS	REAR EXHAUST	11 \$911.30 ✓
2 PCS	REAR FENDERS @\$ 988.30	1 \$1,976.60 ✓
2 PCS	REAR FENDER INNER TRIMS @\$268.50	11 \$537.00 ✓
S.NETT		
17c	BOOTLID TOP SPOILER	one \$880.00 600
17c	REAR LICENCE PLATE W/HOLDER	3rd \$50.00 40
17c	REAR END PANEL SEALANT	rec \$50.00 ✓

(202)

7532
202
6025.6

1 SET

176

REAR FLOOR PANEL INSULATOR
 REAR WINDSCREEN SEALANT

11 \$200.00 X
 11 \$50.00 X

LABOUR CHARGES:

TO CHECK WIRING

\$80.00 30

TO DISMENTLE & REPLACING REVERSE SENSOR

\$80.00 50

TO TRANSFER BOOTLID MECHANISM

\$120.00 60

TO DISMENTLE & REFIX REAR WINDSCREEN

11 \$150.00 X

TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTREY

\$150.00 80

TO DISMENTLE & REFIX REAR EXHAUST

m \$150.00 X

TO DISMENTLE & REFIX PETROL TANK

11 \$100.00 X

TO SPRAY RUST PROOFING

\$150.00 60

TO MOUNT VEHICLE ON CAR O-LINER

11 \$380.00 X

LABOUR FOR PANELBEATING & REPLACING PARTS

\$1,500.00 900

TO PUTTY & SPRAY PAINTING

\$1,500.00 1200

TOTAL

\$18,493.70

9095-6
 7276

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Friday, 27 April 2018 5:19 PM
To: Shu Pei (LKKAUTO)
Subject: RE: OUR REF: SNM18D01990C02/9/LKKDS & YR REF: SLA7776B (TP : LKK REF - CC6/CTI18006994/Umb3) on 14.04.2018
Attachments: MCHM18052694-GZ9159Y.pdf
Follow Up Flag: Follow up
Flag Status: Completed

Dear Shu Pei,

The above attachment is our OI report.

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175

Email: lucas.lee@sg.cntaiping.com

Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 25 April, 2018 10:25 AM
To: Angie Foo; Claims Dept of CTI
Cc: Lucas Lee; Sharon Han; Bevan Lim (LKK Auto); Admin A; Vivian Lau (LKKAUTO); Hsiao Tong (LKKAUTO); Vic (LKKAUTO)
Subject: RE: OUR REF: SNM18D01990C02/9/LKKDS & YR REF: SLA7776B (TP : LKK REF - CC6/CTI18006994/Umb3) on 14.04.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Angie Foo [<mailto:angie.foo@sg.cntaiping.com>]

Sent: Wednesday, 18 April 2018 2:32 PM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>; Sharon Han <sharon.han@sg.cntaiping.com>; Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>

Subject: OUR REF: SNM18D01990C02/9/LKKDS & YR REF: SLA7776B (TP : LKK REF - CC6/CTI18006994/Umb3) on 14.04.2018

Dear Shu Pei,

We refer to your email of 17th April 2018.

We attached a copy of Non-Reporting Letter for your necessary action.

Kindly take note, the claim handler on this case is Adeline Chng 6389 6155 and do not email to me for offer or mandate.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]

Sent: Tuesday, 17 April, 2018 6:01 PM

To: Claims Dept of CTI

Cc: Lucas Lee; Sharon Han; Bevan Lim (LKK Auto); Admin A

Subject: Direct Settlement - Accident Involving GZ9159Y (OI : CAI - TBA) and SLA7776B (TP : LKK REF - CC6/CTI18006994/Umb3) on 14.04.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLA 7776B at M/s Fastech Auto Pte Ltd.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Bevan and he can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D01990/C02/9**

Date: **18 APRIL 2018**

via Ordinary & Registered Mail

**BROADWAY CONTRACTS & SERVICES
803 KING GEORGE'S AVENUE
#01-236
SINGAPORE 200803**

Dear Sir / Madam

**ACCIDENT INVOLVING GZ9159Y AND SLA7776B ON 14 APRIL 2018
ALONG SLIP ROAD TOWARDS CLEMENTI AVE 4**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SLA7776B**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will soon contact you for more information about the accident. Kindly render your assistance and co-operation accordingly.

We understand that you or your driver has not filed an accident report within 24 hours as per Motor Claims Framework. We would urge you to comply with the condition to file your accident report with your vehicle (whether damaged or not) to us IMMEDIATELY through **LKK Auto Consultants Pte Ltd** or any of our **authorized workshops**. You may log onto our website www.sg.cntaiping.com for location of the respective workshops.

We regret to advice that we and/or **LKK Auto Consultants Pte Ltd** will not be handling the third party claim and your NO CLAIM DISCOUNT will be penalized upon renewal of your policy if you fail to comply with the condition of reporting.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : BEVAN
Ref : TP : LKK REF - CC6/CT118006994/Umb3
Contact No : 6749 4274
via Email : bevanlim@lkkauto.com

CC : Agent - (AN0025A) - IP SEARCH RESOURCES

F02/LKKDSANR-2013




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CT118006994/Ueb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 02-01-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GZ 9159Y	Veh. Inspected	SLA 7776B
Policy No.	DMCVSN1667611701	Coverage (\$)	0.00
Claim No.	SNM18D01990C02/9/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	16/04/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA ACCORD (A)	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MRHCP26308P020493	Colour	GREY
Odometer	178737	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/50 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/50 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/50 R17	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/04/2018	Inspection Date	16/04/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 7776B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	BADLY DENTED	921.20	921.20
1	BOOTLID "H" LOGO	NECESSARY	35.00	35.00
1	BOOTLID "ACCORD" EMBLEM	NECESSARY	38.20	38.20
1	BOOTLID "2.4" EMBLEM	NECESSARY	30.50	30.50
1	BOOTLID "IVTEC" EMBLEM	NECESSARY	46.00	46.00
1	BOOTLID OUTER GARNISH	BROKEN	485.20	485.20
1	SET BOOTLID OUTER GARNISH CLIPS	NOT NECESSARY	30.00	-
2	BOOTLID REFLECTORS @\$265.30	CRACKED	530.60	530.60
1	BOOTLID INNER LOCK	TWISTED	266.50	266.50
1	BOOTLID WEATHERSTRIP	TWISTED	292.30	185.20
1	BOOTLID INNER TRIM	DEFORMED / TORN	288.50	288.50
1	SET BOOTLID INNER TRIM CLIPS	NECESSARY	35.00	35.00
1	REAR BUMPER	DISTORTED	766.30	766.30
1	REAR BUMPER LOWER SPOILER	DISTORTED	820.50	620.00
2	REAR BUMPER RETAINERS @\$30.50	BENT	61.00	61.00
1	REAR BUMPER BEAM	BENT	182.30	182.30
4	REAR BUMPER PDC SENSOR @\$225.00	SHORTED (2 PCS ONLY)	900.00	450.00
1	REAR END PANEL	BADLY DENTED	588.20	485.20
1	REAR END PANEL TOP GARNISH	TWISTED	168.90	168.90
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	911.20	-
1	REAR FLOOR PANEL TOP BOARD	TORN	388.60	388.60
1	REAR FLOOR PANEL TOOLS SPONGE N/S	TORN	385.30	385.30
1	REAR FLOOR PANEL SPONGE O/S	TORN	366.50	366.50
2	TAILLAMPS @\$325.50	CRACKED	651.00	651.00
2	TAILLAMP HOUSING PANELS @\$145.00	N/S DENTED / O/S TO REPAIR SEE LABOUR	290.00	145.00
1	REAR EXHAUST	NOT NECESSARY	911.30	-
2	REAR FENDERS @\$988.30	TO REPAIR SEE LABOUR	1,976.60	-

Report Ref No. CC6/CTI18006994/Ueb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TRIMS @\$268.50 LESS 20% DISCOUNT	NOT NECESSARY	537.00 -	- -1,506.40
			12,903.70	6,025.60
	<u>SPECIAL NETT ITEMS</u>			
1	BOOTLID TOP SPOILER (SN)	CRACKED	880.00	600.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
			1,230.00	690.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMENTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM.		120.00	60.00
	TO DISMENTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMENTLE & REFIX REAR EXHAUST.	NOT NECESSARY	150.00	-
	TO DISMENTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		150.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL,O/S TAILLAMP HOUSING PANELS AND REAR FENDERS.		1,500.00	900.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,200.00
			4,360.00	2,380.00
	GRAND TOTAL		18,493.70	9,095.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,250.00

Report Ref No. CC6/CTI18006994/Ueb3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.