

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CC4/ASM18007039/T1ea3q2	
	8 SHENTON WAY AXA TOWERSING		Date	09/02/2021	
,	ATTN:STACEY		Code	: ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLC 1306D	Veh. Inspected	SLS 1985J	
I	Policy No.	GA185671	Coverage (\$)	0.00	
	Claim No.	S8M00DJA	Excess (\$)	0.00	
	Assign From		Assign Date	10/04/2018	
2. Vehicle Particulars & Condition					
l l	Make & Model	HONDA CIVIC 1.6	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	JHMFD46208S200792	Colour	WHITE	
	Odometer	131544 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
l	R/H Front Tyre	225/45 R17	MICHELIN	6 mm	
l	L/H Front Tyre	225/45 R17	MICHELIN	6 mm	
l	R/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
l	L/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
4.	4. Description of Damages				
-	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/04/2018	Inspection Date	16/04/2018	
	Survey held at XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				