



TPA LG.
Xiao Tong.

ESTIMATE

DATE OF ACCIDENT : 11/04/2018	
VEHICLE : SLQ3392S	
MAKE & MODEL : HONDA VEZEL	RU11222294
INSURANCE : AIG ASIA PACIFIC INSURANCE	
SURVEYOR : LKK AUTO	

	PARTS	CONDITION	COST	
1.	FRONT LEFT DOOR <i>Dented.</i>	989.50	\$ 1580	-
2.	REAR LEFT DOOR <i>Dented.</i>	978.40	\$ 1430	-
3.	FRONT LEFT WHEEL ARCH <i>cut</i>		\$ 210	-
4.	REAR LEFT WHEEL ARCH <i>near</i>		\$ 210	+
5.	FRONT LEFT KNUCKLE <i>Best</i>	390.50	\$ 720	?
6.	FRONT LEFT LOWER ARM <i>Best</i>	366.20	\$ 420	✓
7.	FRONT LEFT ANTI ROLL BAR LINK <i>2 year Best</i>		\$ 115	✓
8.	FRONT LEFT ANTI ROLL BAR <i>1 year near</i>		\$ 720	+
9.	FRONT LEFT ABSORBER <i>Best</i>	495	\$ 665	?
10.	FRONT LEFT ABSORBER MOUNTING <i>near</i>		\$ 72	+
11.	FRONT LEFT ABSORBER BEARING <i>near</i>		\$ 38	✓
12.	FRONT LEFT UNDERCARRIAGE COVER <i>near</i>		\$ 142	+
13.	FRONT LEFT STEERING RACK TIE ROD END <i>Best</i>		\$ 85	✓
14.	STEERING RACK <i>changed</i>		\$ 1635	✓
15.	LEFT SIDESKIRT <i>cut</i>		\$ 380	✓
16.	FRONT BUMPER <i>Repaired</i>		\$ 850	+
17.	FRONT BUMPER LOWER LIPS <i>cut</i>		\$ 456	✓
18.	FRONT LEFT BUMPER BRACKET <i>near</i>		\$ 80	35.
19.	FRONT LEFT HEAD LAMP <i>near</i>		\$ 950	+

6173.60

4938.88.



JACK CARS

SPECIAL NETT ITEMS			
1.	FRONT LEFT RIM <i>Pinched at</i>		\$ 418
2.	FRONT LEFT TYRE <i>Pinched.</i>		\$ 380 <i>220.</i>
3.	CLIPS x 30 <i>see</i>	<i>668</i>	\$ 150 <i>30.</i>
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA		\$ 1425 <i>900.</i>
2.	TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.		\$ 1140 <i>700</i>
3.	TO CHECK WIRING & REWIRING		\$ 120 <i>30</i>
7.	TO REMOVE & REPLACE DOORS <i>ittings.</i>		\$ 350 <i>160.</i>
8.	TO REMOVE & REPLACE BUMPER		\$ 120 <i>x.</i>
10.	ANTI RUST TREATMENT <i>1930</i>		\$ 120 <i>40.</i>
11	<i>To dismantle undercarriage</i>	<i>380 220.</i>	
12	<i>To perform wheel alignment</i>		
	<i>150 80</i>	PARTS - 20% :	\$ 8,606.40
		LABOUR :	\$ 3,275
		SPECIAL NETT :	\$ 948
		TOTAL :	\$ 12,829.40
		7% GST :	\$ 898.06
		GRAND TOTAL :	\$ 13,727.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling.

n/s 16/04/18.

ob days

96893735.

total: 7536.88

n/s 6/12.