

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 9858H

DATE 16/4/2018 11:49

AUG

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			50
	Panel Beating			\$ 150.00
	Spray Painting Charge-Mirror only			\$ 150.00
	Wiring Charge			\$ 50.00
	TOTAL LABOUR			\$ 350.00
	ESTIMATE TOTAL			\$ 350.00
	wing Mirror (RH) x repair			
	1 Calum (LKK)			
	16/4/18 1245hr			
	1 Day			
	P/P			
	After Repair photo			
	<div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance CompanyAcknowledged by Repairer Signature: Date:</div>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				