



MOTORVIVA PTE LTD  
10 Tuas Avenue 18 Singapore 638894  
Tel: +65 6665 2518 (Sales) +65 6448 2686 (Service)  
Fax: +65 6561 7956 (Sales) +65 6442 5571 (Service)  
Website: www.goldbell.com.sg  
Co. Reg. No.: 199507614Z

DATE : 12/4/2018

TO : HENG REFRIGERATION AND ELECTRICAL E  
ATTN : MR SEAH  
OFFICE / MOBILE : 9694 5525  
EMAIL ADDRESS : -

FROM : MOTORVIVA PTE LTD  
ATTN : MR LI LEWEI  
OFFICE / MOBILE : 6864-0637 / 9755-7336  
FAX NO. : 6863-0425

VEHICLE NO. : GBB4555E  
MODEL NO. : FIAT DUCATO-2.3 D JTD SWB  
CHASSIS NO. : ZFA25000001144842  
ENGINE NO. : F1AE0481D0478624  
REG. DATE : 30/03/2009

REF. NO. : GBE/SVC/SALES-4616/180412  
D.O.A. : 11/4/2018  
POLICY NO. : VCA/P1839321  
CLAIM TYPE : TP CLAIM - CHINA TAIPING

WORKSHOP : 10 TUAS AVE 18

S/N	PART NO.	DESCRIPTION	QUANTITY	PRICE
1	1364511080	FRONT DOOR RHS <i>x repair</i>	1	\$ 3,006.72
2	1350621080	FRONT DOOR HINGE RHS <i>x</i>	1	\$ 107.09
3	1358220080	FRONT DOOR CHECK RHS <i>x</i>	1	\$ 120.74
4	735422811	FRONT DOOR MOULDING RHS	1	\$ 189.78
5	735432334	SIDE MIDDLE MOULDING RHS <i>= 4 scr</i>	1	\$ 130.49

SUB-TOTAL : \$ 3,554.82  
LESS 10% : \$ 355.48  
BALANCE : \$ 3,199.34

**SPECIAL-NETT ITEMS**

1	COMPANY DETAILS STICKER <i>1 pc</i>	1	\$ 30.00
---	-------------------------------------	---	----------

PARTS TOTAL : \$ 3,229.34

**LABOUR CHARGES**

1	TO REMOVE & REFIT DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	\$ 1,800.00	<i>\$300</i>
2	TO PUTTY, CLEAN, SPRAY PAINT & POLISH	\$ 600.00	<i>\$475</i>
3	TO REMOVE AND REFIX FRONT DOOR COMPARTMENT.	\$ 120.00	<i>x</i>
4	SUNDRIES	\$ 30.00	<i>\$10</i>
	<i>P: 288.24</i>		
	<i>S/N: 30</i>		
	<i>L: 785</i>		
	LABOUR TOTAL :	\$ 2,550.00	
	GRAND TOTAL :	\$ 5,779.34	

*T: \$1,103.24*

PREPARED BY : LI LEWEI

DATE / TIME : *20/4/18*

SURVEYOR : *Guo Qiang*

MOBILE NO. : *8288 0282*

OFFICE FAX NO. :

EMAIL ADDRESS : *Guo.Qiang@lkk Auto.com*

*part by part .  
After repair photos .*