

INS. CASE OWNER:

CC 6 / AIG1800

LKK:  
IDAC:

Surveyor:

DOI:

## ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

( YES / ☒ )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

## STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

## FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ ( days) Reduction: % Email ☐ Call ☐

## FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

Repair Cost: S\$ 5510.07 (Agreed / Assessed) BOLA S/N No.: 23

Loss of Rental (LOR):

S\$

( days)

Loss of Use (LOU):

S\$

(\$ x days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total: S\$ 5512.07

Global Sum S\$:

## FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

PEGASUS ENGINEERING &amp; TRADING PTE LTD

COPY SENT  
13/7/10

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

RECEIVED 13 JUL 2010

06/11/13, wef

ASS. REC. BY: MORIS

REF:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLW 349KA

at Workshop mis: PEPOSUS

of SLB 9461R

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bel. or Market Value: \_\_\_\_\_

WAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GLA PR Seen: X Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum: PIP % S Val: Yes or No

CA / REV / REP. / 24 HRS

7Wx

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLW349KA Reg: 2 18

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA / Hybrid 1496

Colour: Gold A/C: Insured / Std / NI / NA

Sp. Reading: 19996 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/N: R U 31222437

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Mod: NO / STD A/Rim or

Tyre Size: F: 215/60R16  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / CHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 7 mm R/Bal: 7 mm

L/Bal: 7 mm L/Bal: 7 mm

D.O.A: 15/4/18 D.O.I: 17/4/18

Survey held at: Koko hotel

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$ 5149.60 (Red: \$ 1445.29 / 22%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: \_\_\_\_\_

1) \_\_\_\_\_

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2) \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Photo: \_\_\_\_\_

Other: \_\_\_\_\_

TOTAL: \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Accident Date	10/06/2018	Inspection Date	11/06/2018
Survey held at	SME MOTOR PTE LTD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		
5a.	Remarks		
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		



Third Party Insurer :

AIG

Insured's Veh No :

SLB9461R

Date of accident :

15/04/2018

Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

not Arham  
2 hr  
17/4/18  
Taka ph. to Behrenging.  
Sdy.

Quotation No : AR/QO18/04-1069

Quotation Date : 16/04/2018

Estimate To Repair

HONDA VEZEL HYBRID 1.5X AUTO

Vehicle No :

SLW3494A

Chassis No :

RU3-1222437

P/P - \$5149.60 confirmed.

Pages :

1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
<b>SPARE PARTS</b>			
1	1SET	REAR WINDSCREEN MOULDING <i>rec</i>	\$160.00
2	1PC	REAR GATE <i>body</i>	\$1,010.00
3	1PC	REAR GATE "VEZEL" PLATE <i>rec</i>	\$45.00
4	1PC	REAR GATE "HYBRID" PLATE <i>rec</i>	\$60.00
5	1PC	REAR GATE INNER RUBBER <i>tw</i>	\$120.00
6	1PC	REAR GATE LOCK <i>tw</i>	\$105.00
7	1PC	REAR GATE INNER TRIMBOARD <i>1</i>	\$225.00
8	12PC	INNER TRIM CLIPS @ \$5.90 <i>1</i>	\$70.80
9	1PC	REAR BUMPER (CENTRE) <i>7.5</i>	\$810.00
10	1PC	REAR BUMPER LH (CORNER) <i>2.5/12</i>	\$185.00
11	1PC	REAR BUMPER RETAINER LH <i>bul</i>	\$35.00
12	10PC	REAR BUMPER CLIPS @ \$5.90 <i>rec</i>	\$59.00
13	1PC	REAR END PANEL <i>2.5/3.5</i>	\$550.00
14	1PC	REAR END PANEL TOP TRIM <i>1</i>	\$95.00
15	1PC	REAR BUMPER REFLECTOR LH <i>1</i>	\$165.00
16	1PC	REAR GATE LAMP LH <i>5.2</i>	\$435.00
17	1PC	REAR FENDER PROTECTOR LH <i>1</i>	\$225.00
18	6PC	PROTECTOR CLIPS @ \$5.90 <i>1</i>	\$35.40
			<i>432 - 20.20</i>
			\$4,390.20
			<i>3217.60</i>
			\$878.04
			\$3,512.16
			<i>Rec in tail bag \$488</i>
<b>MISC ITEMS</b>			
19	1PC	REVERSE SENSOR <i>shut</i>	\$250.00
20	1PC	REAR WINDSCREEN GUM <i>rec</i>	\$65.00
Total			\$315.00
<b>LABOUR &amp; MISC. CHARGES</b>			
1		WIRE CHECKING	\$30.00
2		REMOVE & REFIX REAR WINDSCREEN	\$120.00
3		REMOVE & REFIX HYBRID SYSTEM	\$280.00
4		TRANSFER REAR GATE COMPONENT FROM OLD TO NEW	\$120.00
5		CAVITY PROTECTION ON ALL AFFECTED AREAS	\$100.00

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418





GST / ROC Company No : 201101753C

Third Party Insurer : AIG

Insured's Veh No : SLB9461R

Date of accident : 15/04/2018

Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

Quotation No : AR/QO18/04-1069

Quotation Date : 16/04/2018

**SUPPLEMENTARY**HONDA VEZEL HYBRID 1.5X AUTO

Vehicle No :

SLW6494A

Chassis No :

RU3-1222437

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
1		<b>PARTS</b>	
		REAR LH TAIL LAMP	<i>C47/</i> <i>CM</i> \$488.00 ✓
			\$488.00
		LESS 20%	\$97.60
			\$390.40
		Sub Total	\$390.40
		GST (7.00%)	\$27.33
		Total	\$417.73

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418



GST / ROC Company No :

201101753C

*not Alhamd  
like  
17/4/18  
take photo before repair.  
Sdy.*

Third Party Insurer :

AIG

Insured's Veh No :

SLB9461R

Date of accident :

15/04/2018

Quotation No : AR/QO18/04-1069

Quotation Date : 16/04/2018

Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

Estimate To Repair

HONDA VEZEL HYBRID 1.5X AUTO

Vehicle No :

SLW6494A

Chassis No :

RU3-1222437

Pages :

1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
<b>SPARE PARTS</b>			
1	1SET	REAR WINDSCREEN MOULDING <i>rec</i>	\$160.00
2	1PC	REAR GATE <i>body</i>	\$1,010.00
3	1PC	REAR GATE "VEZEL" PLATE <i>rec</i>	\$45.00
4	1PC	REAR GATE "HYBRID" PLATE <i>rec</i>	\$60.00
5	1PC	REAR GATE INNER RUBBER <i>tw</i>	\$120.00
6	1PC	REAR GATE LOCK <i>tw</i>	\$105.00
7	1PC	REAR GATE INNER TRIMBOARD	\$225.00
8	12PC	INNER TRIM CLIPS @\$5.90 <i>1.7</i>	\$70.80
9	1PC	REAR BUMPER (CENTRE) <i>7.3</i>	\$810.00
10	1PC	REAR BUMPER LH (CORNER) <i>22/22</i>	\$185.00
11	1PC	REAR BUMPER RETAINER LH <i>3.4</i>	\$35.00
12	10PC	REAR BUMPER CLIPS @\$5.90 <i>rec</i>	\$59.00
13	1PC	REAR END PANEL <i>22/22</i>	\$550.00
14	1PC	REAR END PANEL TOP TRIM	\$95.00
15	1PC	REAR BUMPER REFLECTOR LH	\$165.00
16	1PC	REAR GATE LAMP LH <i>5.2</i>	\$435.00
17	1PC	REAR FENDER PROTECTOR LH	\$225.00
18	6PC	PROTECTOR CLIPS @\$5.90 <i>1.1</i>	\$35.40
			\$4,390.20
LESS 20%			\$878.04
			\$3,512.16
<b>MISC ITEMS</b>			
19	1PC <i>set</i>	REVERSE SENSOR <i>shorted</i>	\$250.00
20	1PC	REAR WINDSCREEN GUM <i>sealant</i> <i>rec</i>	\$65.00
Total			\$315.00
<b>LABOUR &amp; MISC. CHARGES</b>			
1		WIRE CHECKING	\$30.00
2		REMOVE & REFIX REAR WINDSCREEN	\$120.00
3		REMOVE & REFIX HYBRID SYSTEM <i>1.1</i>	\$280.00
4		TRANSFER REAR GATE COMPONENT FROM OLD TO NEW	\$120.00
5		CAVITY PROTECTION ON ALL AFFECTED AREAS	\$100.00

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418



GST / ROC Company No :

201101753C

Third Party Insurer :

AIG

Insured's Veh No :

SLB9461R

Date of accident :

15/04/2018

Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

Quotation No : AR/QO18/04-1069  
Quotation Date : 16/04/2018

**Estimate To Repair**

**HONDA VEZEL HYBRID 1.5X AUTO**

Vehicle No :

SLW6494A

Chassis No :

RU3-1222437

Pages :

1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
6		LABOUR CHARGE	\$850.00
7		SPRAY PAINTING	\$850.00
		Total	\$2,350.00
Sub Total			\$6,177.16
GST (7.00%)			\$432.40
Total			\$6,609.56

600  
800

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418



## Thin Thin (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Friday, 20 April 2018 1:56 PM  
**To:** 'pearlyntanhuikoon@gmail.com'  
**Cc:** 'superduperroy@hotmail.com'  
**Subject:** ACCIDENT INVOLVING SLB 9461R & SLW 3494A ON 15/04/2018



Auto  
Consultants  
Pte Ltd

---

51 UBI AVE, 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18007099/Uua3

20 APRIL 2018

**TAN HUI KOON**  
BLK 40 WOODLANDS DRIVE 16  
#10-40  
SINGAPORE 737774

Dear Sir/Madam,

### **ACCIDENT INVOLVING SLB 9461R & SLW 3494A ON 15/04/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING  
Case Handler  
DID: 6841 2360  
FAX: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd



(Motor Claims Dept)



Your Insured Veh No : **SLB9461R**  
Your Ref :  
Our Ref : **SLW3494A**  
Date : **28/06/2018**

**AIG Asia Pacific Insurance Pte. Ltd**  
**78 Shenton Way #07-16**  
**AIG Building**  
**Singapore 079120**

**WITHOUT PREJUDICE**

Dear Sir/Madam

**Accident involving SLB9461R and SLW3494A**  
**on 15/04/2018 at PIE TOWARDS CHANGI.**

*Please refer only to the boxes marked ( x ).*

- ☒ We refer to ☒ the above accident  
☐ our/your letter dated
- ☒ We have been authorised by the owner of vehicle number **SLW3494A** which was damaged by your insured's motor vehicle number **SLB9461R** in the aforesaid accident.
- ☒ We are instructed that the accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

Cost of Repair / Excess bill	<b><u>\$5,510.07</u></b>
Loss of Income ( days x \$ /day)	-
Loss of Use( days @ \$ per day)	-
Car Rental Fees	-
GIA/LTA search fees	<b><u>\$2.00</u></b>
Others Fee	
Total	<b><u>\$5,512.07</u></b>

- ☒ We forward herewith the following relevant supporting documents:-
- |  |  |
|--|--|
| <input type="checkbox"/> Survey Reports & photographs (To be returned within 7 days on demand) | <input checked="" type="checkbox"/> Copy of NRIC/Driving licence   |
| <input type="checkbox"/> Final repair bill(Tax Invoice)  | <input checked="" type="checkbox"/> Copy of LTA/GIA vehicle search |
| <input checked="" type="checkbox"/> Bill/Receipt for the excess                                | <input checked="" type="checkbox"/> Non-injury motor report form   |
| <input type="checkbox"/> Rental Agreement  | <input checked="" type="checkbox"/> Letter of Authority            |
| <input type="checkbox"/> Income Statement  | <input type="checkbox"/>   |
| <input checked="" type="checkbox"/> Copy of the Insurance Certificate                          |  |
- ☒ Cheque to be make payable to **Messrs PEGASUS ENGINEERING & TRADING PTE LTD.**
- ☐ Any request for a re-survey of our client's vehicle must be arrange within the 14 days upon receipt of this letter. The re-survey must be conducted at our premises, in the presence of our client.
- ☒ Please note that you should send to us an acknowledgment of receipt of this letter within 07 days of your receipt of this letter.

Yours faithfully,

**WE HEREBY ACKNOWLEDGE RECEIPT**

Date: \_\_\_\_\_

**PLEASE CHOP AND SIGN**

**PEGASUS ENGINEERING & TRADING PTE LTD**  
**Mailing Address: 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883**

## Thin Thin (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Friday, 20 April 2018 1:56 PM  
**To:** 'pearlyntanhuikoon@gmail.com'  
**Cc:** 'superduperroy@hotmail.com'  
**Subject:** ACCIDENT INVOLVING SLB 9461R & SLW 3494A ON 15/04/2018



Auto  
Consultants  
Pte Ltd

---

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18007099/Uua3

20 APRIL 2018

**TAN HUI KOON**  
BLK 40 WOODLANDS DRIVE 16  
#10-40  
SINGAPORE 737774

Dear Sir/Madam,

### **ACCIDENT INVOLVING SLB 9461R & SLW 3494A ON 15/04/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING  
Case Handler  
DID: 6841 2360  
FAX: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd



## LETTER OF AUTHORITY

To: M/s Atb Asia Pacific Insurance pte ltd  
Singapore

Accident involving my/our vehicle no. SLW3494A and SLB9461R on 15/04/2018

Along PTE hnds Changi

I/We, Grab Rentals Pte Ltd NRIC No. 2016172006

Of 28 Sin Ming Lane #01-138 Midway city Singapore 573972

the registered owner of vehicle no. SLW3494A at the material time of accident, do

hereby authorise **Messrs PEGASUS ENGINEERING & TRADING PTE LTD** as my/our a

to correspond in, negotiate and settle, on my/our behalf, my/our claim against you as

owner/operator/insurer of vehicle no. SLB9461R.

I/We also authorise them to accept settlement cheque on my/our behalf. Kindly issue

your cheque in favour of "**M/s. PEGASUS ENGINEERING & TRADING PTE LTD**".

Dated this 20 day of 04 20 18



Signature of Owner of his/her/their  
Duly Authorised Representative

Company's Stamp (For Firm).

## AUTHORIZATION TO ACT

TO: PEGASUS ENGINEERING & TRADING PTE LTD

FROM: HIRER OF VEHICLE NUMBER SLW 3494A

ACCIDENT INVOLVING SLB 9461R

ALONG/AT PIE trucks Changi @ 15/04/2018 @ 1500 hrs

I hereby authorize you to act on my behalf in pursuance of my claim for loss of rental / earnings during the repair arising out of the above accident.

This letter serve as the 'AUTHORITY TO ACT'.

We also hereby authorize all agreed settlement payment be made in favour to PEGASUS ENGINEERING & TRADING PTE LTD.

Name :  Ong Jia Wei Melvin

NRIC :  89315910A

Address :  B1K 902 Tampines ave 4 #01-206 (520902)

Contact :  9628 5521

Date :  20/04/2018

Signature



f      w   
Hirer

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, Pegasus Engineering & Trading Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 5,510.07 (Repair Cost), S\$ --- (Loss of Rental/Use), S\$ 2.00 (Disbursement) for vehicle no. SLW 3494A that was damaged pursuant to the accident which occurred on 15/04/2018 (date) along PIE TOWARDS CHANGI (location) involving vehicle no/s SLB 9461R. This is pursuant to the inspection conducted on 17/04/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Grab Rentals Pte Ltd ("the third party claimant") of vehicle no. SLW 3494A make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLW 3494A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 13 (day) of 07 (month) 20 18 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages arising therefrom are excluded from the ambit and application of this document."





Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

GST / ROC Company No : 201101753C

Third Party Insurer : AIG  
Insured's Veh No : SLB9461R  
Date of accident : 15/04/2018  
Make / Model: HONDA VEZEL  
Vehicle No : SLW6494A  
Chassis No : RU3-1222437  
Invoice No: AR/IV18/06-1022  
Invoice Date: 27/06/2018

Pages : 1 of 1

S/NO	QUANTITY	DESCRIPTION	AMOUNT
<b><u>SPARE PARTS</u></b>			
1	1SET	REAR WINDSCREEN MOULDING	\$160.00
2	1PC	REAR GATE	\$1,010.00
3	1PC	REAR GATE "VEZEL" PLATE	\$45.00
4	1PC	REAR GATE "HYBRID" PLATE	\$60.00
5	1PC	REAR GATE INNER RUBBER	\$120.00
6	1PC	REAR GATE LOCK	\$105.00
7	1PC	REAR BUMPER (CENTRE)	\$810.00
8	1PC	REAR BUMPER LH (CORNER)	\$185.00
9	1PC	REAR BUMPER RETAINER LH	\$35.00
10	10PC	REAR BUMPER CLIPS @\$5.90	\$59.00
11	1PC	REAR END PANEL	\$550.00
12	1PC	REAR GATE LAMP LH	\$435.00
13	1PC	REAR LH TAIL LAMP	\$488.00
			\$4,062.00
LESS 20%			\$812.40
			\$3,249.60
<b><u>MISC ITEMS</u></b>			
14	1PC	REVERSE SENSOR	\$200.00
15	1PC	REAR WINDSCREEN GUM	\$40.00
Total			\$240.00
<b><u>LABOUR &amp; MISC. CHARGES</u></b>			
1		WIRE CHECKING	\$20.00
2		REMOVE & REFIX REAR WINDSCREEN	\$120.00
3		TRANSFER REAR GATE COMPONENT FROM OLD TO NEW	\$60.00
4		CAVITY PROTECTION ON ALL AFFECTED AREAS	\$60.00
5		LABOUR CHARGE	\$600.00
6		SPRAY PAINTING	\$800.00
Total			\$1,660.00





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-057031

Date of Request: 16/04/2018

Your Ref No: Online Purchase

SME Motor Pte Ltd  
1 Kaki Bukit Ave 6 #02-15  
AutoBay @ Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 16/04/2018  
Enquiry By: Han Zhuang Chou  
TP Vehicle No: SLB9461R  
Accident Date: 15/04/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLB9461R	AIG Asia Pacific Insurance Pte. Ltd.	27/04/2017-26/04/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-057031  
Date of Request: 16/04/2018

Your Ref No: Online Purchase

SME Motor Pte Ltd  
1 Kaki Bukit Ave 6 #02-15  
AutoBay @ Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 16/04/2018  
Enquiry By Han Zhuang Chou  
TP Vehicle No. SLB9461R  
Accident Date 15/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2018 <a href="#">Edit Reg</a>		17 Apr 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$55,149.60</b> <a href="#">Edit Estimates</a>	<b>\$55,149.60</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<b>Show All</b>
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

TAN HUI KOON, ID: S8417037B

Main Claimant:

GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G

Vehicle Reg. No.:

SLW3494A

Date of Loss:

15/04/2018 00:00 - :59  
[2 Months and 8 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 8877722706SG

Policy/Cover Note No.:

210062844

Vehicle Reg. No. (Insured):

SLB9461R

Policy No. (Claimant):

A29069766MKF

Excess:

Repairer:

Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, S39216 Defu Lane - Tel: 68581846

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M]  
Jaclyn-M.Kesaval@aig.com

Claimant's Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/04/2018]

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

















































[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






## Claim Documents

**\*SLW3494A (8877722706SG)**  
**[SLB9461R]**  
**TP**  
**GRAB RENTALS PTE LTD**  
**Apr 15 2018 12:00AM**  
**[TAN HUI KOON]**  
**Pegasus Engineering & Trading Pte Ltd**

<a href="#">Upload Documents</a>			<a href="#">Upload Photos</a>			<a href="#">Compose New Letter</a>			<a href="#">Upload Video</a>			<a href="#">Upload Audio</a>			<a href="#">View</a>			<a href="#">View in Browser</a>		
<b>Video</b>															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	13/07/18 16:18	Video - From TP													Load MP4					
<b>Letters/Correspondences</b>															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown													Edit					
<b>Assessment Reports</b>															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	18/04/18 14:30	Accident Statement From: OD - Reg. No: SLB9461R, Claimant: TAN HUI KOON													Load HTM					
<b>Photos/Images</b>															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
2	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
3	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
4	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
5	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
6	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
7	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
8	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
9	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
10	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
11	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
12	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
13	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
14	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
15	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
16	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
17	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
18	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
19	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
20	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
21	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
22	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
23	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
24	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
25	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
26	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				
27	17/04/18 19:08	General View													Load JPG	<input checked="" type="checkbox"/>				

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
28	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
55	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
56	17/04/18 19:08	General View	 Load JPG	<input checked="" type="checkbox"/>
57	17/04/18 19:09	General View	 Load JPG	<input checked="" type="checkbox"/>
58	17/04/18 19:09	General View	 Load JPG	<input checked="" type="checkbox"/>
59	17/04/18 19:09	General View	 Load JPG	<input checked="" type="checkbox"/>
60	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	31/05/18 17:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/04/18 16:54	TP ESTIMATE - MARKED	 Load PDF	
2	17/04/18 16:54	TP GIA REPORT	 Load PDF	



Video			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
3	16/07/18 10:03	WORKSHOP INVOICE	 Load PDF	
4	16/07/18 10:03	AUTHORISATION TO ACT FORM	 Load PDF	
5	16/07/18 10:03	Release Voucher	 Load PDF	
6	16/07/18 10:03	GIA SEARCH	 Load PDF	
7	16/07/18 10:03	LETTER TO OI	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a> <a href="#">Save</a> <a href="#">Print</a>
There are no document checklists configured.	
<div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>  <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> <div style="text-align: right; margin-top: 5px;"> <span>^</span>  <span>v</span> </div> </div>	
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLB9461R (Insd veh)	Model:	HONDA VEZEL 1.5 HYBRID
	SLW3494A (TP veh)		(A)
Date of Accident:	15/04/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	7,027.29
Final Repair Cost	:	\$	5,510.07
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	0.00 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	5,512.07

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Pegasus Engineering & Trading Pte Ltd	:	\$ 5,512.07
2)		:	\$

\_\_\_\_\_  
JOANNE LEE KHANG MIN

\_\_\_\_\_  
LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
16 Jul  
2018

\_\_\_\_\_  
Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18007099/UUA3Q2

Date: 16/07/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 210062844  
**Claimant Vehicle No :** SLW3494A **Insured Vehicle No :** SLB9461R  
 Date of Loss: 15/04/2018 Nature of Claim: TP Claim No: 8877722706SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLW3494A**  
 Make & Model: HONDA VEZEL, 1.5 HYBRID (A) Engine No: LEB5922450  
 Reg. Date: 07/02/2018 (Man. Year: 2016) Chassis No: RU31222437  
 Colour: Gold Odometer: 19996 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm  
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,217.56	3,489.60	727.96	17.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,660.00	690.00	29.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,567.56</b>	<b>5,149.60</b>	<b>1,417.96</b>	<b>21.59</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>459.73</b>	<b>360.47</b>	<b>99.26</b>	<b>21.59</b>
<b>Nett Amount (S\$)</b>	<b>7,027.29</b>	<b>5,510.07</b>	<b>1,517.22</b>	<b>21.59</b>
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>5,512.07</b>		

## INSPECTION

Date of Assignment: 17/04/2018  
 Date Inspected: 17/04/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd (HQ)  
 51 DEFU LANE 10  
 Singapore 539216  
 Estimated Period of Repair: 5.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** THIN THIN HLAING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET REAR WINDSCREEN MOULDING	Necessary	160.00 FL	*160.00 FL
2	1		*REAR GATE	Badly Dented	1,010.00 FL	*1,010.00 FL
3	1		*REAR GATE VEZEL PLATE	Necessary	45.00 FL	*45.00 FL
4	1		*REAR GATE HYBRID PLATE	Necessary	60.00 FL	*60.00 FL
5	1		*REAR GATE INNER RUBBER	Twisted	120.00 FL	*120.00 FL
6	1		*REAR GATE LOCK	Twisted	105.00 FL	*105.00 FL
7	1		*REAR GATE INNER TRIMBOARD	Not Necessary	225.00 FL	*- FL
8	12		*INNER TRIM CLIPS	Not Necessary	70.80 FL	*- FL
9	1		*REAR BUMPER (CENTRE)	Distorted	810.00 FL	*810.00 FL
10	1		*REAR BUMPER LH (CORNER)	Dented / Deformed	185.00 FL	*185.00 FL
11	1		*REAR BUMPER RETAINER LH	Bent	35.00 FL	*35.00 FL
12	10		*REAR BUMPER CLIPS	Necessary	59.00 FL	*59.00 FL
13	1		*REAR END PANEL	Dented / Buckled	550.00 FL	*550.00 FL
14	1		*REAR END PANEL TOP TRIM	Not Necessary	95.00 FL	*- FL
15	1		*REAR BUMPER REFLECTOR LH	Not Necessary	165.00 FL	*- FL
16	1		*REAR GATE LAMP LH	Scratched	435.00 FL	*435.00 FL
17	1		*REAR FENDER PROTECTOR LH	Not Necessary	225.00 FL	*- FL
18	6		*PROTECTOR CLIPS	Not Necessary	35.40 FL	*- FL
19	1		*REAR LH TAIL LAMP	Cut / Cracked	488.00 FL	*488.00 FL
20	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
21	1		*REAR WINDSCREEN SEALANT	Necessary	65.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,193.20</b>	<b>4,302.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>975.64</b>	<b>812.40</b>
<b>Total Parts (\$\$)</b>	<b>4,217.56</b>	<b>3,489.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX REAR WINDSCREEN	New	120.00	120.00
3	REMOVE & REFIX HYBRID SYSTEM	New	280.00	0.00
4	TRANSFER REAR GATE COMPONENT FROM OLD TO NEW	New	120.00	60.00
5	CAVITY PROTECTION ON ALL AFFECTED AREAS	New	100.00	60.00
6	LABOUR CHARGE	New	850.00	600.00
7	SPRAY PAINTING	New	850.00	800.00
Gross Labour Cost (S\$)			<b>2,350.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >