

ASS. REC. BY: Adrian Ling

REF:

CC3 / ALG18007128 / Alp9/L

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1700050656

Claims No. 571371507256 300 24/4/18

Sum Insured: _____ Excess: 500 20/4/18

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 150K.

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05/8/18 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SLS2342H.

Yr Regn:

2017 / Sept.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4 Sedan.

cc 1395

Colour:

Black.

A/C:

Insured / Std / NI / NA

Sp. Reading:

14620

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU222F43JA023227.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/35R19.

R:

245/35R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

17/04/18

Survey held at

Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD ALG.

SLS 2342H - CC3 / ALG18007128 / Mwb3

Ref: 0404018

BL4 - Revert via memmen

19/4/18 @ 11.35am Victor informed C/A via memmen.

20/4/18 @ 11.35am Informed Tony C/A to Ex-TRA by email.

24/4/18 @ 10.04am Informed Tony Ex-TRA 300 by email.

18/5/18 @ 10.42am and revert to Victor via memmen. (supplementary)

18/5/18 @ 2.59pm Victor informed C/A at supplementary via memmen.

22/5/18 @ 11.35am Informed Tony C/A provided report on supplementary (07580)

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

11/01/18



Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2) RECEIVED 01 AUG 2018

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format:

WEB-07

Lump Sum / I.B.I. (\$

13762.52



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18007128/Aqb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-04-2018	
		Code : AIG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLS 2342H
Policy No.	1700050656	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	17/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/04/2018	Inspection Date	17/04/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

17/07/18 @ 11.25am confirmed with Mr Soo Ansel fig \$13762.52, 5 days by email,
(Ref # 6061.08, 312)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 17 July 2018 11:25 AM
To: Boo seng yak; SUR; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SLS2342H - OD AIG - SURVEYED 17 APR 18

Dear Mr Boo,

Confirm final fig \$13,762.52 before excess \$300.00 & GST and 5 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Wednesday, 4 July 2018 3:04 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SLS2342H - OD AIG - SURVEYED 17 APR 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$13,762.52 @ 5 days of repairs.

Attached, please find photos of power module replaced.

Your early closure is well appreciated.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 22 May 2018 11:56 AM
To: Claims; SUR
Subject: RE: OD CLAIM FOR SLS 2342 H
Attachments: SLS2342 SUPP.pdf

Dear Tony,

Kindly proceed repair the supplementary as attached.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 24 April 2018 10:04 AM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SLS 2342 H

Dear Tony,

Please be informed that the excess of above vehicle SLS 2342H is \$300.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 23 April 2018 2:03 PM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SLS 2342 H

Dear Tony,

Please be informed that we still pending for insurance's reply.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Monday, 23 April 2018 12:26 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	05 Apr 2018 16:46	Cim Veh Model Changed		[] Merimen Administrator
2	05 Apr 2018 16:46	Cim Created	Reg No: SL52342H, Policy No: 1700050656, Acct Date: 2018/04/04, Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Cr eated from SAS:MPA118045537	[I] Merimen Administrator
3	06 Apr 2018 11:32	Cim Registration Modified	Acct Time:18:50:00->00:00:00.	[I] Abu Kassim, Noor Mariesa
4	09 Apr 2018 09:43	Cim Registration Modified	Init.Est.:>4,000 - 5,000.	[I] Azlan, Syazalrdina
5	17 Apr 2018 17:35	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
6	17 Apr 2018 17:35	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
7	17 Apr 2018 17:35	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
8	17 Apr 2018 17:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/26	[A] CATHERINE CHONG KAI LING
9	17 Apr 2018 17:35	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
10	17 Apr 2018 17:35	Cim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
11	17 Apr 2018 17:35	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] CATHERINE CHONG KAI LING
12	17 Apr 2018 17:35	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
13	18 Apr 2018 12:05	Cim Registration Modified	Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Tr, Tinesh
14	18 Apr 2018 12:05	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
15	18 Apr 2018 16:08	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
16	18 Apr 2018 16:08	Cim Dtl Modified	3PJ Reg. Date: -> 2017/09/14.	[A] DENISE TAY KWEE CHENG
17	18 Apr 2018 16:08	Cim Details Notified		[A] DENISE TAY KWEE CHENG
18	18 Apr 2018 16:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/26	[A] DENISE TAY KWEE CHENG
19	18 Apr 2018 16:15	Adj Mandate Request	Cur.Reg:9236.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
20	19 Apr 2018 11:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/26. Mandate Remarks: Re-inspection to be d one for damage check and supplementary items / labour.	[I] Koh, Victor-CK
21	19 Apr 2018 11:35	Adj Mandate Set	Approved:8009.00:Re-Inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK
22	24 Apr 2018 09:48	Cim Registration Modified	Excess: 600.00 -> 300.00.	[I] Tr, Tinesh
23	18 May 2018 10:40	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/26	[A] SHIAU CHAN
24	18 May 2018 10:42	Adj Mandate Request	Cur.Reg:17116.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY AP PROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
25	18 May 2018 14:53	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/04/26. Mandate Remarks: Supplementary a pprove. Re-inspection to be done for damage check and supplementary items / lab our.	[I] Koh, Victor-CK
26	18 May 2018 14:53	Adj Mandate Set	Approved:15889.00:Supplementary approve. Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 18 May 2018

Preliminary Advice

Vehicle No	: SLS2342H	Accident Date	: 04/04/2018
Make	: AUDI A4	Policy No.	: 1700050656
Assignment Date	: 17/04/2018	Excess	: S\$600.00
Date of Inspection	: 17/04/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,268.00	(ESTIMATE \$11,038.00 + SUPPLEMENTARY \$8,230.00)
Revised Amount	:S\$	15,889.00	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	1,227.00	
Total	:S\$	17,116.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	69,049.00
Salvage Value	:S\$	
Margin for Repair	:S\$	80,951.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 24 April 2018 10:04 AM
To: Claims; SUR
Subject: RE: OD CLAIM FOR SLS 2342 H

Dear Tony,

Please be informed that the excess of above vehicle SLS 2342H is \$300.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 23 April 2018 2:03 PM
To: Claims <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIM FOR SLS 2342 H

Dear Tony,

Please be informed that we still pending for insurance's reply.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Monday, 23 April 2018 12:26 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: OD CLAIM FOR SLS 2342 H

Dear Shiau Cham,

Any update on the excess amount?

Thank you.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shiau Chan (LKKAuto)

From: Tr, Tinesh <Tinesh.Tr@aig.com>
Sent: Tuesday, 24 April 2018 9:51 AM
To: Shiau Chan (LKKAuto)
Cc: SUR; Claims Dept
Subject: RE: SLS2342H / OD / 04/04/2018 / Coverage & Excess update

Hi Shiau,

Excess been changed from \$600 to \$300 (50% waiver applied –in car camera –insured at fault)

Thus Excess is \$300.

Thanks,

Regards,

Tinesh Rajantran
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Tuesday, April 24, 2018 9:34 AM
To: Tr, Tinesh
Cc: SUR
Subject: RE: SLS2342H / OD / 04/04/2018 / Coverage & Excess update

Dear Tinesh,

Please refer to the below email.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]
Sent: Friday, 20 April 2018 11:40 AM
To: do-not-reply@merimen.com
Cc: SUR <sur@lkkauto.com>
Subject: Re: SLS2342H / OD / 04/04/2018 / Coverage & Excess update

This mail is associated with :
***SLS2342H (5313715072SG)**
OD
Apr 4 2018 12:00AM
[CHONG GUO FENG]
Premium Automobiles Pte Ltd

Dear Tinesh,

Kindly confirm the excess as the video footage uploaded.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561
Fax: 6256 4315

<-- Original Message -->

From: AIG_SG
To: LKK_HQ
Sent On: 18/04/2018 12:05 PM
Subject: SLS2342H / OD / 04/04/2018 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$600.00

Thank you
Tr, Tinesh

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 20 April 2018 11:33 AM
To: Claims; SUR
Subject: RE: OD CLAIM FOR SLS 2342 H

Dear Tony,

As instructed by our client AIG , please proceed to repair the insured vehicle **SLS 2342H (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Thursday, 19 April 2018 12:20 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: OD CLAIM FOR SLS 2342 H

Dear all,

Any update for this case?

Thank you.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	05 Apr 2018 16:46	Cim Veh Model Changed		[] Merimen Administrator
2	05 Apr 2018 16:46	Cim Created	Reg No: SLS2342H, Policy No: 1700050656, Acct Date: 2018/04/04, Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118045537	[I] Merimen Administrator
3	06 Apr 2018 11:32	Cim Registration Modified	Acct Time:18:50:00->00:00:00.	[I] Abu Kassim, Noor Mariesa
4	09 Apr 2018 09:43	Cim Registration Modified	Init.Est.:>4,000 - 5,000.	[I] Azlan, Syazalrdina
5	17 Apr 2018 17:35	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
6	17 Apr 2018 17:35	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
7	17 Apr 2018 17:35	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
8	17 Apr 2018 17:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/26	[A] CATHERINE CHONG KAI LING
9	17 Apr 2018 17:35	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
10	17 Apr 2018 17:35	Cim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
11	17 Apr 2018 17:35	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] CATHERINE CHONG KAI LING
12	17 Apr 2018 17:35	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
13	18 Apr 2018 12:05	Cim Registration Modified	Excess: -> 600.00. 2F Remarks: -> Not Applicable, GST: -> 7.00.	[I] Tr, Tinesh
14	18 Apr 2018 12:05	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
15	18 Apr 2018 16:08	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
16	18 Apr 2018 16:08	Cim Dtl Modified	JPJ Reg. Date: -> 2017/09/14.	[A] DENISE TAY KWEE CHENG
17	18 Apr 2018 16:08	Cim Details Notified		[A] DENISE TAY KWEE CHENG
18	18 Apr 2018 16:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/04/26	[A] DENISE TAY KWEE CHENG
19	18 Apr 2018 16:15	Adj Mandate Request	Cur.Req:9236.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
20	19 Apr 2018 11:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/04/26. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
21	19 Apr 2018 11:35	Adj Mandate Set	Approved:8009.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1780749	18/04/2018 16:08	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLS2342H		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 18 Apr 2018

Preliminary Advice

Vehicle No	: SLS2342H	Accident Date	: 04/04/2018
Make	: AUDI A4	Policy No.	: 1700050656
Assignment Date	: 17/04/2018	Excess	: S\$600.00
Date of Inspection	: 17/04/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,038.00
Revised Amount	:S\$	8,009.00
Check Items (Estimated)	:S\$	1,227.00
Total	:S\$	9,236.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	150,000.00
COE / PARF Rebate	:S\$	69,049.00
Salvage Value	:S\$	
Margin for Repair	:S\$	80,951.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8332G
Vehicle Details	
Vehicle No.:	SL52342H
Vehicle to be Exported:	No
Intended De-registration Date:	18 Apr 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC (NAV)
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	CVN045265
Chassis No.:	WAUZZZF43JA023227
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$34,732.00
Original Registration Date:	14 Sep 2017
First Registration Date:	14 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$30,625.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Sep 2027
PARF Rebate Amount:	\$22,968.00
Intended COE Rebate Details	
COE Expiry Date:	13 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$46,081.00
Total Rebate Amount:	\$69,049.00

The information contained herein is correct as at 18 Apr 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/04/2018 15:20
Date Of Accident	04/04/2018 18:50
Exact Location Of Accident	SLIP RD FROM UPPER PAYA LEBAR RD TO AIRPORT RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS2342H
Insured/Policyholder	
Name Of Registered Owner	CHONG GUO FENG
NRIC No	S8718332G
Email Address	GUOFENG87@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90928560
Alternative Phone No	OTHERS-90928560

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700050656
Cover Note Number	

Driver

Name of Driver	CHONG GUO FENG
NRIC No	S8718332G
Date Of Birth	21/06/1987
Occupation	INDOOR
Date Of Driving Pass	02/01/2009
Driving Experience	9 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90928560
Fax Number	
Contact Number	OTHERS-90928560
EMail Address	GUOFENG87@HOTMAIL.COM

Address	BLK 370 BUKIT BATOK STREET 31 #03-201
Postcode	650370
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING MY VEHICLE (SLS2342H) ON 04/04/2018 AT AROUND 1848 HRS AND ENTERED SLIP ROAD FROM UPPER PAYA LEBAR ROAD INTO AIRPORT ROAD. I STOPPED BEHIND VEHICLE SLV9400L AND WAITED FOR TRAFFIC TO CLEAR AND MOVE OFF. I WAS CHECKING FOR VEHICLES FROM THE RIGHT AND MOVED OFF THINKING THAT THE FRONT VEHICLE SLV9400L, HAD MOVED OFF AND CRASHED INTO THE VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV9400L
Vehicle Make/Model/Colour	HONDA VEZEL / GOLD COLOUR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUTHUKUTTI NADAR MAHALINGAM
NRIC/Passport Number	S2698516A
Contact Number	90076671
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 5/11/18 14:56:03

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Joy Fong

NRIC/FIN No.: G2040147X

Sketch Plan #2

SKETCH PLAN



A= SL52342H

B= SLV9400L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving my vehicle (SL52342H) and ~~entered~~ on 4/4/18 at around 1845hrs. and entered slip road from Upper Ryan Lebow Road into Airport Road. I stopped behind vehicle (SLV9400L) and waited for traffic to clear and move off. ~~Because~~ I was checking for vehicles from the right and moved off thinking that the first vehicle (SLV9400L) had moved off ~~and~~ and crashed into the vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 5/4/18 1845hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Tony Fong

NRIC/TIN No: 6206010X

Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8718332G



Name

CHONG GUO FENG

张国丰

Race

CHINESE

Date of birth

21-06-1987

Sex

M

Country of birth

SINGAPORE

S8718332G

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S8718332G

Name

CHONG GUO FENG

Birth Date: 21 Jun 1987

Issue Date: 02 Jan 2009



4402607

NRIC No: S8718332G



Date of issue

15-05-2009

Address

APT BLK 370 BUKIT BATOK STREET 31
#03-201
SINGAPORE 650370

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3A Motor cars without clutch pedals (Auto) <= 3000kg 02 Jan 2009
with <= 7 passengers, exclusive of the driver, and
other motor vehicles without clutch pedals <= 2500kg

NP 428A





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : CHONG GUO FENG
Period of Insurance : 14 Sep 2017 To 13 Sep 2018
Engine No. : CVN045265
Chassis No. : WAUZZZF43JA023227

Vehicle No. : SLS2342H
Policy No. : 1700050656
Endorsement No. :
Issued Date : 22 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDRE") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

CHONG GUO FENG - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 83662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia).

0504125220

PREMIUM LEASING - MH

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Chiang Qian Yee

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0421/2018/CCS
Date	:	06-Apr-18

Vehicle NOT IN workshop. Kindly assist to arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Chong Guo Fend
Address	:	Blk 370 Bukit Batok Street 31 #03-201 Singapore 650370
Telephone	:	HP +65 90928560
Type of Claim	:	Own Damage Claims
Policy No.	:	1700050656
Vehicle No	:	SLS 2342 H
Model Code	:	Audi A4 SEDAN 1.4 TFSI
Model / Year	:	Sep-17
Engine No	:	CVN 045265
Chassis No	:	WAUZZZF43JA023227
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	04-Apr-18
Place of Accident	:	Slip Rd from Upper Paya Lebar Rd to Airport Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 2342 H.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 //	
2	To remove front fittings, dismantle both headlights, remove and renew front bumper, radiator grille, lock carrier bracket and bonnet. Align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,800.00 1000 //	
3	To respray front bumper and bonnet.	\$ 1,500.00 1100 //	
4	To carry out diagnostic checks.	S/N \$ 192.00 //	
TOTAL LABOUR CHARGES		: \$ <u>3,852.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 2342 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Replaced</i>	\$ 2,020.00	✓ 1479.20
2	RADIATOR GRILLE <i>Cracked</i>	\$ 972.00	✓ 772.70
3	FRONT REINFORCEMENT BEAM <i>Not New</i>	\$ 702.00	? 8
4	FRONT BUMPER FOAM <i>Not New</i>	\$ 107.00	? 8
5	FRONT LOCK CARRIER BRACKET <i>Cracked</i>	\$ 118.00	? 44. ✓
6	FRONT BUMPER TOP COVER <i>Not New</i>	\$ 109.00	X
7	SIGN ' CAUTION ' STICKER <i>Not New</i>	\$ 12.00	X
8	BONNET <i>Dented</i>	\$ 2,163.00	✓ 1730.40
9	BONNET ATTACHMENT PARTS <i>Not New</i>	\$ 105.00	X
10	BONNET IMPACT PROTECTION - CENTER <i>2 New</i>	\$ 24.00	✓ 18.88
11	BONNET IMPACT PROTECTION - LH/RH	2 \$ 48.00	✓ 37.76
12	BONNET STOP BUFFER <i>Not New</i>	\$ 17.00	X
13	BONNET LOCK STRIKER - LH/RH <i>Not New</i>	2 \$ 88.00	X
14	BONNET LOCK <i>Not New</i>	2 \$ 376.00	X
15	FRONT NO. PLATE <i>New</i>	S/N \$ 25.00	✓
16	SUNDRIES <i>New</i>	\$ 300.00	? 38.48 ✓
TOTAL SPARE PARTS		:	\$ 7,186.00
TOTAL LABOUR CHARGES		:	\$ 3,852.00
GRAND TOTAL		:	\$ 11,038.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

19823.60

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Loo
Surveyed Date : 17/04/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, OSP's

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0421/2018/CCS
Date 14-May-18
Service Advisor Jeffery Tan
Pages 1
Regn No SLS 2342 H
Model No Audi A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	LED headlight - LHS	\$ 6,973.00	✓ 5578.40
2	Headlight Control Unit - LHS	\$ 657.00	✓ 525.60
		\$ 7,630.00	
LABORS			
1	To renew LHS headlight.	\$ 600.00	250 ✓
TOTAL		\$ 8,230.00	

For Premium Automobiles Pte Ltd

Adrian Ling
15/05/18.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0421/2018/CCS
Date : 6-Apr-18

Vehicle NOT IN workshop. Kindly assist to arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

5 days of repairs - ok - jb - 4 Jul 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chong Guo Fend
Address : Blk 370 Bukit Batok Street 31
#03-201
Singapore 650370
Telephone : HP +65 90928560
Type of Claim : Own Damage Claims
Policy No. : 1700050656
Vehicle No : **SLS 2342 H**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Sep-17
Engine No : CVN 045265
Chassis No : WAUZZZF43JA023227
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 4-Apr-18
Place of Accident : Slip Rd from Upper Paya Lebar Rd to Airport Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 2342 H.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To remove front fittings, dismantle both headlights, remove and renew front bumper, radiator grille, lock carrier bracket and bonnet. Align to position. Re-organise front crash management components. Reinstall all parts removed.	\$	1,800.00	\$ 1,000.00
3	To respray front bumper and bonnet.	\$	1,500.00	\$ 1,100.00
4	Added labour - see attached	\$	600.00	\$ 250.00
5	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,452.00	\$ 2,902.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 2342 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,020.00	\$ 1,479.20
2	RADIATOR GRILLE	\$ 972.00	\$ 777.20
3	FRONT REINFORCEMENT BEAM	\$ 702.00	
4	FRONT BUMPER FOAM	\$ 107.00	
5	FRONT LOCK CARRIER BRACKET	\$ 118.00	\$ 94.00
6	FRONT BUMPER TOP COVER	\$ 109.00	
7	SIGN ' CAUTION ' STICKER	\$ 12.00	
8	BONNET	\$ 2,163.00	\$ 1,730.40
9	BONNET ATTACHMENT PARTS	\$ 105.00	
10	BONNET IMPACT PROTECTION - CENTER	\$ 24.00	\$ 18.88
11	BONNET IMPACT PROTECTION - LH/RH	2 \$ 48.00	\$ 37.76
12	BONNET STOP BUFFER	\$ 17.00	
13	BONNET LOCK STRIKER - LH/RH	2 \$ 88.00	
14	BONNET LOCK	2 \$ 376.00	
15	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
16	<i>Added parts - see attached.</i>	\$ 8,325.00	\$ 6,659.60
18	SUNDRIES	\$ 300.00	\$ 38.48
TOTAL SPARE PARTS		\$ 15,511.00	\$ 10,860.52
TOTAL LABOUR CHARGES		\$ 4,452.00	\$ 2,902.00
GRAND TOTAL		\$ 19,963.00	\$ 13,762.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0421/2018/CCS 14-May-18 Jeffery Tan 1 SLS 2342 H Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	LED headlight - LHS <i>cracked</i>	\$ 6,973.00	\$ 5,578.40
2	Headlight Control Unit - LHS <i>damaged</i>	\$ 657.00	\$ 525.60
3	Power module <i>damaged</i>	\$ 695.00	\$ 555.60
		\$ 8,325.00	\$ 6,659.60
<u>LABORS</u>			
1	To renew LHS headlight.	\$ 600.00	\$ 250.00
TOTAL		\$ 8,925.00	\$ 6,909.60

Premium Automobiles Pte Ltd

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Motor Claims Dept

Yr Ref: SLS 2342 H

Norah Khai

6768 9911

6841 1183

Nora.khai@premiumauto.com.sg

Body & Paint Dept

PA/OD/0421/2018/MAS

31 July 2018

from

Telephone +65-

Telefax +65-

EMail

Our department

Our Ref

Your Ref

Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLS 2342 H, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above mentioned vehicle, no. **SLS 2342 H**, claimant, **Mr. Chong Guo Feng**, please find the related document as per attached.

1. A copy of the Original invoice no. 85012790 - \$14,404.90
2. A copy of letter of Discharge duly signed by client

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer generated document. No signature is required.

Norah Khai

Claims Dept

Encls

AIG Insurance – SLS 2342 H

total pages

Premium Automobiles Pte Ltd
Showroom

9 Leng Kee Road

Singapore 159090

Telephone (65) 6566 1111

Telefax (65) 6471 3733

Service & Parts Centres

55 Ubi Rd 1

Singapore 408699

Telephone (65) 6366 2323

Telefax (65) 684 11183

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8718332G



Name

CHONG GUO FENG

张 国 丰

Race

CHINESE

Date of birth

21-06-1987

Country of birth

SINGAPORE

Sex

M

S8718332G

REPUBLIC OF SINGAPORE DRIVING LICENCE




Licence Number: S8718332G

Name

CHONG GUO FENG

Birth Date: 21 Jun 1987

Issue Date: 02 Jan 2009



001603900A



4402607

NRIC No. S8718332G



Date of issue

15-05-2009

Address

APT BLK 370 BUKIT BATOK STREET 31
#03-201
SINGAPORE 650370

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3A Motor cars without clutch pedals (Auto) $\leq$ 3000kg 02 Jan 2009
with $\leq$ 7 passengers, exclusive of the driver; and
other motor vehicles without clutch pedals $\leq$ 2500kg

NP 428A



Licence No: S8718332G

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : CHONG GUO FENG
 Period of Insurance : 14 Sep 2017 To 13 Sep 2018
 Engine No. : CVN045265
 Chassis No. : WAUZZZF43JA023227

Vehicle No. : SLS2342H
 Policy No. : 1700050656
 Endorsement No. :
 Issued Date : 22 Sep 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
 Engine Capacity/Tonnage : 1,395.00 CC Sum Insured : Market Value First Year of Registration : 2017
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

CHONG GUO FENG - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125220

PREMIUM LEASING - MH
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Janik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE
 Chong Guan Yee



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
35 Ubi Road 1
Singapore 408620
Telephone: 6388 2223

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2323
6628 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 17:57

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012790 Date : 30/07/2018 Order : SLS2342H Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS2342H (V 35007) Regn Date: 14/09/2017 Mileage: 16126 WIP No.: 61296

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF43JA023227 Engine: CVN 045265 Dept: U

VS8 No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
D	EXC	M: 8888 Insurance Excess/Liability	-300.00	1.00	-300.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHTS WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO REMOVE AND FRONT FITTINGS, DISMANTLE BOTH HEADLIGHTS, REMOVE AND RENEW FRONT BUMPER, RADIATOR GRILLE, LOCK CARRIER BRACKET AND BONNET, ALIGN TO POSITION, REORGANISE FRONT CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M:	192.00	1.00	192.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408090
Telephone: 6380 2123

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2323
6628 1233

Page 2 17:57

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012790 Date : 30/07/2018 Order : SLS2342H Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLS2342H (V 35007) Regn Date: 14/09/2017 Mileage: 16126 WIP No.: 61296

Model: AA SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF43JA023227 Engine: CVN 045265 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECKS N:	250.00	1.00	250.00
X	ABW0853651ABRN4	GRILLE	1.00	971.50	777.20
X	ABW0941773A	HEADLIGHT	1.00	6973.00	5,578.40
X	ABW0823029A	HOOD	1.00	2163.00	1,730.40
X	ABW0807065C GRU	COVER	1.00	1849.00	1,479.20
X	ABW0807283	GUIDE	1.00	30.70	24.56
X	ABW0823125	PROTECTION	1.00	23.60	18.88
X	ABW0823126	PROTECTION	1.00	23.60	18.88
X	ABW0807771	BRACKET	1.00	117.50	94.00
X	A4W0907397AD	CTRL UNIT (V)	1.00	657.00	525.60
X	A7PP941572AB200	POWER MOD	1.00	694.50	555.60
X	AN 0161857	POP-RIVET	6.00	2.90	13.92
X	ABW0823124	PROTECTION	1.00	23.60	18.88

Parts 10,835.52
Labour 0.00
Sublet 2,927.00
Menus 0.00
Lubricant 0.00

Sub-Total 13,462.52

7% GST 942.38

Grand Total 14,404.90



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLS2342H

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0421/2018/TF
21 May 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI S tronic
Vehicle Chassis No. : WAUZZZF43JA023227
Vehicle Regn No. : SLS2342H
Vehicle Mileage : 16125KM
Vehicle Owner : Mr. Chong Guo Feng
Certificate No : 1700050656
Policy Excess : S\$856.00 (inclusive GST)
Accident Date : 4 April 2018
Place : Slip Rd From Upper Paya Lebar Rd to Airport Rd
Repair Cost : \$ 14,404.90
WIP No. : 61296
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 22/5/18
Date :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Apr 2018		17 Apr 2018 17:35 Edit Adj Rpt	S\$13,762.52 Edit Estimates	S\$13,762.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHONG GUO FENG , ID: S8718332G, Tel: +6590928560, Email: GUOFENG87@HOTMAIL.COM								
Vehicle Reg. No.:	SLS2342H	Date of Loss:	04/04/2018 00:00 - :59 [6 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 5313715072SG	Policy/Cover Note No.:	1700050656 (Comprehensive)						
		Excess:	S\$300.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/04/2018]								
Driver/Custodian:	CHONG GUO FENG (30 / Male), NRIC: S8718332G, Tel: +6590928560								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (18/05/2018): Alert - Adj Mandate Approved (S\$15889.00) - SLS2342H - Claim Handler: Tr, Tinesh - AIG_SG (24/04/2018): SLS2342H / OD / 04/04/2018 / Coverage & Excess update - AIG_SG (19/04/2018): Alert - Adj Mandate Approved (S\$8009.00) - SLS2342H - Claim Handler: Tr, Tinesh - AIG_SG (18/04/2018): SLS2342H / OD / 04/04/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS2342H (5313715072SG)
OD
Apr 4 2018 12:00AM
[CHONG GUO FENG]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		v	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	20/04/18 11:34	Video - Accident													Load MP4					
															1 per page		v	☒		
Assessment Reports															1 per page		v	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	18/04/18 16:15	Adjuster Immediate Advice													Load HTM					
2	18/05/18 10:40	Adjuster Immediate Advice													Load HTM					
															3 per page		v	☒		
Photos/Images															3 per page		v	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	18/04/18 16:01	General View													Load JPG	☒				
2	18/04/18 16:01	General View													Load JPG	☒				
3	18/04/18 16:01	General View													Load JPG	☒				
4	18/04/18 16:01	General View													Load JPG	☒				
5	18/04/18 16:01	General View													Load JPG	☒				
6	18/04/18 16:01	General View													Load JPG	☒				
7	18/04/18 16:01	General View													Load JPG	☒				
8	18/04/18 16:01	General View													Load JPG	☒				
9	18/04/18 16:01	General View													Load JPG	☒				
10	18/04/18 16:01	General View													Load JPG	☒				
11	18/04/18 16:01	General View													Load JPG	☒				
12	18/04/18 16:01	General View													Load JPG	☒				
13	18/04/18 16:01	General View													Load JPG	☒				
14	18/04/18 16:01	General View													Load JPG	☒				
15	18/04/18 16:01	General View													Load JPG	☒				
16	18/04/18 16:01	General View													Load JPG	☒				
17	18/04/18 16:01	General View													Load JPG	☒				
18	18/04/18 16:01	General View													Load JPG	☒				
19	18/04/18 16:01	General View													Load JPG	☒				
20	18/04/18 16:01	General View													Load JPG	☒				
21	18/05/18 10:41	Reinspection Photo													Load JPG	☒				
22	18/05/18 10:41	Reinspection Photo													Load JPG	☒				
23	18/05/18 10:41	Reinspection Photo													Load JPG	☒				
24	18/05/18 10:41	Reinspection Photo													Load JPG	☒				
25	18/05/18 10:41	Reinspection Photo													Load JPG	☒				
26	18/05/18 10:41	Reinspection Photo													Load JPG	☒				
27	18/05/18 10:41	Reinspection Photo													Load JPG	☒				
28	18/05/18 10:41	Reinspection Photo													Load JPG	☒				
29	18/05/18 10:41	Reinspection Photo													Load JPG	☒				
30	18/05/18 10:41	Reinspection Photo													Load JPG	☒				
31	18/05/18 10:41	Reinspection Photo													Load JPG	☒				

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
32	18/05/18 10:41	Reinspection Photo	 Load JPG	☒
33	18/05/18 10:41	Reinspection Photo	 Load JPG	☒
34	18/05/18 10:41	Reinspection Photo	 Load JPG	☒
35	18/05/18 10:41	Reinspection Photo	 Load JPG	☒
36	18/05/18 10:41	Reinspection Photo	 Load JPG	☒
37	18/05/18 10:41	Reinspection Photo	 Load JPG	☒
38	18/05/18 10:41	Reinspection Photo	 Load JPG	☒
39	18/05/18 10:41	Reinspection Photo	 Load JPG	☒
40	18/05/18 10:41	Reinspection Photo	 Load JPG	☒
41	16/07/18 19:27	Reinspection Photo	 Load JPG	☒
42	16/07/18 19:27	Reinspection Photo	 Load JPG	☒
43	16/07/18 19:27	Reinspection Photo	 Load JPG	☒
44	16/07/18 19:27	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 16:00	Certificate of Insurance	 Load PDF	
2	18/04/18 16:00	Driver's Driving License	 Load PDF	
3	18/04/18 16:00	ESTIMATE	 Load PDF	
4	18/04/18 16:00	Singapore Accident Statement	 Load PDF	
5	14/08/18 09:35	WORKSHOP INVOICE	 Load PDF	
6	14/08/18 09:35	DISCHARGE VOUCHER	 Load PDF	
7	14/08/18 09:35	SUPPLEMENTARY PART	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	05/04/18 16:46	Accident Statement	 Load HTM		
Photos/Images			3 per page	☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	05/04/18 16:42	Accident Photo	 Load JPG	☒	
2	05/04/18 16:42	Accident Photo	 Load JPG	☒	
3	05/04/18 16:42	Accident Photo	 Load JPG	☒	
4	05/04/18 16:42	Accident Photo	 Load JPG	☒	
5	05/04/18 16:42	Accident Photo	 Load JPG	☒	
6	05/04/18 16:42	Accident Photo	 Load JPG	☒	
7	05/04/18 16:42	Accident Photo	 Load JPG	☒	
8	05/04/18 16:42	Accident Photo	 Load JPG	☒	
9	05/04/18 16:42	Accident Photo	 Load JPG	☒	
10	05/04/18 16:42	Accident Photo	 Load JPG	☒	
11	05/04/18 16:42	Accident Photo	 Load JPG	☒	
Documentation			1 per page	☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	05/04/18 16:43	Sketch Plan	 Load JPG	☒	
2	05/04/18 16:43	Sketch Plan #2	 Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18007128/AQBQ2

Date: 14/08/2018

REFERENCE

Insured/Claimant: CHONG GUO FENG Policy No: 1700050656
Date of Loss: 04/04/2018 Nature of Claim: OD Claim No: 5313715072SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS2342H**
Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN045265
Reg. Date: 14/09/2017 (Man. Year: 2017) Chassis No: WAUZZZF43JA023227
Colour: Black Odometer: 14620 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$150,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 245/35 R19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,845.60	10,860.52	2,985.08	21.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,452.00	2,902.00	1,550.00	34.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,297.60	13,762.52	4,535.08	24.79
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	17,997.60	13,462.52	4,535.08	25.20
+ GST 7.00/7.00% (S\$)	1,259.83	942.38	317.45	25.20
Nett Amount (S\$)	19,257.43	14,404.90	4,852.53	25.20

INSPECTION

Date of Assignment: 17/04/2018
Date Inspected: 17/04/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,020.00 FS	*1,479.20 FS
2	1		*RADIATOR GRILLE	Cracked	972.00 FS	*777.20 FS
3	1		*FRONT REINFORCEMENT BEAM	Not Necessary	702.00 FS	*- FS
4	1		*FRONT BUMPER FOAM	Not Necessary	107.00 FS	*- FS
5	1		*FRONT LOCK CARRIER BRACKET	Cracked	118.00 FS	*94.00 FS
6	1		*FRONT BUMPER TOP COVER	Not Necessary	109.00 FS	*- FS
7	1		*SIGN CAUTION STICKER	Not Necessary	12.00 FS	*- FS
8	1		*BONNET	Dented	2,163.00 FS	*1,730.40 FS
9	1		*BONNET ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
10	1		*BONNET IMPACT PROTECTION -CENTER	Necessary	24.00 FS	*18.88 FS
11	2		*BONNET IMPACT PROTECTION -LH/RH	Necessary	48.00 FS	*37.76 FS
12	1		*BONNET STOP BUFFER	Not Necessary	17.00 FS	*- FS
13	2		*BONNET LOCK STRIKER -LH/RH	Not Necessary	88.00 FS	*- FS
14	2		*BONNET LOCK	Not Necessary	376.00 FS	*- FS
15	1		*FRONT NO .PLATE	Necessary	25.00 FS	*25.00 FS
16	1		*SUNDRIES	Necessary	300.00 FS	*38.48 FS
17	1		*LED HEADLIGHT -LHS	Cracked	5,578.40 FS	*5,578.40 FS
18	1		*HEADLIGHT CONTROL UNIT-LHS	Cracked	525.60 FS	*525.60 FS
19	1		*POWER MODULE	Damaged	555.60 FS	*555.60 FS
Total Parts (\$\$)					13,845.60	10,860.52

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE FRONT FITTINGS ,DISMANTLE BOTH HEADLIGHTS ,REMOVE AND RENEW FRONT BUMPER ,RADIATOR GRILLE ,LOCK CARRIER BRACKET AND BONNET.ALIGN TO POSITION .RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,800.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
5	TO RENEW LHS HEADLIGHT	New	600.00	250.00
Gross Labour Cost (\$\$)			4,452.00	2,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >