



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18007141/Kga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 09-07-2019



ATTN: SAW THENG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 822H	Veh. Inspected	SLN 4133H
Policy No.	GA300046/1	Coverage (\$)	0.00
Claim No.	S8M00E3I	Excess (\$)	0.00
Assign From	SAW THENG	Assign Date	17/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU803556649	Colour	METALLIC PEARL WHITE
Odometer	68477	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	YOKOHAMA	9 mm
L/H Front Tyre	195/65R15	YOKOHAMA	9 mm
R/H Rear Tyre	195/65R15	YOKOHAMA	9 mm
L/H Rear Tyre	195/65R15	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/04/2018	Inspection Date	17/04/2018
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------