

Surveyor: ADMAN DOI: 16-04-18 Date / Time: 16-04-18

Pre-assign / CCU / FTE



Insured Vehicle No.: SKD 8614 A  
 Name of Insured: CHAN CHOI FOONG  
 Insured Tel No.: HP:  
 Excess Sec II :SS D.O.A. 09-04-18  
 Is driver the owner? ( YES / NO ) Nature of Accident:

Claim No.: 62582493056  
 Policy No.: 180005176  
 Make / Model: M-BENZ C180  
 Place of Accident: Serangoon Ave 2

If NO, Driver Name / Age: SG 5781R OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
 Driver Tel No.: (V/L: YES / NO) Insured Liability: % Final ? Yes / No



INSRS: WSP: u2 spray  
 Tel: painting  
 Liability:  
 RMKS:



INSRS:  
 WSP:  
 Tel:  
 Liability:  
 RMKS:



INSRS:  
 WSP:  
 Tel:  
 Liability:  
 RMKS:



INSRS:  
 WSP:  
 Tel:  
 Liability:  
 RMKS:

Date/ Time

09/05/18

SG 5781R - X;  
SKD 8614 A, MALACCA 60199-7144; VIN: 18710111  
PAINTING  
CONTRACTOR will do if he was the owner of  
BEHIND VEHICLE.  
spoke to UJ (Mc Nam) at 9327 0611, UJ loaned the  
accident statement, I turned her about the TP claim and HED  
issue. UJ agreed and waive the HED issue will letter to UJ  
together with addendum document.  
TP LOD IN BY EMAIL  
SEND SET OFFER TO TP.  
TP ACCEPTED OFFER.  
All Doc IN ORDER.  
TO close.

| STAGE                             | DATE / PIC                          |
|-----------------------------------|-------------------------------------|
| Non-Reporting ltr (1st):          |                                     |
| Non-Reporting ltr (2nd):          |                                     |
| Non-Reporting ltr (Final):        |                                     |
| Notification ltr (if non-pickup): |                                     |
| Call OI:                          |                                     |
| After call ltr to OI:             | <u>16/4/2018</u>                    |
| Documentation Check List: Handler | Typist                              |
| Notification ltr (if non-pickup)  | <input checked="" type="checkbox"/> |
| After call ltr to OI:             | <input checked="" type="checkbox"/> |
| Authorisation To Act:             | <input checked="" type="checkbox"/> |
| Release Voucher:                  | <input checked="" type="checkbox"/> |
| Final Repair Bill:                | <input checked="" type="checkbox"/> |
| Car Rental Invoice:               | <input type="checkbox"/>            |
| Towing Invoice:                   | <input type="checkbox"/>            |
| LTA / GIA:                        | <input type="checkbox"/>            |
| Medical Bill:                     | <input type="checkbox"/>            |
| PIR:                              | <input type="checkbox"/>            |
| Mandate/Reject Instruction:       | <input type="checkbox"/>            |
| LOD                               | <input checked="" type="checkbox"/> |
| Payment Breakdown Form:           | <input type="checkbox"/>            |
| Post-Repair Photos:               | <input type="checkbox"/>            |
| Others:                           | <input type="checkbox"/>            |

RECEIVED 14 MAY 2018  
RECEIVED 23 MAY 2018

|  |   |  |                                  |
|--|---|--|----------------------------------|
| <b>PRELIMINARY ADVICE</b>  |   | Date/Time:   | Sent By:                         |
| <b>FINALIZATION</b>  |   | Date/Time:   | Confirm with:                    |
| Repair Cost:   | <u>46</u>   | SS <u>3,800.00</u>   | Confirm by:                      |
| <b>FINAL SETTLEMENT</b>  |   | Date/Time:   | Confirm with:                    |
| Final Liability:   | % <u>100</u>  | (Agreed / Assessed)  | BOLA S/N No.: <u>27</u>          |
| Repair Cost:   | SS <u>3,800.00</u>  | Email <input type="checkbox"/> Call <input type="checkbox"/> |                                  |
| Loss of Rental (LOR):  | SS <u>-</u>   | If NO or B 28, Ass. Lia: <u>LOI REPAIR - ENJOY TO</u>        |                                  |
| Loss of Use (LOU):   | SS <u>420.00</u>  | x <u>7</u> days  |                                  |
| Loss of Income (LOI):  | SS <u>-</u>   | x <u>-</u> days  |                                  |
| LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> | LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> | [Tick only one]  |                                  |
| GIA/LTA Search   | SS <u>-</u>   | 1) Claim status: <u>Normal/Reject/Private Settle</u>         |                                  |
| Medical:   | SS <u>-</u>   | 2) Report Format:  |                                  |
| Disbursement:  | SS <u>-</u>   | (e.g Tow/ Independent)                                       |                                  |
| Legal Cost   | SS <u>-</u>   | 3) Survey fee: <u>4320.00</u>                                |                                  |
| Total:   | SS <u>3,920.00</u>  | Global Sum SS:   | <u>3,900.00</u>                  |
| <b>FINAL PAYMENT</b>   |   | Date/Time:   | Confirm with:                    |
| Payee 1:   | SS <u>3,900.00</u>  | Name 1:  | <u>U2 SPRAY PAINTING PTB LOD</u> |
| Payee 2: (Strike if N.A.)  | SS <u>-</u>   | Name 2:  | <u>-</u>                         |
| Payee 3: (Strike if N.A.)  | SS <u>-</u>   | Name 3:  | <u>-</u>                         |

ASS. REC. BY: Adrian King

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJ6578 IR. Yr Regn: 2008 July.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic c.c. 1595Colour: Bronze A/C: Insured / Std / NI / NASp. Reading: 309510 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHMF D452085201842Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55 R16R: 205/55 R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 16/04/18Survey held at U2 Spray PaintingDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.L/B \$3,500.00CRD: \$4,863.40 (56%)MV: 14KPV: 9.6KNett: 4.4K.

Date/Time, File Pass to?

☐ : Preli. Report1) \_\_\_\_\_  
Date/Time, File Return to?☐ : Final Report

2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) \$ + RS \$ \_\_\_\_\_☐ : Interview (\$ \_\_\_\_\_) Photos \_\_\_\_\_☐ : Tech. Invs (\$ \_\_\_\_\_) Others \_\_\_\_\_☐ : Weekend (\$ \_\_\_\_\_) TOTAL \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |  |                            |            |   |
|---|--|----------------------------|------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD  |  | Ref : CC6/AIG18007144/Aha3 |            |   |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120   |  | Date : 17-04-2018          |            |  |
| Code : AIG  |  |                            |            |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |                            |            |   |
| Insured Veh.  | SKD 8614A  | Veh. Inspected             | SJG 5781R  |   |
| Policy No.  |  | Coverage (\$)              | 0.00       |   |
| Claim No.   |  | Excess (\$)                | 0.00       |   |
| Assign From   |  | Assign Date                | 17/04/2018 |   |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |                            |            |   |
| Make & Model  |  | c.c                        | 0          |   |
| Engine No.  | HIDDEN   | Year of Reg.               |            |   |
| Chassis No.   |  | Colour                     |            |   |
| Odometer  | -  | Steering                   |            |   |
| Brakes  |  | Modification               |            |   |
| General   |  |                            |            |   |
| <b>3. Conditions of Tyres</b>   |  |                            |            |   |
|   | Size   | Make                       | Balance    |   |
| R/H Front Tyre  |  |                            | mm         |   |
| L/H Front Tyre  |  |                            | mm         |   |
| R/H Rear Tyre   |  |                            | mm         |   |
| L/H Rear Tyre   |  |                            | mm         |   |
| <b>4. Description of Damages</b>  |  |                            |            |   |
|   |  |                            |            |   |
| <b>5. General Information</b>   |  |                            |            |   |
| Accident Date   | 09/04/2018   | Inspection Date            | 16/04/2018 |   |
| Survey held at  | U2 SPRAY PAINTING PTE LTD<br>25 KAKI BUKIT ROAD 4<br>#06-43 SYNERGY @ KB<br>SINGAPORE 417800 |                            |            |   |
| <b>5a. Remarks</b>  |  |                            |            |   |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                            |            |   |

Enquire PARF/COE Rebate for Registered Vehicle

|                                     |                          |
|-------------------------------------|--------------------------|
| <b>Vehicle Owner Particulars</b>    |                          |
| Owner ID Type:                      | Singapore NRIC           |
| Owner ID:                           | 8785G                    |
| <b>Vehicle Details</b>              |                          |
| Vehicle No.:                        | SJG5781R                 |
| Vehicle to be Exported:             | Yes                      |
| Intended De-registration Date:      | 14 Apr 2018              |
| Vehicle Make:                       | HONDA                    |
| Vehicle Model:                      | CIVIC 1.6L VTI 5MT       |
| Primary Colour:                     | Grey                     |
| Manufacturing Year:                 | 2008                     |
| Engine No.:                         | R16A13005673             |
| Chassis No.:                        | JHMFD452085201842        |
| Maximum Power Output:               | 92.0 kW (123 bhp)        |
| Open Market Value:                  | \$18,548.00              |
| Original Registration Date:         | 07 Jul 2008              |
| First Registration Date:            | 07 Jul 2008              |
| Transfer Count:                     | 0                        |
| Actual ARF Paid:                    | \$18,548.00              |
| <b>Intended PARF Rebate Details</b> |                          |
| PARF Eligibility:                   | Yes                      |
| PARF Eligibility Expiry Date:       | 06 Jul 2018              |
| PARF Rebate Amount:                 | \$9,274.00               |
| <b>Intended COE Rebate Details</b>  |                          |
| COE Expiry Date:                    | 06 Jul 2018              |
| COE Category:                       | A - Car (1600cc & below) |
| COE Period (Years):                 | 10                       |
| QP Paid:                            | \$14,590.00              |
| COE Rebate Amount:                  | \$331.00                 |
| <b>Total Rebate Amount:</b>         | <b>\$9,605.00</b>        |

The information contained herein is correct as at 14 Apr 2018.

OK



## ANNOUNCING Universe Motoring as sgCarMart Premium Dealer 2018

**UNIVERSE**  
MOTORING

honda civic

Price Range

Depreciation

2008

Vehicle Type

Advanced Search

### Used Car Comparison

--- Comparing 4 Vehicles ---

Honda Civic 1.8A VTI-S

Honda Civic 1.8A VTI-S

Honda Civic 1.8A VTI-S GL

Honda Civic 1.6A VTI



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

#### CAR DETAILS

|                   |   |  |   |  |
|-------------------|---|--|---|--|
| Price             | \$18,888  | \$15,800   | \$19,800  | \$17,388   |
| Instalment        | \$13,255  | \$3,714  | \$2,014   | \$1,769  |
| Registration Date | 15-Jun-2008   | 18-Jul-2008  | 21-Nov-2008   | 25-Nov-2008  |
| Manufactured      | 2008  | 2008   | 2008  | 2008   |
| Mileage           | 128,925 km  | 148,305 km   | 100,000 km  | 122,000 km   |
| Transmission      | Auto  | Auto   | Auto  | Auto   |
| Engine Cap        | 1,799 cc  | 1,799 cc   | 1,799 cc  | 1,595 cc   |
| Road Tax          | \$978 /yr   | \$978 /yr  | \$978 /yr   | \$740 /yr  |
| Power             | -   | 103.0 kW (138 bhp)   | 103.0 kW (138 bhp)  | 92.0 kW (123 bhp)  |
| Curb Weight       | 0 kg  | 1,219 kg   | 1,240 kg  | 1,220 kg   |
| Features          | -   | 1.8L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Multi Function Steering Wheel, Paddle Shifters, Reverse Sensors, Auto Climatic Air-con.  | Responsive SOHC 16V, 138 BHP I-VTEC Engine, 5 Speed Auto Transmission With Paddle Shift, SRS Airbags, ABS System, Immobilizer.  | Powerful SOHC 16 Val Engine, SRS Airbags, 5 Transmission, Tyres C Drive, Original Rims, L  |
| Accessories       | -   | Sport Rims, Factory Fitted Audio System, Solar Film, Electrical Retractable Side Mirrors With Indicator, Upholstery Leather Seats.   | Upgraded 18" Sport Rims, Premium Pioneer Full ICE System, Auto Climatic Control! Type-R Bodykit! Door Visors! Fog Lamps! Reverse Sensors And Camera!  | Upgraded DVD Player Leather Seats, Sports Reverse Sensors, Retr. Mirrors, Fog Lamps.   |
| Description       | Suspension, Engine Mounting And Alternator Replace In Feb 2016. Overall Working Fine, Very Good For COE Renewal. Suitable For Short Term Usage As Well. SMS Only. | \$0 Down Payment Available! Ideal For Short Term Usage! Only 1 Owner! Very Low Mileage! Extended Warranty Available! Well Kept By Previous Owner In Tip Top Condition, With Evident From The Car Itself! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Visit Us At Our Showroom To Appreciate It In Pristine Condition Now! | Ex DPC Converted. Type R Body Kit. One And Only In The Market! Ment To Be Pampered And Renew Another 10 Years! View To Appreciate! Facelift Model With Octagon Tail Lamps! Call For Appointment Before It's Gone! | With New 10 Year COE Year COE At : \$38888. Renewed Till End Of C Servicing Done At 115 Ideal For COE Renewa By Fussy Owner. No R Low Petrol Consumptk Based On City Driving. Welcomed, Loan And Available, Viewing By |
| COE               | \$16,898  | \$14,689   | \$1,643   | \$10,455   |
| OMV               | \$20,467  | \$20,495   | \$23,235  | \$20,211   |
| ARF               | \$20,467  | \$20,495   | \$20,588  | \$20,211   |
| Depreciation      | -   | -  | \$15,920 /yr  | \$11,970 /yr   |
| No. of Owners     | 1   | 1  | 1   | 2  |
| Type of Vehicle   | Sedan   | Sedan  | Sedan   | Sedan  |
| Category          | PARF Car, Direct Owner Sale   | PARF Car   | PARF Car  | PARF Car   |
| Availability      | Available   | Available  | Available   | Available  |

# U2 SPRAY PAINTING PTE LTD

Block 25 Kaki Bukit Road 4, #06-43 Synergy @ KB Singapore 417800  
HP: 96583371

LOH JUAT LENG

Bk 25 Kaki Bukit Rd 4

# 06-43 SYNERGY @KB

Singapore 417800

14<sup>th</sup> April 2018

Accident date: 09<sup>th</sup> April 2018

Estimated repair cost for vehicle no: SJG5781R HONDA CIVIC 1.6 '08

| S/n | Qty | Items  | U/price  | Amount             |
|-----|-----|--|----------|--------------------|
| 1   | 1   | Rear Boot Lid <i>Painted</i>                           |          | \$580.70 ✓         |
| 2   | 2   | Rear Boot Lid Hinges <i>new</i>                        | \$59.60  | \$119.20 +         |
| 3   | 1   | Rear Boot Lid Civic logo <i>2pc</i>                    |          | \$33.00 ✓          |
| 4   | 1   | Rear Boot Lid honda logo                               |          | \$31.00 ✓          |
| 5   | 2   | Rear Boot Lid side reflector <i>LH cut, RH cracked</i> | \$183.00 | \$366.00 ✓         |
| 6   | 1   | Rear boot lid 1.6 logo <i>2pc</i>                      |          | \$30.00 ✓          |
| 7   | 1   | Rear boot lid i-vtec logo                              |          | \$38.10 ✓          |
| 8   | 1   | Rear boot lid inner rubber <i>at</i>                   |          | \$128.60 ✓         |
| 9   | 1   | Rear Boot Lid Inner Lock <i>2pc</i>                    |          | \$197.20 ✓         |
| 10  | 1   | Rear Boot Lid key Lock <i>new</i>                      |          | \$128.60 +         |
| 11  | 1   | Rear Boot Lid Number Plate <i>new</i>                  |          | \$50.00 ✓          |
| 12  | 10  | Rear Boot Lid Inner Trim board clips <i>2pc</i>        | \$6.50   | \$65.00 +          |
| 13  | 1   | Rear Boot Lid Inner Trim board                         |          | \$252.80 +         |
| 14  | 2   | Rear Boot Lid inner side rubber <i>new</i>             | \$18.80  | \$37.60 +          |
| 15  | 2   | Rear tail lamp <i>LH cut, RH cracked</i>               | \$315.00 | \$630.00 ✓         |
| 16  | 2   | Rear tail lamp panel <i>2pc</i>                        | \$98.10  | \$196.20 +         |
| 17  | 1   | Rear end panel <i>Painted</i>                          |          | \$308.10 ✓         |
| 18  | 1   | Rear End Panel Top Garnish <i>Painted</i>              |          | \$105.20 ✓         |
| 19  | 1   | Rear Bumper <i>Painted</i>                             |          | \$920.30 - 638     |
| 20  | 2   | Rear Bumper Side Bracket <i>new</i>                    | \$28.90  | \$57.80 ✓          |
| 21  | 1   | Rear Bumper reverse sensor <i>2pc</i>                  |          | \$350.00 - 200/200 |
| 22  | 8   | Rear bumper clips <i>new</i>                           | \$3.50   | \$28.00 ✓          |
| 23  | 1   | Rear Exhaust <i>2pc</i>                                |          | \$780.00 +         |
| 24  | 1   | Rear Exhaust chrome pipe <i>new</i>                    |          | \$160.00 ✓         |

Subtotal :- \$5,593.40

Labour charges

|                                  |      |                         |
|----------------------------------|------|-------------------------|
| To Remove & refix cushion        |      | <del>\$120.00</del> 60  |
| To Remove & refix exhaust        |      | <del>\$200.00</del> 80  |
| To Remove & refix reverse Sensor |      | <del>\$100.00</del> 50  |
| To Remove & refix windscreen     |      | <del>\$120.00</del> +   |
| Gum                              |      | <del>\$50.00</del> +    |
| Tuff kote                        | 1710 | <del>\$120.00</del> 40  |
| To Check Wiring System           |      | <del>\$60.00</del> 30   |
| Panel beating                    |      | <del>\$800.00</del> 250 |
| Spray painting                   |      | <del>\$800.00</del> 200 |

Subtotal :- \$2,370.00

Total:- \$7,963.40

Adrian L  
w/s 16/04/18.  
obhys.

total 4447.36  
w/s 3.5K

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## Vic (LKKAUTO)

---

**From:** chan pick yuen <chris\_chanbebe@hotmail.com>  
**Sent:** Wednesday, 9 May, 2018 7:03 PM  
**To:** Vic (LKKAUTO)  
**Subject:** Re: SJG5781R & SKD8614A DOA 09.04.2018 LKK REF CC6/AIG18007144/Aha3  
**Attachments:** DV.jpg

Dear Vic ,

Enclosed is the DV .  
Please let us have your payment soon . Thanks

Regards,  
Chris Chan Pick Yuen

---

**From:** Vic (LKKAUTO) <vicalpeh@lkkauto.com>  
**Sent:** Wednesday, May 9, 2018 2:57 PM  
**To:** chan pick yuen  
**Cc:** Admin A; Vic (LKKAUTO); Bevan Lim (LKK Auto)  
**Subject:** RE: SJG5781R & SKD8614A DOA 09.04.2018 LKK REF CC6/AIG18007144/Aha3

WITHOUT PREJUDICE

Dear Chris,

We refer to your below email.

On a without prejudice basis and purely for an amicable settlement on a without admission of liability to our Insured's part, we propose to settle your client's claim at a global sum of **\$3,900.00** (all in).

If agreeable, kindly chop and sign the attached DV and forward to us(LKK) for payment processing.

The above amount is to be made payable to **U2 SPRAY PAINTING PTE LTD.**

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.*




Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Shu Pei (LKKAuto)

**Sent:** Wednesday, 9 May, 2018 12:55 PM

**To:** chan pick yuen

**Cc:** Admin A; Vic (LKKAuto)

**Subject:** FW: SJG5781R & SKD8614A DOA 09.04.2018

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

| LKK ref              | Officer in charge |
|----------------------|-------------------|
| CC6/AIG18007144/Aha3 | Vic               |

***To check availability of the case handler, you may contact the undersigned.***

Best Regards,

**Shu Pei** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** chan pick yuen [[mailto:chris\\_chanbebe@hotmail.com](mailto:chris_chanbebe@hotmail.com)]

**Sent:** Tuesday, 8 May 2018 11:30 PM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** Mei Kwan (LKKAuto) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>

**Subject:** SJG5781R & SKD8614A DOA 09.04.2018

Dear Sir / Mdm ,

Enclosed is our client's GIA , INVOICE & LOA .

Claim AIG , surveyed by Mr Adrian .  
Please advise OIC & claim number .  
As request following :

1. RC \$ 3500 ( As agreed )
2. LOU \$ 560 ( \$80 X 7 Days ) -6 days recommend + 1 days weekend

@ 100% ( direct from behind )

Total \$ 4060/-.

Please let us have your reply soon . Thanks

Regards,  
Chris Chan Pick Yuen  
U2 SPRAY PAINTING PTE LTD  
Block 25 Kaki Bukit Road 4  
# 06-43 Synergy & KB  
Singapore 417800  
HP: 92712214

## Vic (LKKAUTO)

**From:** Shu Pei (LKKAUTO)  
**Sent:** Wednesday, 9 May, 2018 12:55 PM  
**To:** chan pick yuen  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** FW: SJG5781R & SKD8614A DOA 09.04.2018  
**Attachments:** GIA.pdf; loa invoice.pdf

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

| LKK ref              | Officer in charge |
|----------------------|-------------------|
| CC6/AIG18007144/Aha3 | Vic               |

*To check availability of the case handler, you may contact the undersigned.*

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** chan pick yuen [mailto:[chris\\_chanbebe@hotmail.com](mailto:chris_chanbebe@hotmail.com)]  
**Sent:** Tuesday, 8 May 2018 11:30 PM  
**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Cc:** Mei Kwan (LKKAUTO) <[Meikwan@lkkauto.com](mailto:Meikwan@lkkauto.com)>  
**Subject:** SJG5781R & SKD8614A DOA 09.04.2018

Dear Sir / Mdm ,

Enclosed is our client's GIA , INVOICE & LOA .

Claim AIG , surveyed by Mr Adrian .

Please advise OIC & claim number .

As request following :

1. RC \$ 3500 ( As agreed )

2. LOU \$ 560 ( \$80 X 7 Days ) -6 days recommend + 1 days weekend

@ 100% ( direct from behind )

Total \$ 4060/-.

Please let us have your reply soon . Thanks

Regards,  
Chris Chan Pick Yuen  
U2 SPRAY PAINTING PTE LTD  
Block 25 Kaki Bukit Road 4  
# 06-43 Synergy & KB  
Singapore 417800  
HP: 92712214



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC6/AIG18007144/Aha3**

26<sup>th</sup> April 2018

**CHAN CHOI FOONG**

38 Lorong Tanggam  
Singapore 798739

Dear Sir/Madam,

**ACCIDENT INVOLVING SKD 8614A AND SJG 5781R ON 09.04.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Chong Poh Kin  
Case Handler  
DID: 6841 2132  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## LETTER OF AUTHORISATION

U2 SPRAY PAINTING PTE LTD  
BLK 25 KAKI BUKIUT ROAD 4  
# 06-43 SYNERGY @KB  
Singapore 417800

Dear Sir,

Accident on Serangoon Avenue 2, 9/4/2018

Involving Vehicle Nos SJG 5781R

Along Serangoon Avenue 2

I/We the registered owner /driver of vehicle registration no: SJG 5781R  
have involved in the above accident.

I/We hereby authorize **M/S U2 SPRAY PAINTING PTE LTD** to commence repairs of the said vehicle forthwith.

I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitors - to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.  
Thank you.

Yours truly,



Owner's Signature  
(Company's stamp if applicable)

Name: LOH JUA7 LEV9

NRIC No: S130878567

Date: 25-04-2018

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **U2 SPRAY PAINTING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3,900.00** (Global Sum – all in) for vehicle no. **SJG 5781R** that was damaged pursuant to the accident which occurred on **09/04/2018** (date) along **SERANGOON AVENUE 2** (location) involving vehicle no/s **SKD 8614A**. This is pursuant to the inspection conducted on **16/04/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **LOH JUAT LENG** ("the third party claimant") of vehicle no. **SJG 5781R** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJG 5781R** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 9/5/18



LWP

Signed by appointed surveyor

**U2 SPRAY PAINTING PTE LIM**  
ROC No. 201808263F

Signed by "the workshop" (with chop)



# U2 SPRAY PAINTING PTE LTD

Block 25 Kaki Bukit Road 4, #06-43 Synergy @ KB Singapore 417800  
HP: 96583371

## INVOICE

LOH JUAT LENG  
25 KAKI BUKIT ROAD 4  
#06-43 Synergy @ KB  
Singapore 417800

Date: 27-Apr-18

Accident date: 09 APRIL 2018  
Final Bill For Vehicle No: SJG5781R HONDA CIVIC 1.6 '08

| Descriptions  | AMOUNT     |
|---|------------|
| Lump Sum repair cost as recommended by<br>LKK AUTO CONSULTANTS PTE LTD<br>Surveyor : Mr Adrian Ling | \$3,500.00 |
| Total   | \$3,500.00 |

S/DLRS: THREE THOUSAND AND FIVE HUNDRED ONLY

...CLAIM SUBFOLDER...(Pending for Survey Report)  
Fastlane

| CLAIM SUBFOLDER TRACKING |   |               |   |  |  |             |   |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt  | Adj Submitted                                  | Ins Auth'ed | Status  |
| Main                     | 18 Apr 2018<br><a href="#">Edit Reg</a> |               | 16 Apr 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$3,500.00</b><br><a href="#">Edit Estimates</a> | <b>S\$3,500.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:

CHAN CHOI FOONG, ID: S1474334J

Main Claimant:

LOH JUAT LENG, ID: S1308785G

Vehicle Reg. No.:

SJG5781R

Date of Loss:

09/04/2018 10:00 - :59  
[117 Months and 2 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 6258224930SG

Policy/Cover Note No.:

1800005176 (Comprehensive)

Vehicle Reg. No. (Insured):

SKD8614A

Policy No. (Claimant):

DMAPI7S501121

Excess:

Repairer:

U2 Spary Painting Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #06-43 SYNERGY@KB, 417800 Kaki Bukit - Tel: 86186474

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com

Claimant's Insurer:

Etiqa Insurance Pte Ltd (HQ) - Tel: 63360477

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 26/04/2018]

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

• AIG\_SG (18/04/2018): TP GIA REPORT

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

Claim Documents

\*SJG5781R (6258224930SG)  
[SKD8614A]  
TP  
LOH JUAT LENG  
Apr 9 2018 10:00AM  
[CHAN CHOI FOONG]  
U2 Spary Painting Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences














































1 per page

| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ)                  | Thumbnail | Print |
|----|--------------|--|-----------|-------|
| 1  | (Draft)      | Third Party Express Settlement – Payment Breakdown |           | Edit  |

Photos/Images

3 per page

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print    |
|----|-----------------|-----------------------------------|-----------|----------|
| 1  | 23/04/18 16:37  | General View                      |           | Load JPG |
| 2  | 23/04/18 16:37  | General View                      |           | Load JPG |
| 3  | 23/04/18 16:37  | General View                      |           | Load JPG |
| 4  | 23/04/18 16:37  | General View                      |           | Load JPG |
| 5  | 23/04/18 16:37  | General View                      |           | Load JPG |
| 6  | 23/04/18 16:37  | General View                      |           | Load JPG |
| 7  | 23/04/18 16:37  | General View                      |           | Load JPG |
| 8  | 23/04/18 16:37  | General View                      |           | Load JPG |
| 9  | 23/04/18 16:37  | General View                      |           | Load JPG |
| 10 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 11 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 12 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 13 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 14 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 15 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 16 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 17 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 18 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 19 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 20 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 21 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 22 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 23 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 24 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 25 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 26 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 27 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 28 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 29 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 30 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 31 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 32 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 33 | 23/04/18 16:37  | General View                      |           | Load JPG |
| 34 | 23/04/18 16:37  | General View                      |           | Load JPG |

| Letters/Correspondences |                 |   | 1 per page   | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|---|--|-------------------------------------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail  | Print                               |
|                         |                 |   |  | <input checked="" type="checkbox"/> |
| 35                      | 23/04/18 16:37  | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                      | 23/04/18 16:37  | General View                              |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG  | <input checked="" type="checkbox"/> |
| 54                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 55                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 56                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 57                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 58                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 59                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 60                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 61                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 62                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 63                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 64                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 65                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 66                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 67                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 68                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 69                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 70                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 71                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| 72                      | 23/04/18 16:37  | Reinspection Photo                        |  Load JPG | <input checked="" type="checkbox"/> |
| Documentation           |                 |   | 1 per page   | <input checked="" type="checkbox"/> |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail  | Print                               |
| 1                       | 19/04/18 07:55  | TP GIA REPORT                             |  Load PDF |                                     |
| 2                       | 24/04/18 09:06  | TP ESTIMATE - MARKED                      |  Load PDF |                                     |
| 3                       | 30/04/18 13:29  | LETTER TO OI                              |  Load PDF |                                     |
| 4                       | 24/05/18 08:27  | WORKSHOP INVOICE                          |  Load PDF |                                     |
| 5                       | 24/05/18 08:27  | AUTHORISATION TO ACT FORM                 |  Load PDF |                                     |
| 6                       | 24/05/18 08:27  | Release Voucher                           |  Load PDF |                                     |
| No                      | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail  | Print                               |
| 1                       | 18/04/18 11:32  | OI GIA REPORT                             |  Load PDF |                                     |

Documents Checklist

|   |                       |                      |                       |
|---|-----------------------|----------------------|-----------------------|
| <b>DOCUMENTS CHECKLIST</b>  | <a href="#">Reset</a> | <a href="#">Save</a> | <a href="#">Print</a> |
| There are no document checklists configured.                                  |                       |                      |                       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>              |                       |                      |                       |
| <div></div>   |                       |                      |                       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer             |                       |                      |                       |
| <small>Note: Remarks are private unless you show it to other parties.</small> |                       |                      |                       |

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)

|                   |                     |        |                         |
|-------------------|---------------------|--------|-------------------------|
| Vehicle No:       | SKD8614A (Insd veh) | Model: | HONDA CIVIC 1.6 VTI (A) |
|                   | SJG5781R (TP veh)   |        |                         |
| Date of Accident: | 09/04/2018          |        |                         |

|                                   |   |   |                              |
|-----------------------------------|---|---|------------------------------|
| Global Sum Settlement             | : | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No  |
| Repair Estimate                   | : | \$                                      | 7,963.40                     |
| Final Repair Cost                 | : | \$                                      | 3,900.00                     |
| Loss of Use                       | : | \$                                      | 7.00 days at \$60.00 per day |
| Rental (if any)                   | : | \$                                      | days                         |
| LTA / GIA Search Fee              | : | \$                                      |                              |
| Others:                           | : | \$                                      |                              |
|                                   | : | \$                                      |                              |
| Final Settlement Sum (Global Sum) | : | \$                                      | 3,900.00                     |

|  |  |  |  |                         |
|--|--|--|--|-------------------------|
| Is Third Party Workshop GIA Registered?  |  | <input type="checkbox"/> YES                       | <input checked="" type="checkbox"/> NO | (Kindly indicate below) |
| A) For <u>Non GIA Registered Workshop</u> :  |  | Agreed Liability ____ 100 ____ (%)                 |  |                         |
| B) For <u>GIA Registered Workshop</u> :  |  | BOLA Applicable: Yes/ No    BOLA Scenario No: ____ |  |                         |
| BOLA Liability: ____ (%)   |  | Assessed Liability (*): ____ (%)                   |  |                         |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. |  |  |  |                         |
| Remarks _____  |  |  |  |                         |

| Payment Instruction: Payee's Breakdown |                           |   |             |
|--|---------------------------|---|-------------|
| 1)                                     | U2 Spary Painting Pte Ltd | : | \$ 3,900.00 |
| 2)                                     |                           | : | \$          |

JOANNE LEE KHANG MIN

24 May  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18007144/AHA3Q2

Date: 24/05/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 1800005176

Claimant Vehicle No : SJG5781R

Insured Vehicle No : SKD8614A

Date of Loss: 09/04/2018

Nature of Claim: TP

Claim No: 6258224930SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJG5781R

Make &amp; Model: HONDA CIVIC, 1.6 VTI (A)

Engine No: R16A13005673

Reg. Date: 07/07/2008 (Man. Year: 2008)

Chassis No: JHMF45208S201842

Colour: Bronze

Odometer: 309510 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre tread depth

| COST OF CLAIMS                           | Repairer's | Adjuster's | Difference | Diff % |
|--|------------|------------|------------|--------|
| Parts                                    | 5,593.40   | 2,737.36   | 2,856.04   | 51.06  |
| Miscellaneous Items                      | 0.00       | 0.00       | 0.00       |        |
| Labour                                   | 2,370.00   | 1,710.00   | 660.00     | 27.85  |
| Paintwork Labour                         | 0.00       | 0.00       | 0.00       |        |
| Towing                                   | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)             | 7,963.40   | 4,447.36   | 3,516.04   | 44.15  |
| Approved Total (Overridden) (S\$)        |            | 3,500.00   |            |        |
| Nett Amount (S\$)                        | 7,963.40   | 3,500.00   | 4,463.40   | 56.05  |
| + Loss of Use (7.0 x S\$60.00/day) (S\$) |            | 420.00     |            |        |
| Nett Liability (S\$)                     |            | 3,920.00   |            |        |
| Global Sum Settlement (S\$)              |            | 3,900.00   |            |        |

## INSPECTION

Date of Assignment: 16/04/2018

Date Inspected: 16/04/2018 Inspected At:

U2 Spary Painting Pte Ltd (HQ)  
25 KAKI BUKIT ROAD 4, #06-43  
SYNERGY@KB  
Singapore 417800

Estimated Period of Repair: 6.0 days



---

**Adjuster:** ADRIAN LING

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition             | Repairer's | Amount     |
|-----|-----|----------|---------------------------------------|-----------------------|------------|------------|
| 1   | 1   |          | *REAR BOOT LID                        | Dented                | 580.70 F   | *580.70 FL |
| 2   | 2   |          | *REAR BOOT LID HINGES                 | Not Necessary         | 119.20 F   | *- FL      |
| 3   | 1   |          | *REAR BOOT LID CIVIC LOGO             | Necessary             | 33.00 F    | *33.00 FL  |
| 4   | 1   |          | *REAR BOOT LID HONDA LOGO             | Necessary             | 31.00 F    | *31.00 FL  |
| 5   | 2   |          | *REAR BOOT LID SIDE REFLECTOR         | N/S Cut / O/S Cracked | 366.00 F   | *366.00 FL |
| 6   | 1   |          | *REAR BOOT LID 1.6 LOGO               | Necessary             | 30.00 F    | *30.00 FL  |
| 7   | 1   |          | *REAR BOOT LID I-VTEC LOGO            | Necessary             | 38.10 F    | *38.10 FL  |
| 8   | 1   |          | *REAR BOOT LID INNER RUBBER           | Cut                   | 128.60 F   | *128.60 FL |
| 9   | 1   |          | *REAR BOOT LID INNER LOCK             | Damaged               | 197.20 F   | *197.20 FL |
| 10  | 1   |          | *REAR BOOT LID KEY LOCK               | Not Necessary         | 128.60 F   | *- FL      |
| 11  | 1   |          | *REAR BOOT LID NUMBER PLATE           | Not Necessary         | 50.00 F    | *- FL      |
| 12  | 10  |          | *REAR BOOT LID INNER TRIM BOARD CLIPS | Not Necessary         | 65.00 F    | *- FL      |
| 13  | 1   |          | *REAR BOOT LID INNER TRIM BOARD       | Not Necessary         | 252.80 F   | *- FL      |
| 14  | 2   |          | *REAR BOOT LID INNER SIDE RUBBER      | Not Necessary         | 37.60 F    | *- FL      |
| 15  | 2   |          | *REAR TAIL LAMP                       | N/S Cut / O/S Cracked | 630.00 F   | *630.00 FL |
| 16  | 2   |          | *REAR TAIL LAMP PANEL                 | Repair                | 196.20 F   | *- FL      |
| 17  | 1   |          | *REAR END PANEL                       | Dented                | 308.10 F   | *308.10 FL |
| 18  | 1   |          | *REAR END PANEL TOP GARNISH           | Deformed              | 105.20 F   | *105.20 FL |
| 19  | 1   |          | *REAR BUMPER                          | Deformed              | 920.30 F   | *638.00 FL |
| 20  | 2   |          | *REAR BUMPER SIDE BRACKET             | Necessary             | 57.80 F    | *57.80 FL  |
| 21  | 1   |          | *REAR BUMPER REVERSE SENSOR           | Damaged               | 350.00 FS  | *200.00 FS |
| 22  | 8   |          | *REAR BUMPER CLIPS                    | Necessary             | 28.00 F    | *28.00 FL  |
| 23  | 1   |          | *REAR EXHAUST                         | Repair                | 780.00 F   | *- FL      |
| 24  | 1   |          | *REAR EXHAUST CHROME PIPE             | Not Necessary         | 160.00 F   | *- FL      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |          |          |
|--|----------|----------|
| Sub Total (\$\$)                                   | 5,593.40 | 3,371.70 |
| - List Item Discount on L Items 0.00/20.00% (\$\$) | 0.00     | 634.34   |
| Total Parts (\$\$)                                 | 5,593.40 | 2,737.36 |

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

| No                              | Particulars                      | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                  |          |                 |                 |
| 1                               | TO REMOVE & REFIX CUSHION        | New      | 120.00          | 60.00           |
| 2                               | TO REMOVE & REFIX EXHAUST        | New      | 200.00          | 80.00           |
| 3                               | TO REMOVE & REFIX REVERSE SENSOR | New      | 100.00          | 50.00           |
| 4                               | TO REMOVE & REFIX WINDSCREEN     | New      | 120.00          | 0.00            |
| 5                               | GUM                              | New      | 50.00           | 0.00            |
| 6                               | TUFF KOTE                        | New      | 120.00          | 40.00           |
| 7                               | TO CHECK WIRING SYSTEM           | New      | 60.00           | 30.00           |
| 8                               | PANEL BEATING                    | New      | 800.00          | 750.00          |
| 9                               | SPRAY PAINTING                   | New      | 800.00          | 700.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                  |          | <b>2,370.00</b> | <b>1,710.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >