

ASS. REC. BY:

REF:

CS / FCL18007190 / TN bnz

Special Instruction:

Survivor:

Tantikh

ASSIGNMENT (Office)

From (Person):

WS

Karen Tan

of

FCL

Date/Time:

18042018 309pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GIBB 5385Y

Insured:

SHA 3236S

at Workshop m/s

Sng Ah Tee

Tel:

6268 6185

of

Blk 3 Pioneer Rd North #01-18

Policy No:

Claim No:

D18002900MF5H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13042018

(Client's Record)

CA / REV / REP. / REV 24 HRS

DS

H.O.D. Endorsement:

Date/Time:

18042018 311pm

Person Contacted:

Joyce

Vehicle IN

OUT

Date/Time

Action/Instruction (✓) Estimate

GIBB 5385Y - CS / FCL16020467 / Tlgkss2

DFA: 121016

SHA 3236S - CS / FCL17012275 / mltbe2

DFA: 170617

24/4/18

Email preli revised to FCL

11/7/18

LS \$3000 confirmed by email (Red 2343.41, 4490)

Note:

MV: \$15K (EST) LTA: \$765 NV: \$14,235

From: Date: 23042018

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBB 538BY

at Workshop m/s: Sng Ah Tee

of: Blk 3 Pioneer Rd North #01-18

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 415K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBB538BY Yr Regn: 2009 May.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar C.C. 2953

Colour: Silver A/C: Insured / Std / NI / NA

Sp.Reading: 194019 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1SC2F2420800924

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 195/AR15 R: 165/AR13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front BS 6 mm Rear GT Radial


R/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 23/4/18R 164

Survey held at: Sng Ah Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



RECEIVED 11 JUL 2019

Date/Time, File Pass to?

1) ☐ : Preli. Report

2) ☐ : Final Report

Date/Time, File Return to?

11/7 - typst

Report Format: cws

Lump Sum / I.B.I: (\$ 3000)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation: S + RS, SI

Photos

Other

TOTAL

140

50

50

58

298



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002900MFSH

Our ref: CS/FC118007190/T1vb

Date: 24/4/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBB 5385Y


We thank you for your instruction on 18/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23/4/2018 at the premises of M/s SNG AH TEE MOTOR & PANEL SERVICE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,343.41
Revised Estimate Amount	: S\$2,528.28
"Check" Items Amount	: S\$294.12
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

MOTOR SURVEY ASSIGNMENT

Date	16-04-2018	Our Ref No. D18002900MFSH
Accident Date	13-04-2018	Claim Type. Third Party
Insured Vehicle	SHA3236S	Third Party Vehicle. GBB5385Y
Survey Location	BLK 3 PIONEER ROAD NORTH #01-18	
Contact Person.	JOYCE TAN	
Contact No.	62686183/ 0	Fax No. 62681429
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 11 July 2018 9:33 AM
To: 'Sharon Sng'; Taufikh (LKKAUTO); SUR
Subject: RE: GBB5385Y - FINALISE

Dear Sharon,

WITHOUT PREJUDICE

Confirmed Lump Sum \$3000 @ 6 working days.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng [mailto:sharon@sngahtee.com]
Sent: Tuesday, 10 July 2018 5:48 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: GBB5385Y - FINALISE

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 24 April 2018 2:27 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002900MFSH/1, GBB 5385Y
Attachments: GBB 5385Y PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBB 5385Y
Date of survey: 23/4/2018
Number of days: 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 18 April 2018 3:26 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002900MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 18 April, 2018 3:09 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002900MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	8832R

Vehicle Details

Vehicle No.:	GBB5385Y
Vehicle to be Exported:	No
Intended De-registration Date:	11 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T
Primary Colour:	Gold
Manufacturing Year:	2009
Engine No.:	ZD30224043K
Chassis No.:	JN15C2F24Z0800924
Maximum Power Output:	-
Open Market Value:	\$26,803.00
Original Registration Date:	30 May 2009
First Registration Date:	30 May 2009
Transfer Count:	0
Actual ARF Paid:	\$1,341.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	29 May 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$7,302.00
COE Rebate Amount:	\$765.00
Total Rebate Amount:	\$765.00

The information contained herein is correct as at 17 Apr 2018

OK

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003750

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE: 18/04/2018

ACCIDENT DATE: 13/04/2018

VEHICLE NO: GBB5385Y

CHASSIS/ENG.NO:

VEHICLE MODEL: NISSAN CABSTAR

CLAIM NO:

POLICY NO:

REMARK: 5385 FIRST CAPITAL
TP AGST SHA3236S

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
SUB-TOTAL:							0.00
** NETT PRICE **							
1	1	PC	FRT BUMPER	945.10	10	850.59	de 850.59
2	1	PC	FRT GRILLE	578.60	10	520.74	Rx 520.74
3	1	PC	FRT GRILLE EMBLEM	55.10	10	49.59	nn X 49.59
4	1	PC	REAR TAILGATE	1,399.70	10	1,259.73	✓ 1bt x 1,259.73
5	3	PC	REAR TAILGATE HINGE	53.30	10	47.97	Rx 143.91
6	4	PC	REAR END PANEL RUBBER STOPPER	8.90	10	8.01	nn X 32.04
7	1	PC	REAR TAILLAMP (RH)	248.60	10	223.74	nn 223.74
8	1	PC	REAR NUMBER PLATE HOLDER	65.50	10	58.95	bb 58.95
9	2	PC	REAR SIDE PANEL LOCK CATCH	326.80	10	147.06	X nn 294.12
SUB-TOTAL							3,433.41
** SPECIAL NETT PRICE **							
1	1	PC	FRT NUMBER PLATE	25.00		25.00	nn X 25.00
2	1	PC	REAR NUMBER PLATE	25.00		25.00	bt 25.00
3	1	PC	REAR TAILGATE 70KM STICKER	10.00		10.00	nn 10.00
4	1	PC	REAR REVERSE SENSOR	320.00		320.00	nn 320.00
SUB-TOTAL							380.00
** WORK LABOUR **							
TO CHECK WIRING						30.00	✓ 30.00
TO APPLY ANTI RUST COATING						100.00	30 100.00
TO KNOCK, WELD, REMOVE AND REPLACE ABOVE PARTS						600.00	500 600.00
TO SPRAY PAINTING ON AFFECTED AREAS						800.00	600 800.00

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

EST/QUOTE NO. SQ003750

DATE 18/04/2018

ACCIDENT DATE : 13/04/2018

VEHICLE NO : GBB5385Y

CHASSIS/ENG.NO :

VEHICLE MODEL : NISSAN CABSTAR

CLAIM NO :

POLICY NO :

REMARK : 5385 FIRST CAPITAL
TP AGST SHA3236S

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
SUB-TOTAL							1,530.00

Tan Jiah 97445749
- WP
23/4/18 @ 1640
Resurvey after repair.
sure (blank) in
6 days
30/5/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOYCE

(Signature)

PAGE: 2 of 2

SUB-TOTAL : S\$ 5,343.41

ADD 7% GST. S\$ 374.04

GRAND TOTAL : S\$ 5,717.45

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003750

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

DATE 18/04/2018

ACCIDENT DATE : 13/04/2018

VEHICLE NO : GBB5385Y

CHASSIS/ENG.NO :

VEHICLE MODEL : NISSAN CABSTAR

CLAIM NO :

POLICY NO :

REMARK : 5385 FIRST CAPITAL
TP AGST SHA3236S

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
							SUB-TOTAL: 0.00
** NETT PRICE **							
1	1	PC	FRT BUMPER	945.10	10	850.59	850.59 <i>de✓</i>
2	1	PC	FRT GRILLE	578.60	10	520.74	520.74 <i>Rx</i>
3	1	PC	FRT GRILLE EMBLEM	55.10	10	49.59	49.59 <i>X</i>
4	<i>*</i> 1	PC	REAR TAILGATE	1,399.70	10	<i>(quote)</i> 1,259.73	1,259.73 <i>Rx✓</i>
5	3	PC	REAR TAILGATE HINGE	53.30	10	47.97	143.91 <i>Rx</i>
6	4	PC	REAR END PANEL RUBBER STOPPER	8.90	10	8.01	32.04 <i>X</i>
7	1	PC	REAR TAILLAMP (RH)	248.60	10	223.74	223.74 <i>cur✓</i>
8	1	PC	REAR NUMBER PLATE HOLDER	65.50	10	58.95	58.95 <i>bb✓</i>
9	2	PC	REAR SIDE PANEL LOCK CATCH	163.40	10	147.06	294.12
							SUB-TOTAL 3,433.41
** SPECIAL NETT PRICE **							
1	1	PC	FRT NUMBER PLATE	25.00		25.00	25.00 <i>X</i>
2	1	PC	REAR NUMBER PLATE	25.00		25.00	25.00 <i>bb✓</i>
3	1	PC	REAR TAILGATE 70KM STICKER	10.00		10.00	10.00 <i>ur✓</i>
4	1	PC	REAR REVERSE SENSOR	320.00		320.00	320.00 <i>cur✓</i>
							SUB-TOTAL 380.00
** WORK LABOUR **							
TO CHECK WIRING						30.00	30.00 <i>✓</i>
TO APPLY ANTI RUST COATING						100.00	100.00 <i>30</i>
TO KNOCK, WELD, REMOVE AND REPLACE ABOVE PARTS						600.00	600.00 <i>500</i>
TO SPRAY PAINTING ON AFFECTED AREAS						800.00	800.00 <i>600</i>

JOYCE

PAGE: 1 of 2

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003750

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

DATE 18/04/2018

ACCIDENT DATE : 13/04/2018

VEHICLE NO : GBB5385Y

CHASSIS/ENG.NO :

VEHICLE MODEL : NISSAN CABSTAR

CLAIM NO :

POLICY NO :

REMARK : 5385 FIRST CAPITAL
TP AGST SHA3236S

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

SUB-TOTAL 1,530.00

\$1160

Tan Jiah 97495749
- WP

23/4/18 @ 1640

Resuming after repair.

sure (kuan) in
6 days

total \$3788.01
less 20% = \$3030.40
= \$3000 Lump Sum
ok? pls revert.
Shann 10/07/2018

* R.R. Tailgate 25/4/2018 Darren Informed Saver to replace R.R. Tailgate

JOYCE

PAGE: 2 of 2

SUB-TOTAL : S\$ 5,343.41

ADD 7% GST. S\$ 374.04

GRAND TOTAL : S\$ 5,717.45



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007190/T1vbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 12-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3236S	Veh. Inspected	GBB 5385Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002900MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	18/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JN1SC2F24Z0800924	Colour	SILVER	
Odometer	194019	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	165 R13 (D)	GT RADIAL	6/6 mm	
L/H Rear Tyre	165 R13 (D)	GT RADIAL	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/04/2018	Inspection Date	23/04/2018	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBB 5385Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER (N)	DEFORMED	945.10	945.10
1	FRT GRILLE (N)	TO REPAIR SEE LABOUR	578.60	-
1	FRT GRILLE EMBLEM (N)	NOT NECESSARY	55.10	-
1	REAR TAILGATE (N)	BENT	1,399.70	1,399.70
3	REAR TAILGATE HINGE @\$53.30 (N)	TO REPAIR SEE LABOUR	159.90	-
4	REAR END PANEL RUBBER STOPPER @\$8.90 (N)	NOT NECESSARY	35.60	-
1	REAR TAILLAMP (RH)(N)	CRACKED	248.60	248.60
1	REAR NUMBER PLATE HOLDER (N)	BENT	65.50	65.50
2	REAR SIDE PANEL LOCK CATCH @\$163.40 (N)	NOT NECESSARY	326.80	-
	LESS 10% DISCOUNT		-381.49	-265.89
			3,433.41	2,393.01
SPECIAL NETT ITEMS				
1	FRT NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR NUMBER PLATE (SN)	BENT	25.00	25.00
1	REAR TAILGATE 70KM STICKER (SN)	NECESSARY	10.00	10.00
1	REAR REVERSE SENSOR (SN)	CRACKED	320.00	200.00
			380.00	235.00
LABOUR				
	TO CHECK WIRING.		30.00	30.00
	TO APPLY ANTI RUST COATING.		100.00	30.00
	TO KNOCK,WELD,REMOVE AND REPLACE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRT GRILLE AND REAR TAILGATE HINGE.		600.00	500.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		800.00	600.00
			1,530.00	1,160.00
GRAND TOTAL			5,343.41	3,788.01
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00



Report Ref No. CS/FCI18007190/T1vbn2

MARKET VALUE: \$15,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$765.00=NETT VALUE: \$14,235.00

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.