

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGE8953M
7P/6Q

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433
ATTN: Motor Claim Department

FAX: 62243903

Not Authorized

WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 14/04/2018
TP Veh Reg No: SJH8683R

*1. B.1
Presumably B4 claim*

6 days

Claim No: ES1890403
Estimate No: ES1890403/WL
Date: 16 Apr 2018
Policy No: 5078341193-02
Veh Reg No: SGE8953M
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD
Chassis No: RU11110773
Engine No: L15B4030776
Reg. Date: 15/03/2016

Estimate Repair Cost to Vehicle No : SGE8953M

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 REAR BUMPER	230.00	1 PC	230.00	✓
2 REAR BUMPER LH SIDE PAD	80.00	1 PC	80.00	✓
3 REAR BUMPER LH SIDE RETAINER	10.00	1 PC	10.00	✓
4 REAR BUMPER REFLECTORS	38.00	2 PCS	76.00	?
5 REAR BUMPER CLIPS	2.00	6 PCS	12.00	✓
6 REAR LH FENDER WHEEL ARP GARNISH	60.00	1 PC	60.00	?
7 REAR TAILGATE	610.00	1 PC	610.00	✓
8 TAILGATE INNER LOCK	78.00	1 PC	78.00	✓
9 TAILGATE INNER RUBBER	55.00	1 PC	55.00	✓
10 TAILGATE LH SHOCK ABSORBER	90.00	1 PC	90.00	?
11 TAILGATE EMBLEM 'VEZEL'	28.00	1 PC	28.00	✓
12 REAR WINDSCREEN GLASS MOULDING	68.00	1 PC	68.00	✓
13 REAR CENTRE PANEL	310.00	1 PC	310.00	?
14 REAR CENTRE PANEL INNER TOP GARNISH	40.00	1 PC	40.00	✓
15 REAR TOOL BOX	120.00	1 PC	120.00	?
16 REAR TOOL BOX TOP COVER	160.00	1 PC	160.00	?
17 REAR COMPARTMENT UNDER COVER	90.00	1 PC	90.00	?
18 REAR COMPARTMENT UNDER COVER CLIPS	2.00	4 PCS	8.00	?
19 REAR EXHAUST PIPE	320.00	1 PC	320.00	?
			2,445.00	
	Add 20%		489.00	2,934.00
Special Net				
20 REVERSE SENSOR	200.00	1 SET	200.00	✓
21 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
				240.00

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department

WS Ref: TP/EQ/WL
Claim Type: Third Party
Accident Date: 14/04/2018
TP Veh Reg No: SJH8683R

Claim No: ES1890403
Estimate No: ES1890403/WL
Date: 16 Apr 2018
Policy No: 5078341193-02
Veh Reg No: SGE8953M
Make/Model: HONDA VEZEL 1.5X
CVT ABS D/AIRBAG
2WD
Chassis No: RU11110773
Engine No: L15B4030776
Reg. Date: 15/03/2016

Estimate Repair Cost to Vehicle No : SGE8953M

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
23 PANEL BEATING ON REAR PORTION	800.00	1 LA	800.00	?
24 PUTTY & RESPRAY ON REAR AFFECTED AREAS	800.00	1 LA	800.00	700.00
25 REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM	60.00	1 LA	60.00	✓
26 RUSTPROOFING	60.00	1 LA	60.00	?
27 REMOVE & REFIX REVERSE CAMERA,RESET SYSTEM	60.00	1 PC	60.00	✓
				1,880.00

Total	S\$ 5,054.00
Add GST @ 7%	353.78
Total Amount payable	<u>S\$ 5,407.78</u>

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE