

ASS. REC. BY:

REF: CS/LPC18007204/mlwbsz

Special Instruction:

UNVELOP

merimen

ma

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

LPC

Date/Time:

18/04/2018 11:31am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCX 1308 U

Insured:

at Workshop m/s

Cheng Hoe Motor

Tel:

6481 2001

of

Blk 1019 Yishun Ind Park A #01-374 / 382

Policy No:

Z17VP05016079

Claim No:

17/18/18/VP05/020551

Sum Insured:

Excess:

NIL

Make of Veh:

D.O.A.

16/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

18/04/2018 11:50am

Person Contacted:

Darlyn

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate	
	SCX 1308 U - C4 / LPC18007168 / mlwbsz	DGA: 16/04/18
19/4/18	Revert by merimen	
19/4/18	Rece authorise repair by email	
19/4/18	@ 11:58am Informed Darlyn c/A on part by part not exceeding \$14,500/2	

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

CHENG HU

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

Nil.

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 65k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SCX13084

Yr Regn:

JAN 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA CITY

C.C.

1497

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

NIC

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR4GM6600EP000145

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt orBrake: ☒ Order / Jammed / Leaked / Burnt orModi: Nil / ☒ Rim / STD A/Rim or

Tyre Size:

F:

185/55/R16

R:

185/55/R16

BS / DUN / EXNOVA / GY / FS / LIZA (MIC) / OHTSU / PIR / SUMI /

TOYO / YOKO or

MIC

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

16/4/2018.

D.O.I.

18/4/2018

Survey held at

Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/10/18 Final fig \$ 13,513.10 confirmed by email (Ref 1647.35, 1110)

RECEIVED 20 OCT 2018

Signature

24/10/2018

5x15=75
75+120=245
245x20%=49

Survey Fee:	49+245=294
Transportation:	50
	50+150+50
	149
	580+110
TOTAL:	643+110

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

24/10 - typist

Days Of Repair:

12

Resurvey No. of Trip:

3

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format :

merimen

Lump Sum / I.B.I. (\$)

13,513.10

TOTAL:

580
+110
690



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18007204/M1vb

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 18-04-2018



Code : LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SCX 1308U
Policy No.	Z17VP05016029	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020551	Excess (\$)	0.00
Assign From	MERIMEN (GERALD POH)	Assign Date	18/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/04/2018	Inspection Date	18/04/2018
Survey held at	10 ANG MO KIO IND PARK 2A #01-04		
Repairer	CHENG HOE MOTOR PL		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Apr 2018 Sendback Est	18 Apr 2018 11:00 S\$15,160.45	18 Apr 2018 11:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS																								
Insured: JACQUELINE LEE SIOW YEN, ID: S6976694C, Tel: +6597232280, Email: jaclee.sg@gmail.com																								
Vehicle Reg. No.: SCX1308U		Date of Loss: 16/04/2018 18:00 - :59 [39 Months and 14 Days From LTA Reg Date (Man Yr)]																						
Claim Type: OD / 17/18/18/VP05/020551		Policy/Cover Note No.: Z17VP05016029 (Comprehensive)																						
		Excess: S\$0.00																						
Repairer: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142																								
Handling Insurer: Longpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]																								
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/04/2018]																								
Driver/Custodian: JACQUELINE LEE SIOW YEN (48 / Female), NRIC: S6976694C, Tel: +6597232280																								
Adj Asg. Remarks: Survey & revert. Excess is Nil.																								
ASSOCIATED MAIL RECEIVED																								
There are no mail for this case.																								
ALL ASSOCIATED TASKS																								
☐ View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Veron Chen (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Thursday, 19 April 2018 11:47 AM
To: 'GERALD POH WEE BIN'; SUR
Cc: 'MT_Claim_SG'; assignments
Subject: RE: ACCIDENT INVOLVING SCX1308U & SJP5630X ON 16.4.2018

Dear Mr Gerald,

Thank you for your email.

Dear Veron,

FYNA. Our ref: CS/LPC18007204/M1vb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Thursday, 19 April, 2018 11:31 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: ACCIDENT INVOLVING SCX1308U & SJP5630X ON 16.4.2018

Our Ref : 17/18/18/VP05/020551

Dear Catherine,

Your letter 19 of April 2018 refers.

You may proceed to authorize repair as per your adjustment.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Longpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse Singapore 199555	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Gerald Poh	Date: 19 Apr 2018

Preliminary Advice

Vehicle No	: SCX1308U	Accident Date	: 16/04/2018
Make	: HONDA CITY	Policy No.	: Z17VP05016029
Assignment Date	: 18/04/2018	Excess	: S\$0.00
Date of Inspection	: 18/04/2018	Est. Duration of Repair	: 12.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,160.45
Revised Amount	:S\$	11,864.00
Check Items (Estimated)	:S\$	2,614.10
Total	:S\$	14,478.10
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	65,000.00
COE / PARF Rebate	:S\$	50,400.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,600.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/04/2018 10:22
Date Of Accident	16/04/2018 18:30
Exact Location Of Accident	TOA PAYOH LOR 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCX1308U
Insured/Policyholder	
Name Of Registered Owner	JACQUELINE LEE SIOW YEN
NRIC No	S6976694C
Email Address	JACLEE.SG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97232280
Alternative Phone No	OTHERS-97232280

Vehicle Particulars

Manufacturer	HONDA
Model	CITY-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z17VP05016029
Cover Note Number	10/11/2017 - 09/11/2018

Driver

Name of Driver	JACQUELINE LEE SIOW YEN
NRIC No	S6976694C
Date Of Birth	26/07/1969
Occupation	INDOOR
Date Of Driving Pass	07/03/1996
Driving Experience	22 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-97232280
Fax Number	
Contact Number	OTHERS-97232280
EMail Address	JACLEE.SG@GMAIL.COM

SKETCH PLAN

VEHICLE NO.: SCX1308U
INSURER : LONDAC
DATE & TIME: 16/04/2018 @ 1830

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



17/4/18

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Bodhyu (Amik)
NRIC/FIN No.: 17/04/18

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6694C
Vehicle Details	
Vehicle No.:	SCX1308U
Vehicle to be Exported:	No
Intended De-registration Date:	19 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 SV CVT
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	L15Z11414255
Chassis No.:	MRHGM6660EP000145
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$16,539.00
Original Registration Date:	02 Jan 2015
First Registration Date:	02 Jan 2015
Transfer Count:	2
Actual ARF Paid:	\$6,539.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jan 2025
PARF Rebate Amount:	\$4,904.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,889.00
COE Rebate Amount:	\$45,496.00
Total Rebate Amount:	\$50,400.00

The information contained herein is correct as at 19 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6694C
Vehicle Details	
Vehicle No.:	SCX1308U
Vehicle to be Exported:	Yes
Intended De-registration Date:	17 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 SV CVT
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	L15Z11414255
Chassis No.:	MRHGM6660EP000145
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$16,539.00
Original Registration Date:	02 Jan 2015
First Registration Date:	02 Jan 2015
Transfer Count:	2
Actual ARF Paid:	\$6,539.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jan 2025
PARF Rebate Amount:	\$4,904.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,889.00
COE Rebate Amount:	\$45,533.00
Total Rebate Amount:	\$50,437.00

The information contained herein is correct as at 17 Apr 2018

OK



ANNOUNCING Henly Enterprises Co

as sgCarMart Premium Dealer for the 6th Consecutive Year

Contact us at 63363133 / 96351017 for your Hire Purchase needs and COE renewal loans at attractive rates



Advanced Search

Home » Used Cars » 1axis » Honda City 1.5A SV

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Tyres



Join DBS Treasures Private Client and indulge in the warm hospitality of members-only priority privileges.

JOIN US NOW



DBS TREASURES PRIVATE CLIENT

Honda City 1.5A SV

Overview Financial Accessories Similar Research Photos Map

1axis

Car Details

Price	\$63,800	?
Depreciation	\$9,020 /yr View models with similar depreciation	?
Reg Date	26-Dec-2014 (6yrs 8mths 7days COE left)	?
Manufactured	2014	?
Mileage	34,000 km (10.3k /yr)	?
Transmission	Auto	?
Engine Cap	1,497 cc	?
Road Tax	\$684 /yr	?
Power	88.0 kW (118 bhp) View specs of the Honda City (2014-2017)	?
Curb Weight	1,096 kg	?
Features	1.5L I-VTEC Engine Producing 118Bhp And 145Nm Torque, Earth Dreams CVT, Multi Function Steering Controls, Push Start Engine, Keyless Entry.	?
Accessories	Sport Rims, Leather Seats, 7" Factory Fitted Touch Screen Audio System, Reverse Camera, Fog Lamps, Bluetooth, ECO Drive Mode, Cruise Control.	?
Description	Full Loan At \$1072 Only. Low Mileage At 34000km. Beautiful Metallic Blue. 1 Careful Owner, Well Maintained By Previous Owner And Agent Maintained. Very Spacious And Big Boot Space. Ideal For Those Who Fancy Spacious And Comfort Interior Yet Powerful Drive! Loans And In House Loan Can Be Arranged. Call Now To View.	?
COE	\$65,889	?
OMV	\$16,804	?
ARF	\$6,804	?
Dereg Value	\$49,204 as of today (change)	?
No. of Owners	1	?
Type of Veh	Mid-Sized Sedan	?
Category	PARF Car	?
Availability	Available	?

Posted on: 14-Apr-2018 | Last Updated on: 15-Apr-2018

Tags: Honda City, 2014 Honda City, Honda, City, Used Honda



Seller Information

Company	1axis
	- dealer's pricelist 58 vehs sold 22 vehs available
Address	5 Yishun Industrial Street 1 #01-18 Search cars nearby this location
Location	North Spring Bizhub
Contact Person(s)	Jack 84306433 Edward Chen 81800536 Viki 90270337

Upfront Payment

+ more Financial Info

Transfer Fee	\$25	?
Down Payment	\$19,140 (change)	?
1st Instalment	\$669	?
Total Upfront Payment	\$19,834 (excluding insurance)	?

[Website](#)
[Company Profile](#)
[Used Car List](#)


Make sure of this car condition with STA Evaluation

Compare



ANNOUNCING Henly Enterprises Co

as sgCarMart Premium Dealer for the 6th Consecutive Year

Contact us at 63363133 / 96351017 for your Hire Purchase needs and COE renewal loans at attractive rates



Advanced Search

Home » Used Cars » Henly Enterprises Co » Honda City 1.5A SV

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Commercial Vehicle



Join DBS Treasures Private Client and indulge in the warm hospitality of members-only priority privileges.

JOIN US NOW



Honda City 1.5A SV

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)


HENLY ENTERPRISES COMPANY PRIVATE LIMITED

18 Ubi Road 4, #01-05/07/08 Ubi Car Mall Singapore 408616 Tel: 6336 3133


[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price	\$69,800
Depreciation	\$9,350 /yr View models with similar depreciation
Reg Date	08-May-2015 (7yrs 19days COE left)
Manufactured	2015
Mileage	-
Transmission	Auto
Engine Cap	1,497 cc
Road Tax	\$684 /yr
Power	88.0 kW (118 bhp) View specs of the Honda City (2014-2017)
Curb Weight	1,096 kg
Features	4 Cylinder Inline SOHC I-1-VTEC Water-Cooled Engine Producing 118Bhp And 145Nm Torque Coupled With 7 Speed CVT Gearbox. Front Wheel Drive.
Accessories	7" Touchscreen Intuitive Display With Smartphone/HDMI/Aux Input, Bluetooth, Reverse Camera, Paddle Shifters, Keyless Entry/Start, Cruise Control.
Description	Most Popular Honda Sedan For Your Family. Well Maintained And Service With Agent. Still Under Kah Motors Warranty. Beautiful Paintwork With Clean And Neat Interior. Bank Or In-House Loan Available. Purchased With Assurance From Henly Enterprises, Well Established Since 1972. Hurry! Call Us Now For Viewings & Test Drive Appointment.
COE	\$67,601
OMV	\$17,639
ARF	\$7,639
Dereg Value	\$53,439 as of today (change)
No. of Owners	1
Type of Veh	Mid-Sized Sedan
Category	PARF Car
Availability	Available

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 14-Apr-2018 | Last Updated on: 17-Apr-2018
 Tags: Honda City, 2015 Honda City, Honda, City, Used Honda



Seller Information

Company	Henly Enterprises Co * dealer's pricelist * 97 vehs sold 57 vehs available	
Address	61 Ubi Avenue 2 #05-19 Search cars nearby this location	
Location	Automobile Megamart	
Website	www.henly.com.sg	
Office No	67469930	
Contact Person(s)	Johnny Lim	92300868
	Shirley Shi	94596113

[view our used cars & company profile](#)


Upfront Payment

[* more Financial info](#)

Transfer Fee	\$25	
Down Payment	\$20,940 (change)	Maximum 70% Loan
1st Instalment	\$703	

[Compare](#)

Make sure of this car condition with STA Evaluation



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD/LONPAC
Policy No:	Z17VP05016029	Date of Loss:	16/04/2018
Vehicle Reg. No.:	SCX1308U	Driveable?	
Driver Age/Info:	48 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	JACQUELINE LEE SIOW YEN	Contact No:	+6597232280
Driver:	JACQUELINE LEE SIOW YEN		
Make/Model:	HONDA CITY, 1.5 (A)	Vehicle Reg. Date:	02/01/2015
Vehicle Colour:	Blue		
Engine No:	L15Z11414255	Chassis No:	MRHGM6660EP000145
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	TRAFFIC WAS HEAVY AND WE ARE ON 'STOP AND MOVE' MOTION. HALFWAY THROUGH, SOMETHING HIT ONTO MY LEG AND CAUSED MY RIGHT LEG TO ACCIDENTALLY STEP HARDER ON THE ACCELERATOR DUE TO THE SHOCK. MY VEHICLE THEN WENT FORWARD AND HIT ONTO THE REAR OF MOTOR CAR SJP5630X. NO ONE WAS INJURED, MY CAR WAS TOWED TO THE NEAREST AWS AFTER THE ACCIDENT.		
Remarks:	VEHICLE TOW IN TO ANG MO KIO WORKSHOP ON 16/04/2018 NIGHT		
Present Location:	CHENG HOE MOTOR PTE LTD (AMK)		

COST OF CLAIMS

	Amount
Parts	11,595.45
Miscellaneous Items	295.00
Labour	3,270.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	15,160.45
+ GST 7.00% (\$\$)	1,061.23
Nett Amount (\$\$)	16,221.68

This claim is handled by: DORLYN LI YAZHU

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Apr 2018)
Parts:	143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Cheng Hoe Motor Pte Ltd/SCX1308U/18/04/2018 11:00	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*1 pc front bumper	det ✓	0.00	0.00	*180.00 F	
2	1		*1 pc front bumper reinforcement	bt ✓	0.00	0.00	*150.00 F	
3	1		*1 pc front bumper lower centre grille	dis ✓	0.00	0.00	*50.00 F	
4	1		*1 pc front bumper tow cover	dis ✓	0.00	0.00	*12.00 F	
5	1		*1 pc front bumper RH fog lamp	dis ✓	0.00	0.00	*195.00 F	
6	1		*1 pc front bumper RH fog lamp cover	dis ✓	0.00	0.00	*18.00 F	
7	1		*1 pc front bumper lower rubber	dis ✓	0.00	0.00	*15.00 F	
8	1		*2 pcs front bumper side retainers @ \$9/pc	dis ✓	0.00	0.00	*18.00 F	
9	1		*8 pcs front bumper clips @ \$2/pc	dis ✓	0.00	0.00	*16.00 F	
10	1		*1 pc front bumper aircon temperature sensor bracket	dis ✓	0.00	0.00	*10.00 F	
11	1		*1 pc bonnet	bt ✓	0.00	0.00	*350.00 F	
12	1		*1 pc bonnet inner lock	bt ✓	0.00	0.00	*75.00 F	
13	1		*2 pcs bonnet hinges @ \$28/pc	bt ✓	0.00	0.00	*56.00 F	
14	1		*1 pc bonnet insulator	dis ✓	0.00	0.00	*45.00 F	
15	1		*5 pcs bonnet insulator clips @ \$2/pc	dis ✓	0.00	0.00	*10.00 F	
16	1		*1 pc frt grille housing	dis ✓	0.00	0.00	*70.00 F	
17	1		*1 pc frt grille outer garnish	dis ✓	0.00	0.00	*155.00 F	
18	1		*1 pc frt grille outer chrome	dis ✓	0.00	0.00	*28.00 F	
19	1		*1 pc frt grille logo	dis ✓	0.00	0.00	*18.00 F	
20	1		*1 pc frt grille inner centre bracket	dis ✓	0.00	0.00	*13.00 F	
21	1		*1 pc frt grille upper grille	dis ✓	0.00	0.00	*18.00 F	
22	1		*2 pcs frt fenders @ \$160/pc	dis ✓	0.00	0.00	*320.00 F	
23	1		*2 pcs frt fender inner shields @ \$32/pc	dis ✓	0.00	0.00	*64.00 F	
24	1		*12 pcs frt fender inner shield clips @ \$2/pc	dis ✓	0.00	0.00	*24.00 F	
25	1		*2 pcs frt fender inner top side garnish @ \$18/pc	dis ✓	0.00	0.00	*36.00 F	
26	1		*2 pcs frt fender quarter garnishes @ \$20/pc	dis ✓	0.00	0.00	*40.00 F	✓DIS
27	1		*2 pcs headlamps @ \$195/pc	dis ✓	0.00	0.00	*390.00 F	
28	1		*2 pcs headlamp lower brackets @ \$18/pc	dis ✓	0.00	0.00	*36.00 F	
29	1		*1 pc RH horn	dis ✓	0.00	0.00	*35.00 F	
30	1		*1 pc frt support panel	dis ✓	0.00	0.00	*305.00 F	
31	1		*1 pc frt support panel inner top garnish	dis ✓	0.00	0.00	*22.00 F	
32	1		*6 pcs frt support panel inner top garnish clips @ \$2/pc	dis ✓	0.00	0.00	*12.00 F	
33	1		*1 pc frt support panel LH air duct	dis ✓	0.00	0.00	*28.00 F	
34	1		*2 pcs frt support panel side garnishes @ \$20/pc	dis ✓	0.00	0.00	*40.00 F	
35	1		*1 pc aircon condenser	dis ✓	0.00	0.00	*350.00 F	
36	1		*1 pc aircon condenser liquid pipe with switch	dis ✓	0.00	0.00	*90.00 F	
37	1		*1 pc aircon condenser discharge hose	dis ✓	0.00	0.00	*80.00 F	
38	1		*1 pc aircon condenser suction hose	dis ✓	0.00	0.00	*80.00 F	✓JBT
39	1		*1 pc radiator	dis ✓	0.00	0.00	*380.00 F	
40	1		*2 pcs radiator top brackets @ \$15/pc	dis ✓	0.00	0.00	*30.00 F	
41	1		*1 pc radiator top hose	dis ✓	0.00	0.00	*18.00 F	
42	1		*1 pc radiator bottom hose	dis ✓	0.00	0.00	*20.00 F	X
43	1		*1 pc radiator fan cowl	dis ✓	0.00	0.00	*55.00 F	
44	1		*1 pc radiator fan motor	dis ✓	0.00	0.00	*155.00 F	✓CUT
45	1		*1 pc radiator fan blade	dis ✓	0.00	0.00	*35.00 F	✓CRA
46	1		*1 pc radiator spare tank	dis ✓	0.00	0.00	*22.00 F	
47	1		*1 pc aircon fan cowling	dis ✓	0.00	0.00	*60.00 F	✓CRA

48	1	*1 pc aircon fan blade	7	0.00	0.00	*40.00 F	✓CRA
49	1	*1 pc aircon fan motor	7	0.00	0.00	*155.00 F	✓CRA
50	1	*1 pc wiper washer tank	det	0.00	0.00	*40.00 F	✓CRA
51	1	*1 pc alternator	nn	0.00	0.00	*500.00 F	X
52	1	*1 pc battery tray	3	0.00	0.00	*14.00 F	✓DIS
53	1	*1 pc RH engine mounting	3	0.00	0.00	*110.00 F	✓BT
54	1	*1 pc gearbox mounting	3	0.00	0.00	*90.00 F	✓DD
55	1	*1 pc gearbox oil cooler	3	0.00	0.00	*185.00 F	✓BT
56	1	*1 pc air filter housing assy	7	0.00	0.00	*160.00 F	✓CRA
57	1	*1 pc frt airbag sensor	nn	0.00	0.00	*80.00 F	
58	1	*1 pc frt windscreen glass	avg	0.00	0.00	*400.00 F	
59	1	*1 set frt windscreen glass mouldings (3 pcs)	nn	0.00	0.00	*90.00 F	
60	1	*1 pc frt dashboard	nn	0.00	0.00	*540.00 F	
61	1	*1 pc passenger airbag	act	0.00	0.00	*950.00 F	
62	1	*1 pc steering airbag	act	0.00	0.00	*650.00 F	
63	1	*1 pc steering airbag spiral cable	act	0.00	0.00	*230.00 F	✓
64	1	*1 pc airbag ECU	nn	0.00	0.00	*620.00 F	
65	1	*2 pcs frt seat belts @ \$410/pc	act	0.00	0.00	*820.00 F	
66	1	*2 pcs frt seat belt lower garnishes @ \$90/pc	nn	0.00	0.00	*180.00 F	X

F=Franchise part.

Sub Total (\$\$)	10,083.00
+ Margin on L,N Items 15.00% (\$\$)	1,512.45
Total Parts (\$\$)	11,595.45

Cheng Hoe Motor Pte Ltd/SCX1308U/18/04/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 pc battery <i>nn</i>	160.00 <i>?</i> <i>X</i>
2	1	1 pc ERP IU bracket	25.00 <i>W</i>
3	1	1 pc frt number plate	35.00 <i>W</i>
4	1	1 unit coolant	35.00 <i>W</i>
5	1	1 unit frt windscreen glass sealant	40.00 <i>W</i>
Sub Total (\$\$)			295.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Towing (bill attach)	New	50.00 ✓
2	Remove & refix aircon condenser, check, vacuum & refill gas	New	100.00 ✓
3	Remove & refix frt bumper, bonnet & attachments, grille, headlamps, both frt fenders; to cut, weld & renew frt support panel; knocking & repair frt chassis frames & realign both doors the same	New	1,200.00 <i>1000</i>
4	Putty & respray frt bumper, bonnet, both fenders, both doors, frt support panel, frt chassis frames & all affected areas	New	1,200.00 <i>11000</i>
5	Remove & refix frt windscreen glass	New	100.00 ✓
6	Remove & refix airbags, frt seat belts, airbag ECU, reset & reprogrammes the same	New	250.00 ✓
7	Remove & refix frt dashboard to facilitate repair	New	250.00 <i>200</i> ✓
8	Remove & refix gearbox oil cooler, engine mountings, gearbox mounting & realign the same	New	120.00 ✓
Gross Labour Cost (\$\$)			3,270.00

Cheng Hoe Motor Pte Ltd/SCX1308U/18/04/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Revert.
PIP Repw.
Before Paint photo
Hte Auto Club.
18/4/2018
12 w days*

*[Signature]
2/5/18*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

張建福 (機件) 拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 19848

Date: 16.04.2018

寶號

Messrs:

車號

Vehicle No:

由

From:

時間 (日/夜)

Time (day/night):

其他

Others:

cheag Hoe motor

SCX1308V

車型

Model No:

Honda city

到

To:

Auto point

TPY

CASH \$:

50

CHEQUE:

經手人

Authorised by:

子

收貨人

Received by:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

Att: MR Ma

OK

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Apr 2018)
 Parts: 143 HONDA CITY 1.5 (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/SCX1308U/18/04/2018 11:00
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 pc front bumper	0.00	0.00	*180.00 F
2	1		*1 pc front bumper reinforcement	0.00	0.00	*150.00 F
3	1		*1 pc front bumper lower centre grille	0.00	0.00	*50.00 F
4	1		*1 pc front bumper tow cover	0.00	0.00	*12.00 F
5	1		*1 pc front bumper RH fog lamp	0.00	0.00	*195.00 F X
6	1		*1 pc front bumper RH fog lamp cover	0.00	0.00	*18.00 F
7	1		*1 pc front bumper lower rubber	0.00	0.00	*15.00 F
8	1		*2 pcs front bumper side retainers @ \$9/pc	0.00	0.00	*18.00 F
9	1		*8 pcs front bumper clips @ \$2/pc	0.00	0.00	*16.00 F
10	1		*1 pc front bumper aircon temperature sensor bracket	0.00	0.00	*10.00 F
11	1		*1 pc bonnet	0.00	0.00	*350.00 F
12	1		*1 pc bonnet inner lock	0.00	0.00	*75.00 F
13	1		*2 pcs bonnet hinges @ \$28/pc	0.00	0.00	*56.00 F
14	1		*1 pc bonnet insulator	0.00	0.00	*45.00 F
15	1		*5 pcs bonnet insulator clips @ \$2/pc	0.00	0.00	*10.00 F
16	1		*1 pc frt grille housing	0.00	0.00	*70.00 F
17	1		*1 pc frt grille outer garnish	0.00	0.00	*155.00 F
18	1		*1 pc frt grille outer chrome	0.00	0.00	*28.00 F
19	1		*1 pc frt grille logo	0.00	0.00	*18.00 F
20	1		*1 pc frt grille inner centre bracket	0.00	0.00	*13.00 F
21	1		*1 pc frt grille upper grille	0.00	0.00	*18.00 F
22	1		*2 pcs frt fenders @ \$160/pc	0.00	0.00	*320.00 F
23	1		*2 pcs frt fender inner shields @ \$32/pc	0.00	0.00	*64.00 F
24	1		*12 pcs frt fender inner shield clips @ \$2/pc	0.00	0.00	*24.00 F
25	1		*2 pcs frt fender inner top side garnish @ \$18/pc	0.00	0.00	*36.00 F X
26	1		*2 pcs frt fender quarter garnishes @ \$20/pc	0.00	0.00	*40.00 F ✓
27	1		*2 pcs headlamps @ \$195/pc	0.00	0.00	*390.00 F
28	1		*2 pcs headlamp lower brackets @ \$18/pc	0.00	0.00	*36.00 F
29	1		*1 pc RH horn	0.00	0.00	*35.00 F
30	1		*1 pc frt support panel	0.00	0.00	*305.00 F
31	1		*1 pc frt support panel inner top garnish	0.00	0.00	*22.00 F
32	1		*6 pcs frt support panel inner top garnish clips @ \$2/pc	0.00	0.00	*12.00 F
33	1		*1 pc frt support panel LH air duct	0.00	0.00	*28.00 F X
34	1		*2 pcs frt support panel side garnishes @ \$20/pc	0.00	0.00	*40.00 F
35	1		*1 pc aircon condenser	0.00	0.00	*350.00 F
36	1		*1 pc aircon condenser liquid pipe with switch	0.00	0.00	*90.00 F
37	1		*1 pc aircon condenser discharge hose	0.00	0.00	*80.00 F ✓
38	1		*1 pc aircon condenser suction hose	0.00	0.00	*80.00 F ✓
39	1		*1 pc radiator	0.00	0.00	*380.00 F
40	1		*2 pcs radiator top brackets @ \$15/pc	0.00	0.00	*30.00 F X
41	1		*1 pc radiator top hose	0.00	0.00	*18.00 F
42	1		*1 pc radiator bottom hose	0.00	0.00	*20.00 F X
43	1		*1 pc radiator fan cowling	0.00	0.00	*55.00 F
44	1		*1 pc radiator fan motor	0.00	0.00	*155.00 F ✓
45	1		*1 pc radiator fan blade	0.00	0.00	*35.00 F ✓
46	1		*1 pc radiator spare tank	0.00	0.00	*22.00 F
47	1		*1 pc aircon fan cowling	0.00	0.00	*60.00 F ✓

48	1	*1 pc aircon fan blade	7	0.00	0.00	*40.00 F	✓
49	1	*1 pc aircon fan motor	7	0.00	0.00	*155.00 F	✓
50	1	*1 pc wiper washer tank	det	0.00	0.00	*40.00 F	
51	1	*1 pc alternator	7	0.00	0.00	*500.00 F	X
52	1	*1 pc battery tray	7	0.00	0.00	*14.00 F	✓
53	1	*1 pc RH engine mounting	7	0.00	0.00	*110.00 F	✓
54	1	*1 pc gearbox mounting	7	0.00	0.00	*90.00 F	✓
55	1	*1 pc gearbox oil cooler	7	0.00	0.00	*185.00 F	✓
56	1	*1 pc air filter housing assy	7	0.00	0.00	*160.00 F	✓
57	1	*1 pc frt airbag sensor	7	0.00	0.00	*80.00 F	
58	1	*1 pc frt windscreen glass	7	0.00	0.00	*400.00 F	
59	1	*1 set frt windscreen glass mouldings (3 pcs)	7	0.00	0.00	*90.00 F	
60	1	*1 pc frt dashboard	7	0.00	0.00	*540.00 F	
61	1	*1 pc passenger airbag	7	0.00	0.00	*950.00 F	
62	1	*1 pc steering airbag	7	0.00	0.00	*650.00 F	
63	1	*1 pc steering airbag spiral cable	7	0.00	0.00	*230.00 F	✓
64	1	*1 pc airbag ECU	7	0.00	0.00	*620.00 F	
65	1	*2 pcs frt seat belts @ \$410/pc	7	0.00	0.00	*820.00 F	
66	1	*2 pcs frt seat belt lower garnishes @ \$90/pc	7	0.00	0.00	*180.00 F	X

F=Franchise part.

Sub Total (S\$)	9094	10,083.00
+ Margin on L,N Items 15.00% (S\$)	1364.10	1,512.45
Total Parts (S\$)	10458.10	11,595.45

Cheng Hoe Motor Pte Ltd/SCX1308U/18/04/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

SCX1308U

60/Lope C

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 pc battery	160.00 X
2	1	1 pc ERP IU bracket	25.00
3	1	1 pc frt number plate	35.00
4	1	1 unit coolant	35.00
5	1	1 unit frt windscreen glass sealant	40.00
Sub Total (S\$)			295.00

135

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Towing (bill attach)	New	50.00 ✓
2	Remove & refix aircon condenser, check, vacuum & refill gas	New	100.00 ✓
3	Remove & refix frt bumper, bonnet & attachments, grille, headlamps, both frt fenders; to cut, weld & renew frt support panel; knocking & repair frt chassis frames & realign both doors the same	New	1,200.00 ✓
4	Putty & respray frt bumper, bonnet, both fenders, both doors, frt support panel, frt chassis frames & all affected areas	New	1,200.00 ✓
5	Remove & refix frt windscreen glass	New	100.00 ✓
6	Remove & refix airbags, frt seat belts, airbag ECU, reset & reprogrammes the same	New	250.00 ✓
7	Remove & refix frt dashboard to facilitate repair	New	250.00 ✓
8	Remove & refix gearbox oil cooler, engine mountings, gearbox mounting & realign the same	New	120.00 ✓
Gross Labour Cost (S\$)			3,270.00

2920

Cheng Hoe Motor Pte Ltd/SCX1308U/18/04/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Revert.
PIP Repair.
Before paint photo
18/4/2018
12 working days

PARTS: 10458.10
SN: 135
L: 2920
13513.10

PIP: 13513.10

PLS CHECK & CONFIRM.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Apr 2018 Sendback Est	18 Apr 2018 11:00 S\$15,160.45	18 Apr 2018 11:31 Edit Adj Rpt	S\$13,513.10 Edit Estimates	S\$13,513.10 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	JACQUELINE LEE SIOW YEN, ID: S6976694C, Tel: +6597232280, Email: jaclee.sg@gmail.com		
Vehicle Reg. No.:	SCX1308U	Date of Loss:	16/04/2018 18:00 - :59 [39 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 17/18/18/VP05/020551	Policy/Cover Note No.:	Z17VP05016029 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 27/04/2018]		
Driver/Custodian:	JACQUELINE LEE SIOW YEN (48 / Female), NRIC: S6976694C, Tel: +6597232280		
Adj Asg. Remarks:	Survey & revert. Excess is Nil.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- LONPAC_HQ (19/04/2018): Alert - Adj Mandate Approved (S\$14478.10) - SCX1308U - Claim Handler: Gerald Poh

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

SCX1308U (17/18/18/VP05/020551)

OD

Apr 16 2018 6:00PM

[JACQUELINE LEE SIOW YEN]

Cheng Hoe Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

Assessment Reports

No	Finalized On		1 per page	Thumbnail	Print
1	18/04/18 11:00	Cheng Hoe Motor Pte Ltd (Yishun)		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/04/18 10:16	Adjuster Immediate Advice		Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	Thumbnail	Print
1	19/04/18 08:32	General View		Load JPG	☒
2	19/04/18 08:32	General View		Load JPG	☒
3	19/04/18 08:32	General View		Load JPG	☒
4	19/04/18 08:32	General View		Load JPG	☒
5	19/04/18 08:32	General View		Load JPG	☒
6	19/04/18 08:32	General View		Load JPG	☒
7	19/04/18 08:32	General View		Load JPG	☒
8	19/04/18 08:32	General View		Load JPG	☒
9	19/04/18 08:32	General View		Load JPG	☒
10	19/04/18 08:32	General View		Load JPG	☒
11	19/04/18 08:32	General View		Load JPG	☒
12	19/04/18 08:32	General View		Load JPG	☒
13	19/04/18 08:32	General View		Load JPG	☒
14	19/04/18 08:32	General View		Load JPG	☒
15	19/04/18 08:32	General View		Load JPG	☒
16	19/04/18 08:32	General View		Load JPG	☒
17	19/04/18 08:32	General View		Load JPG	☒
18	19/04/18 08:32	General View		Load JPG	☒
19	19/04/18 08:32	General View		Load JPG	☒
20	19/04/18 08:32	General View		Load JPG	☒
21	19/04/18 08:32	General View		Load JPG	☒
22	19/04/18 08:32	General View		Load JPG	☒
23	19/04/18 08:32	General View		Load JPG	☒
24	19/04/18 08:32	General View		Load JPG	☒
25	19/04/18 08:32	General View		Load JPG	☒
26	19/04/18 08:32	General View		Load JPG	☒
27	19/04/18 08:32	General View		Load JPG	☒
28	19/04/18 08:32	General View		Load JPG	☒
29	19/04/18 08:32	General View		Load JPG	☒
30	19/04/18 08:32	General View		Load JPG	☒
31	19/04/18 08:32	General View		Load JPG	☒
32	19/04/18 08:32	General View		Load JPG	☒

Assessment Reports			1 per page ▾	✓
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
33	19/04/18 08:32	General View	 Load JPG	✓
34	19/04/18 08:32	General View	 Load JPG	✓
35	19/04/18 08:32	General View	 Load JPG	✓
36	19/04/18 08:32	General View	 Load JPG	✓
37	19/04/18 08:32	General View	 Load JPG	✓
38	19/04/18 08:32	General View	 Load JPG	✓
39	19/04/18 08:32	General View	 Load JPG	✓
40	19/04/18 08:32	General View	 Load JPG	✓
41	19/04/18 08:32	General View	 Load JPG	✓
42	19/04/18 08:32	General View	 Load JPG	✓
43	19/04/18 08:32	General View	 Load JPG	✓
44	19/04/18 08:32	General View	 Load JPG	✓
45	19/04/18 08:32	General View	 Load JPG	✓
46	19/04/18 08:32	General View	 Load JPG	✓
47	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
48	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
49	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
50	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
51	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
52	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
53	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
54	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
55	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
56	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
57	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
58	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
59	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
60	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
61	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
62	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
63	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
64	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
65	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
66	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
67	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
68	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
69	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
70	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
71	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
72	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
73	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
74	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
75	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
76	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
77	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
78	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
79	24/10/18 10:27	Reinspection Photo	 Load JPG	✓
80	24/10/18 10:27	Reinspection Photo	Load JPG	✓

Assessment Reports			1 per page ▾	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
81	24/10/18 10:27	Reinspection Photo	 Load JPG	☒
82	24/10/18 10:27	Reinspection Photo	 Load JPG	☒
83	24/10/18 10:27	Reinspection Photo	 Load JPG	☒
84	24/10/18 10:27	Reinspection Photo	 Load JPG	☒
85	24/10/18 10:29	Reinspection Photo	 Load JPG	☒
86	24/10/18 10:29	Reinspection Photo	 Load JPG	☒
87	24/10/18 10:29	Reinspection Photo	 Load JPG	☒
88	24/10/18 10:29	Reinspection Photo	 Load JPG	☒
89	24/10/18 10:29	Reinspection Photo	 Load JPG	☒
90	24/10/18 10:29	Reinspection Photo	 Load JPG	☒
91	24/10/18 10:29	Reinspection Photo	 Load JPG	☒
92	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
93	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
94	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
95	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
96	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
97	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
98	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
99	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
100	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
101	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
102	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
103	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
104	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
105	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
106	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
107	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
108	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
109	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
110	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
111	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
112	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
113	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
114	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
115	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
116	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
117	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
118	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
119	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
120	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
121	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
122	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
123	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
124	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
125	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
126	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
127	24/10/18 10:32	Reinspection Photo	 Load JPG	☒
128	24/10/18 10:32	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
129	24/10/18 10:32	Reinspection Photo	Load JPG	☒
130	24/10/18 10:32	Reinspection Photo	Load JPG	☒
131	24/10/18 10:32	Reinspection Photo	Load JPG	☒
132	24/10/18 10:32	Reinspection Photo	Load JPG	☒
133	24/10/18 10:32	Reinspection Photo	Load JPG	☒
134	24/10/18 10:32	Reinspection Photo	Load JPG	☒
135	24/10/18 10:32	Reinspection Photo	Load JPG	☒
136	24/10/18 10:32	Reinspection Photo	Load JPG	☒
137	24/10/18 10:32	Reinspection Photo	Load JPG	☒
138	24/10/18 10:32	Reinspection Photo	Load JPG	☒
139	24/10/18 10:32	Reinspection Photo	Load JPG	☒
140	24/10/18 10:32	Reinspection Photo	Load JPG	☒
141	24/10/18 10:32	Reinspection Photo	Load JPG	☒
142	24/10/18 10:32	Reinspection Photo	Load JPG	☒
143	24/10/18 10:32	Reinspection Photo	Load JPG	☒
144	24/10/18 10:32	Reinspection Photo	Load JPG	☒
145	24/10/18 10:32	Reinspection Photo	Load JPG	☒
146	24/10/18 10:32	Reinspection Photo	Load JPG	☒
147	24/10/18 10:33	Photo After Spray	Load JPG	☒
148	24/10/18 10:33	Photo After Spray	Load JPG	☒
149	24/10/18 10:33	Photo After Spray	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	18/04/18 10:56	TOWING BILL	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/04/18 10:16	MARK ESTIMATE	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	1 per page	☒
1	17/04/18 12:47	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	17/04/18 12:47	Accident Photo	Load JPG	☒
2	17/04/18 12:47	Accident Photo	Load JPG	☒
3	17/04/18 12:47	Accident Photo	Load JPG	☒
4	17/04/18 12:47	Accident Photo	Load JPG	☒
5	17/04/18 12:47	Accident Photo	Load JPG	☒
6	17/04/18 12:47	Accident Photo	Load JPG	☒
7	17/04/18 12:47	SCENE PHOTO	Load JPG	☒
8	17/04/18 12:47	SCENE PHOTO	Load JPG	☒
9	17/04/18 12:47	SCENE PHOTO	Load JPG	☒
10	17/04/18 12:47	SCENE PHOTO	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print

Assessment Reports				1 per page	☒
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	17/04/18 12:46	Sketch Plan		Load JPG	☒
2	17/04/18 12:46	Sketch Plan #2		Load JPG	☒
3	17/04/18 12:46	Sketch Plan #3		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18007204/M1VBS2
Date: 08/11/2018

REFERENCE

Insured/Claimant: JACQUELINE LEE SIOW YEN Policy No: Z17VP05016029
Date of Loss: 16/04/2018 Nature of Claim: OD Claim No: 17/18/18/VP05/020551

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCX1308U**
Make & Model: HONDA CITY, 1.5 (A) Engine No: L15Z11414255
Reg. Date: 02/01/2015 (Man. Year: 2014) Chassis No: MRHGM6660EP000145
Colour: Blue Odometer: 0 km
Engine Capacity: 1497 cc
Market Value/New Car Price: S\$65,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R16 Rear Tyre Size: 185/55R16
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm
The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,595.45	10,458.10	1,137.35	9.81
Miscellaneous Items	295.00	135.00	160.00	54.24
Labour	3,270.00	2,920.00	350.00	10.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,160.45	13,513.10	1,647.35	10.87
+ GST 7.00/7.00% (S\$)	1,061.23	945.92	115.31	10.87
Nett Amount (S\$)	16,221.68	14,459.02	1,762.66	10.87

INSPECTION

Date of Assignment: 18/04/2018 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 18/04/2018 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Estimated Period of Repair: 12.0 days Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Adjuster: MA CHIN FOOK

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2018)
Parts:	143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCX1308U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc front bumper (WCP)	Deformed	180.00 F	*180.00 F
2	1		*1 pc front bumper reinforcement (WCP)	Bent	150.00 F	*150.00 F
3	1		*1 pc front bumper lower centre grille (WCP)	Distorted	50.00 F	*50.00 F
4	1		*1 pc front bumper tow cover (WCP)	Distorted	12.00 F	*12.00 F
5	1		*1 pc front bumper RH fog lamp (WCP)	Serviceable	195.00 F	*- F
6	1		*1 pc front bumper RH fog lamp cover (WCP)	Missing	18.00 F	*18.00 F
7	1		*1 pc front bumper lower rubber (WCP)	Necessary	15.00 F	*15.00 F
8	1		*2 pcs front bumper side retainers @ \$9/pc (WCP)	Distorted	18.00 F	*18.00 F
9	1		*8 pcs front bumper clips @ \$2/pc (WCP)	Necessary	16.00 F	*16.00 F
10	1		*1 pc front bumper aircon temperature sensor bracket (WCP)	Distorted	10.00 F	*10.00 F
11	1		*1 pc bonnet (WCP)	Bent	350.00 F	*350.00 F
12	1		*1 pc bonnet inner lock (WCP)	Bent	75.00 F	*75.00 F
13	1		*2 pcs bonnet hinges @ \$28/pc (WCP)	Bent	56.00 F	*56.00 F
14	1		*1 pc bonnet insulator (WCP)	Distorted	45.00 F	*45.00 F
15	1		*5 pcs bonnet insulator clips @ \$2/pc (WCP)	Necessary	10.00 F	*10.00 F
16	1		*1 pc frt grille housing (WCP)	Missing	70.00 F	*70.00 F
17	1		*1 pc frt grille outer garnish (WCP)	Missing	155.00 F	*155.00 F
18	1		*1 pc frt grille outer chrome (WCP)	Missing	28.00 F	*28.00 F
19	1		*1 pc frt grille logo (WCP)	Missing	18.00 F	*18.00 F
20	1		*1 pc frt grille inner centre bracket (WCP)	Missing	13.00 F	*13.00 F
21	1		*1 pc frt grille upper grille (WCP)	Missing	18.00 F	*18.00 F
22	1		*2 pcs frt fenders @ \$160/pc (WCP)	Bent	320.00 F	*320.00 F
23	1		*2 pcs frt fender inner shields @ \$32/pc (WCP)	Distorted	64.00 F	*64.00 F
24	1		*12 pcs frt fender inner shield clips @ \$2/pc (WCP)	Cut	24.00 F	*24.00 F
25	1		*2 pcs frt fender inner top side garnish @ \$18/pc (WCP)	Serviceable	36.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*2 pcs frt fender quarter garnishs @ \$20/pc (WCP)	Distorted	40.00 F	*40.00 F
27	1		*2 pcs headlamps @ \$195/pc (WCP)	Cracked	390.00 F	*390.00 F
28	1		*2 pcs headlamp lower brackets @ \$18/pc (WCP)	Distorted	36.00 F	*36.00 F
29	1		*1 pc RH horn (WCP)	Dented	35.00 F	*35.00 F
30	1		*1 pc frt support panel (WCP)	Bent	305.00 F	*305.00 F
31	1		*1 pc frt support panel inner top garnish (WCP)	Distorted	22.00 F	*22.00 F
32	1		*6 pcs frt support panel inner top garnish clips @ \$2/pc (WCP)	Necessary	12.00 F	*12.00 F
33	1		*1 pc frt support panel LH air duct (WCP)	Serviceable	28.00 F	*- F
34	1		*2 pcs frt support panel side garnishs @ \$20/pc (WCP)	Distorted	40.00 F	*40.00 F
35	1		*1 pc aircon condenser (WCP)	Bent	350.00 F	*350.00 F
36	1		*1 pc aircon condenser liquid pipe with switch (WCP)	Bent	90.00 F	*90.00 F
37	1		*1 pc aircon condenser discharge hose (WCP)	Bent	80.00 F	*80.00 F
38	1		*1 pc aircon condenser suction hose (WCP)	Bent	80.00 F	*80.00 F
39	1		*1 pc radiator (WCP)	Bent	380.00 F	*380.00 F
40	1		*2 pcs radiator top brackets @ \$15/pc (WCP)	Repair	30.00 F	*- F
41	1		*1 pc radiator top hose (WCP)	Distorted	18.00 F	*18.00 F
42	1		*1 pc radiator bottom hose (WCP)	Not Necessary	20.00 F	*- F
43	1		*1 pc radiator fan cowling (WCP)	Distorted	55.00 F	*55.00 F
44	1		*1 pc radiator fan motor (WCP)	Cut	155.00 F	*155.00 F
45	1		*1 pc radiator fan blade (WCP)	Cracked	35.00 F	*35.00 F
46	1		*1 pc radiator spare tank (WCP)	Distorted	22.00 F	*22.00 F
47	1		*1 pc aircon fan cowling (WCP)	Cracked	60.00 F	*60.00 F
48	1		*1 pc aircon fan blade (WCP)	Cracked	40.00 F	*40.00 F
49	1		*1 pc aircon fan motor (WCP)	Cut	155.00 F	*155.00 F
50	1		*1 pc wiper washer tank (WCP)	Deformed	40.00 F	*40.00 F
51	1		*1 pc alternator (WCP)	Not Necessary	500.00 F	*- F
52	1		*1 pc battery tray (WCP)	Distorted	14.00 F	*14.00 F
53	1		*1 pc RH engine mounting (WCP)	Bent	110.00 F	*110.00 F
54	1		*1 pc gearbox mounting (WCP)	Dented	90.00 F	*90.00 F
55	1		*1 pc gearbox oil cooler (WCP)	Bent	185.00 F	*185.00 F
56	1		*1 pc air filter housing assy (WCP)	Cracked	160.00 F	*160.00 F
57	1		*1 pc frt airbag sensor (WCP)	Necessary	80.00 F	*80.00 F
58	1		*1 pc frt windscreen glass (WCP)	Cracked	400.00 F	*400.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
59	1		*1 set frt windscreen glass mouldings (3 pcs) (WCP)	Necessary	90.00 F	*90.00 F
60	1		*1 pc frt dashboard (WCP)	Torn	540.00 F	*540.00 F
61	1		*1 pc passenger airbag (WCP)	Activated	950.00 F	*950.00 F
62	1		*1 pc steering airbag (WCP)	Activated	650.00 F	*650.00 F
63	1		*1 pc steering airbag spiral cable (WCP)	Activated	230.00 F	*230.00 F
64	1		*1 pc airbag ECU (WCP)	Necessary	620.00 F	*620.00 F
65	1		*2 pcs frt seat belts @ \$410/pc (WCP)	Activated	820.00 F	*820.00 F
66	1		*2 pcs frt seat belt lower garnishs @ \$90/pc (WCP)	Not Necessary	180.00 F	*- F

F=Franchise part.

Sub Total (\$\$)	10,083.00	9,094.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	1,512.45	1,364.10
Total Parts (\$\$)	11,595.45	10,458.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 pc battery (NOT NECESSARY)	160.00	0.00
2	1	1 pc ERP IU bracket (NECESSARY)	25.00	25.00
3	1	1 pc frt number plate (BENT)	35.00	35.00
4	1	1 unit coolant (NECESSARY)	35.00	35.00
5	1	1 unit frt windscreen glass sealant (NECESSARY)	40.00	40.00
Sub Total (S\$)			295.00	135.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Towing (bill attach)	New	50.00	50.00
2	Remove & refix aircon condenser,check,vacuum & refill gas	New	100.00	100.00
3	Remove & refix frt bumper,bonnet & attachments,grille,headlamps,both frt fenders; to cut,weld & renew frt support panel;knocking & repair frt chassis frames & realign both doors the same	New	1,200.00	1,000.00
4	Putty & respray frt bumper,bonnet,both fenders,both doors,frt support panel,frt chassis frames & all affected areas	New	1,200.00	1,100.00
5	Remove & refix frt windscreen glass	New	100.00	100.00
6	Remove & refix airbags,frt seat belts,airbag ECU,reset & reprogrammes the same	New	250.00	250.00
7	Remove & refix frt dashboard to facilitate repair	New	250.00	200.00
8	Remove & refix gearbox oil cooler,engine mountings,gearbox mounting & realign the same	New	120.00	120.00
Gross Labour Cost (S\$)			3,270.00	2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >