



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD/LONPAC
Policy No:	Z17VP05016029	Date of Loss:	16/04/2018
Vehicle Reg. No.:	SCX1308U	Driveable?	
Driver Age/Info:	48 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	JACQUELINE LEE SIOW YEN	Contact No:	+6597232280
Driver:	JACQUELINE LEE SIOW YEN		
Make/Model:	HONDA CITY, 1.5 (A)	Vehicle Reg. Date:	02/01/2015
Vehicle Colour:	Blue		
Engine No:	L15Z11414255	Chassis No:	MRHGM6660EP000145
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	TRAFFIC WAS HEAVY AND WE ARE ON 'STOP AND MOVE' MOTION. HALFWAY THROUGH, SOMETHING HIT ONTO MY LEG AND CAUSED MY RIGHT LEG TO ACCIDENTALLY STEP HARDER ON THE ACCELERATOR DUE TO THE SHOCK. MY VEHICLE THEN WENT FORWARD AND HIT ONTO THE REAR OF MOTOR CAR SJP5630X. NO ONE WAS INJURED, MY CAR WAS TOWED TO THE NEAREST AWS AFTER THE ACCIDENT.		
Remarks:	VEHICLE TOW IN TO ANG MO KIO WORKSHOP ON 16/04/2018 NIGHT		
Present Location:	CHENG HOE MOTOR PTE LTD (AMK)		

COST OF CLAIMS	Amount
Parts	11,595.45
Miscellaneous Items	295.00
Labour	3,270.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	15,160.45
+ GST 7.00% (\$)	1,061.23
Nett Amount (\$)	16,221.68

This claim is handled by: DORLYN LI YAZHU

*Generated using **Merimen e-Claims Internet Estimation & Adjusting System***

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 18 Apr 2018)
Parts:	143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	Cheng Hoe Motor Pte Ltd/SCX1308U/18/04/2018 11:00		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*1 pc front bumper	det ✓	0.00	0.00	*180.00 F
2	1		*1 pc front bumper reinforcement	det ✓	0.00	0.00	*150.00 F
3	1		*1 pc front bumper lower centre grille	dis ✓	0.00	0.00	*50.00 F
4	1		*1 pc front bumper tow cover	dis ✓	0.00	0.00	*12.00 F
5	1		*1 pc front bumper RH fog lamp	dis ✓	0.00	0.00	*195.00 F
6	1		*1 pc front bumper RH fog lamp cover	dis ✓	0.00	0.00	*18.00 F
7	1		*1 pc front bumper lower rubber	dis ✓	0.00	0.00	*15.00 F
8	1		*2 pcs front bumper side retainers @ \$9/pc	dis ✓	0.00	0.00	*18.00 F
9	1		*8 pcs front bumper clips @ \$2/pc	dis ✓	0.00	0.00	*16.00 F
10	1		*1 pc front bumper aircon temperature sensor bracket	dis ✓	0.00	0.00	*10.00 F
11	1		*1 pc bonnet	dis ✓	0.00	0.00	*350.00 F
12	1		*1 pc bonnet inner lock	dis ✓	0.00	0.00	*75.00 F
13	1		*2 pcs bonnet hinges @ \$28/pc	dis ✓	0.00	0.00	*56.00 F
14	1		*1 pc bonnet insulator	dis ✓	0.00	0.00	*45.00 F
15	1		*5 pcs bonnet insulator clips @ \$2/pc	dis ✓	0.00	0.00	*10.00 F
16	1		*1 pc frt grille housing	dis ✓	0.00	0.00	*70.00 F
17	1		*1 pc frt grille outer garnish	dis ✓	0.00	0.00	*155.00 F
18	1		*1 pc frt grille outer chrome	dis ✓	0.00	0.00	*28.00 F
19	1		*1 pc frt grille logo	dis ✓	0.00	0.00	*18.00 F
20	1		*1 pc frt grille inner centre bracket	dis ✓	0.00	0.00	*13.00 F
21	1		*1 pc frt grille upper grille	dis ✓	0.00	0.00	*18.00 F
22	1		*2 pcs frt fenders @ \$160/pc	dis ✓	0.00	0.00	*320.00 F
23	1		*2 pcs frt fender inner shields @ \$32/pc	dis ✓	0.00	0.00	*64.00 F
24	1		*12 pcs frt fender inner shield clips @ \$2/pc	dis ✓	0.00	0.00	*24.00 F
25	1		*2 pcs frt fender inner top side garnish @ \$18/pc	dis ✓	0.00	0.00	*36.00 F
26	1		*2 pcs frt fender quarter garnishes @ \$20/pc	dis ✓	0.00	0.00	*40.00 F
27	1		*2 pcs headlamps @ \$195/pc	dis ✓	0.00	0.00	*390.00 F
28	1		*2 pcs headlamp lower brackets @ \$18/pc	dis ✓	0.00	0.00	*36.00 F
29	1		*1 pc RH horn	dis ✓	0.00	0.00	*35.00 F
30	1		*1 pc frt support panel	dis ✓	0.00	0.00	*305.00 F
31	1		*1 pc frt support panel inner top garnish	dis ✓	0.00	0.00	*22.00 F
32	1		*6 pcs frt support panel inner top garnish clips @ \$2/pc	dis ✓	0.00	0.00	*12.00 F
33	1		*1 pc frt support panel LH air duct	dis ✓	0.00	0.00	*28.00 F
34	1		*2 pcs frt support panel side garnishes @ \$20/pc	dis ✓	0.00	0.00	*40.00 F
35	1		*1 pc aircon condenser	dis ✓	0.00	0.00	*350.00 F
36	1		*1 pc aircon condenser liquid pipe with switch	dis ✓	0.00	0.00	*90.00 F
37	1		*1 pc aircon condenser discharge hose	dis ✓	0.00	0.00	*80.00 F
38	1		*1 pc aircon condenser suction hose	dis ✓	0.00	0.00	*80.00 F
39	1		*1 pc radiator	dis ✓	0.00	0.00	*380.00 F
40	1		*2 pcs radiator top brackets @ \$15/pc	dis ✓	0.00	0.00	*30.00 F
41	1		*1 pc radiator top hose	dis ✓	0.00	0.00	*18.00 F
42	1		*1 pc radiator bottom hose	dis ✓	0.00	0.00	*20.00 F
43	1		*1 pc radiator fan cowling	dis ✓	0.00	0.00	*55.00 F
44	1		*1 pc radiator fan motor	dis ✓	0.00	0.00	*155.00 F
45	1		*1 pc radiator fan blade	dis ✓	0.00	0.00	*35.00 F
46	1		*1 pc radiator spare tank	dis ✓	0.00	0.00	*22.00 F
47	1		*1 pc aircon fan cowling	dis ✓	0.00	0.00	*60.00 F

48	1	*1 pc aircon fan blade	7	0.00	0.00	*40.00 F
49	1	*1 pc aircon fan motor	7	0.00	0.00	*155.00 F
50	1	*1 pc wiper washer tank	del 7	0.00	0.00	*40.00 F
51	1	*1 pc alternator	3	0.00	0.00	*500.00 F
52	1	*1 pc battery tray	3	0.00	0.00	*14.00 F
53	1	*1 pc RH engine mounting	3	0.00	0.00	*110.00 F
54	1	*1 pc gearbox mounting	3	0.00	0.00	*90.00 F
55	1	*1 pc gearbox oil cooler	3	0.00	0.00	*185.00 F
56	1	*1 pc air filter housing assy	3	0.00	0.00	*160.00 F
57	1	*1 pc frt airbag sensor	new assy 7	0.00	0.00	*80.00 F
58	1	*1 pc frt windscreen glass	avg 7	0.00	0.00	*400.00 F
59	1	*1 set frt windscreen glass mouldings (3 pcs)	new 7	0.00	0.00	*90.00 F
60	1	*1 pc frt dashboard	don 7	0.00	0.00	*540.00 F
61	1	*1 pc passenger airbag	act 7	0.00	0.00	*950.00 F
62	1	*1 pc steering airbag	act 7	0.00	0.00	*650.00 F
63	1	*1 pc steering airbag spiral cable	7	0.00	0.00	*230.00 F
64	1	*1 pc airbag ECU	new 7	0.00	0.00	*620.00 F
65	1	*2 pcs frt seat belts @ \$410/pc	new 7	0.00	0.00	*820.00 F
66	1	*2 pcs frt seat belt lower garnishes @ \$90/pc	act 7	0.00	0.00	*180.00 F

F=Franchise part.

Sub Total (\$\$)	10,083.00
+ Margin on L,N Items 15.00% (\$\$)	1,512.45
Total Parts (\$\$)	11,595.45

Cheng Hoe Motor Pte Ltd/SCX1308U/18/04/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 pc battery	160.00
2	1	1 pc ERP IU bracket	25.00
3	1	1 pc frt number plate	35.00
4	1	1 unit coolant	35.00
5	1	1 unit frt windscreen glass sealant	40.00
Sub Total (\$)			295.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Towing (bill attach)	New	50.00
2	Remove & refix aircon condenser,check,vacuum & refill gas	New	100.00
3	Remove & refix frt bumper,bonnet & attachments,grille,headlamps,both frt fenders; to cut,weld & renew frt support panel;knocking & repair frt chassis frames & realign both doors the same	New	1,200.00
4	Putty & respray frt bumper,bonnet,both fenders,both doors,frt support panel,frt chassis frames & all affected areas	New	1,200.00
5	Remove & refix frt windscreen glass	New	100.00
6	Remove & refix airbags,frt seat belts,airbag ECU,reset & reprogrammes the same	New	250.00
7	Remove & refix frt dashboard to facilitate repair	New	250.00
8	Remove & refix gearbox oil cooler,engine mountings,gearbox mounting & realign the same	New	120.00
Gross Labour Cost (\$)			3,270.00

Cheng Hoe Motor Pte Ltd/SCX1308U/18/04/2018 11:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Revert.
PIP Repair.
Before Paint photo
HKK Auto
18/4/2018
12 working days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: