Quotation Details - Quotation No SN-002012-18-20015

Customer Details:

MS SABINA TEO

201E JOO CHIAT PLACE SINGAPORE 427920

View Photo Accident Photo

Vehicle Details

Vehicle No : SKD 7139 L

Vehicle Make : VW

: TOURAN 2011

Vehicle Engine :

Vehicle

Model

No Engine Chasis No

Mileage:

Owner's Accident

<u>Details</u>

Job No SN-: 002012-18-20015

Date Created: 5/5/2015

JobCategory TP - : Lump Sum

Date of Acident:
Owner's Insurer:
Location of:
Accident

Suveyor's Details

Surveyor Name : Surveyor : Company Surveyor :

ContactNo
Surveyor FaxNo:
Quotation:
Submission

Date

Surveyor : Approve Date Supplementary :

Date

Supplementary : Approve Date

Not Northankel	
61 Em 87	
Berny Ath Pains	
The said	
Menney dallants hence notify	,
Menneth Table 1 (1) I following: 1 (1) I following: 1 (1) I following: 1 (2) I following: 2 (2) I following: 2 (2) I following: 2 (2) I following: 3 (2) I following: 4 (2) I following: 4 (2) I following: 4 (2) I following: 5 (2) I following: 5 (2) I following: 6 (2) I following: 7 (2) I following: 8 (2) I following: 1 (2) I following: 1 (2) I following: 1 (2) I following: 1 (2) I following: 2 (2) I following: 2 (2) I following: 3 (2) I following: 4 (2) I following: 4 (2) I following: 5 (2) I following: 6 (2) I following: 7 (2) I following: 8 (2) I following: 9 (2) I following: 1 (2) I following: 2 (2) I following: 2 (2) I following: 3 (2) I following: 4 (2) I following: 5 (2) I following: 6 (2) I following: 7 (2) I following: 8 (2) I following: 9 (2) I following: 1 (2) I following: 2 (2) I following: 2 (2) I following: 2 (2) I following: 3 (2) I following: 4 (2) I following: 5 (2) I following: 6 (2) I following: 7 (2) I following: 8 (2) I following: 1 (2) I following: 1 (2) I following: 1 (2) I following: 2 (2) I following: 2 (2) I foll	
subject to confirmation	
lem(s) is allowed "ejudice" basis	
al approval from insurance	
by Repairer	

Item N	No Ref No	Description	QTY	Unit List Price	Mark Up / Discount %	Mark Up / Discount Price	Total Price	Rev I Qty	Rev Unit Price	Total Surveyor Price Approval
Mate	erials									
1	1	Tailgate (Repair)	1	\$0.00	0.00	\$0.00	\$0.00	0	0	\$0.00
2	2	Tailgate Logo	1	\$140.99	-10.00	\$126.89	\$126.89	0	0 Me	\$0.00
3	3	Tailgate Emblem "Touran"	1	\$140.99	-10.00	\$126.89	\$126.89	0	0 M	\$0.00
4	4	Rear Bumper	1	\$1,600.71	-10.00	\$1,440.64	\$1,440.64	. 0	0 cm	\$0.00
5	5	Rear Bumper Retainer LH	1	\$68.78	-10.00	\$61.90	\$61.90	0	0 14	\$0.00 🗶
6	6	Rear Bumper Retainer RH		\$68.78	-10.00	\$61.90	\$61.90	0	0 /n	\$0.00 X
7	7	Rear Bumper Bracket LH	1	\$90.17	-10.00	\$81.15	\$81.15	0	0	\$0.00 7
8	8	Rear Bumper Bracket RH	1	\$90.17	-10.00	\$81.15	\$81.15	0	0	\$0.00_7

9	9	Rear Bumper Reflector 1 LH	\$100.71	-10.00	\$90.64	\$90.64	0	0	Sin \$0.00_
10	10	Rear Bumper Reflector 1	\$100.71	-10.00	\$90.64	\$90.64	0	0	\$n \$0.00 X
11	11	Rear Bumper Reverse 1 Sensor	\$239.70	-10.00	\$215.73	\$215.73	0	0	\$0.00
12	12	Rear Bumper 1 Reinforcement	\$700.71	-10.00	\$630.64	\$630.64	0	0	\$0.00
13	13	Rear Bumper Clips 10	\$7.00	-10.00	\$6.30	\$63.00	0	0	Ma \$0.00
14	14	Rear End Panel 1	\$1,200.77	-10.00	\$1,080.69	\$1,080.69	0	0	n \$0.00 x
15	15	Rear End Panel Top 1 Garnish	\$268.78	-10.00	\$241.90	\$241.90	0	0	\$0.00 X
16	16	Rear End Panel Top 6 Garnish Clips	\$7.00	-10.00	\$6.30	\$37.80	0	0	~~ \$0.00_X_

Material Total: \$4,431.57 Final Sub-Total: \$0.00

Special Nett Items

Final Sub-Total: \$0.00 Special Nett Items Total: \$0.00 Labour \$0.00 17 Straighten & Panel Bear 1 \$800.00 0.00 \$800.00 \$800.00 Accident Area \$0.00 18 Check & Reconnet Wiring 1 0.00 \$60.00 \$60.00 2 \$60.00 \$0.00 3 19 Rust Proof \$80.00 0.00 \$80.00 \$80.00 Respray damaged area \$0.00 \$600.00 4 20 \$600.00 0.00 \$600.00 0

Labour Total: \$1,540.00 Final Sub-Total: \$0.00

Others

Others Total: \$0.00 Final Sub-Total: \$0.00

Total Price: \$5,971.57 Final Total Price: \$0.00